

Not Notified
11 Aug 87
Resony After Paint
3 days

C. S. ONG AUTO PTE. LTD.

Company & GST Reg No.: 201408916W
10, Ang Mo Kio Ind. Park 2A, #02-16, AMK AutoPoint, Singapore (568047)
Tel: 6484 1933 | Fax: 6484 1922
E-Mail: csongauto@yahoo.com.sg

To: Motor Claims Department,

Date: 16 /07/2018

Accident Involving Vehicles SMA8996P & SH8873C [Your Insured] 14/07/2018 @
1915 Hrs Along Singapore Zoo Carpark.

Estimated Repair Costs For SMA8896P Toyota Wish (1.8 CVT)

1Pc Front Bumper	Bu	\$	560.60	✓
1Set Front Bumper Clips	na	\$	30.00	✓
1Pc Front Bumper Side Retainer LH	na	\$	75.30	✓
1Pc Front Headlight LH with Bracket		\$	933.70	✓
1Pc Front Fender LH		\$	795.95	X
1Pc Front Fender Inner Shield LH		\$	158.70	X
1Set Front Fender LH Inner Shield Clips		\$	30.00	X
Total:		\$	2,584.25	
Parts Less 25%:		\$	646.06	
Parts Total:		\$	1,938.19	

Labour & MISC Charges

<u>Description</u>	<u>Amount</u>
* To panel beat, repair & replace all front damaged panels.	\$ 800.00 3001
* To putty & re-spray new paintwork on all rear affected areas.	\$ 900.00 4401
* To conduct a check on all wiring systems.	\$ 100.00 201
* To anti-rust all affected areas.	na \$ 100.00 X

Labour & Charges Total: \$ 1,900.00
Parts Total: \$ 1,938.19
Labour & Charges Total: \$ 1,900.00
Total Cost of Repair: \$ 3,838.19
(Non inclusive of 7% GST)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: