




SMRT Automotive Service Pte Ltd  
60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592  
Estimator Telephone Number : 68662623  
Accident Reporting Number : 68662672

## SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB49X  
Ref. No : BUS/06/18/1023  
Reg. Date : 27/06/2018  
Vehicle Type : BUS -12M  
Make : MBOC500 (MERCEDES)  
Model : MERCEDES MBOC500  
Name of Driver : Rahmat Bin Kasmani  
Type of Accident : SIDE SWIPE  
Date / Time of Accident : 24/06/2018 02:26:00 PM  
Accident Reported Date / Time : 25/06/2018 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by : AIG  
Vehicle is Towed Back? : No  
Towed Back Date/Time :  
Replacement Vehicle issued? : No  
Accident Repair Job Card No :  
Special Instruction to ARC, if any :  
SMB49X - FRONT PORTION  
SJJ3681T (TP) - INSURED WITH AIG  
Prepared Date : 27/06/2018 08:41:01 AM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tauhid 97495349  
17/6/18 - WP

sure lkk@com

02 days

lumpsum

Chassis No :  
Work Shop :

Mileage :

0

Repair Completed Date / Time :

### Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	1,060.00	0.00
Total Spray Painting Charges	616.00	0.00
Total Material Charges	1,922.52	1,922.52
Other Charges	0.00	0.00
<b>TOTAL</b>	<b>3,598.52</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>3,600.00</b>	<b>0.00</b>
No. of Repair Days	3.00	0.00
Prepared / Adjusted By		2 days
Arc / Surveyor Sling Off Date	27/06/2018 10:12:50 AM	01/01/1900 12:00:00 AM

5

Prepared / Adjusted Date :

Remarks :

Prepared Date : 27/06/2018 10:12:50 AM

### Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :  
Quotation Date :  
Invoice Amount :

Invoice No :  
Invoice Date :  
Prepared Date :



Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
	VE	6009509	FRONT HEADLAMP LH	1	1,276.50	10.00	1,148.85	Replace	Replace	No <i>Can</i>
	VE	6009700	FRONT SIGNAL LAMP LH	1	155.30	10.00	139.77	Replace	Replace	No <i>dis</i>
	FRONT	6009358	FRONT BUMPER LH	1	621.00	10.00	558.90	Replace	Replace	No <i>Can</i>
	COMMO	4005301	SMART STICKER (S)	1	75.00	0.00	75.00	Replace	Replace	No <i>all</i>
TOTAL MATERIALS										1,922.52 1,922.52
TOTAL MATERIALS(Discouted)										1,922.52 1,922.52

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,060.00	0.00
<b>Total Labour</b>	<b>1,060.00</b>	<b>0.00</b> 795

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	616.00	0.00 500
<b>Total Spray Painting &amp; Panel Beating</b>	<b>616.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		