

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8387X

DATE 7/17/2018 14:17

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00
	Rear Bumper Clips 10 pcs ✓			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover ✓			\$ 225.80
	Rear Bumper Reflector Lamp (LH) ✓			\$ 32.00
	SUB TOTAL			\$ 1,891.15
	LESS 20%			\$ 378.23
	DISCOUNTED TOTAL			\$ 1,512.92
	Rear Bumper Reverse Sensor ✕			\$ 135.70
				\$ 135.70
	Labour Charge			200
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 280.00
	Wiring Charge			\$ 30.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 780.00
	ESTIMATE TOTAL			\$ 2,428.62

16/11/14
 17/7/18 14:15h.
 20/7/18
 PIP
 Before Part photo

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged parts during resurvey
 • Panel prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

Nett
 200
 200
 30
 30

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.