

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9667L**AAD1807-100***Not Authorized
11 Sep @ 1500h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 9667L

KL1LA69RJBB123331

CHEVROLET

EPICA 2.0

10.7.2018

*AK***PART****LIST**

1	1	Rear Bumper	\$	<i>CM / Bm</i> 1,202.00	✓
2	1	Rear Bumper Beam	\$	<i>N</i> 239.94	X
3	1	Rear Bumper Centre Absorber	\$	<i>Sn</i> 260.00	X
4	1	Rear Bumper Side Retainer RH	\$	<i>in Bm</i> 68.76	X
5	1	Rear Bumper Side Retainer LH	\$	<i>Sn</i> 68.76	X
6	1	Rear Bumper Reflectors RH	\$	<i>Sn</i> 119.74	} X
7	1	Rear Bumper Reflectors LH	\$	<i>Sn</i> 119.74	
8	1	Rear Bumper Tow Hook Cover	\$	<i>Sn</i> 93.00	
9	1	Rear End Panel Outer	\$	<i>N</i> 623.76	
10	1	Rear End Panel Inner Trim	\$	<i>Sn</i> 263.84	
11	1	Rear Luggage Floor Panel	\$	<i>N</i> 973.00	
12	1	Rear Luggage Floor Panel Insulator	\$	<i>Sn</i> 63.50	
13	1	Rear Luggage Floor Panel Trim Board	\$	<i>Sn</i> 378.00	
14	1	Bootlid	\$	<i>N</i> 973.00	
15	1	Bootlid inner trim board	\$	<i>Sn</i> 400.00	
16	1	Bootlid Weatherstrip	\$	<i>Sn</i> 344.28	
17	1	Bootlid Lock - Top	\$	<i>N</i> 466.56	
18	1	Bootlid 'CHEVROLET' Badge	\$	<i>na</i> 120.62	
19	1	Bootlid Logo	\$	<i>na</i> 138.84	
20	1	Bootlid 'EPICA LT' Badge	\$	<i>na</i> 119.84	
21	1	Bootlid Reflector Centre	\$	<i>Sn</i> 217.97	
22	1	Bootlid Reflector RH	\$	<i>Sn</i> 128.40	
23	1	Bootlid Reflector LH	\$	<i>Sn</i> 128.40	
24	1	Rear Tail Lamp RH	\$	<i>Sn</i> 479.30	
25	1	Rear Tail Lamp LH	\$	<i>N</i> 479.30	
26	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>N</i> 1,110.00	
27	1	Rear Fender RH	\$	<i>N</i> 1,145.00	
28	1	Rear Fender Inner Trim RH	\$	<i>Sn</i> 418.44	
29	1	Rear Fender LH	\$	<i>N</i> 1,145.00	

Trans-cab Auto Services Pte Ltd**AAD1807-100**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9667L

30 1 Rear Fender Inner Trim LH

\$ *su* 418.44 X

TOTAL	\$	12,707.43
10%	\$	1,270.74
	\$	11,436.69

Special Nett

1	1Set	Bootlid inner trim board Clip	\$	<i>nn</i> 40.00 X
2	1Set	Rear Bumper Parking Sensor	\$	<i>shan</i> 300.00 ✓
3	1Set	Rear Bumper Fastener Clip	\$	<i>nn</i> 44.00 —
4	1Set	Rear Fender Inner Trim Clip LH	\$	<i>nn</i> 30.00
5	1Set	Rear Bumper End Dust Cover Clip	\$	<i>nn</i> 30.00
6	1	Rear Exhaust Mounting	\$	<i>su</i> 300.00
7	2	Rear Windscreen Sealant	\$	<i>nn</i> 80.00
8	1	Rear Windscreen Inner Sponge Seal	\$	<i>nn</i> 100.00
9	1	Spare Tyre	\$	<i>su</i> 180.00
10	1	Spare Wheel Rim	\$	<i>nn</i> 126.74

TOTAL	\$	1,230.74
--------------	-----------	-----------------

TOTAL PARTS	\$	12,667.43
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 3,500.00 *2001*

To Check Electrical Lighting Concerned.

\$ 170.00 *101*

To Rust-Proofing Of The Affected Areas.

\$ *nn* 170.00 X

Putty And Spray Painting Of The Affected
Portion.

\$ 3,200.00 *2001*

To reinstall rear bumper parking sensor.

\$ 170.00 *801*

Trans-cab Auto Services Pte Ltd**AAD1807-100**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9667L

To transfer of end panel fittings and conduct
water seepage test.

\$ *nn* 170.00 X

To transfer of boot fittings and conduct water
seepage test.

\$ *nn* 170.00 X

To remove and refit interior fittings, trimings,
garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

To check steering geometry and computer
wheel alignment

\$ *nn* 220.00 X

\$ **8,150.00**

TOTAL \$ 20,817.43

Repair Days (LUMP SUM)~~10 Days~~*1 1/2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: