



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
MS ONG SIEW YEN JESSIE	Cust No/Name /MS ONG SIEW YEN JESSIE
2B SIMON LANE	Reg No/Reg Date SBN1331R / 10/07/201
#01-13	Date In/Mileage / 0
SINGAPORE 546019	Chassis No KNAHU815VH7185350
Contact No Mobile: 91181932	Engine No D4FDHH107803
	Make/Model KIA/CARENS 1.7 A D SX FL DY6
	Colour/Trim AAP MYSTERIOUS BLUE/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	16/07/2018/ 19:24	QUE	261 / Edwin Caina	32105
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW & RE-ALIGN ACCIDENT DAMAGED AREA:				1100 2200.00
	RENEW LHR DOOR				
	REPAIR LHR FENDER & LH SIDE SILL PNL				
E PNT98000	RESpray LHR DOOR , LHR FENDER & LH SIDE SILL PNL				1260 1680.00
E PNT88000	REMOVE & REFIT LHR DOOR COMPONENTS				120 150.00
M SUNDRY	RENEW LHR SPORT RIM & TRANSFER TYRE				30 50.00
E PNT88000	REMOVE & REFIT RR SEAT, TRIM & CARPET TO FACILITATE REPAIR				120 200.00
A 54900099	CHECK WIRING & ELECTRICAL SYSTEM				30 50.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				200.00
	USING HI-SCAN PRO TEST				
A WHEELALIGNMENTBP	To Conduct Computerize Full Wheel Alignment				120.00
M SUNDRY	APPLY ANTI CORROSION ON AFFECTED AREAS				80 120.00
M SUNDRY	Sundries				20 50.00
M PANEL ASSY-REAR DOOR, LH		1.00	842.00	00.00	842.00
M TAPE-RR DR BLACK FRAME FR, LH		1.00	11.00	00.00	11.00
M TAPE-RR DR BLACK FRAME UPR, LH		1.00	12.00	00.00	12.00
M TAPE-RR DR BLACK RR, LH		1.00	9.00	00.00	9.00
M WHEEL ASSY-ALUMINIUM		1.00	704.00	00.00	704.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SURVEYOR NAME:

Rasul - Hp 90010068

SURVEYOR SIGNATURE:

Rasul

Confirm & accepted by

DATE:

31/07/18 @ 1040

REMARKS:

Resy 64 part

7% GST on

Nett

6349.00

6,349.00

444.43

Total Payable

6,793.43

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.