

1000000

INS. CASE OWNER:

CC 4/III1801 2040, 4 wbb/4 LKJ: IDAC:

Surveyor:

UJS

DOI:

ASSIGNMENT

10/1/18

Date / Time:

17/1/18

Registered in Merimen:

18/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHA 26226

Name of Insured:

UTP

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

6/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

LOH Kiam Siong - 72 years

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

MU18120181

Policy No.:

M16M0016

Make / Model:

Huay Dai

Place of Accident:

MARINA BOULEVARD 200MS

OI GIA REPORT: YES / NO

YES

TP GIA REPORT: YES / NO

YES

Insured Liability:

%

Final? Yes / No

SHA 48222

SHA 26226

SHA 30330



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

20/1/18
vian

48/20370-8

SHA 26226 - 04 (KAPASIS/2018) 12/01/18

STAGE

DATE / PIC

Non-Reporting Itr (1st)

Non-Reporting Itr (2nd)

Non-Reporting Itr (Final)

Notification Itr (if non-pickup)

Call OI

After call Itr to OI

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Timing Invoice

LTA / GIA

Medical Bill

PIR

Mandate/Reject Instruction

LOD

Payment Breakdown Form

Post-Repair Photos

Others:

27/1/18

Seek liability via merimen

28/1/18

liability cover via merimen

6/2/18

File pass to typist type report

3/10/18

Seek mandate via merimen

10/10/18

Mandate approve via merimen

RECEIVED 15 NOV 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

SS

days) Reduction:

%

Confirm by:

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with P. Wen.

Email ☐ Call ☐

Final Liability:

%

100 (Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

07.

Repair Cost:

SS

3959.00

000 involved in 35.0

000 is the month.

Loss of Rental (LOR):

SS

days)

Loss of Use (LOU):

SS

600-00 (5 100 x 6 days)

Loss of Income (LOI):

SS

(5 x days)

LOR only ☐

LOU only ☐

LOR + LOU ☐

LOR + LO ☐

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

COPY SENT 15/1/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

4555.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

4559.00

Name 1:

Progressive Automotive Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

ASSIGNMENT

From: _____ Date: 30/07/18

Estimated Cost: _____

On: ☒ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To inspect Vehicle No: SBT 7077D

at Workshop m/s: Progressive

of: Blk 3022A Ubi Rd 1 # 01-45/46

Insured: _____

Policy No.: _____

Claims No.: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Morning

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SBT 7077D Yr Regn: 8.15

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /Truck / Trailer or (#)Make: Toyota wellfire c.c. 2493Colour: black A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NASp. Reading: 71405 T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: AGH 300017881Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: F: _____

R: 235/50 R18☒ BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 6/7/18 D.O.I. 30/7/18

Survey held at _____

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/9/18 Confirm US \$3700.00 with 4 working days

(Pd. \$7740.01
43%)

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee:

☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CC4/III18013040/wb3

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 18-07-2018



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 3632G	Veh. Inspected	SBT 7077D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	18/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/07/2018	Inspection Date
Survey held at	PROGRESSIVE AUTOMOTIVE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
 GST:201006949C RCB NO:201006949C

M/S : NG YOK HAN JOHN
 61 DUKU ROAD
 SINGAPORE 429224

ATTN:

Your Ref No: TP 0718-5138
 Claim Type: Third Party
 Accident Date: 06/07/2018
 TP Veh Reg No: SHA 3632 G

Not Allowed
h/s 30/7/18
30/7/18
John Han
 Estimate No: **EST1503818**
 Date: 07 Jul 2018
 Policy No: GA115052
 Veh Reg No: **SBT7077D**
 Make/Model: TOYOTA VELLFIRE
 2.5Z EDITION CVT 2WD
 5DR
 Chassis No: AGH300017881
 Engine No: 2ARH566538
 Reg. Date: 14/08/2015

Estimate Repair Cost to Vehicle No :SBT7077D

Description	U/Price	Quantity	Price SS	Amount SS
List Price				
1 REAR BOOT VELLFIRE WORDING <i>nee</i>	105.6000	1 PCS	105.60	✓
2 REAR BOOT OUTER LOWER CHROME <i>nee</i>	780.8000	1 PCS	780.80	✓
3 REAR BUMPER <i>DD</i>	1,380.400	1 PC	1,380.40	✓
4 REAR BUMPER CLIPS <i>nee</i>	9.6000	10 PC	96.00	✓
5 REAR BUMPER SIDE HOLDER - LH <i>nee</i>	105.6000	1 PCS	105.60	✓
6 REAR BUMPER SIDE HOLDER - RH <i>nee</i>	105.6000	1 PCS	105.60	✓
7 REAR BUMPER REINFORCEMENT BRACKET - LH <i>11</i>	110.8000	1 PCS	110.80	X
8 REAR BUMPER REINFORCEMENT BRACKET - RH <i>11</i>	110.8000	1 PCS	110.80	X
9 REAR BUMPER SENSOR <i>shut</i>	418.7000	4 PC	1,674.80	1 PC
10 REAR BUMPER TOW COVER - LH <i>11</i>	96.8000	1 PCS	96.80	X
11 REAR BUMPER TOW COVER - RH <i>11</i>	96.8000	1 PC	96.80	X
12 REAR PANEL <i>3ed 500</i>	988.7000	1 PC	988.70	✓
13 REAR PANEL TOP GARNISH <i>nee</i>	240.6500	1 PCS	240.65	✓
			5,893.35	
	Less 25%		1,473.34	4,420.01
Labour				
14 TO KNOCK OUT DENTS, RR BOOT, CUT/WELD, RR PANEL, RR BUMPER AND REMOVE, REPLACE ACCIDENT PARTS	800.0000	1 JOB	800.00	600
15 TO RESPRAY PAINT ON ACCIDENT PORTIONS	900.0000	1 JOB	900.00	800
16 TO CHECK WIRING	20.0000	1 JOB	20.00	✓
17 TO REMOVE, REFIX REAR GARNISH	80.0000	1 JOB	80.00	✓
18 TO TUFF-KOTE	60.0000	1 JOB	60.00	50
19 TO REMOVE, TRANSFER REAR BUMPER SENSOR	100.0000	1 JOB	100.00	✓
20 TO RESET CHECK LIGHT	60.0000	1 JOB	60.00	✓
			2,020.00	2,020.00

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

M/S : NG YOK HAN JOHN
61 DUKU ROAD
SINGAPORE 429224

ATTN:

Your Ref No: TP 0718-5138
Claim Type: Third Party
Accident Date: 06/07/2018
TP Veh Reg No: SHA 3632 G

Estimate No: EST1503818
Date: 07 Jul 2018
Policy No: GA115052
Veh Reg No: SBT7077D
Make/Model: TOYOTA VELLFIRE
2.5Z EDITION CVT 2WD
5DR
Chassis No: AGH300017881
Engine No: 2ARH566538
Reg. Date: 14/08/2015

Estimate Repair Cost to Vehicle No :SBT7077D

Description	U/Price	Quantity	Price S\$	Amount S\$
			Total	S\$ 6,440.01
			Add GST @ 7%	450.80
			Total Amount Payable	S\$ 6,890.81

TOTAL: SINGAPORE DOLLAR SIX THOUSAND EIGHT HUNDRED NINETY AND CENTS EIGHTY ONE ONLY

For PROGRESSIVE AUTOMOTIVE PTE
LTD

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 3535D

Vehicle Details

Vehicle No.: SBT7077D
Vehicle to be Exported: No
Intended De-registration Date: 30 Jul 2018
Vehicle Make: TOYOTA
Vehicle Model: VELLFIRE 2.5Z EDITION CVT 2WD 5DR
Primary Colour: Black
Manufacturing Year: 2015
Engine No.: 2ARH566538
Chassis No.: AGH300017881
Maximum Power Output: 134.0 kW (179 bhp)
Open Market Value: \$31,661.00
Original Registration Date: 14 Aug 2015
First Registration Date: 14 Aug 2015
Transfer Count: 1
Actual ARF Paid: \$36,326.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 13 Aug 2025
PARF Rebate Amount: \$27,244.00

Intended COE Rebate Details

COE Expiry Date: 13 Aug 2025
COE Category: E - Open Category
COE Period(Years): 10
QP Paid: \$57,885.00
COE Rebate Amount: \$40,737.00
Total Rebate Amount: \$67,981.00

Message

The information contained herein is correct as at 30 Jul 2018

OK



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)



Post an Advertisement

Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

New 5 Years Coe Renewal Toyota Wish 1.8A



\$2800 Downpayment Monthly
From \$688 Onwards. Lowest
3.65%PA @GV Cars Financing
GV Credit Pte Ltd StarAd



Browse by Category

Sort by Date Posted 20 results/page

7 vehicles

Advanced Search [Submit](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Vellfire		Any	Any	2015	Any	Any	Any	Available
	Toyota Vellfire	2.4A Z	\$120,800	\$15,140 /yr	16-Feb-2015	2,362 cc	-	MPV	Available
Elegant Black MPV, One Owner Only, With Twin Moonroof, Low Maintenance Cost, Very Well Maintained, Flexible In House Loan Packages Available. Prime Motor & Leasing Posted: 26-Jul-2018 Tags: 2015 Toyota Vellfire, Toyota Vellfire, Toyota, Vellfire, Used Toyota									
	Toyota Vellfire	3.5A Z Golden Eyes II	\$132,800	\$15,590 /yr	25-Jun-2015	3,456 cc	60,000 km	MPV	Available
Almost Brand New Condition. Golden Eyes II Edition, Warranty Extended, Loan Up To 90%, Call To View Now! Posted: 27-Jul-2018 Tags: 2015 Toyota Vellfire, Toyota Vellfire, Toyota, Vellfire, Used Toyota									
	Toyota Vellfire	2.5A Z G-Edition	\$147,888	\$17,500 /yr	01-Oct-2015	2,493 cc	50,000 km	MPV	Available
Free Extended 3 Years Warranty, Luxury Pearl Black Z G-Edition. One Of The High Spec Facelifted Model Of The Toyota Vellfire. Immaculate Condition. Always Parked Under Shelter. Chauffeured Driven. Wel... Euro Performance Asia Pte Ltd Posted: 26-Jul-2018 Tags: 2015 Toyota Vellfire, Toyota Vellfire, Toyota, Vellfire, Used Toyota									
	Toyota Vellfire	2.5A Z A-Edition	\$150,000	\$18,230 /yr	28-Sep-2015	2,493 cc	45,000 km	MPV	Available
Aftermarket Accessories: 20 Inch Work Balmung Rims With New Tyres. Automatic Rear Tailgate. Japan Made Sixth Sense Side/rear Led Light Indicators And Internal Accessories. Glass Coating Redone 6 Month... Posted: 23-Jul-2018 Tags: 2015 Toyota Vellfire, Toyota Vellfire, Toyota, Vellfire, Used Toyota									
Car BuyingCar SellingCar Ownership Car AftermarketOn The MoveLifestyle 									
	Toyota Vellfire	2.5A Z G-Edition	\$149,000	\$16,850 /yr	24-Dec-2015	2,493 cc	85,500 km	MPV	Available
1 Owner, Comfortable 2.5L 7 Seater MPV. Price Inclusive GST. Motor-Way Credit Pte Ltd Posted: 17-Jul-2018 Tags: 2015 Toyota Vellfire, Toyota Vellfire, Toyota, Vellfire, Used Toyota									
	Toyota Vellfire	2.5A X	\$131,800	\$16,010 /yr	30-Jul-2015	2,493 cc	27,300 km	MPV	Available
(Lowest Depreciation! 1 Owner! Low Mileage!) High In House Loan Up To 90% High For Trade In! Don't Miss It. Meet Our Friendly Consultant For An Non Obligation Advice. Call Us Now! Hamilton Autohub Pte Ltd Posted: 14-Jul-2018 Tags: 2015 Toyota Vellfire, Toyota Vellfire, Toyota, Vellfire, Used Toyota									

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST: 201006949C RCB NO 201006949C

M/S : NG YOK HAN JOHN
61 DUKU ROAD
SINGAPORE 429224

ATTN:

Your Ref No: TP 0718-5138
Claim Type: Third Party
Accident Date: 06/07/2018
TP Veh Reg No: SHA 3632 G

Estimate No: EST1503818
Date: 07 Jul 2018
Policy No: GA115052
Veh Reg No: SBT7077D
Make/Model: TOYOTA VELLFIRE
2.5Z EDITION CVT 2WD
5DR
Chassis No: AGH300017881
Engine No: 2ARH566538
Reg. Date: 14/08/2015

Estimate Repair Cost to Vehicle No : SBT7077D

Description	U/Price	Quantity	Price S\$	Amount S\$
List Price				
1 REAR BOOT VELLFIRE WORDING <i>dec</i>	105.6000	1 PCS	105.60	—
2 REAR BOOT OUTER LOWER CHROME <i>dec</i>	780.8000	1 PCS	780.80	—
3 REAR BUMPER <i>DD</i>	1,380.400	1 PC	1,380.40	—
4 REAR BUMPER CLIPS <i>dec</i>	9.6000	10 PC	96.00	—
5 REAR BUMPER SIDE HOLDER - LH <i>bet</i>	105.6000	1 PCS	105.60	—
6 REAR BUMPER SIDE HOLDER - RH <i>bet</i>	105.6000	1 PCS	105.60	—
7 REAR BUMPER REINFORCEMENT BRACKET - LH <i>11</i>	110.8000	1 PCS	110.80	X
8 REAR BUMPER REINFORCEMENT BRACKET - RH <i>11</i>	110.8000	1 PCS	110.80	X
9 REAR BUMPER SENSOR <i>shel</i>	418.7000	4 PC	1,674.80	1 PC
10 REAR BUMPER TOW COVER - LH <i>11</i>	96.8000	1 PCS	96.80	X
11 REAR BUMPER TOW COVER - RH <i>11</i>	96.8000	1 PC	96.80	X
12 REAR PANEL <i>Sub 3000</i>	988.7000	1 PC	988.70	X
13 REAR PANEL TOP GARNISH <i>11</i>	240.6500	1 PCS	240.65	X
			5,893.35	
	Less 25%		1,473.34	4,420.01
Labour				
14 TO KNOCK OUT DENTS, RR BOOT, CUT/WELD, RR PANEL, RR BUMPER AND REMOVE, REPLACE ACCIDENT PARTS	800.0000	1 JOB	800.00	600
15 TO RESPRAY PAINT ON ACCIDENT PORTIONS	900.0000	1 JOB	900.00	800
16 TO CHECK WIRING	20.0000	1 JOB	20.00	✓
17 TO REMOVE, REFIX REAR GARNISH	80.0000	1 JOB	80.00	✓
18 TO TUFF-KOTE	60.0000	1 JOB	60.00	50
19 TO REMOVE, TRANSFER REAR BUMPER SENSOR	100.0000	1 JOB	100.00	100
20 TO RESET CHECK LIGHT	60.0000	1 JOB	60.00	100
			2,020.00	2,020.00

Not Allowed
h/s 3700
30/7/18
Sub 3000

confirmed 15/8/18

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST: 201006949C RCB NO: 201006949C

M/S : NG YOK HAN JOHN
61 DUKU ROAD
SINGAPORE 429224

ATTN:

Your Ref No: TP 0718-5138
Claim Type: Third Party
Accident Date: 06/07/2018
TP Veh Reg No: SHA 3632 G

Estimate No: EST1503818
Date: 07 Jul 2018
Policy No: GA115052
Veh Reg No: SBT7077D
Make/Model: TOYOTA VELLFIRE
2.5Z EDITION CVT 2WD
5DR
Chassis No: AGH300017881
Engine No: 2ARH566538
Reg. Date: 14/08/2015

Estimate Repair Cost to Vehicle No : SBT7077D

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 6,440.01
			Add GST @ 7%	450.80
			Total Amount Payable	S\$ 6,890.81

TOTAL: SINGAPORE DOLLAR SIX THOUSAND EIGHT HUNDRED NINETY AND CENTS EIGHTY ONE ONLY

For PROGRESSIVE AUTOMOTIVE PTE
LTD

AUTHORISED SIGNATURE

P- 3901.4
25%
2926.05
1700
4626.05
3700

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No repair modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

View Received Message

This mail is associated with :

***SBT7077D (MCT18070181)
[SHA3632G]**

TP
NG YOK HAN JOHN
Jul 6 2018 7:00PM
[COMFORT TRANSPORTATION PTE LTD]
Progressive Automotive Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 27/07/2018 10:40 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SBT7077D - Claim Handler: Sherini Pillai

Approved:0.00.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SBT7077D (MCT18070181)
[SHA3632G]**

TP

NG YOK HAN JOHN

Jul 6 2018 7:00PM

[COMFORT TRANSPORTATION PTE LTD]

Progressive Car Care Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 10/10/2018 11:34 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$4559.00) - SBT7077D - Claim Handler: Sherini Pillai

Approved:4559.00.

DOCUMENTS SUMMARY

There are no documents.



PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

Tel.: 6741 5336 (6 Lines) Fax: 6741 7208

E-mail: progauto@progauto.com.sg

Reg. No.: 201006949C

We specialise in repairing, panel beating, spray painting of all kinds of Vehicles and also insurance claims. All enquiries are welcome.

Our Ref: TP 0718-5138

30.08.2018

INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street #04/#05

IOB Building

Singapore 049711

Attn: Motor Claims Department

Dear Sir,

ACCIDENT INVOLVING VEHICLE: SBT 7077 D & SHA 3632 G ON 06.07.2018

We are the authorized repair workshop for the owner of motor vehicle no: **SBT 7077 D** which was involved in the above captioned accident with your insured vehicle: **SHA 3632 G**. The vehicle owner has requested and authorized us to assist him in presenting the claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

01)	Cost of Repair (incl gst)	\$	3,959.00
02)	Reimbursement - Loss of Use (7days x \$120/day)	\$	840.00
		\$	<u>4,799.00</u>


We enclosed herewith the following documents to support the claims:-

- a) Letter of Authorisation / GIA report(s) / Insurance Certificate, etc...
- b) Final Tax Invoice

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

Thank you
Yours faithfully


Pei Wen
For Progressive Automotive Pte Ltd
Email : claims@procarcare.com.sg



PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

Tel: 6741 5336 (6 Lines) Fax: 6741 7208

E-mail: progauto@progauto.com.sg

Reg. No.: 201006949C

We specialise in repairing, panel beating, spray painting of all kinds of Vehicles and also insurance claims. All enquiries are welcome.

Date : 30 August 2018

Our Ref : TP 0718-5138

I/we Ng Yok Han John Nric No S7633535D

Residing at 61 Duku Road Singapore 429224 owner of

Vehicle No SBT 707FD hereby authorize PROGRESSIVE AUTOMOTIVE PTE LTD at

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716 to resolve the above matter.

In respect of this authorization, I / We confirmed to accept whatsoever settled or agreed by them

and also agreed that all Payments include Loss of Use to make in favour of

PROGRESSIVE AUTOMOTIVE PTE LTD.

I / We am/are fully aware that all settlement made in respect of the accident occurred on

6/7/18 Along / at Marina Boulevard will be full and

Final discharge of the claims inclusive of damages, loss of use etc.



[Signature]

SIGNATURE OF OWNER

EXPRESS SETTLEMENT

DISCHARGE VOUCHER

III-Direct Settlement (PODS)

India Ref: MUTIS0181
Claimant Ref: SBT 7077D

We/I, Progressive Automotive Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 3,959.00 (repair cost), S\$ 600.00 (loss of use/rental), S\$ NIL (search fee), vehicle no. SBT 7077D that was damaged pursuant to the accident which occurred on 06/07/2018 (date) at MARINA BOULEVARD (location) involving vehicle no. SHA3632G (insured vehicle). This is pursuant to the inspection conducted on 30/07/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner NG YOK HAN JOHN ("the third party claimant") of vehicle no. SBT 7077D to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SBT 7077D (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 4,559.00 to Progressive Automotive Pte Ltd.

Dated this 8 day of November 20 18

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

PROGRESSIVE AUTOMOTIVE PTE LTD

NRIC:

Blk 3022A Ubi Road 1 # 01-45/46
Singapore 408716

Address:

Tel: 6741 5336 Fax: 6741 7208
Email: progauto@progauto.com.sg

Nationality:

Malaysian

Occupation:

Admin Administrator

WITNESS:

Signature:

UCS LKK
Signed by appointed Surveyor

Name:

NRIC:

Address:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25,
Paya Ubi Industrial Park
Singapore 408933

Nationality:

Occupation:

PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: progauto@progauto.com.sg
GST:201006949C RCB NO:201006949C

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street

IOB Building #04-05

Singapore 049711

TEL: 63476100

FAX: 62244174 , 62257743

ATTN: Motor Claim Department

Claim No: EST1503818

Final No: PS1502744

Date: 30 Aug 2018

Policy No: GA115052

Veh Reg No: SBT7077D

Make/Model: TOYOTA VELLFIRE
2.5Z EDITION CVT 2WD
5DR

Your Ref No: TP 0718-5138

Claim Type: Third Party

Accident Date: 06/07/2018

TP Veh Reg No: SHA 3632 G

Chassis No: AGH300017881

Engine No: 2ARH566538

Reg. Date: 14/08/2015

Final Repair Bill SBT7077D

Description	Quantity	Price S\$	Amount S\$
Spare Parts			
I TO PROCEED ON LUMP SUM REPAIR	I JOB	3,700.00	
		3,700.00	3,700.00
Total			S\$ 3,700.00
Add GST @ 7%			259.00
Total Amount Payable			S\$ 3,959.00

TOTAL: SINGAPORE DOLLAR THREE THOUSAND NINE HUNDRED FIFTY NINE ONLY

For PROGRESSIVE AUTOMOTIVE PTE LTD
PROGRESSIVE AUTOMOTIVE PTE LTD
Blk 3022A Ubi Road 1 # 01-45/46
Singapore 408716
Tel: 6741 5336 Fax: 6741 7208
Email: progauto@progauto.com.sg
AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jul 2018 Edit Reg		17 Jul 2018 00:00 Edit Adj Rpt	S\$3,700.00 Edit Estimates	S\$3,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -		
Main Claimant:	NG YOK HAN JOHN, ID: S7633535D		
Vehicle Reg. No.:	SBT7077D	Date of Loss:	06/07/2018 19:00 - :59 [34 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18070181	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHA3632G	Policy No. (Claimant):	GA115052
		Excess:	
Repairer:	Progressive Automotive Pte Ltd (HQ) BLK 3022A UBI ROAD 1 #01-45/46,, 048716 Ubi - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 27/07/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (10/10/2018): Alert - Adj Mandate Approved (S\$4559.00) - SBT7077D - Claim Handler: Sherini Pillai
- III_SG (03/10/2018): Alert - Adj Mandate Maintained - SBT7077D - Claim Handler: Sherini Pillai
- III_SG (27/07/2018): Alert - Adj Mandate Approved (S\$0.00) - SBT7077D - Claim Handler: Sherini Pillai

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SBT7077D (MCT18070181)
[SHA3632G]
TP
NG YOK HAN JOHN
Jul 6 2018 7:00PM
[COMFORT TRANSPORTATION PTE LTD]
Progressive Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Photos/Images								3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	03/10/18 15:08	General View							Load JPG	☒	
2	03/10/18 15:08	General View							Load JPG	☒	
3	03/10/18 15:08	General View							Load JPG	☒	
4	03/10/18 15:08	General View							Load JPG	☒	
5	03/10/18 15:08	General View							Load JPG	☒	
6	03/10/18 15:08	General View							Load JPG	☒	
7	03/10/18 15:08	General View							Load JPG	☒	
8	03/10/18 15:08	General View							Load JPG	☒	
9	03/10/18 15:08	General View							Load JPG	☒	
10	03/10/18 15:08	General View							Load JPG	☒	
11	03/10/18 15:08	General View							Load JPG	☒	
12	03/10/18 15:08	General View							Load JPG	☒	
13	03/10/18 15:08	General View							Load JPG	☒	
14	03/10/18 15:08	General View							Load JPG	☒	
15	03/10/18 15:08	General View							Load JPG	☒	
16	03/10/18 15:08	General View							Load JPG	☒	
17	03/10/18 15:08	General View							Load JPG	☒	
18	03/10/18 15:08	General View							Load JPG	☒	
19	03/10/18 15:08	General View							Load JPG	☒	
20	03/10/18 15:08	General View							Load JPG	☒	
21	03/10/18 15:08	General View							Load JPG	☒	
22	03/10/18 15:08	General View							Load JPG	☒	
23	03/10/18 15:08	General View							Load JPG	☒	
24	03/10/18 15:08	General View							Load JPG	☒	
25	03/10/18 15:08	General View							Load JPG	☒	
26	03/10/18 15:08	General View							Load JPG	☒	
27	03/10/18 15:08	General View							Load JPG	☒	
28	03/10/18 15:08	General View							Load JPG	☒	
29	03/10/18 15:08	General View							Load JPG	☒	
30	03/10/18 15:08	General View							Load JPG	☒	
31	03/10/18 15:08	General View							Load JPG	☒	
32	03/10/18 15:08	General View							Load JPG	☒	
33	03/10/18 15:08	General View							Load JPG	☒	
34	03/10/18 15:08	General View							Load JPG	☒	
35	03/10/18 15:08	General View							Load JPG	☒	
36	03/10/18 15:08	General View							Load JPG	☒	
37	03/10/18 15:08	General View							Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	03/10/18 15:08	General View	 Load JPG	☒
39	03/10/18 15:08	General View	 Load JPG	☒
40	03/10/18 15:08	General View	 Load JPG	☒
41	03/10/18 15:08	General View	 Load JPG	☒
42	03/10/18 15:08	General View	 Load JPG	☒
43	03/10/18 15:08	General View	 Load JPG	☒
44	03/10/18 15:08	General View	 Load JPG	☒
45	03/10/18 15:08	General View	 Load JPG	☒
46	03/10/18 15:08	General View	 Load JPG	☒
47	03/10/18 15:08	General View	 Load JPG	☒
48	03/10/18 15:08	General View	 Load JPG	☒
49	03/10/18 15:08	General View	 Load JPG	☒
50	03/10/18 15:08	General View	 Load JPG	☒
51	03/10/18 15:08	General View	 Load JPG	☒
52	03/10/18 15:08	General View	 Load JPG	☒
53	03/10/18 15:08	General View	 Load JPG	☒
54	03/10/18 15:08	General View	 Load JPG	☒
55	03/10/18 15:08	Replacement Part Photo	 Load JPG	☒
56	03/10/18 15:08	Replacement Part Photo	 Load JPG	☒
57	03/10/18 15:08	Replacement Part Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/07/18 14:27	TP EST & GIA REPORT	 Load PDF	
2	18/07/18 14:27	EMAIL FROM III DD 17072018	 Load PDF	
3	31/07/18 19:16	TP ESTIMATE- MARKED	 Load PDF	
4	27/09/18 10:56	WORKSHOP INVOICE	 Load PDF	
5	27/09/18 10:56	LOD	 Load PDF	
6	16/11/18 09:29	DISCHARGE VOUCHER	 Load PDF	
7	16/11/18 09:29	AUTHORISATION TO ACT FORM	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	19/07/18 09:04	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18013040/UWB3Q2

Date: 16/11/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No: MCOM0015

Claimant Vehicle No : SBT7077D

Insured Vehicle No : SHA3632G

Date of Loss: 06/07/2018

Nature of Claim: TP

Claim No: MCT18070181

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SBT7077D

Make & Model: TOYOTA VELLFIRE, 2.5 Z G-EDITION CVT (A)

Engine No: 2ARH566538

Reg. Date: 14/08/2015 (Man. Year: 2015)

Chassis No: AGH300017881

Colour: Black

Odometer: 71405 km

Engine Capacity: 2493 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18

Rear Tyre Size: 235/50 R18

Front Left Side: Bridgestone 7 mm

Rear Left Side: Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,420.01	3,166.54	1,253.47	28.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,020.00	1,650.00	370.00	18.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,440.01	4,816.54	1,623.47	25.21
Approved Total (Overridden) (S\$)		3,700.00		
(S\$)	6,440.01	3,700.00	2,740.01	42.55
+ GST 7.00/7.00% (S\$)	450.80	259.00	191.80	42.55
Nett Amount (S\$)	6,890.81	3,959.00	2,931.81	42.55
+ Loss of Use (6.0 x S\$100.00/day) (S\$)		600.00		
Nett Liability (S\$)		4,559.00		

INSPECTION

Date of Assignment: 17/07/2018

Date Inspected: 30/07/2018 Inspected At:

Progressive Car Care Pte Ltd (HQ)
Blk 3022A Ubi Road 1, #01-45/46
Singapore 408716

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Sep 2018)
Parts:	M1-MPV	TOYOTA VELLFIRE 2.5 Z G-EDITION CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBT7077D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT VELLFIRE WORDING	Necessary	105.60 FL	*105.60 FL
2	1		*REAR BOOT OUTER LOWER CHROME	Necessary	780.80 FL	*780.80 FL
3	1		*REAR BUMPER	Dented	1,380.40 FL	*1,380.40 FL
4	10		*REAR BUMPER CLIPS	Necessary	96.00 FL	*96.00 FL
5	1		*REAR BUMPER SIDE HOLDER -LH	Bent	105.60 FL	*105.60 FL
6	1		*REAR BUMPER SIDE HOLDER -RH	Bent	105.60 FL	*105.60 FL
7	1		*REAR BUMPER REINFORCEMENT BRACKET-LH	Not Necessary	110.80 FL	*- FL
8	1		*REAR BUMPER REINFORCEMENT BRACKET-RH	Not Necessary	110.80 FL	*- FL
9	1		*REAR BUMPER SENSOR (4 PCS)	Shorted (1 PCS ONLY)	1,674.80 FL	*418.70 FL
10	1		*REAR BUMPER TOW COVER-LH	Not Necessary	96.80 FL	*- FL
11	1		*REAR BUMPER TOW COVER-RH	Not Necessary	96.80 FL	*- FL
12	1		*REAR PANEL	Badly Dented	988.70 FL	*988.70 FL
13	1		*REAR PANEL TOP GARNISH	Necessary	240.65 FL	*240.65 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) **5,893.35** **4,222.05**
 - List Item Discount on L Items 25.00/25.00% (S\$) **1,473.34** **1,055.51**

Total Parts (S\$) 4,420.01 3,166.54

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTED,RR BOOT ,CUT/WELD ,RR PANEL,RR BUMPER AND REMOVE,REPLACE ACCIDENT PARTS	New	800.00	600.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	900.00	800.00
3	TO CHECK WIRING	New	20.00	20.00
4	TO REMOVE,REFIX REAR GARNISH	New	80.00	80.00
5	TO TUFF-KOTE	New	60.00	50.00
6	TO REMOVE,TRANSFER REAR BUMPER SENSOR}	New	100.00	100.00
7	TO RESET CHECK LIGHT }	New	60.00	0.00
Gross Labour Cost (S\$)			2,020.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >