

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited  
7 Temasek Boulevard  
#10-01 Suntec Tower One  
Singapore 038987

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 24 Jul 2018

## **Preliminary Advice**

Insured Vehicle No	: SJX3049X	Accident Date	: 14/07/2018
TP Vehicle No	: SKC5169T	Assignment Date	: 23/07/2018
Make	: BMW X5	Est. Duration of Repair	: 7/Days
Date of Inspection	: 23/07/2018		
Inspection At	: PERFORMANCE MOTORS LTD		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages ...Rear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,166.25
Revised Amount	:S\$	11,105.35
Check Items (Estimated)	:S\$	6,140.90
Total	:S\$	17,246.25

Lump Sum Repair	:S\$
-----------------	------

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :We have not authorized repairs.