

Your Ref: PCS.CCC.2018.215747.TM

Date: 08th October 2018

Our Ref: CS1/LAW18013052/Dqbs2

M/s ComLaw LLC
64 Cecil Street #03-02
IOB Building
Singapore 049711

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SLC 9972C INSURED VEHICLE: YN 7117G ACCIDENT DATE: 23/12/2016**

We thank you for your instruction on 18/07/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLC 9972C from M/s Koays Accident Reconstruction Pte Ltd.
- b) Survey report by S K Auto Consultants with colour photographs.
- c) Final Repair Bill of SLC 9972C from M/s Service @ Riverview Pte Ltd.
- d) Singapore Accident Statement of Vehicles SLC 9972C and YN 7117G.
- e) Colour damaged vehicle photographs of SLC 9972C.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLC 9972C
Make & Model	: Honda Shuttle, 1.5 (A)
Year of Registration	: 2016
Chassis Number	: GK81002540
Engine Capacity	: 1496 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.