

15/5/2010

INS. CASE OWNER:

Vale

CC 4^{hsm} AXA1801

3054, Kmbb52

LKK:

IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

18/7/18

Date / Time:

18/7/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLV 3855Y

Name of Insured:

MEERU LONG CHING WEI

Insured Tel No.:

HP: 94526377

Excess Sec II :SS

D.O.A.:

4/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: SAMUEL NG WEI YONG

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

S8M00001 / 5826

Policy No.:

CN868286

Make / Model:

BMW

Place of Accident:

JIN ENNS

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final? Yes / No

SHD933H

INSRS:
WSP:
Tel:
Liability:
RMKS:Trans
CMLINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

20/7/18
TTN

SHD933H-Y

SLV 3855Y-X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

28/08/19 - VIC

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA/GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others: DO FORM

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

L19

SS 3,900.00 (3 days) Reduction:

90 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

9

If NO or B 28, Ass. Lia:

Repair Cost: (w/gst)

SS

4,173.00

Loss of Rental (LOR):

SS

555.84 (4 days) x 4

83.46

Loss of Use (LOU):

SS

200.00 x 4 days

800.00

Loss of Income (LOI):

SS

(S x days)

-

LOR only

LOU only

LOR + LOU

LOR + LOU

[Tick only one]

GIA/LTA Search

SS

7.49

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

4,714.33

Global Sum SS:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

4,714.33

Name 1:

TRANS-CAD AUTO SERVICES PTE LTD

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

COPY SENT

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4350.00

ASSIGNMENT

From: Date: 18/7/18

Estimated Cost:

OP: ☒ TP / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SHD 9737H

at Workshop m/s Trans-Cab

of No. 2 AMK st-63

Insured:

Policy No:

Claims No:


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHD 9737H Yr Regn: 12, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Latitude c.c. 1995

Colour: M. White / Red A/C: Insured / Std / NI / NA

Sp. Reading: 631101 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VF1A BL 15 AUG 276142

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Giti 215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front

Rear

R/Bal. 9 mm R/Bal. 5 mm

L/Bal. 9 mm L/Bal. 5 mm

D.O.A. 14/7/18 D.O.I. 18/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Acc

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19/7 K4 1911 to Corke

11 Lm 839001

CRAD: 936.540.52/90°/6)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18013054/Kub3	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811			Date : 18-07-2018	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLV 3855Y	Veh. Inspected	SHD 9737H	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	18/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/07/2018	Inspection Date	18/07/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9737H**AAD1807-133***Not Authorised*
11 Sep @ 3900

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9737H

VF1ABL15AUC276142

RENAULT

LATITUDE

14.7.2018

AXA**PART****LIST**

1	1	DOOR PANEL REAR LH	\$	<i>B</i> 2,844.66 ✓
2	1	DOOR LOCK REAR LH	\$	<i>n</i> 908.75
3	1	DOOR HANDLE OUTER REAR LH	\$	<i>sn</i> 126.49
4	1	DOOR HANDLE CAP REAR LH	\$	<i>sn</i> 35.52
5	1	DOOR HANDLE SEAL REAR LH	\$	<i>sn</i> 7.89
6	1	DOOR HANDLE COVER REAR LH	\$	<i>sn</i> 13.22
7	1	DOOR HANDLE MODULE REAR LH	\$	<i>sn</i> 133.60
8	1	DOOR REGULATOR REAR LH	\$	<i>n</i> 1,135.10
9	1	DOOR REGULATOR MOTOR REAR LH	\$	<i>n</i> 893.75
10	1	DOOR REGULATOR NUT REAR LH	\$	<i>sn</i> 12.43
11	1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>sn</i> 6.31
12	1	DOOR FINISHER REAR LH	\$	<i>sn</i> 423.10
13	1	DOOR MOULDING REAR LH	\$	<i>sn</i> 176.82
14	1	DOOR MOULDING CLIP L70Y	\$	<i>sn</i> 5.92
15	1	DOOR MOULDING SCREW L70Y	\$	<i>sn</i> 6.91
16	1	DOOR CASING REAR LH	\$	<i>sn</i> 1,509.06
17	1	DOOR WATER SHIELD REAR LH	\$	<i>sn</i> 30.39
18	1	DOOR CASING CLIP	\$	<i>sn</i> 12.63
19	1	DOOR CASING LIGHT L70Y	\$	<i>sn</i> 48.74
20	1	DOOR FINISHER INNER REAR LH	\$	<i>sn</i> 323.44
21	1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>n</i> 46.97
22	1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>n</i> 20.33
23	1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>n</i> 20.33
24	1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>n</i> 20.33
25	1	DOOR GRAB HANDLE REAR LH	\$	<i>sn</i> 210.96
26	1	DOOR BLIND REAR LH	\$	<i>sn</i> 741.80
27	1	DOOR WEATHERSTRIP REAR LH	\$	<i>sn</i> 410.66
28	1	DOOR SEAL REAR LH	\$	<i>sn</i> 162.02
29	1	DOOR GLASS RUNNER SEAL REAR LH	\$	<i>sn</i> 229.31

10 x 17.44

Trans-cab Auto Services Pte Ltd**AAD1807-133**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9737H

30	1	DOOR WAIST SEAL OUTER REAR LH	\$	334.69	} X
31	1	DOOR WAIST SEAL INNER REAR LH	\$	115.64	
32	1	FENDER PANEL REAR LH	\$	3,299.13	
33	1	WHEELARCH REAR LH	\$	543.47	
34	1	FENDER PANEL INNER TRIM REAR RH	\$	671.45	
35	1	FENDER PANEL REAR RH	\$	3,299.13	
36	1	WHEELARCH REAR RH	\$	543.47	
37	1	CHASSIS PANEL REAR RH	\$	3,766.43	
38	1	KUCKLE ARM REAR RH L70Y	\$	736.67	
39	1	BRAKE DISC REAR L70Y	\$	525.91	
40	1	WHEEL HUB NUT L70Y	\$	51.11	
41	1	WHEEL HUB CAP L70Y	\$	57.82	
42	1	ABS SENSOR REAR RH L70Y	\$	255.75	
43	1	REAR AXLE L70Y	\$	4,167.03	
44	1	AXLE ARM RH L70Y	\$	117.22	
45	1	LOWER ARM REAR RH L70Y	\$	905.99	
46	1	ABSORBER REAR	\$	389.75	
47	1	STABILIZER BAR REAR RH	\$	604.65	
48	1	BRAKE CALIPER REAR RH	\$	1,300.67	

*1 Rec Repair**Br**1108.46*

TOTAL	\$	29,358.77
10%	\$	2,935.88
	\$	26,422.89

*32203.42**28983.08***Specical Nett**

1SET	FENDER WHEELARCH REAR RH CLIP	\$	35.00	} X
1SET	FENDER WHEELARCH REAR LH CLIP	\$	35.00	
1	FENDER INNER TRIM CLIP LH	\$	28.00	
1	FENDER INNER TRIM CLIP LH	\$	28.00	
1	TAILLAMP CLIP RH	\$	5.00	
1	TAILLAMP CLIP LH	\$	5.00	
2	REAR WINDSCREEN SELANT	\$	80.00	
1	WINDSCREEN MOULDING	\$	100.00	
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
1	DOOR CHECK BOLT	\$	22.69	
1	DOOR GUIDE SCREW	\$	10.85	
1	DOOR HINGE BOLT	\$	10.85	

Trans-cab Auto Services Pte Ltd**AAD1807-133**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9737H

1 DOOR HINGE NUT RH	\$	14.60	}	X
1 DOOR CHECK BOLT	\$	22.69		
1 DOOR CHECK NUT	\$	3.75		
1 DOOR LOCK SCREW L70Y	\$	6.12		
1 DOOR CATCH SCREW L70Y	\$	10.06		
1 LEFT REAR TYRE	\$	330.00	}	
1 LEFT REAR TYRE RIM	\$	380.00		
1 REAR DOOR STICKER '6555-3333'	\$	80.00		
TOTAL	\$	1,307.63		

TOTAL PARTS \$ 27,730.52**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	6601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	5001
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To reinstall rear bumper parking sensor.	\$	170.00	170.00 X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	170.00 X
To repair and realign rear exhaust pipe.	\$	170.00	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	170.00 X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	170.00 X

Trans-cab Auto Services Pte Ltd**AAD1807-133**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9737H

To supply and re-do rear luggage floor panel insulation padding.

\$ ~ 380.00 X

To transfer of rear fender fittings, attachment and perform water seepage test.

\$ 380.00 601

To transfer of rear windscreen fittings and conduct water seepage test.

\$ ~ 170.00 X

To check steering geometry and computer wheel alignment

\$ ~ 220.00 X

To transfer of rear door fittings, attachment and perform water seepage test.

\$ ~ 380.00 X

TOTAL \$ 12,540.00 12920**Over All Total \$ 40,270.52****(LUMP SUM)****Repair Days****20 DAYS****3 days**

43210.69

44208.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

◀ Service Request Details

Claim

S8M0000I

Reference

None 

Loss Date

July 14, 2018

Request Date

July 17, 2018

Due Date

July 24, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Trans Cab
Kenneth

Actions

Next Step

Agree to perform service

Vehicle Information

Incident Vehicle Registration #

SHD9737H

Make

TPVD RENAULT

Model

LATITUDE-2.0 L (A)

Service Address

...

Primary Contact/Insured

LONG CHING WEI (CHEARLY)

3D LORONG SALLEH, #01-03, 416751, Singapore

94526177

CHEERLYLONG@GMAIL.COM

Claim Handler

OH Vale

6568804897

vale.oh@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

[New Message](#)

Vic (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Monday, 29 April, 2019 3:34 PM
To: Vic (LKKAUTO)
Cc: claims@transcab.com.sg
Subject: RE: TCS REF: AAD1807-133--Accident involving SLV3855Y (AXA) & SHD9737H on 14.07.18 LKK REF CC4/ASM18013054/Khb3
Attachments: AAD1807-133 - DV + AUHORIZATION.pdf

WITHOUT PREJUDICE

Dear Vic

Attach duly signed DV for your action.

Original hard copy will pass to Kenneth bring back your office.

Hope to receive the payment soon.

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Vic (LKKAUTO) [mailto:vicalpeh@lkkauto.com]
Sent: Tuesday, 2 April, 2019 10:31 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Cc: claims@transcab.com.sg; Admin A <admin-a@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>
Subject: RE: TCS REF: AAD1807-133--Accident involving SLV3855Y (AXA) & SHD9737H on 14.07.18 LKK REF CC4/ASM18013054/Khb3

Without Prejudice

Dear Wai Yin,

We refer further to the below email.

Purely for an amicable settlement on a without prejudice basis and without admission of liability, we have our principal's mandate and we offer settlement as below:

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

Our Ref : AAD1807-133

Your Ref : SLV3855Y

Date : 11.October 2018

Lxc

AXA INSURANCE S PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SHD9737H AND SLV3855Y ON 14/07/18 09:25 AM ALONG JALAN EUNOS

It appears that the above accident was caused by your insured's negligence. We, therefore seeking compensation from you for our financial loss as itemized below :-

1.	Cost of Repair (inclusive of 7% GST)	\$	4,173.00
2.	Loss of Rental for <u>5</u> days @ \$ <u>83.46</u> per day	\$	417.30
3.	Loss of Income for <u>5</u> days @ \$ <u>50</u> per day	\$	250.00
4.	LTA Search Fee	\$	7.49
5.	Survey Fee	\$	0.00
	Total	\$	4,847.79

We enclose a copy of the following documents for your consideration :-

GIA report lodged by our driver

Rental rate and mileage records

Certificate of Insurance

Authorization To Act

Original final repair bill

LTA Search Fee

Kindly let us have the discharge voucher within the next 14 days, failing which we shall proceed to hand over the conduct of this matter to our solicitors without further reference to you.

Yours Faithfully

Trans-Cab Services Pte Ltd

Jasmine Tan

General Manager

Tel No. : 6603 1250 (DID)

Note : Please email any further correspondence to claims@transcab.com.sg (6603 1259)

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLV 3855Y (Insd veh)	Model:	RENAULT LATITUDE (A)
	SHD 9737H (TP veh)		
Date of Accident:	14/07/2018		

Global Sum Settlement	:	☐ Yes	☒ No	
Repair Estimate	:	\$	47,302.88	
Final Repair Cost	:	\$	4,173.00	
Loss of Token Sum	:	\$	200.00	4 days at \$50.00 per day
Rental (if any)	:	\$	333.84	4 days
LTA / GIA Search Fee	:	\$	7.49	

Others: : \$

Final Settlement Sum : \$ 4,714.33

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
BOLA Liability: _____ 100 _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks PLEASE SEND THE CHEQUE PAYMENT TO TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111	

Payment Instruction: Payee's Breakdown			
1)	TRANS-CAB AUTO SERVICES PTE LTD	:	\$ 4,714.33

NUR SHAQILAH BTE ABDOL
WAHAB

08/05/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18013054/Khb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 08-05-2019



ATTN: VALE OH

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLV 3855Y	Veh. Inspected	SHD 9737H
Policy No.	CN868286	Coverage (\$)	0.00
Claim No.	S8M000OI	Excess (\$)	0.00
Assign From	VALE OH	Assign Date	18/07/2018

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	VF1ABL15AUC276142	Colour	METALLIC WHITE / RED
Odometer	631101	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	GITI	9 mm
L/H Front Tyre	215/60R16	GITI	9 mm
R/H Rear Tyre	215/60R16	GITI	5 mm
L/H Rear Tyre	215/60R16	GITI	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	14/07/2018	Inspection Date	18/07/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9737H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	DOOR PANEL REAR LH (CONSISTENT)	BENT	2,844.66	2,844.66
1	DOOR LOCK REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	908.75	-
1	DOOR HANDLE OUTER REAR LH (CONSISTENT)	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR LH (CONSISTENT)	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR LH (CONSISTENT)	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR LH (CONSISTENT)	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR LH (CONSISTENT)	SERVICEABLE	133.60	-
1	DOOR REGULATOR REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	1,135.10	-
1	DOOR REGULATOR MOTOR REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	893.75	-
1	DOOR REGULATOR NUT REAR LH (CONSISTENT)	SERVICEABLE	12.43	-
1	DOOR REGULATOR MOTOR SCREW REAR L70Y (CONSISTENT)	SERVICEABLE	6.31	-
1	DOOR FINISHER REAR LH (CONSISTENT)	SERVICEABLE	423.10	-
1	DOOR MOULDING REAR LH (CONSISTENT)	SERVICEABLE	176.82	-
1	DOOR MOULDING CLIP L70Y (CONSISTENT)	NOT NECESSARY	5.92	-
1	DOOR MOULDING SCREW L70Y (CONSISTENT)	SERVICEABLE	6.91	-
1	DOOR CASING REAR LH (CONSISTENT)	SERVICEABLE	1,509.06	-
1	DOOR WATER SHIELD REAR LH (CONSISTENT)	SERVICEABLE	30.39	-
1	DOOR CASING CLIP (CONSISTENT)	NOT NECESSARY	12.63	-
1	DOOR CASING LIGHT L70Y (CONSISTENT)	SERVICEABLE	48.74	-
1	DOOR FINISHER INNER REAR LH (CONSISTENT)	SERVICEABLE	323.44	-
1	DOOR FINISHER BRACKET INNER REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	46.97	-
1	DOOR FINISHER BRACKET INNER REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	20.33	-
1	DOOR FINISHER BRACKET INNER REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	20.33	-
1	DOOR GRAB HANDLE REAR LH (CONSISTENT)	SERVICEABLE	210.96	-

Report Ref No. CC4/ASM18013054/Khb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR BLIND REAR LH (CONSISTENT)	SERVICEABLE	741.80	-
1	DOOR WEATHERSTRIP REAR LH (CONSISTENT)	SERVICEABLE	410.66	-
1	DOOR SEAL REAR LH (CONSISTENT)	SERVICEABLE	162.02	-
1	DOOR GLASS RUNNER SEAL REAR LH (CONSISTENT)	SERVICEABLE	229.31	-
1	DOOR WAIST SEAL OUTER REAR LH (CONSISTENT)	SERVICEABLE	334.69	-
1	DOOR WAIST SEAL INNER REAR LH (CONSISTENT)	SERVICEABLE	115.64	-
1	FENDER PANEL REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH (CONSISTENT)	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH (CONSISTENT)	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH (CONSISTENT)	SERVICEABLE	543.47	-
1	CHASSIS PANEL REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	3,766.43	-
1	KNUCKLE ARM REAR RH L70Y (CONSISTENT)	SERVICEABLE	736.67	-
1	BRAKE DISC REAR L70Y (CONSISTENT)	SERVICEABLE	525.91	-
1	WHEEL HUB NUT L70Y (CONSISTENT)	SERVICEABLE	51.11	-
1	WHEEL HUB CAP L70Y (CONSISTENT)	SERVICEABLE	57.82	-
1	ABS SENSOR REAR RH L70Y (CONSISTENT)	SERVICEABLE	255.75	-
1	REAR AXLE L70Y (CONSISTENT)	SERVICEABLE	4,167.03	-
1	AXLE ARM RH L70Y (CONSISTENT)	SERVICEABLE	117.22	-
1	LOWER ARM REAR RH L70Y (CONSISTENT)	SERVICEABLE	905.99	-
1	ABSORBER REAR (CONSISTENT)	SERVICEABLE	389.75	-
1	STABILIZER BAR REAR RH (CONSISTENT)	SERVICEABLE	604.65	-
1	BRAKE CALIPER REAR RH (CONSISTENT)	SERVICEABLE	1,300.67	-
1	REAR BUMPER (CONSISTENT)	BUCKLED	1,108.46	1,108.46
	LESS 10% DISCOUNT		-3,331.19	-395.32
			29,980.69	3,557.80
	SPECIAL NETT ITEMS			
1	SET FENDER WHEELARCH REAR RH CLIP (SN) (CONSISTENT)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN) (CONSISTENT)	NOT NECESSARY	35.00	-

Report Ref No. CC4/ASM18013054/Khb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FENDER INNER TRIM CLIP LH (SN) (CONSISTENT)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN) (CONSISTENT)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN) (CONSISTENT)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN) (CONSISTENT)	NOT NECESSARY	5.00	-
2	REAR WINDSCREEN SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	DOOR CHECK BOLT (SN) (CONSISTENT)	NOT NECESSARY	22.69	-
1	DOOR GUIDE SCREW (SN) (CONSISTENT)	NOT NECESSARY	10.85	-
1	DOOR HINGE BOLT (SN) (CONSISTENT)	NOT NECESSARY	10.85	-
1	DOOR HINGE NUT RH (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	14.60	-
1	DOOR CHECK BOLT (SN) (CONSISTENT)	SERVICEABLE	22.69	-
1	DOOR CHECK NUT (SN) (CONSISTENT)	SERVICEABLE	3.75	-
1	DOOR LOCK SCREW L70Y (SN) (CONSISTENT)	SERVICEABLE	6.12	-
1	DOOR CATCH SCREW L70Y (SN) (CONSISTENT)	SERVICEABLE	10.06	-
1	LEFT REAR TYRE (SN) (CONSISTENT)	SERVICEABLE	330.00	-
1	LEFT REAR TYRE RIM (SN) (CONSISTENT)	SERVICEABLE	380.00	-
1	REAR DOOR STICKER '6555-3333' (SN) (CONSISTENT)	NECESSARY	80.00	60.00
			1,307.61	60.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	660.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF DOOR LOCK REAR LH, DOOR REGULATOR REAR LH, DOOR REGULATOR MOTOR REAR LH, DOOR FINISHER BRACKET INNER REAR LH, FENDER PANEL REAR LH, FENDER PANEL REAR RH, CHASSIS PANEL REAR RH AND DOOR HINGE NUT RH.		4,200.00	500.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.	NOT NECESSARY	170.00	-
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-

Report Ref No. CC4/ASM18013054/Khb3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL, FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			12,920.00	1,250.00
GRAND TOTAL			44,208.30	4,867.80

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,900.00
---	--	--	-----------------

Report Ref No. CC4/ASM18013054/Khb3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.