

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9737H**AAD1807-133***Not Authored
C/Ping @ 3900*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9737H

VF1ABL15AUC276142

RENAULT

LATITUDE

14.7.2018

AXA

		PART		LIST
1	1	DOOR PANEL REAR LH	\$	<i>Bz</i> 2,844.66 ✓
2	1	DOOR LOCK REAR LH	\$	<i>n</i> 908.75
3	1	DOOR HANDLE OUTER REAR LH	\$	<i>sn</i> 126.49
4	1	DOOR HANDLE CAP REAR LH	\$	<i>sn</i> 35.52
5	1	DOOR HANDLE SEAL REAR LH	\$	<i>sn</i> 7.89
6	1	DOOR HANDLE COVER REAR LH	\$	<i>sn</i> 13.22
7	1	DOOR HANDLE MODULE REAR LH	\$	<i>sn</i> 133.60
8	1	DOOR REGULATOR REAR LH	\$	<i>n</i> 1,135.10
9	1	DOOR REGULATOR MOTOR REAR LH	\$	<i>n</i> 893.75
10	1	DOOR REGULATOR NUT REAR LH	\$	<i>sn</i> 12.43
11	1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>sn</i> 6.31
12	1	DOOR FINISHER REAR LH	\$	<i>sn</i> 423.10
13	1	DOOR MOULDING REAR LH	\$	<i>sn</i> 176.82
14	1	DOOR MOULDING CLIP L70Y	\$	<i>nn</i> 5.92
15	1	DOOR MOULDING SCREW L70Y	\$	<i>sn</i> 6.91
16	1	DOOR CASING REAR LH	\$	<i>sn</i> 1,509.06
17	1	DOOR WATER SHIELD REAR LH	\$	<i>sn</i> 30.39
18	1	DOOR CASING CLIP	\$	<i>nn</i> 12.63
19	1	DOOR CASING LIGHT L70Y	\$	<i>sn</i> 48.74
20	1	DOOR FINISHER INNER REAR LH	\$	<i>sn</i> 323.44
21	1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>n</i> 46.97
22	1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>n</i> 20.33
23	1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>n</i> 20.33
24	1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>n</i> 20.33
25	1	DOOR GRAB HANDLE REAR LH	\$	<i>sn</i> 210.96
26	1	DOOR BLIND REAR LH	\$	<i>sn</i> 741.80
27	1	DOOR WHEATHESTRIP REAR LH	\$	<i>sn</i> 410.66
28	1	DOOR SEAL REAR LH	\$	<i>sn</i> 162.02
29	1	DOOR GLASS RUNNER SEAL REAR LH	\$	<i>sn</i> 229.31

Trans-cab Auto Services Pte Ltd**AAD1807-133**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9737H

30	1	DOOR WAIST SEAL OUTER REAR LH	\$	Sn	334.69	}
31	1	DOOR WAIST SEAL INNER REAR LH	\$	Sn	115.64	
32	1	FENDER PANEL REAR LH	\$	Sn	3,299.13	
33	1	WHEELARCH REAR LH	\$	Sn	543.47	
34	1	FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45	
35	1	FENDER PANEL REAR RH	\$	Sn	3,299.13	
36	1	WHEELARCH REAR RH	\$	Sn	543.47	
37	1	CHASSIS PANEL REAR RH	\$	Sn	3,766.43	
38	1	KUCKLE ARM REAR RH L70Y	\$	Sn	736.67	
39	1	BRAKE DISC REAR L70Y	\$	Sn	525.91	
40	1	WHEEL HUB NUT L70Y	\$	Sn	51.11	
41	1	WHEEL HUB CAP L70Y	\$	Sn	57.82	
42	1	ABS SENSOR REAR RH L70Y	\$	Sn	255.75	
43	1	REAR AXLE L70Y	\$	Sn	4,167.03	
44	1	AXLE ARM RH L70Y	\$	Sn	117.22	
45	1	LOWER ARM REAR RH L70Y	\$	Sn	905.99	
46	1	ABSORBER REAR	\$	Sn	389.75	
47	1	STABILIZER BAR REAR RH	\$	Sn	604.65	
48	1	BRAKE CALIPER REAR RH	\$	Sn	1,300.67	
1 Rec Range Bu 1108.46 ✓						

TOTAL \$ 29,358.77**10% \$ 2,935.88****\$ 26,422.89****Special Nett**

1SET	FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	}	X
1SET	FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00		
1	FENDER INNER TRIM CLIP LH	\$	nn	28.00		
1	FENDER INNER TRIM CLIP LH	\$	nn	28.00		
1	TAILLAMP CLIP RH	\$	nn	5.00		
1	TAILLAMP CLIP LH	\$	nn	5.00		
2	REAR WINDSCREEN SELANT	\$	nn	80.00		
1	WINDSCREEN MOULDING	\$	nn	100.00		
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00		
1	DOOR CHECK BOLT	\$	nn	22.69		
1	DOOR GUIDE SCREW	\$	nn	10.85		
1	DOOR HINGE BOLT	\$	nn	10.85		

Trans-cab Auto Services Pte Ltd**AAD1807-133**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9737H

1 DOOR HINGE NUT RH	\$	14.60	}	X
1 DOOR CHECK BOLT	\$	22.69		
1 DOOR CHECK NUT	\$	3.75		
1 DOOR LOCK SCREW L70Y	\$	6.12		
1 DOOR CATCH SCREW L70Y	\$	10.06		
1 LEFT REAR TYRE	\$	330.00	}	
1 LEFT REAR TYRE RIM	\$	380.00		
1 REAR DOOR STICKER '6555-3333'	\$	80.00		
TOTAL	\$	1,307.63		

TOTAL PARTS \$ 27,730.52**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	6601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	5001
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To reinstall rear bumper parking sensor.	\$	170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X
To repair and realign rear exhaust pipe.	\$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	X

Trans-cab Auto Services Pte Ltd**AAD1807-133**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9737H

To supply and re-do rear luggage floor panel insulation padding.	\$	~ 380.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00 601
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~ 170.00 X
To check steering geometry and computer wheel alignment	\$	~ 220.00 X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	~ 380.00 X

TOTAL \$ 12,540.00**Over All Total \$ 40,270.52****(LUMP SUM)****Repair Days****20 DAYS****3 days****LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer**Signature:****Date:**