

23/05/2001

ASS. REC. BY:

REF CS/FCI/8013055/RMD3⁷² Special Instruction:

Surveyor

From (Person):

Rasul
Gileen Lee

ASSIGNMENT (Office)

of FCI

Date/Time: 18/7/18 @ 2:07pm

Estimated Cost:

OD/TP WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

at Workshop m/s

of

Policy No:

Sum Insured:

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 2:24pm @ 18/7/18

Person Contacted:

Claim No:

Excess:

D.O.A. 16/07/2018

H.O.D. Endorsement:

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate	DOA: 7/11/2017
	SKS 97284 - NBA / MSG 1702/287/Y	DOA: 01/05/2018
	SH 6418 Y - CS/FCI/8011075/VSD3	

6/8/18

4/9/18

Email preli revised to FCI

@ 4:11pm Paul will email us finalised

@ 4:16.555.67 confirmed by email (Red 13,380.33, 459)

Pass

REF: FCL

5976J

ASSIGNMENT

From: Date: 02082018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKS 9728U

at Workshop m/s

Wearnes

of

45 Long Kee Rd

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Paul

(Policy Condition)

after 12.30 pm
11.30

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

RECEIVED 06 SEP 2018

Veh No: SKS 9728U Yt Reg: 5 / 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Land Rover Range Rover 3.0 2995

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp Reading:

037451

T/Radio: Insured / Std / NI / NA

Eng/No:

SALWA 2VE1FA325216

Gen. Cond: Good / Fair / Poor / Burnt

Steering: in order / Jammed / Leaked / Burnt or

Brake: in order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

275/45R21

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CONTINENTAL

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A:

16/07/18

D.O.I:

02/08/18

Survey held at

WEARNES

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

49 - typist

Report Format:

CWS

Lump Sum / I.B. / \$

16,555.67

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp: \$

☐

Interview: \$

☐

Tech. Invs: \$

☐

Weekend: \$

Survey Fee:

Transportation:

1. S. R. \$

1. Photo: 580

1. Other: 050

OSP

6/6/18

19x15 = 285

170 + 285

50

50

58

613



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18013055/R1vd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 18-07-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 6418Y	Veh. Inspected	SKS 9728U
Policy No.		Coverage (\$)	0.00
Claim No.	D18005475MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	18/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	16/07/2018	Inspection Date	02/08/2018
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18005475MFSH
Our Ref: CS/FCI18013055/R1vd3

Date :6/8/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO.SKS 9728U


We thank you for your instruction on 18/7/2018

Please be informed that we had conducted the inspection of the above mentioned
2/8/2018 at the premises of M/s WEARNES AUTOMOTIVE PTE LTD
and have the following to report:-

Workshop Estimate Amount	: S\$29,936.00
Revised Estimate Amount	: S\$17,672.80
"Check" Items Amount	: S\$8,863.20
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
rear portion.



Comments/Present Status:
Damages Consistent

Yours faithfully,

MOHAMMED RASUL
Automotive Assessor

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 6 September 2018 11:18 AM
To: 'Paul Ong Qing Yong'
Cc: SUR
Subject: RE: SKS9728U finalise

Sensitivity: Confidential

Dear Paul,

WITHOUT PREJUDICE

Confirmed amount \$16,555.67 before GST @ 6 working days.

Kindly send Final invoice and all supporting documents to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Paul Ong Qing Yong <paul.ong@wearnes.com>
Sent: Wednesday, 5 September 2018 8:46 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: SKS9728U finalise
Sensitivity: Confidential

Attached

Best Regards,

Paul Ong
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
M (65) 8126 1237 D (65) 6378 9336
www.wearnesauto.com paul.ong@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

MOTOR SURVEY ASSIGNMENT

Date	17-07-2018	Our Ref No.	D18005475MFSH
Accident Date	16-07-2018	Claim Type.	Third Party
Insured Vehicle	SH6418Y	Third Party Vehicle.	SKS9728U
Survey Location	BODY AND PAINT DEPT 249 ALEXANDRA ROAD		
Contact Person.	PAUL ONG		
Contact No.	63789336/ 81261237	Fax No.	0
Survey Type	DIRECT SETTLEMENT:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	WEARNES AUTOMOTIVE PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	EILEEN LEE		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242449)



PRI Documents



Close X

PRI Header Details

Claim No	D18005475MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & WEARNES
Workshop Name	WEARNES AUTOMOTIVE PTE LTD (Contact Person : PAUL ONG)	Survey Location & Contact Details	BODY AND PAINT DEPT 249 ALEXANDRA ROAD Mobile: 81261237 , Phone: 63789336 , Fax: 0 EmailId: PAUL.ONG@WEARNES.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH6418Y	TP Vehicle No	SKS9728U
PRI Recieved Date	17-07-2018 04:53:10 PM	Surveyor Appointed Date	18-07-2018 02:06:45 PM	Surveyor Accept Date	18-07-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	18-07-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 6 August 2018 2:29 PM
To: 'Claim Workflow System'
Cc: SUR; Eileen Lee
Subject: RE: SURVEY ASSESSMENT - D18005475MFSH/1, SKS 9728U
Attachments: SKS 9728U PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKS 9728U
Date of survey: 2/8/2018
Number of days : 7 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 18 July 2018 2:07 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005475MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Passport Country/Region: Hong Kong
Owner ID:	19942
Vehicle Details	
Vehicle No.:	SKS9728U
Vehicle to be Exported:	No
Intended De-registration Date:	06 Aug 2018
Vehicle Make:	LAND ROVER
Vehicle Model:	RANGE ROVER SPORT 3.0S/C TSS 7S SR
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	15030202590306PS
Chassis No.:	SALWA2VE1FA525216
Maximum Power Output:	250.0 kW (335 bhp)
Open Market Value:	\$102,856.00
Original Registration Date:	18 May 2015
First Registration Date:	18 May 2015
Transfer Count:	0
Actual ARF Paid:	\$157,141.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 May 2025
PARF Rebate Amount:	\$117,855.00
Intended COE Rebate Details	
COE Expiry Date:	17 May 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$78,001.00
COE Rebate Amount:	\$52,881.00
Total Rebate Amount:	\$170,736.00

The information contained herein is correct as at 06 Aug 2018

OK

SERVICE ESTIMATE

81028 - C00001 SL: SERVICE SALES - PC

Mr Sam Lee
41 Pasir Panjang Hill
#05-07 Horizon Residences

Singapore 118862

GST Reg.No:M28920628X
Inv.No. : B&P 0 Page 1
Inv.date. : 17/07/2018
WIP No. : 16908
Veh.In/Out:
*Tel.No. : Mobile: +852 96653353
Reg.No. : SKS9728U
Reg.date : 18/05/2015
Mileage : 0
Chassis No: SALWA2VE1FA525216

Closed by : Paul Ong Qing Yong
Svc Consultant :
Remarks : Mr Sam Lee

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, BOOTLID, REAR TOW COVER, UNDERTRAY, REINFORCEMENT, ETC	0	4800.00	0		4,800.00 S 2400 ✓	
800	TO PUTTY SPRAYPAINT ON REAR BUMPER, BOOTLID, ETC	0	3000.00	0		3,000.00 S 2000 ✓	
802	TO REPLACE REAR WINDSCREEN	0	1200.00	0		1,200.00 S ✓	
0080	TO INSTALL REAR WINDSCREEN FIL	0	280.00	0		280.00 S ✓	
802	TO REMOVE & REFIT BOOTLID PART	0	500.00	0		500.00 S ✓	
802	TO REPLACE REAR LEFT & RIGHT EXHAUST ASSY	0	2400.00	0		2,400.00 S 1200? X 1M ✓	
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	486.00	0		486.00 S ✓	
1	BUMPER COVER REAR RR	1.0 EA	1910.20			1,910.20 S	Cal - 1719.18
2	BUMPER MOULDING TOW	1.0 EA	427.70			427.70 S	MCS - 348.48
3	BRACKET - BUMPER MOU	1.0 EA	212.00			212.00 S	? X sur
4	UNDERTRAY TOWBAR RRS	1.0 EA	401.50			401.50 S	? X sur

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rare
Hp 9006068
6-7 days
02/08/18 @ 1150
Reg by paint
6/8/18



SL: SERVICE SALES - PC

#05-07 Horizon Residences

WIP No. : 16908

Veh. In/Out:

*Tel.No. . : Mobile: +852 96653353

Reg.No. : SKS9728U

Reg. date. : 18/05/2015

Mileage : 0

Chassis No: SALWA2VE1FA525216

Svc Consultant :

Remarks : Mr Sam Lee

QTY	DESCRIPTION	UNIT	PRICE	AMOUNT	REMARKS
5	BRACKET - BUMPER MOU	1.0 EA	161.40	161.40	S
6	BRACKET - BUMPER MOU	1.0 EA	196.50	196.50	S
7	REINFORCEMENT - REAR	1.0 EA	1187.80	1,187.80	S
8	MUFFLER - REAR RH	1.0 EA	1993.10	1,993.10	S
9	MUFFLER - REAR LH	1.0 EA	1993.10	1,993.10	S
10	CLAMP - EXHAUST	2.0 EA	158.90	317.80	S
11	TAILGATE - LESS HING	1.0 EA	4913.00	4,913.00	S
12	WINDSCREEN REAR RRS3	1.0 EA	2193.60	2,193.60	S
13	ADHESIVE AND SEALER	2.0 EA	116.10	232.20	S
14	*D* PRIMER GLASS & P	1.0 EA	37.40	37.40	S
15	BADGE "RANGE" REAR R	1.0 EA	211.30	211.30	S
16	BADGE "ROVER" REAR R	1.0 EA	183.20	183.20	S
17	LLR053808/BADGE OVAL	1.0 EA	91.20	91.20	S
18	NAME PLATE - PLASTIC	1.0 EA	181.60	181.60	S
19	ADHESIVE SEALER FL2	1.0 EA	425.40	425.40	S

Labour	Total	12,666.00
Parts	Total	17,270.00
Package	Total	0.00

GST @ 7.0%	2,095.52
------------	----------

Total.....	32,031.50
------------	-----------

Paid.....	0.00
-----------	------

Please Pay..	32,031.50
--------------	-----------

SERVICE ESTIMATE

0 - F00003 SL: FIRST CAPITAL INSURANCE LTD
FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01, CITY HOUSE
SINGAPORE
Singapore 068877
GST Reg.No: M28920628X
Inv.No. : B&P 0 Page 1
Inv.date : 05/09/2018
WIP No. : 16908
Veh.In/Out: 02/08/2018 17/08/2018
*Tel.No. :
Reg.No. : SKS9728U
Reg.date : 18/05/2015
Mileage : 33,451
Chassis No: SALWA2VE1FA525216
Closed by : Paul Ong Qing Yong
Svc Consultant : ACC
Remarks : Mr Sam Lee

Op.No	Description	Rech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, BOOTLID, REAR TOW COVER, ETC	0	2400.00	0		2,400.00	\$
800	TO PUTTY SPRAYPAINT ON REAR BUMPER, BOOTLID, ETC	0	2000.00	0		2,000.00	\$
802	TO REPLACE REAR WINDSCREEN	0	1200.00	0		1,200.00	\$
0080	TO INSTALL REAR WINDSCREEN FIL	0	280.00	0		280.00	\$
802	TO REMOVE & REFIT BOOTLID PART	0	500.00	0		500.00	\$
280	TO CHECK WIRING INCLUDE RESETTNG OF ALL ELECTRICAL MODULES	0	486.00	0		486.00	\$
1	BUMPER COVER REAR RR	1.0 EA	1910.20	10		1,719.18	\$
1	TAILGATE - LESS HING	1.0 EA	4913.00	10		4,421.70	\$
1	WINDSCREEN REAR RRS3	1.0 EA	2193.60	10		1,974.24	\$
1	ADHESIVE AND SEALER	2.0 EA	116.10	10		208.98	\$
1	*D* PRIMER GLASS & P	1.0 EA	37.40	10		33.66	\$
1	BADGE "RANGE" REAR R	1.0 EA	211.30	10		190.17	\$
1	BADGE "ROVER" REAR R	1.0 EA	183.20	10		164.88	\$

SERVICE ESTIMATE

0 - F00003 SL: FIRST CAPITAL INSURANCE LTD
 FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01, CITY HOUSE
 SINGAPORE
 Singapore 068877

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2
 Inv.date: 05/09/2018
 WIP No. : 16908
 Veh.In/Out: 02/08/2018 17/08/2018
 *Tel.No. :
 Reg.No. : SKS9728U
 Reg.date: 18/05/2015
 Mileage : 33,451
 Chassis No: SALWA2VE1FAS25216

Closed by : Paul Ong Qing Yong
 Svc Consultant : ACC
 Remarks : Mr Sam Lee

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	1. LLR053808/BADGE OVAL	1.0 EA	91.20	10		82.08	S
	2. NAME PLATE - PLASTIC	1.0 EA	181.60	10		163.44	S
	3. ADHESIVE SEALER FL2	1.0 EA	425.40	10		382.86	S
	4. TOW BAR COVER DEPLOY	1.0 EA	387.20	10		348.48	S

Gross Total. 16,555.67

Labour Total 6,866.00
 Parts Total 9,689.67
 Package Total 0.00

Net..... 16,555.67
 GST @ 7.0% 1,158.90
 Total..... 17,714.57
 Paid..... 0.00
 Please Pay.. 17,714.57

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FC118013055/R1vd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 12-09-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 6418Y	Veh. Inspected	SKS 9728U
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18005475MFSH	Excess (\$)	0.00
Assign From	EILEEN	Assign Date	18/07/2018

2. Vehicle Particulars & Condition

Make & Model	LAND ROVER RANGE ROVER 3.0	c.c	2995
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	SALWA2VE1FA525216	Colour	GREY
Odometer	33451	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/45 R21	CONTINENTAL	6 mm
L/H Front Tyre	275/45 R21	CONTINENTAL	6 mm
R/H Rear Tyre	275/45 R21	CONTINENTAL	6 mm
L/H Rear Tyre	275/45 R21	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	16/07/2018	Inspection Date	02/08/2018
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 9728U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER REAR RR (SN)	CUT	1,910.20	1,719.18
1	BUMPER MOULDING TOW (SN)	MISSING	427.70	348.48
1	BRACKET-BUMPER MOU (SN)	SERVICEABLE	212.00	-
1	UNDERTRAY TOWBAR RRS (SN)	SERVICEABLE	401.50	-
1	BRACKET-BUMPER MOU (SN)	SERVICEABLE	161.40	-
1	BRACKET-BUMPER MOU (SN)	SERVICEABLE	196.50	-
1	REINFORCEMENT-REAR (SN)	SERVICEABLE	1,187.80	-
1	MUFFLER-REAR RH (SN)	SERVICEABLE	1,993.10	-
1	MUFFLER-REAR LH (SN)	SERVICEABLE	1,993.10	-
2	CLAMP-EXHAUST (SN)	SERVICEABLE	317.80	-
1	TAILGATE-LESS HING (SN)	CRACKED	4,913.00	4,421.70
1	WINDSCREEN REAR RRS3 (SN)	NECESSARY	2,193.60	1,974.24
2	ADHESIVE AND SEALER (SN)	NECESSARY	232.20	208.98
1	*D* PRIMER GLASS & P (SN)	NECESSARY	37.40	33.66
1	BADGE "RANGE" REAR R (SN)	NECESSARY	211.30	190.17
1	BADGE "ROVER" REAR R (SN)	NECESSARY	183.20	164.88
1	LLR053808/BADGE OVAL (SN)	NECESSARY	91.20	82.08
1	NAME PLATE-PLASTIC (SN)	NECESSARY	181.60	163.44
1	ADHESIVE SEALER FL2 (SN)	NECESSARY	425.40	382.86
			17,270.00	9,689.67
LABOUR				
	TO REPLACE REAR BUMPER,BOOTLID,REAR TOW COVER,UNDERTRAY,REINFORCEMENT,ETC.		4,800.00	2,400.00
	TO PUTTY SPRAYPAINT ON REAR BUMPER,BOOTLID,ETC.		3,000.00	2,000.00
	TO REPLACE REAR WINDSCREEN.		1,200.00	1,200.00
	TO INSTALL REAR WINDSCREEN FIL.		280.00	280.00
	TO REMOVE & REFIT BOOTLID PART.		500.00	500.00
	TO REPLACE REAR LEFT & RIGHT EXHAUST ASSY.	NOT NECESSARY	2,400.00	-

Report Ref No. CS/FCI18013055/R1vd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES		486.00	486.00
			12,666.00	6,866.00
GRAND TOTAL			29,936.00	16,555.67
RECOMMENDED COST OF REPAIRS				16,555.67

Report Ref No. CS/FCI18013055/R1vd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.