

15/02/2010

INS. CASE OWNER:

CC 4/AXA1801

3059, T1 pb3

LKK:

IDAC:

Surveyor:

Tan Aich

DOI:

ASSIGNMENT

18/7/18

Date / Time:

18/7/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLE 450R

Name of Insured:

YAN WENY THOR

Insured Tel No.:

HP: 96574285

Excess Sec II :SS

D.O.A: 27/6/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

YAN JIA YI

Driver Tel No.:

91559567

(V/L / YES / NO)

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

FBG 1827P

INSRS:
WSP:
Tel:
Liability:
RMKS:long
sengINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

18/7/18
UT

18/7/18

28/2/18

31/4/18

22/10/18

FBG 1827P 2-400/m36180294/4 000-27/6/18
SLE 450R

* 9 martidam

ps ✓

Old turned out from minor road
collided with 1 who was on main
road.

DV sent

File pass to Shu Per to close

RECEIVED 23 OCT 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

9 (d).

Repair Cost:

SS 5500.00

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

175.00

(25 x 7 days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

7.45

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS 5682.45

Global Sum SS: 5680.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

5680.00

Name 1:

Leong Seng Motor Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

ASS. REC. BY:

Tayy

REF:

AXA

p

ASSIGNMENT

From: Date: 18/7/18

Estimated Cost:

OP: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: FBG 1827 P

at Workshop m/s: Leong Seng Motor

of: 81K 1006, Bkt Meruh June 2 #01-08

Insured:

Policy No:

Claims No:


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$7K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: FBG 1827 P Yr Regn: 2012, April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha FZ16 c.c. 153

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: — T/Radio: Insured / Std / NI / NA

Eng/No: ME1216072C2030025

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 120/70 R17 110/70 R17

R: 130/55 R17 140/70 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Metzeler

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. mm L/Bal. mm

D.O.A. D.O.I. 18/7/18

Survey held at Leong Seng Motor

Des. of Damages: F/R / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LIC \$ 5500 (Red \$ 2677.90 / 324.7)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18013059/pb3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 18-07-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLE 450R	Veh. Inspected	FBG 1827P	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	18/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/06/2018	Inspection Date		
Survey held at	LEONG SENG MOTOR PTE LTD BLK 1006, BUKIT MERAH LANE 2 #01-08 ALEXANDRA VILLAGE SINGAPORE 159762.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Veh No : FBG1827P

Model : FZ16

S/N	Parts Description	QTY	List Price	Nett Price	Remark
1	Handle bar		\$ 150.00		bt ✓
2	Handle grip		\$ 25.00		tn ✓
3	Mirror		\$ 50.00		ant ✓
4	Clutch lever		\$ 45.00		ant ✓
5	Air gul		\$ 65.00		bro ✓
6	Air cover (R)		\$ 87.00		ant ✓
7	Fuel tank side cover		\$ 180.00		ant ✓
8	Fuel tank centre cover		\$ 160.00		ant ✓
9	Side cover (L)		\$ 185.00		ant ✓
10	Front fork assy ←		\$ 860.00	bt ✓	?
11	Fork under bracket ←		\$ 285.00	bt ✓	?
12	Front wheel rim ←		\$ 380.00	bt ✓	?
13	Front wheel axle ←		\$ 95.00	bt ✓	?
14	Gear pedal		\$ 78.00		bt ✓
15	Front foot rest (L)		\$ 50.00		ant ✓
16	Clutch cover		\$ 220.00		ca ✓
17	Oil filter cover & O ring		\$ 68.00		bro ✓
18	Oil filter cover screw	3	\$ 15.00		bt ✓
19	Oil filter		\$ 15.00		ner ✓
20	Engine oil		\$ 25.00		ner ✓
21	Brake pedal		\$ 98.00		bt ✓
22	Rear brake tie rod		\$ 64.00		bt ✓
23	Front foot rest (R)		\$ 50.00		ant ✓
24	Front foot protector (R)		\$ 75.00		xm ✓
25	Main stand		\$ 120.00		bt ✓
26	Rear swing arm		\$ 320.00	photo	bt ✓
27	Swing arm brush ←		\$ 75.00	de ✓	?
28	Rear shock absorber ←		\$ 380.00	bt ✓	?
29	Rear foot rest (R)		\$ 45.00		ant ✓
30	Tail cover	2	\$ 370.00		ant ✓
31	Tail center cover		\$ 68.00		de ✓
32	Tail bar	2	\$ 150.00		R ✓
33	Rear signal lamp		\$ 45.00		xm ✓
34	Rear fender		\$ 168.00		de ✓
35	Rear mudguard		\$ 155.00		ant ✓
36	Rear wheel rim ←		\$ 450.00	photo	bt 300
37	Rear wheel bearing	2	\$ 50.00		ner ✓
38	Rear wheel axle ←		\$ 95.00	bt ✓	?
39	Rear sprocket & chain ←		\$ 70.00	bt ✓	?

Less 10%

\$ 5,886.00
\$ 588.60
\$ 5,297.40

5966

Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Veh No : FBG1827P

Model : FZ16

S/N	Parts Description	QTY	List Price	Nett Price	Remark
40	Rear sprocket hub		\$ 105.00		X n
41	ERP IU			\$ 156.00	X n
42	IU bracket			\$ 25.00	X n
43	Top cowling			\$ 235.00	cm
44	Front no plate			\$ 15.00	un
45	Front wheel slider LH			\$ 130.00	mis
46	Gear pedal rubber cover			\$ 15.00	out
47	Center cover			\$ 120.00	Cus
48	Racing exhaust - full system			\$ 985.00	bt
49	Rear no plate			\$ 20.00	bt
50	Oil pressure release valve			\$ 65.00	bt
51	Repair main frame ←		photo 70	\$ 450.00	300
52	Towing -2 way			\$ 120.00	80 X
53	Labour			\$ 400.00	250.
54					
55	Tanjilun 97495749		Parts -	7051	
56	WP		- 10%	6345.90	
57	18/7/18 P 1750		Labour -	630	
58	Resumy after repair.			6975.80	
59			4/5	5550	
60	7 days			*	
61	sur & repair.com				
62				8127.90	
63					
64	Resumy after 23/8/18				
65					
66					
67					
68					
69					
70					
71					
72					
73					
74					
75					
76					
77					
78					

\$ 105.00 \$ 2,736.00

Less 10%

\$ 10.50

\$ 94.50

Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Veh No : FBG1827P

Model : FZ16

S/N	Parts Description	QTY	List Price	Nett Price	Remark
1	Handle bar		\$ 150.00		bt ✓
2	Handle grip		\$ 25.00		try ✓
3	Mirror		\$ 50.00		cut ✓
4	Clutch lever		\$ 45.00		cut ✓
5	Air gul		\$ 65.00		brd ✓
6	Air cover (R)		\$ 87.00		cut ✓
7	Fuel tank side cover		\$ 180.00		cut ✓
8	Fuel tank centre cover		\$ 160.00		cut ✓
9	Side cover (L)		\$ 185.00		cut ✓
10	Front fork assy ←		\$ 860.00	bt ✓	?
11	Fork under bracket ←		\$ 285.00	bt ✓	?
12	Front wheel rim ←		\$ 380.00	bt ✓	?
13	Front wheel axle ←		\$ 95.00	bt ✓	?
14	Gear pedal		\$ 78.00		bt ✓
15	Front foot rest (L)		\$ 50.00		cut ✓
16	Clutch cover		\$ 220.00		cut ✓
17	Oil filter cover & O ring		\$ 68.00		brd ✓
18	Oil filter cover screw	3	\$ 15.00		bt ✓
19	Oil filter		\$ 15.00		rel ✓
20	Engine oil		\$ 25.00		rel ✓
21	Brake pedal		\$ 98.00		bt ✓
22	Rear brake tie rod		\$ 64.00		bt ✓
23	Front foot rest (R)		\$ 50.00		cut ✓
24	Front foot protector (R)		\$ 75.00	nm ✓	✗
25	Main stand		\$ 120.00		bt ✓
26	Rear swing arm		\$ 320.00	plwto ✓	bt ✓
27	Swing arm brush ←		\$ 75.00	de ✓	?
28	Rear shock absorber ←		\$ 380.00	bt ✓	?
29	Rear foot rest (R)		\$ 45.00		cut ✓
30	Tail cover	2	\$ 370.00		cut ✓
31	Tail center cover		\$ 68.00		de ✓
32	Tail bar	2	\$ 150.00	nm ✓	Rv ✓
33	Rear signal lamp		\$ 45.00	nm ✓	✗
34	Rear fender		\$ 168.00		de ✓
35	Rear mudguard		\$ 155.00		cut ✓
36	Rear wheel rim ←		\$ 450.00	plwto ✓	bt 300 ✓
37	Rear wheel bearing	2	\$ 50.00		rel ✓
38	Rear wheel axle ←		\$ 95.00	bt ✓	?
39	Rear sprocket & chain ←		\$ 70.00	bt ✓	?

\$ 5,886.00 \$

Less 10%

\$ 588.60

\$ 5,297.40

Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Veh No : FBG1827P

Model : FZ16

S/N	Parts Description	QTY	List Price	Nett Price	Remark
40	Rear sprocket hub		\$ 105.00		?
41	ERP IU			\$ 156.00	X
42	IU bracket			\$ 25.00	X
43	Top cowling			\$ 235.00	✓
44	Front no plate			\$ 15.00	✓
45	Front wheel slider LH			\$ 130.00	mis ✓
46	Gear pedal rubber cover			\$ 15.00	✓
47	Center cover			\$ 120.00	✓
48	Racing exhaust - full system			\$ 985.00	✓
49	Rear no plate			\$ 20.00	✓
50	Oil pressure release valve			\$ 65.00	✓
51	Repair main frame ←		photo 7	\$ 450.00	300
52	Towing -2 way			\$ 120.00	80
53	Labour			\$ 400.00	250.
54					
55	Tanfer 97995744				
56	WP				
57	15/7/18 P 1730				
58	Resumy after repair				
59					
60	7 days				
61	sur P. Khant.com				
62					
63					
64	Resumy further 23/8/18				
65					
66					
67					
68					
69					
70					
71					
72					
73					
74					
75					
76					
77					
78					

\$ 105.00 \$ 2,736.00

Less 10%

\$ 10.50

\$ 94.50



Service Request Details

Claim

S8M00MJ7

Reference

None

Loss Date

June 27, 2018

Request Date

July 17, 2018

Due Date

July 24, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

17072018 @ 2:08pm
Mr Teo veh in
Hong Seng motor.
Blk 1006 Bukit merah lane 2
#01-08
request Taufik survey on
18072018

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

FBG1827P

Make

TPVD YAMAHA

Model

FZ16-153CC (M)

Service Address

...

Primary Contact/Insured

LAU WENG THOR

BLK 71 #05-17, CHOA CHU KANG LOOP, 689673, Singapore

96534385

Claim Handler

TAY Ernest

6568804835

ernest.tay@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Hsiao Tong (LKKAUTO)

From: Jiayi Lau <laujiayi89@hotmail.com>
Sent: Monday, 30 July 2018 10:20 PM
To: Hsiao Tong (LKKAUTO)
Cc: Danny Lau
Subject: GA113445/1 (SLE 450R)
Attachments: Annex C - Photos.zip; Annex A - Police Report.PDF; Annex B - Driving License.zip

Dear Sir/Madam,

Your Ref: GA113445/1 (SLE 450R)

Accident Involving SLE 450R and FBG 1827P Along/at Teck Whye Lane Towards Teck Whye Ave on 27/06/2018

I refer to your above letter dated 26 July 2018.

Please find attached herewith the documents you may require:

Annex A - Police Report

Annex B - Driver's Driving License

Annex C - Photographs of accident Scene and damage to vehicles


For your follow-up and necessary action please.

Thank You,

Best Regards,
Lau Jia Yi (Mr)
9155 9567



























<SEEK MANDATE> - S8M00MJ7 [ACCIDENT INVOLVING SLE 450R(OI) & FBG 1827P(TP) ON 27/06/2018]

Type

🔗 Question

Message

Liability: 100%. Insured turned out from minor road and collided with third party. Inform OI about third party claim. Agreed to settle and aware NCD issue. We seek your mandate from \$5,345.89 - \$ 7,456.39. IA with mandate had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 08 Aug 2018

Reply