

Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Veh No : FBG1827P

Model : FZ16

S/N	Parts Description	QTY	List Price	Nett Price	Remark
1	Handle bar		\$ 150.00		bt✓
2	Handle grip		\$ 25.00		tn✓
3	Mirror		\$ 50.00		ant✓
4	Clutch lever		\$ 45.00		ant✓
5	Air gul		\$ 65.00		br✓
6	Air cover (R)		\$ 87.00		ant✓
7	Fuel tank side cover		\$ 180.00		ant✓
8	Fuel tank centre cover		\$ 160.00		ant✓
9	Side cover (L)		\$ 185.00		ant✓
10	Front fork assy		\$ 860.00		?
11	Fork under bracket		\$ 285.00		?
12	Front wheel rim		\$ 380.00		?
13	Front wheel axle		\$ 95.00		?
14	Gear pedal		\$ 78.00		bt✓
15	Front foot rest (L)		\$ 50.00		ant✓
16	Clutch cover		\$ 220.00		ca✓
17	Oil filter cover & O ring		\$ 68.00		br✓
18	Oil filter cover screw	3	\$ 15.00		bt✓
19	Oil filter		\$ 15.00		ner✓
20	Engine oil		\$ 25.00		ner✓
21	Brake pedal		\$ 98.00		bt✓
22	Rear brake tie rod		\$ 64.00		bt✓
23	Front foot rest (R)		\$ 50.00		at✓
24	Front foot protector (R)		\$ 75.00		x
25	Main stand		\$ 120.00		bt✓
26	Rear swing arm		\$ 320.00	to photo	bt✓
27	Swing arm brush		\$ 75.00		?
28	Rear shock absorber		\$ 380.00		?
29	Rear foot rest (R)		\$ 45.00		ant✓
30	Tail cover	2	\$ 370.00		at✓
31	Tail center cover		\$ 68.00		de✓
32	Tail bar	2	\$ 150.00		R✓
33	Rear signal lamp		\$ 45.00		x
34	Rear fender		\$ 168.00		de✓
35	Rear mudguard		\$ 155.00		ant✓
36	Rear wheel rim		\$ 450.00	photo	bt✓ 300
37	Rear wheel bearing	2	\$ 50.00		ner✓
38	Rear wheel axle		\$ 95.00		?
39	Rear sprocket & chain		\$ 70.00		?

\$ 5,886.00 \$ -

Less 10%

\$ 588.60

\$ 5,297.40

Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Veh No : FBG1827P

Model : FZ16

S/N	Parts Description	QTY	List Price	Nett Price	Remark
40	Rear sprocket hub		\$ 105.00		?
41	ERP IU			\$ 156.00	x
42	IU bracket			\$ 25.00	x
43	Top cowling			\$ 235.00	cm
44	Front no plate			\$ 15.00	wh
45	Front wheel slider LH			\$ 130.00	mis
46	Gear pedal rubber cover			\$ 15.00	out
47	Center cover			\$ 120.00	cm
48	Racing exhaust - full system			\$ 985.00	bt
49	Rear no plate			\$ 20.00	bt
50	Oil pressure release valve			\$ 65.00	bt
51	Repair main frame		photo	\$ 450.00	250
52	Towing -2 way			\$ 120.00	80
53	Labour			\$ 400.00	250
54					
55					
56					
57					
58					
59					
60					
61					
62					
63					
64					
65					
66					
67					
68					
69					
70					
71					
72					
73					
74					
75					
76					
77					
78					

Tanpin 97995744
WP
18/7/18 @ 1730
Resurvey after repair.

7 days
sur & repair.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 105.00 \$ 2,736.00

Less 10%

\$ 10.50

\$ 94.50