



Adrian Lkk - CTP
新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

HOO BOON TECK

17/07/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP China
Asher

Accident date: 14/07/2018

Estimated repair cost for vehicle no: SKT9578E MAZDA 3 1.5 A '15

S/n	Qty	Items / List	U/price	Amount
1	2	Front Head Lamp <i>zmbd</i>	\$873.30	\$1,746.60 ✓
2	2	Front Head Lamp Lower Bracket <i>zmbd</i>	\$25.20	\$50.40 X
3	1	Front Bumper <i>Delbond</i>		\$925.10 ✓
4	10	Front Bumper Clip <i>Neu</i>	\$6.50	\$65.00 30
5	2	Front Bumper Side Retainer <i>neu</i>	\$28.70	\$57.40 ✓
6	1	Front Bumper Emblem Logo <i>neu</i>		\$74.40 ✓
7	1	Front Bumper Number Plate <i>lt</i>		\$50.00 30
8	1	Front Bumper Centre Lower Cover <i>neu</i>		\$92.70 X
9	1	Front Bumper Reinforcement <i>Neu neu</i>		\$565.10 X
10	2	Front Bumper Fog Lamp <i>zmbd</i>	\$257.30	\$514.60 +
11	2	Front Bumper Fog Lamp Cover <i>zmbd</i>	\$42.70	\$85.40 X
12	1	Front Grille <i>zmbd</i>		\$233.70 ✓
13	2	Front Grille Chrome Moulding <i>lt</i>	\$176.70	\$353.40 ✓
14	1	Front Support Panel <i>neu</i>		\$469.70 +
15	1	Front Support Panel Top Cover <i>zmbd</i>		\$122.40 ✓
16	1	Front Air-con Condenser <i>zmbd</i>		\$987.00 X
17	1	Front Radiator <i>zmbd</i>		\$1,064.90 X

3513

Subtotal :- \$7,457.80

2858.40

Labour charges

To remove & refit air-con condenser, radiator, fan motor & top up gas	\$380.00 *
To check wiring	\$60.00 30
Tuff kote	\$150.00 *
Panel beating	\$850.00 300
Spray painting	\$850.00 300

Subtotal :- \$2,290.00

Total:- \$9,747.80

Adrian King
h/s 17/07/18

Supplementary: 268.08

03 aug

total: 3756.48

h/s 3K

3K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- Subject to final approval from Insurance Company
- Signed by Repairer



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

HOO BOON TECK

17/07/2018

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 14/07/2018

Estimated repair cost for vehicle no: SKT9578E MAZDA 3 1.5 A '15

S/n	Qty	Items / List	U/price	Amount
1	1	Front Grille Top Cover <i>phnd</i>		\$335.10 ✓
Total:-				<u>\$335.10</u>

335.10

268.08