

003/2002

SS, EC, BY:

Surveyor

REF:

CS3/SPF18013068/0462

Special Instruction:

From (Person):

Maimy

Abdul Rahman

ASSIGNMENT (Office)

SPF

Date/Time:

18072018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

Insured:

Qx 555M

To Inspect Vehicle No:

SLW 7760C

Tel:

9735 1788

at Workshop m/s

M.S. Panel Beating
2 Kaki Bukit Ave 2

of

Claim No:

AEMD/105/009/2018/087

Policy No:

Excess:

D.O.A. 14072018

Sum Insured:

Make of Veh:

19.07.2018

(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS '10p'

Pauline

Vehicle ☒ IN ☐ OUT

Date/Time: 18072018 340pm

Person Contacted:

Date/Time Action/Instruction (X) Estimate

SLW 7760C - NA / M18012900/24

DAR: 14072018

Qx 555M - CS3/SPF1708246/Tlbs2-1

DAR: 29082017

20/7/18

Dismantled

DAR:

Submit DAR Report Lump Sum 147501-

Grip 2

(08/11/13) Wef

REF: SPF

ASS. REC. BY: Marcus

ASSIGNMENT

From: _____ Date: 19/7/18

Estimated Cost: _____

OP ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No: SLN 7760C

at Workshop m/s M-S. Panel Beating

of 2 kaki Bkt Ave 2 #02-17

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLN 7760C Yr Regn: 2017, May 17

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /Truck / Trailer or ☒ Car /

Make: Toyota CHR c.c. 1797

Colour: maroon A/C: Insured / Std / NI / NA

Sp. Reading: 34355 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 24X10 2012634

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil / ☒ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 215/60R17

R: _____

BS / ☒ BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. _____

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 19/7/18

Survey held at _____

Des. of Damages: Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

No settlement.

16 - 20

Range 24K - 24K

Repair days 14

RECEIVED 28 AUG 2018

TOTAL

kin 21/8/18

Date/Time, File Pass to?

☐

: Preli. Report

1) 2018 Typist

☒

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 14

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: 280

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format: TP

Lump Sum / I.B.I.: (\$ 14750/-)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS3/SPF18013068/Ut6

ACCIDENT CLAIM SECTION
(SINGAPORE POLICE FORCE)

1 MOUNT PLEASANT ROAD

BLK 8 OLD POLICE ACADEMYSINGAPORE 298333

Date : 18-07-2018



Code : SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	QX 555M	Veh. Inspected	SLN 7760C
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/087	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	18/07/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	14/07/2018	Inspection Date	18/07/2018
Survey held at	M.S. PANEL BEATING WORKSHOP 2 KAKI BUKIT AVENUE 2 #02-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref : SLN7760C

Our Ref : AEMD/105/009/2018/087

Date : 18 July 2018

Tel: 64784840

Fax: 64784848

M/s LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 #01/02-25
Singapore 408933

Via Fax only: 62564315

Dear Sir/Madam,

RTA ON 14 JULY 2018 INVOLVING GOVT VEH QX555M AND OTHER VEH SLN7760C

We refer to the above matter.

- 2 Please arrange for a Pre Repair Inspection of vehicle no. **SLN7760C** at **M/s Panel Beating Workshop** of **2 Kaki Bukit Ave 2 #02-17, AutoHub@Kaki Bukit, Singapore 417921.**
- 3 For appointment please contact **Pauline** at **97391788.**
- 4 Estimates were not provided by the workshop.
- 5 Thank you.

Yours sincerely,

Abdul Rahman
Accident Claims Officer
for Assistant Director

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/07/2018 16:56
Date Of Accident	14/07/2018 11:00
Exact Location Of Accident	ALONG BEDOK RESERVOIR RD AFTER JUNC BEDOK NORTH RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN7760C
Insured/Policyholder	
Name Of Registered Owner	KUAH SIEW LIAN
NRIC No	S7042732Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96216131
Alternative Phone No	OFFICE-96216131

Vehicle Particulars

Manufacturer	TOYOTA
Model	C-HR HYBRID 1.8S CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	M497411
Cover Note Number	

Driver

Name of Driver	KUAH SIEW LIAN
NRIC No	S7042732Z
Date Of Birth	09/12/1970
Occupation	INDOOR
Date Of Driving Pass	26/04/2002
Driving Experience	16 YEARS AND 2 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96216131
Fax Number	
Contact Number	OFFICE-96216131
EEmail Address	NOEMAIL

Address	BLK 609 BEDOK RESERVOIR ROAD #10-678
Postcode	470609
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	KAMPONG UBI NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 9 EUNOS CRESCENT #01-2687 , POSTCODE: 400009 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7479999 - FAX NO: 67453410
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20180714/2105.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX555M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)	3
Passenger 1	NAME: : GENDER: :
Passenger 2	NAME: : GENDER: :

DETAILS OF INJURED PERSON 1

Name	KUAH SIEW LIAN
Approximate Age	
Injuries Sustain	NECK & BACK
Injured person in which vehicle?	SLN7760C
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report - 7/20180714/2105.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Police Report



**SINGAPORE
POLICE FORCE**



T/20180714/2105

1 of 3

Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

Report No. T/20180714/2105

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/07/2018 15:36	Vide Report No.:	Station Diary No.: 22
--	------------------	--------------------------

Informant's Particulars

Name of Informant: KUAH SIEW LIAN			Address: APT BLK 609 BEDOK RESERVOIR ROAD #10-678 SINGAPORE 470609		2
ID Type / ID No: NRIC NO / S7042732Z			Contact No.: Home/Office: Mobile: 96216131		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 47	Date of Birth: 09/12/1970	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: DIRECTOR			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Police Vehicle	Drink Drive: No	Date/Time of Accident: 14/07/2018 11:00	Type of Location:
Location: BEDOK NORTH ROAD Junction of Bedok North Road and Bedok Reservoir Rd				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow:		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
QX555M	Car				Seriously Damaged	3
SLN7760C	Car	TOYOTA	C-HR HYBRID 1.8S CVT	Red	Seriously Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------

Police Report



**SINGAPORE
POLICE FORCE**



T/20180714/2105

2 of 3

Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

Report No. T/20180714/2105

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLN7760C	INDIA INTERNATIONAL INSURANCE PTE LTD	M497411	17/05/2018	16/05/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Name	Unknown		ID No	NIL
Isolated Vehicle	QX555M (Car)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL
Driver				
Name	KUAH SIEW LIAN		ID No.	S7042732Z
Related Vehicle	SLN7760C (Car)		Contact No.	96216131
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL

Brief Details.

On 14/07/2018 at about 11:00am I was travelling on the second lane along Bedok Reservoir towards Tampines while a police car was on the first lane. While I was making a right turn into bedok north road into the second lane towards PIE, the police vehicle suddenly encroached into my lane causing me to not be able to brake in time and subsequently collided into the front left of the police car. I then stopped by the side of the road to prevent road congestion. Traffic police then came down to assist me.

Police Report



SINGAPORE
POLICE FORCE



T/20180714/2105

3 of 3

Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No. 1800-7479999

Report No. T/20180714/2105

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 1 CHUN KHANG YEE	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 14/07/2018 15:36
Officer In Charge Of Case: TP / DDGVT / Sr Staff Sgt CHONG GUAN FATT Contact No.: 65476198	Classification Of Case:
Authentication Stamp NP168	

MOTOR CAR (Frt)

Aug 2005

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	20.00	BR	✓
1002	991887	Frt Number Plate Base	20.00	BR	✓
1003	991889	Frt Number Plate Garnish	271.85	BR	✓
1004	991300	Frt Bumper	374.45	CRU	✓
1005	992341	Frt Bumper Clips	30.00	NC	✓
1006	991325	Frt Bumper Bracket	141.45	BR	✓ 2
1007	991462	Frt Bumper Side Retainer	266.70	NC	✓ 2
1008	991433	Frt Bumper Reinforcement	337.00	BT	✓
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge	181.90	BR	✓
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille	274.45	BR	✓
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover	75.00	BR	✓
1018	991355	Frt RH Bumper Fog Lamp Cover	75.00	BR	✓
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	367.95	DIS	✓
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	700.00	DIS	✓
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel	300.00	DIS	✓
1029	995153	Frt LH Headlamp Assy	2821.40	BR	✓
1030	991821	Frt RH Headlamp Assy	2821.40	BR	✓
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	800.00	BT	✓
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock	280.00	BT	✓
1036	990285	Bonnet Insulator	300.00	TN	✓
1037	990273	Bonnet Hinge	153.00	BT	✓ 2
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber	25.00	BR	✓
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser	1218.50	DT	✓
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier	215	NC	✓
1050	990111	Air Con Compressor Assy	2921.45	BT	✓ X SVC
1051	995294	Air Con Belt			
1052	995074	Radiator	1871.10	BR	✓
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy	280.85	BR	✓
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top	60.00	TN	✓
1057	992757	Radiator Hose Bottom	60.00	TN	✓
1058	992741	Radiator Expansion Tank	150.50	DD	✓
1059	990151	Air Duct	181.90	BR	✓
1060	990070	Air Cleaner Assy	250.00	BR	✓
1061	990056	Air Cleaner Hose	181.90	DIS	✓
1062	990089	Air Cleaner Resonator	200.00	BR	✓
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

Vehicle No: SLN-7760C

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender	645.10	BR	✓
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector 2H			
1100	991740	Frt LH Fender Inner Shield			155.50
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender	645.10	BR	✓
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector 2H			
1109	991740	Frt RH Fender Inner Shield			155.50
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
		Frt Fender Hub			
		Camshaft			
		Air con s.d. sensor			2
		Ft bumper brackets			2

No of items:

Author:

Park

19179.65

Condition (ACON)

(1) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(7) Deformed (8) Shifted (9) Buckled (10) Broken (11) Necessary (12) Missing
(13) Torn (14) Unconfirmed (15) Not Working

MOTOR CAR (RH)

ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (?)
(4) Not Consistent (NC)

Aug 2005

Vehicle No: **SLN 7760 C**

Right Portion

NAC	INC	Item	CON	AC	Qty
1316	995327	Frt RH Door			
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1320	991583	Frt RH Door Garnish			
1321	991639	Frt RH Door Glass Outer Moulding			
1322	991588	Frt RH Door Glass Inner Moulding			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1328	991607	Frt RH Door Inner Handle			
1329	991625	Frt RH Door Lock w/Key			
1330	991624	Frt RH Door Lock			
1331	991562	Frt RH Door Central Lock			
1332	991675	Frt RH Door Switch			
1333	991617	Frt RH Door Inner Trim Board			
1334	991568	Frt RH Door Checker			
1335	991575	Frt RH Door Felt			
1336	991688	Frt RH Door Wire Harness			
1337	991683	Frt RH Door Window Glass Pillar			
1338	991640	Frt RH Door Outer Pillar			
1339	991613	Frt RH Door Inner Pillar			
1340	991646	Frt RH Door Pillar Inner Garnish			
1341	990554	Centre Pillar RH			
1342	990543	Centre Inner Pillar RH			
1343	990518	Centre Pillar Upper Garnish RH			
1344	990565	Centre Pillar Lower Garnish RH			
1345	991670	Frt RH Door Step Garnish			
1346	994058	Rocker Panel RH			
1347	994049	Rocker Panel Inner Panel RH			
1348	994047	Rocker Panel Garnish RH			
1349	994055	Rocker Panel Outer Side Skirt RH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1030	991821	Frt RH Headlamp Assy			
1032	995089	Frt RH Side Lamp			
1105	995071	Frt RH Fender			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			

NAC	INC	Item	CON	AC	Qty
1350	993201	Rear RH Door			
1351	993284	Rear RH Door Protector			
1352	995307	Rear RH Door Hinge			
1353	993228	Rear RH Door Garnish			
1354	993278	Rear RH Door Glass Outer Moulding			
1355	993231	Rear RH Door Glass Inner Moulding			
1356	993229	Rear RH Door Glass			
1357	993289	Rear RH Door Glass Regulator			
1358	993240	Rear RH Door Glass Regulator Motor			
1359	993294	Rear RH Door Rubber			
1360	993276	Rear RH Door Outer Handle			
1361	993251	Rear RH Door Inner Handle			
1362	993261	Rear RH Door Lock			
1363	993256	Rear RH Door Inner Trim Board			
1364	993218	Rear RH Door Checker			
1365	993230	Rear RH Door Glass Channel			
1366	993242	Rear RH Door Glass Triangle Garnish			
1367	993285	Rear RH Door 1/4 Glass			
1368	993288	Rear RH Door 1/4 Glass Rubber			
1369	993287	Rear RH Door 1/4 Glass Pillar			
1370	993306	Rear RH Door Step Garnish			
1371	993309	Rear RH Door Switch			
1371	994070	Roof Top Panel			
1372	994098	Roof Top Moulding			
1373	994085	Roof Top Air-bag			
1374	994084	Roof Top Air-bag Sensor			
1375	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1166	995116	Rear RH Taillamp			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1136	990247	Sticker			
Labour					
1		check electric functions			50.00
2		To remove and install all affected parts			1600.00
3		To provide materials, spray paint the affected parts			1200.00
A		To provide undercoating and rust proofing of affected parts			800.00

No of Items: _____

Assessor: _____

Parts & Labour 22339.65
Repair days 14

MOTOR CAR (LH)

Left Portion

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door	SCR	R	X
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1259	995102	Frt LH Door Garnish			
1260	991593	Frt LH Door Glass Outer Moulding			
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key			
1269	991624	Frt LH Door Lock			
1270	991562	Frt LH Door Central Lock			
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker			
1274	991575	Frt LH Door Felt			
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH			
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1029	995153	Frt LH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1096	995070	Frt LH Fender			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			

Vehicle No: **SLN 7760C**

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door			
1290	993282	Rear LH Door Protector			
1291	995194	Rear LH Door Hinge			
1292	993228	Rear LH Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding			
1294	993231	Rear LH Door Glass Inner Moulding			
1295	995190	Rear LH Door Glass			
1296	993238	Rear LH Door Glass Regulator			
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber			
1299	993275	Rear LH Door Outer Handle			
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock			
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker -			
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Door 1/4 Glass			
1307	993288	Rear LH Door 1/4 Glass Rubber			
1308	993287	Rear LH Door 1/4 Glass Pillar			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1163	993851	Rear LH Taillamp			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1136	990247	Sticker			

No of Items: _____ Assessor: _____



DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGINEERING & MGT DIVISION
ACCIDENT CLAIM SECTION
(SINGAPORE POLICE FORCE) 1 MOUNT
PLEASANT ROAD BLK 8 OLD POLICE
ACADEMYSINGAPORE 298333

Ref: CS3/SPF18013068/Utbs2

Date: 28-08-2018



ATTN: ABDUL RAHMAN

Code: SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	QX 555M	Veh. Inspected	SLN 7760C
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/087	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	18/07/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA CHR (A)	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ZYX102012634	Colour	MAROON
Odometer	34359 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R17	BRIDGESTONE	7 mm
L/H Front Tyre	215/60R17	BRIDGESTONE	7 mm
R/H Rear Tyre	215/60R17	BRIDGESTONE	7 mm
L/H Rear Tyre	215/60R17	BRIDGESTONE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/07/2018	Inspect Date / Time	19/07/2018 (10:51 AM)
Survey held at	M.S. PANEL BEATING WORKSHOP 2 KAKI BUKIT AVENUE 2 #02-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	14 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

OPINION ON REPAIR COST FOR VEHICLE NO. SLN 7760C

Qty	Description of Parts	Condition	Recommended (\$)
	<u>REPLACEMENT OF PARTS</u>		
1	FRT NUMBER PLATE	CUT	20.00
1	FRT NUMBER PLATE BASE	BROKEN	20.00
1	FRT NUMBER PLATE GARNISH	BROKEN	271.85
1	FRT BUMPER	CRUSHED	974.45
1	FRT BUMPER CLIPS	NECESSARY	30.00
2	FRT BUMPER BRACKET @ \$141.45	BROKEN	282.90
2	FRT BUMPER SIDE RETAINER	NECESSARY	266.70
1	FRT BUMPER REINFORCEMENT	BENT	337.00
1	FRT BUMPER SPONGE	BROKEN	181.90
1	FRT BUMPER GRILLE	BROKEN	274.45
1	FRT LH BUMPER FOG LAMP COVER	CUT	75.00
1	FRT RH BUMPER FOG LAMP COVER	CUT	75.00
1	FRT GRILLE	DISTORTED	367.75
1	FRT GRILLE EMBLEM RADAR SENSOR	SHORTED	1,571.00
1	FRT SUPPORT PANEL	DISTORTED	700.00
1	FRT SUPPORT PANEL TOP GARNISH COVER	BROKEN	258.85
1	FRT BRACE PANEL	DISTORTED	300.00
1	FRT LH HEADLAMP ASSY	BROKEN	2,821.40
1	FRT RH HEADLAMP ASSY	BROKEN	2,821.40
1	BONNET	BENT	800.00
1	BONNET LOCK	BENT	280.00
1	BONNET INSULATOR	TORN	300.00
2	BONNET HINGE	BENT	153.00
1	BONNET RUBBER	CUT	25.00
1	AIR CON CONDENSER	DENTED	1,218.50
1	AIR CON DISCHARGE PIPE (HIGH PRESSURE)	BENT	60.00
1	AIR CON RECEIVER DRIER	DISLODGE	215.00
1	AIR CON COMPRESSOR ASSY	SERVICEABLE	-
1	RADIATOR	PUNCTURE	1,871.10
1	RADIATOR FAN ASSY	BROKEN	280.85
1	RADIATOR HOSE TOP	TWISTED	60.00
1	RADIATOR HOSE BOTTOM	TWISTED	60.00
1	RADIATOR EXPANSION TANK	DENTED	150.50

Report Ref No. CS3/SPF18013068/Utbs2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Recommended (\$)
1	AIR DUCT	BROKEN	181.90
1	AIR CLEANER ASSY	BROKEN	250.00
1	AIR CLEANER HOSE	DISTORTED	181.90
1	AIR CLAENER RESONATOR	BROKEN	200.00
1	FRT LH FENDER	BENT	645.10
1	FRT LH FENDER PROTECTOR LH	TORN	211.00
1	FRT LH FENDER INNER SHIELD	CUT	155.50
1	FRT RH FENDER	DENTED	645.10
1	FRT RH FENDER PROTECTOR	TORN	211.00
1	FRT RH FENDER INNER SHIELD	TORN	155.50
2	FRONT FENDER 'HYBRID' EMBLEM	NOT NECESSARY	78.00
2	AIR CON SIDE GARNISHS @ \$145.00	TORN	290.00
2	FRT BUMPER BRACKETS @ \$125.00	BENT	250.00
1	FRT RH DOOR (NPA)	TO REPAIR SEE LABOUR	-
	LESS 25% DISCOUNT		-5,144.65
			15,433.95
	LABOUR		
	CHECK ELECTRIC FUNCTIONS.		80.00
	TO REMOVE AND INSTALL ALL AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF FRT RH DOOR.		1,600.00
	TO PROVIDE MATERIALS, SPRAY PAINT THE AFFECTED PARTS.		1,200.00
	TO PROVIDE UNDERCOATING AND RUSTPROOFING OF AFFECTED PARTS.		80.00
			2,960.00
	GRAND TOTAL		18,393.95
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			14,750.00

Report Ref No. CS3/SPF18013068/Utbs2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.