

15/5/2010

INS. CASE OWNER:

Lynthia

CC 4/AXA1801

2072, 72 463⁵²

LKK:

IDAC:

Surveyor:

Tautik

DOI:

18/7/2018

Date / Time:

18/7/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

WC 4544H

Claim No.:

8800007/58284

Name of Insured:

HSS ENVIKO PIC

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

62000.00

D.O.A.:

16/7/18

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

S 1801CO

INSRS:
WSP:
Tel:
Liability:
RMKS:Te
AntoineINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

18/7/18
paukin

S 1801CO -x

WC 4544H -x

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: 14/8/2018

After call ltr to OI: 14/8/18

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

15/8/2018

Sent By:

CPK

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

15

If NO or B 28, Ass. Lia:

Repair Cost:

SS

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

(\$

x

days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

OJD changing lane
4/9/19

4350/-

ASSIGNMENT

From: _____ Date: 12/11/13

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: 21-1-15

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 21-1-15

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 1-0-1 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS ^{up}

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

ShawnVeh No: S1801CD Yr Regn: 2014, Feb.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Teana c.c. 1997Colour: Bronze A/C: Insured / Std / NI / NASp. Reading: 37925 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MNTKBA253Z000646

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 18/7/18 @ 1220Survey held at TC Automobile

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S u/c

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

P/P = \$4795.72

2 Hem = \$415.04

(Red = \$215.12 / 6-T)

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I. (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18013072/T1fb3	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 18-07-2018	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	WC 4544H	Veh. Inspected	S 1801CD
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	18/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	16/07/2018	Inspection Date	
Survey held at	TC AUTOCLINIC PTE LTD 25 LENG KEE RD SINGAPORE 159097		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 140/IC/TCAC/CCR/2018
DATE : 16-JUL-2018

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : M/S HIGH COMMISSION OF CANADA
ADDRESS : ONE GEORGE STREET
#11-01
S(049145)
TELEPHONE NO : 96541934(MR RAZAK)

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : GA315713/1
VEHICLE NO : S1801CD
MODEL CODE : BDRAREZL33EYA---D-
MODEL/YEAR : TEANA 2.0XL CVT
ENGINE NO : MR20034958R
CHASSIS NO : MNTBBAL3320001696
MILEAGE : 37925 KM
DATE IN : 16/07/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 16/07/2018

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Jiah 97495749
WP

18/7/18 @ 1220

Resurvey before paint
sur@lkkauto.com

6 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO S18D1CD

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 CONI	PERFORM VEHICLE ELECTRONIC SYSTEM DIAGNOSIS, INTERROGATION & REPROGRAM MODULE WITH CONSULT	240.00	✓
2 FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	3/✓
3 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	✓
4 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	X
5 WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	93.00	✓
6 WHI	CHECK & INSPECT WIRE HARNESS FOR DAMAGE & OPEN/ SHORT CIRCUIT, REPAIR WHEN NECESSARY	240.00	X
7 ZZ/001	REPLACE FRONT BUMPER, FRONT RIGHT FENDER, WING MIRROR, HEADLAMP, FOG LAMP, BRACKETS, RETAINERS ETC	nn	
8 ZZ/002	REPAIR PANELS 250	1000.00	625
9 ZZ/003	REPLACE RIM & TYRE	30.00	✓
10 ZZ/004	RESPRAY FRONT BUMPER, RIGHT FENDER, WING MIRROR, SUPPORT PANELS ETC 200	1000.00	500.
11 ZZ/005	QC, RETUNE & CONSULT CHECK	nn	
12 ZZ/006	WASH & VACUUM, POLISH & WAX, SHINE ALL TYRES	120.00	X
TOTAL LABOUR CHARGES		2991.00	

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO S1B01CD

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	215/55R17 MICHELIN PRIMACY 3ST	TYRE			270.00 <i>Ant 80% painted ✓</i>
2	RIM CAP	40343-2DR0A			32.90 <i>de -</i>
3	RIM	D0300-3TU2B			1397.30 <i>ant</i>
4	RIGHT WING MIRROR COVER	K6373-3RMOA	105.70	<i>Kp</i>	
5	RIGHT WING MIRROR	96301-3TU1A	394.00	<i>cut ✓</i>	
6	RIGHT PROTECTOR	63840-3TS0A	81.60	<i>ant ✓</i>	
7	FENDER STAY	F3180-3TUMA	55.40	<i>?</i>	
8	RIGHT FENDER BAFFLE PLATE	63130-3TS0A	80.00	<i>?</i>	
9	RIGHT FENDER	F3100-3TUMA	621.00	<i>bt ✓</i>	
10	BUMPER UPPER COVER	62078-3TS0A	168.00	<i>X un</i>	
11	LOWER CENTRE BUMPER RETAINER	62299-3TS0A	180.00	<i>?</i>	
12	RIGHT ENERGY ABSORBER	62092-3TS0A	50.40	<i>?</i>	
13	ENERGY ABSORBER	62090-3TS0A	265.10	<i>✓ un</i>	
14	TOP BUMPER LOWER RETAINER	62240-3TS0B	84.00	<i>?</i>	
15	TOP BUMPER LOWER RETAINER	62242-3TS0A	42.00	<i>?</i>	
16	TOP BUMPER RETAINER	62240-3TS0A	252.00	<i>?</i>	
17	TOP RIGHT BUMPER RETAINER	62244-3TS0A	42.00	<i>?</i>	
18	RIGHT BUMPER BRACKET	62226-3TS0A	20.90	<i>?</i>	
19	RIGHT BUPER BRACKET	62220-3TS0A	20.90	<i>?</i>	
20	RIGHT BUMPER STIFFENER	62058-3TS0A	60.00	<i>?</i>	
21	FOG LAMP COVER	62256-3TU0B	69.50	<i>X un</i>	
22	TOW HOOK COVER	622A0-3TS0H	19.30	<i>X un</i>	
23	FRONT BUMPER	62022-3TD6H	830.30	<i>de ✓</i>	
24	RIGHT FOG LAMP	26150-8994A			321.60 <i>?</i>
25	RIGHT HEADLAMP	26010-3TD3A	419.20	<i>?</i>	

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO S1801CD

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
SUB TOTAL			3861.30	0.00	2021.80	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			772.26	0.00	0.00	
GRAND TOTAL			3089.04	0.00	2021.80	
OVERALL TOTAL			5110.84			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO S1801CD

TOTAL LABOUR CHARGES	2991.00
TOTAL SPARE PARTS CHARGES	5110.84

GRAND TOTAL	8101.84 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.



Service Request Details

Claim
S8M00OVJ

Reference
None 

Loss Date
July 16, 2018

Request Date
July 18, 2018

Due Date
July 25, 2018

Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss
Third Party Vehicle Damage

Services
Pending verification - Direct Settlement



18/7/2018 @ 1057am
Shown veh in.
Taufikh.

Actions

Next Step
Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #
S1801CD

Make
TPVD NISSAN

Model

TEANA-2.0 CVT (A)

Service Address

...

Primary Contact/Insured

HSS ENVIRO PTE LTD
BLK 13 OLD AIRPORT ROAD, #01-57, 390013, Singapore
65471626
nicki@flexi-assure.com

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Additional Instructions
NON REPORTED

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message