

51 UBLAVE 1, #02-25 PAYA UBLINDUSTRIAL PARK, SINGAPORE 408933 TEL; (065) 62563561 FAX; (065) 62564315

Immediate Advice

To: AXA Insurance Pte Ltd

Date: 15/08/2018

Survey Details:

Date of loss	16-Jul-18
Date of appointment	18-Jul-18
Date of survey	18-Jul-18
Location of survey	TC AUTOCLINIC PTE LTD

Vehicle Details:

Claim Type:	Third party	
Vehicle number	S 1801CD	
Make and Model	NISSAN TEANA 2.0L CVT	
Date of registration	11/2/201	
Excess		
Market Value	\$0	
Parf Rebate		
Nett Loss	\$0 \$0	

Repair details:

Initial Estimate	Ś	8.101.84

Proposed/Revised repair cost:

Total Lump Sum(if applicable)	\$ 6,210.76
Labour	\$ 1,608.00
Check items (estimate)	\$ 1,415.04
Parts	\$ 3,187.72

Number of days for repair	6



51 UBLAVE 1, #02-25 PAYA UBLINDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Remarks:

We have not authorized repairs.	
Estimate rentals =\$150.00 x 8 days = \$1,200.00	

Mandate:

Liability(TP)	100%	100%
	with check item	no check item
Proposed repair cost(w/gst)	\$ 6,645.50	\$ 5,131.40
Loss of use	\$ (4)	\$
Loss of rental (estimate)	\$ 1,200.00	\$ 1,200.00
Loss of income	\$ 1.50	\$ (*)
LTA search fees	\$ 7.49	\$ 7.49
Others	\$ -	\$
Proposed Total	\$ 7,852.99	\$ 6,338.89

English (default) -

LKK AUTO CONSULTANTS PTE LTD (TP) -



SERVICE REQUESTS

MESSAGES

CLAIMS



Re:PROCEED DS

Type

Question

Message

Please submit your report & inv



2.05	oort Remarks Entry - CC4/ASM18013072/T1gb3		
Re	emarks		
-	Add		
	Remarks 1	Ву	On
	S 1801CD; WC 4544H	LSP	18/7/2018 3:45:15 PM
	EST :\$8101.84 SUR : MTH WKSP ; TC AUTOCLINIC PTE LTD	LSP	20/7/2018 2:22:53 PM
	Claim S8M00OVJ	LSP	18/7/2018 3:45:32 PM
	Services Pending verification - Direct Settlement	LSP	18/7/2018 3:45:38 PM
	Additional Instructions NON REPORTED	LSP	18/7/2018 3:45:43 PM
	NO OI GIASENT LETTER TO OI***FILE PASS TO ACC	LSP	19/7/2018 10:13:28 AM
	FILE PASS TO POH KIN	LSP	19/7/2018 10:13:33 AM
	PENDING SUR ASSIGNMENT	LSP	19/7/2018 10:13:43 AM
	IA UPLOADED IN VIEWS	LSP	20/7/2018 2:34:40 PM
]	ESTIMATE & SURVEYOR ASSGNMENT PAPER PASS TO HANDLER	LSP	23/7/2018 10:20:11 AM
	3/8/18 11:09 AM LOH Cynthia PROCEED DSOl's AVF attached (1) Please obtain ID's D/L and check the validity of ID's D/L - refer to policy attached / All Claims Excess \$2000 is applicable for ID's d/exp less than 1 year	LSP	3/8/2018 3:54:55 PM
]	14/08/2018, spoke to Connie (PIC of HSS ENVIRO), confirmed accident details (BOLA 15), Informed her about TP claim and NCD issue. she agreed to settle and aware the NCD issue. requesting driver D/L from her. she request drop her e-mail. send letter to OI via e- mail.	CPK	14/8/2018 12:40:09 PM
]	KIV Driver driving license	CPK	14/8/2018 12:40:39 PM
	received driving license	CPK	14/8/2018 5:14:18 PM
	15/08/2018, IA and mandate uploaded, KIV approval	CPK	2/10/2018 10:33:42 AM
	10/3/18 2:47 PM LOH Cynthia- PROCEED DS- MANDATE APPROVED	LSP	3/10/2018 4:58:44

		PM
05/11/2018, taufikh spoke to TP repairer (shawn?), they convert to OD, KIV TP revert to us.	CPK	5/11/2018 3:49:19 PM
Pls submit W/P report	ттн	5/12/2018 2:46:02 PM
12/5/18 2:54 PM LOH Cynthia - Please submit your report & inv	LSP	5/12/2018 5:33:36 PM
FILE TRANSFER TO CECILIA FROM PK	CPK	6/8/2019 4:24:47 PM
to close WP report	СРК	6/8/2019 4:24:57 PM

Poh Kin (LKKAuto)

From:

Poh Kin (LKKAuto)

Sent:

Tuesday, 14 August 2018 11:18 AM

To:

'ADMIN@KKLE.COM.SG'

Cc:

Hsiao Tong (LKKAuto)

Subject:

ROAD TRAFFIC ACCIDENT INVOLVING WC 4544H AND S 1801CD ALONG JUNCTION

OF CECIL STREET AND MARINA BOULEVARD ON 16.07.2018

Importance:

High

HSS ENVIRO PTE LTD

13 Old Airport Road, #01-57, Singapore 390013.

Attn: Ms Connie

Dear Sirs.

OUR REF

: CC4/ASM18013072/T1fb3

YOUR REF : \

: WC 4544H

ROAD TRAFFIC ACCIDENT INVOLVING WC 4544H AND S 1801CD ALONG JUNCTION OF CECIL STREET AND MARINA BOULEVARD ON 16.07.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s TC Autoclinic Pte Ltd, acting on behalf of the owner of S 1801CD against your motor insurance policy.

Based on the video footage and accident report, accident scenario, it was show that your vehicle had encroached to third party lane and collided into the Third Party vehicle S 1801CD while crossing the junction. As such, liability is down against us.

Our principal, AXA shall keep you informed of when to make the excess payment, which cheque is to be made in favor of "AXA Insurance Pte Ltd". Please indicate your vehicle registration number and the date of accident on the back of the cheque.

As Insurers, AXA shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to AXA and acknowledged by AXA.

Your full co-operation in the handling of the claim is required and kindly submit the following to pohkin@lkkauto.com, if not provided at AXA's reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- · Driver's driving license or foreign driving license (if any)

- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- · Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep
 us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to AXA immediately. You may email it to cst@axa.com.sg or deliver it by hand to AXA's Customer Care Centre.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorized driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2132 or email us at pohkin@lkkauto.com. Please quote our claim reference when you contact us that we can assist you more effectively.

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

AXA	INSURANCE PT	ELTD	Ref : CC4/ASM1801:	3072/T1gb3s2		
AXA	HENTON WAY #24 A TOWERSINGAPO 'N: CYNTHIA LOH	ORE 068811	Date: 10-09-2019 Code: ASM			
1.	HAT HAVE SEE	Policy Particul	ars :- THIRD PARTY CLAI	M		
	Insured Veh.	WC 4544H	Veh. Inspected	S 1801CD		
	Policy No.	P1924060	Coverage (\$)	0.00		
- 1	Claim No.	S8M00OVJ	Excess (\$)	0.00		
	Assign From	CYNTHIA LOH	Assign Date	18/07/2018		
2.		Vehicle Pa	articulars & Condition			
	Make & Model	NISSAN TEANA	c.c	1997		
	Engine No.	HIDDEN	Year of Reg.	2014		
	Chassis No.	MNTBBAL33Z0001696	Colour	BRONZE		
	Odometer	37925	Steering	IN ORDER		
	Brakes			SPORTS RIM		
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make	Balance		
	R/H Front Tyre	215/55 R17	MICHELIN	6 mm		
	L/H Front Tyre	215/55 R17	MICHELIN	6 mm		
	R/H Rear Tyre	215/55 R17	MICHELIN	6 mm		
	L/H Rear Tyre	215/55 R17	MICHELIN	6 mm		
4.		Descri	iption of Damages			
	THE VEHICLE SU	STAINED DAMAGES AT THE	FRONT O/S PORTION AND U	INDERCARRIAGE.		
5.			eral Information	KY TOUT BUT SHIP WAY		
	Accident Date	16/07/2018	Inspection Date	18/07/2018		
	Survey held at	TC AUTOCLINIC PTE LTD		Service and the service and th		
		25 LENG KEE RD SINGAPORE 159097				
5a.			Remarks			
	A)THE INSPECTION B)IN ACCORDANCE	ON WAS CONDUCTED ON A"\ CE TO YOUR INSTRUCTIONS	WITHOUT PREJUDICE" BASI , WE HAVE NOT AUTHORISE	S. ED REPAIRS.		
5b.			ate Days of Repair			
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	6 Working Days	1		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. S 1801CD

ty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	RIGHT WING MIRROR COVER (N) (CONSISTENT)	TO REPAIR SEE LABOUR	105.70	
1	RIGHT WING MIRROR (N) (CONSISTENT)	сит	394.00	394.00
1	RIGHT PROTECTOR (N) (CONSISTENT)	CUT	81.60	81.60
1	FENDER STAY (N) (CONSISTENT)	* CHECK	55.40	
1	RIGHT FENDER BAFFLE PLATE (N) (CONSISTENT)	* CHECK	80.00	
1	RIGHT FENDER (N) (CONSISTENT)	BENT	621.00	621.00
1	BUMPER UPPER COVER (N) (CONSISTENT) LOWER CENTRE BUMPER RETAINER (N) (CONSISTENT)	NOT NECESSARY * CHECK	168.00 180.00	19
1	RIGHT ENERGY ABSORBER (N) (CONSISTENT)	* CHECK	50.40	
1	ENERGY ABSORBER (N) (CONSISTENT)	NOT NECESSARY	265.10	
1	TOP BUMPER LOWER RETAINER (N) (CONSISTENT)	* CHECK	84.00	
1	TOP BUMPER LOWER RETAINER (N) (CONSISTENT)	* CHECK	42.00	
1	TOP BUMPER RETAINER (N) (CONSISTENT)	* CHECK	252.00	
1	TOP RIGHT BUMPER RETAINER (N) (CONSISTENT)	* CHECK	42.00	
1	RIGHT BUMPER BRACKET (N) (CONSISTENT)	* CHECK	20.90	
1	RIGHT BUMPER BRACKET (N) (CONSISTENT)	* CHECK	20.90	
1	RIGHT BUMPER STIFFENER (N) (CONSISTENT)	* CHECK	60.00	
1	FOG LAMP COVER (N) (CONSISTENT)	NOT NECESSARY	69.50	
1	TOW HOOK COVER (N) (CONSISTENT)	NOT NECESSARY	19.30	
1	FRONT BUMPER	DEFORMED	830.30	830.30
1	RIGHT HEADLAMP (N) (CONSISTENT)	* CHECK	419.20	
	LESS 20% DISCOUNT		-772.26	-385.38
			3,089.04	1,541.52
	SPECIAL NETT ITEMS			
	215/55R17 MICHELIN PRIMACY 3ST (80%) (SN) (CONSISTENT)	PUNCTURE	270.00	216.00
1	RIM CAP (SN) (CONSISTENT)	NECESSARY	32.90	32.90
1	RIM (SN) (CONSISTENT)	сит	1,397.30	1,397.30
1	RIGHT FOG LAMP (SN) (CONSISTENT)	* CHECK	321.60	2
			2,021.80	1,646.20

Report Ref No. CC4/ASM18013072/T1gb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR		1	377
	PERFORM VEHICLE ELECTRONIC SYSTEM DIAGNOSIS, INTERROGATION & REPROGRAM MODULE WITH CONSULT.		240.00	240.00
	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION.	* CHECK	48.00	
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.		120.00	120.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.	NOT NECESSARY	100.00	8-
	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGELS TO STANDARD SPECIFICATION - PASSENGER.		93.00	93.00
	CHECK & INSPECT WIRE HARNESS FOR DAMAGE & OPEN / SHORT CIRCUIT, REPAIR WHEN NECESSARY.	NOT NECESSARY	240.00	82
- 1	REPLACE FRONT BUMPER, FRONT RIGHT FENDER, WING MIRROR, HEADLAMP, FOG LAMP, BRACKETS, RETAINERS ETC. (NPA)	NOT NECESSARY	1 52	
	REPAIR PANELS. INCLUSIVE OF THE REPAIR OF RIGHT WING MIRROR COVER.		1,000.00	625.00
	REPLACE RIM & TYRE.		30.00	30.00
	RESPRAY FRONT BUMPER, RIGHT FENDER, WING MIRROR, SUPPORT PANELS ETC.		1,000.00	500.00
	QC, RETUNE & CONSULT CHECK. (NPA)	NOT NECESSARY	84	12
	WASH & VACUUM, POLISH & WAX, SHINE ALL TYRES.	NOT NECESSARY	120.00	-
			2,991.00	1,608.00
	GRAND TOTAL		8,101.84	4,795.72
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS \$\$1,415.04 NETT)			4,795.72

Report Ref No. CC4/ASM18013072/T1gb3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

HO LEONG CHUAN

Automotive Assessor

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.