

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 140/IC/TCAC/CCR/2018
DATE : 16-JUL-2018

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : M/S HIGH COMMISSION OF CANADA
ADDRESS : ONE GEORGE STREET
#11-01
S(049145)
TELEPHONE NO : 96541934(MR RAZAK)

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : GA315713/1
VEHICLE NO : S1801CD
MODEL CODE : BDRAREZL33EYA---D-
MODEL/YEAR : TEANA 2.0XL CVT
ENGINE NO : MR20034958R
CHASSIS NO : MNTBBAL33Z0001696
MILEAGE : 37925 KM
DATE IN : 16/07/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 16/07/2018

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO S1801CD

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	CONI	PERFORM VEHICLE ELECTRONIC SYSTEM DIAGNOSIS, INTERROGATION & REPROGRAM MODULE WITH CONSULT	240.00	
2	FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	
3	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	
4	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	
5	WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	93.00	
6	WHI	CHECK & INSPECT WIRE HARNESS FOR DAMAGE & OPEN/ SHORT CIRCUIT, REPAIR WHEN NECESSARY	240.00	
7	ZZ/001	REPLACE FRONT BUMPER,FRONT RIGHT FENDER,WING MIRROR,HEADLAMP,FOG LAMP,BRACKETS,RETAINERS ETC		
8	ZZ/002	REPAIR PANELS	1000.00	
9	ZZ/003	REPLACE RIM & TYRE	30.00	
10	ZZ/004	RESPRAY FRONT BUMPER,RIGHT FENDER,WING MIRROR, SUPPORT PANELS ETC	1000.00	
11	ZZ/005	QC, RETUNE & CONSULT CHECK		
12	ZZ/006	WASH & VACUUM, POLISH & WAX, SHINE ALL TYRES	120.00	
		TOTAL LABOUR CHARGES	2991.00	

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO S1801CD

			DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	215/55R17 MICHELIN PRIMACY 3ST	TYRE			270.00	
2	RIM CAP	40343-2DR0A			32.90	
3	RIM	D0300-3TU2B			1397.30	
4	RIGHT WING MIRROR COVER	K6373-3RMOA	105.70			
5	RIGHT WING MIRROR	96301-3TU1A	394.00			
6	RIGHT PROTECTOR	63840-3TS0A	81.60			
7	FENDER STAY	F3180-3TUMA	55.40			
8	RIGHT FENDER BAFFLE PLATE	63130-3TS0A	80.00			
9	RIGHT FENDER	F3100-3TUMA	621.00			
10	BUMPER UPPER COVER	62078-3TS0A	168.00			
11	LOWER CENTRE BUMPER RETAINER	62299-3TS0A	180.00			
12	RIGHT ENERGY ABSORBER	62092-3TS0A	50.40			
13	ENERGY ABSORBER	62090-3TS0A	265.10			
14	TOP BUMPER LOWER RETAINER	62240-3TS0B	84.00			
15	TOP BUMPER LOWER RETAINER	62242-3TS0A	42.00			
16	TOP BUMPER RETAINER	62240-3TS0A	252.00			
17	TOP RIGHT BUMPER RETAINER	62244-3TS0A	42.00			
18	RIGHT BUMPER BRACKET	62226-3TS0A	20.90			
19	RIGHT BUPER BRACKET	62220-3TS0A	20.90			
20	RIGHT BUMPER STIFFENER	62058-3TS0A	60.00			
21	FOG LAMP COVER	62256-3TU0B	69.50			
22	TOW HOOK COVER	622A0-3TS0H	19.30			
23	FRONT BUMPER	62022-3TD6H	830.30			
24	RIGHT FOG LAMP	26150-8994A			321.60	
25	RIGHT HEADLAMP	26010-3TD3A	419.20			

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO S1801CD

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO S1801CD

TOTAL LABOUR CHARGES	2991.00
TOTAL SPARE PARTS CHARGES	5110.84
GRAND TOTAL	8101.84 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.