rom (Person): Chin lee	Ying of AG	Dete/Time: 18/7/18/6 10:05am
o Inspect Vehicle No:	SKS 94854 N-51 Automotive Kaki BK Are 2 # 01-13	Insured: \$15 65097 Tel: 68420051
f Blk2	2 Kaki Bkf Ave 2 # 01-13	
Sum Insured,	Excess.	
Make of Veh:		D.O.A. 6 07 18
CA / REV / REP. / REV Date/Time 16:13amo	24 HRShup? 817/18_Person Contacted:Melod	H.O.D. Endorsement
Sks q.	ction (X) Estimate 4854-NAMSG17021519/r 5097-X	3 DOA:10/11/2017

(08/11/13), wef PCS ASS. REC. BY: V N. Q REF: AIG	64862
Nibw i	SIGNMENT
From: Date: 18 17 118 Estimated Cost:	Veh No: SKS9485 U Yr Regn: 15 Mgy 2e/5 Type: M.Cas/ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
on TP Ws / TP RES / OD RES / EVA / INV / MV To Inspect Vehicle No: SKS 9485 U at Workshop m/s N-51 tutomotive of 2 kerki Bk+ tvc 2 # 01-17 Insured: Policy No. Claims No. Sum Insured: Excess: (Client's Record) Make of Veh:	Truck / Trailer or Make:
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: days Res.: Yes or No	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Front R/Bal. R/Bal. R/Bal. R/Bal. B mm L/Bal. D.O.A. D.O.I. Rear D.O.I. R/Bal. D.D.D.D. R/Bal. D.D.D. R/
CA / REV / REP. / 24 HRS Vehicle: IN / OU Date: Person Contacted:	
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
24/3/18 Endring 219 R Regard	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
1) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to? 2) Add Fo	Transportation: ee: Site Insp (\$)S+RS,SI
2) Add Fi	ee. Site Insp (\$)s*Rs,si
Report Format :	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$: Weekend (\$
)	TOTAL

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying

assignments@lkkauto.com, Admin A To:

Cc: Fong, Andy-SY

Sent: 18/7/2018 10:05:28 AM

Attachments:

18072018094843.pdf 17072018160817-0001.pdf

17072018173038.pdf

Hi LKK,

Kindly assist to survey, vehicle in.

Thanks.

Best Regards Lee Ying, Chin

Claims | AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Singapore 079120 Tel +(65) 6419 1947 | Fax +(65) 6835 7416 Lee-Ying Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub 2 Kaki Bukit Ave 2, #01-17 Singapore 417921

Tel No.: +65 6744 0510 / 6842 0051 Fax No.: +65 6741 0510

Company Reg. No.: 200714616M GST Registration No.: 200714616M

Our Ref:

SKS 9485 U

Your ref:

SLS 6509 T

17 July 2018

AIG ASIA PACIFIC INSURANCE PTE. LTD.

BY EMAIL Aashweenjeetkaur.Mithoosingh@aig.com ONLY

NO: 78 SHENTON WAY #07-16 CHARTIS BUILDING SINGAPORE 079120

Attn: Motor Claims Department

Dear Sir/Madam.

NAME OF CLAIMANT: LEE LENG CHET

VEHICLE NUMBER: SKS 9485 U

YOUR INSURED VEHICLE NUMBER: SLS 6509 T

ACCIDENT ON 16 July 2018 ALONG WOODLANDS AVE 9 JUNCTION

WOODLANDS INDUSTRIAL PK E4 AT ABOUT 15:30 HOURS

We refer to your email/fax dated 17 July 2018 wherein there is no agreement to the appointment to the appointment of Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

TWINCAR AUTOMOTIVE PTE LTD

Kaki Bukit Autohub 2 Kaki Bukit Avenue 2 #01-17

Singapore 417921

Contact Person: 6842 0051 / 6744 0510 (Melody)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,

FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you! Appointed surveyor

(Name & Signature)

Date & Time of Inspection:

Twincar Automotive Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Inte	rnationale Des Experts En Autom	nobile			
AIG A	ASIA PACIFIC INS	SURANCE PTE LTD	Ref : CS3/AIG18013	073/Gz4d3			
CHA	HENTON WAY #08 RTIS BUILDING SAPORE 079120	3-16	Date: 18-07-2018				
1.		Policy Particul	ars :- (THIRD PARTY CLAI	IM)			
	Insured Veh.	SLS 6509T	Veh. Inspected	SKS 9485U			
-	Policy No.		Coverage (\$)	0.00			
	Claim No.		Excess (\$)	0.00			
	Assign From	CHIN LEE YING	Assign Date	18/07/2018			
2.	TE CHILDREN	Vehicle I	Particulars & Condition				
	Make & Model		c.c	0			
	Engine No.	HIDDEN	Year of Reg.				
Chassis No.			Colour				
Odometer -			Steering				
	Brakes		Modification				
	General						
3.	- Co. 25 - No. 11	Co	nditions of Tyres				
		Size	Make	Balance			
	R/H Front Tyre			mm			
	L/H Front Tyre			mm			
	R/H Rear Tyre			mm			
	L/H Rear Tyre			mm			
4.		Desc	cription of Damages				
5.			neral Information	18/07/2018			
	Accident Date	16/07/2018 N-51 AUTOMOTIVE PL	Inspection Date	10/07/2010			
	Survey held at	2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTO SINGAPORE 417921	HUB				
5a.			Remarks				
	B) THE REPAIR E	ON WAS CONDUCTED ON STIMATE WAS NOT PRESE VAS TOLD TO PREPARE TH EASE FIND DAMAGED VE	A "WITHOUT PREJUDICE" BA NTED AT THE TIME OF INSPE IE ESTIMATE. HICLE PHOTOGRAPHS.	ASIS. ECTION.			

MSME18092355 / SME Motor Pte Ltd - Kaki Bukit ENTRY DATE & TIME: 17/07/2018 16:05 SUBMITTED BY: Farida Wen

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/07/2018 16:05
Date Of Accident	16/07/2018 15:30
Exact Location Of Accident	WOODLANDS AVE 9 JUNCTION W'LANDS INDUSTRIAL PK E4.
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SKS9485U
Insured/Policyholder	
Name Of Registered Owner	LEE LENG CHET
NRIC No	S7866486Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97567481
Alternative Phone No	OFFICE-97567481
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HARIIER
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA352495/1
Cover Note Number	
Driver	
Name of Driver	LEE LENG CHET

Name of Driver LEE LENG CHET NRIC No S7866486Z Date Of Birth 12/01/1978 Occupation INDOOR Date Of Driving Pass 22/10/2001

16 YEARS AND 8 MONTHS Driving Experience

Gender MALE

Mobile Number (LOCAL) +65-97567481

Fax Number

Contact Number OFFICE-97567481

NOEMAIL EMail Address

Address

BLK 804 YISHUN RING ROAD #10-4317

Postcode

760804

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

ON 16/07/2018 AT 1530 HRS, I STOPPED AT THE JUNCTION OF WOODLANDS AVE 9 BY WOODLANDS INDUSTRIAL PAR E4 DUE TO RED LIGHT. SUDDENLY A VEHICLE SLS6509T FROM BEHIND COLLIDED ONTO THE REAR PORTION OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLS6509T

Vehicle Make/Model/Colour

VEH B

Details Of Properties

PRIVATE CAR

Vehicle Category Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Oriver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the ladgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling end/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (b) for complying with requirements under any regulations, laws or court orders.

Poscyholder's Signature Date & Time:

Driver's Signature (if driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature Mamor

NEIC/FIN No.:

Accident Sketch Plan Pg. 1

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Unorthands Are 9 by Woodlands Indistrict Perk Et due to red light suddenly, a vehicle (368 65097) from behind collected onto the rear portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time:

Oriver's Signature (If driver is not the policyhaider) Date & Time: Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6486Z
Zehicle Details	
/ehicle No.:	SKS9485U
/ehicle to be Exported:	No
ntended De-registration Date:	19 Jul 2018
/ehicle Make:	TOYOTA
/ehicle Model:	HARRIER PREMIUM 2.0 A
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	3ZRB443882
Chassis No.:	ZSU600024151
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$29,498.00
Original Registration Date:	15 May 2015
First Registration Date:	15 May 2015
ransfer Count:	1
Actual ARF Paid:	\$23,298.00
ntended PARF Rebate Details	在第一点,1945年第二章的第二人,1955年2月1日第四届大学
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 May 2025
PARF Rebate Amount:	\$17,473.00
ntended COE Rebate Details	
COE Expiry Date:	14 May 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$77,600.00
COE Rebate Amount:	\$52,909.00
Total Rebate Amount:	\$70,382.00

The information contained herein is correct as at 19 Jul 2018

ОК

Vehicle No: SKS 9485 U

NAC	-INC	Item	CON	AC	Ot
1137	993626	Rear Number Plate	1001	-	1
1138		Rear Number Plate Base		-	-
1139	993630	Rear Number Plate Garnish	-	-	
1140		Rear Number Plate Lamp	1	-	
1141	992958	Rear Bumper	DD	/	\vdash
1142	993085	Rear Bumper Upper	1	Ĺ	Г
1143	993017	Rear Bumper Lower			1
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover		_	-
1146	992341	Rear Bumper Clips	NEL	V	
1147	992976	Rear Bumper Bracket	1150	-	\vdash
1148	993068	Rear Bumper Side Retainer	-	-	1
1149	993045	Rear Bumper Reinforcement		-	-
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge	CUT	V	
1152	992999	Rear Bumper Damper	1		
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding	l mil		
1156	993044	Rear Bumper Reflector (Jouler)	BR	V	2
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DM	-	2
1160	993327	Rear End Panel	BUC	/	
1161	993339	Rear End Panel Top Garnish Rear End Panel Inner Trim	CUT	V	
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	20	7	_
1164	993853	Rear LH Taillamp Garnish	SK.	V.	_
1165	993859	Rear LH Taillamp Panel		-	
1166	995116	Rear RH Taillamp	BR	1	-
1167	993853	Rear RH Taillamp Garnish	D.C.	V	-
1168	993859	Rear RH Taillamp Panel		-	-
1169	993554	Rear Apron Panel		\dashv	
1170	992895	Bootlid		\dashv	-
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174		Bootlid Reflector			
1176	993222	Bootlid Lamp LH Bootlid Lamp RH			
1177	992099	Bootlid Lock			
	990377	Bootlid Rubber		1	_
1179		Bootlid Hinge	- 1	- 1	_
1180	-	Bootlid Spoiler	-	-	-
1181		Tailgate	1	0	
1182		Tailgata Emble	SCR	1	
	994643	Tailgate Outer Handle	NEC	1	-
1184	994640	Tailgate Moulding	-	-	-
1185	994545	Tailgate Garnish	-+	+	\dashv
1186	994648	Tailgate Reflector		-	-
1187	994549	Tailgate Lamp		+	\dashv
1188	994646	Tailgate Protector		+	\dashv
1189	994676	Tailgate Wiper Arm		1	\neg
1190	994677	Tailgate Wiper Blade		1	
1191	994679	Tailgate Wiper Nozzle		1	\dashv
1192	994555	Tailgate Wiper Motor		+	\dashv
1193	994602	Tailgate Glass	T	+	\neg
1194	994606	l'ailgate Glass Rubber		-	\dashv
1195	994604	Tailgate Glass Moulding		+	\dashv
1196	994607	Tailgate Glass Sealant		1	\dashv
1197	994629	Tailgate Lock	JUT -	1	\dashv
1198	994651	Tailgate Rubber	1	1	-
1199	994611	l'ailgate Hinge		+	\dashv
200	994594	Failgate Damper	-	1	\exists
201 9		Tailgate Inner Board			

			· ciritate rice · Q RO	77 60		-
-1	NAC	INC	Item	CON	AC	Ot
Ī	1202	00378/	Spare Tyre Board	_		ندا
ł	1202	. 273 / 04	Spare Tyre Board	-		
- 1	1203	994328	Spare Tyre Panel			18
1	1204	995065	Spare Tyre			
Ì	1205	994326	Spare Tyre Lock Screw	1		-
ł	1206	00270	Spare Tyre Cover	-		-
ł						
ı	1207	995323	Triangle Breakdown Sign	1	6.1	-
-[1208	990507	CD Changer Assy			
đ			Antenna	+	-	-
ŀ						-
1	1210	990534	Centre Exhaust Pipe Assy .			
١	1211	990532	Centre Exhaust Mounting			
ı	1212	993366	Rear Exhaust Pipe	-		_
ł	1012	993304	Rear Exhaust Fipe			_
ŀ	1213	993357	Rear Exhaust Chrome Pipe			
Į.	1214	993361	Rear Exhaust Mounting		218	
١	1215	993358	Rear Exhaust Heat Shield			
ı	1216	995223	Rear LH Chassis Member			
ı	1217	993165	Rear RH Chassis Member			_
ŀ					- 4	_
ŀ			Rear LH Fender			10000
1	1219	993449	Rear LH Fender Protector			
ſ	1220	993420	Rear LH Fender Inner Panel			
t				1		_
ŀ	1221	773431	Rear LH Fender Inner Trim			
1	1222	993415	Rear LH Fender Inner Garnish			
L	1223	993425	Rear LH Fender Inner Shield			
	1224	993621	Rear LH Mudflap			_
1	1225	993933	Rear LH Wheel Rim		-	
t	1226	994025	Rear LH Rim Cover		-	
H	1227	905066	Rear LH Tyre	-	-	
Н	1227	993003	Rear LH Tyre			
L			Rear RH Fender			
L	1229	993450	Rear RH Fender Protector			
Γ	1230	993420	Rear RH Fender Inner Panel		\neg	-
r	1231	003/31	Rear RH Fender Inner Trim	-	-	_
H	1022	773431	Rear KH Fender Inner Inm			_
L	1232	993415	Rear RH Fender Inner Garnish			
L	1233	993425	Rear RH Fender Inner Shield		\neg	-
Г	1234	993622	Rear RH Mudflap		\rightarrow	-
r	1235	003034	Rear RH Wheel Rim	-	-	
H	1226	004006	Real Kit Wheel Kim		_	
H	1230	994025	Rear RH Rim Cover			- 8
ŀ	1237	995065	Rear RH Tyre			
L	1238	995162	Rear Fender Extension Panel LH		\neg	
1	1239	993401	Rear Fender Extension Panel RH	-	\neg	
Г	1240	993430	Rear Fender Inner Top Garnish		-	-
t	1241	993673	Rear Fender 1/4 Glass	-	-	-
H			Rear Fender 1/4 Glass		1	
L	1242	993452	Rear Fender 1/4 Glass Rubber	-13.00		
L	1243	993453	Rear Fender 1/4 Glass Sealant			
1	1244	993949	Rear Windscreen Glass			
	1245		Rear Windscreen Rubber	-		-
			New Windscreen Rubber			
H	1440	333961	Rear Windscreen Moulding			
	1247		Rear Windscreen Sealant			
	1248		Third Brake Light			
Г	1249	993385	Rear Fender Air Grille	- 5	+	\dashv
Г	1250	992167	Fuel Lid	-	1	\dashv
-	1251	002160	Fuel Neck		1	_
-	1255	774108	Fuel Neck			
			Fuel Tank		0	
			Fuel Tank Bracket		1	
			Fuel Tank Float		+	\dashv
35	10.60	990247	Sticker	-		\dashv
PE.	4,000	330247	SHEKEF			
L			N			1
1						
			matte	-	+	-
-	-		1 11			
-						
L						
1	CERTA		341712017			
		-		-	-	-
-				-	-	-
_	-					
				V.		
		=2,8				
						7
-	_				1	_

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj Subi	mitted	Ins Auth'ed	Status		
Main	19 Jul 2018 Edit Reg		18 Jul 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estima	tes	S\$0.00 View Rp			Pending for Surve Report Cancel Case		ey .
	Main	Re	ference		laim I	Details	\Box	Docume	nts	Sho	IIA wo
CLAIM SU	BFOLDER DI	ETAILS					[Create	ed by adjuster]			
Insured:	Oh Beng	Yong, ID: S1688	356E								
Main Claimant:	LEE LENG	CHET, ID: S78	56486Z								
Vehicle Reg No.:	^{29.} SKS9485U				Date	of Loss:		07/2018 00:00 - :59 Months and 1 Days From LTA Reg Date (M.			Yr)]
Claim Type:	Type: TP / 5624208761SG					y/Cover No.:	1700069335 (Comprehensive)				
Vehicle Reg No. (Insured):	SLS6509	т			- No 3 (3 (5 (5))	y No. mant):	E				
					Exce	55:					
Repairer:	N-51 Aut	omotive Pte Ltd	HQ) BLK 2 KAK	I BUKIT, #01	-17/18	KAKI BU	KIT AUTO	OHUB, 417921 Kal	ki Bukit - Tel	: 68420051	
Handling Insurer:		Pacific Insurance dNoor@aig.com	Pte. Ltd. (Exp	oress) - Tel:	65-641	9-3000	[Handle	ed by MdNoor, N	orsiah]		
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561.	[Han	dled by X	ING GU	O QIANG] [Fi	nal Rpt di	ue 27/07/	2018
ASSOCIAT	ED MAIL RE	CEIVED							View All	Compose C	ase Ma
AIG_SG	(19/07/2018)	Request To Uple	oad TP GIA Rep	port						-	
ALL ASSO	CIATED TAS	sks⊟					View A	All Search Tasks	Create Ne	w Task C	omple
Due Date	e Priority	Type Task	Group Subj	ect Hand	ler	Assign	ed By	Completed O		sted On	Don
No results							5)	55			

Claim Documents

*SKS9485U (5624208761SG)

[SLS6509T]

TP

LEE LENG CHET

Jul 16 2018 12:00AM

[Oh Beng Yong]

N-51 Automotive Pte Ltd

-	COLUMN TO THE PARTY OF THE PART	pad Photos Compose New Letter Upload Video Upload Audio	View View in Bro	wser ▼
	otos/Images		3 per page ▼	•
No 1	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnai	l Prin
2	19/07/18 11:56 19/07/18 11:56	General View General View	■ Load JPG	€
3		0.10.10.10.00.00.00.00.00.00.00.00.00.00	1 Load JPG	•
4	19/07/18 11:56 19/07/18 11:56	General View	1 Load JPG	•
5	Care of the contract of the co	General View	1 Load JPG	•
6	19/07/18 11:56	General View	1 Load JPG	•
7	19/07/18 11:56	General View	1 Load JPG	€
2	19/07/18 11:56	General View	1 Load JPG	•
8	19/07/18 11:56	General View	1 Load JPG	•
9	19/07/18 11:56	General View	6 Load JPG	•
10	19/07/18 11:56	General View	Load JPG	•
11	19/07/18 11:56	General View	1 Load JPG	✓
12	19/07/18 11:56	General View	● Load JPG	•
13	19/07/18 11:56	General View	1 Load JPG	•
14	19/07/18 11:56	General View	1 Load JPG	•
15	19/07/18 11:56	General View	Load JPG	•
16	19/07/18 11:56	General View	1 Load JPG	•
17	19/07/18 11:56	General View	1 Load JPG	•
18	24/07/18 17:55	Dismantled Parts	Load JPG	•
19	24/07/18 17:55	Dismantled Parts	Load JPG	•
20	24/07/18 17:55	Dismantled Parts	1 Load JPG	•
21	24/07/18 17:55	Dismantled Parts	1 Load JPG	•
22	24/07/18 17:55	Dismantled Parts	1 Load JPG	•
23	24/07/18 17:55	Dismantled Parts	Load JPG	•
24	24/07/18 17:55	Dismantled Parts	1 Load JPG	•
25	24/07/18 17:55	Dismantled Parts	1 Load JPG	•
26	24/07/18 17:55	Dismantled Parts	1 Load JPG	•
27	24/07/18 17:55	Dismantled Parts	1 Load JPG	•
8.	24/07/18 17:55	Dismantled Parts	1 Load JPG	V
9	24/07/18 17:55	Dismantled Parts	Load JPG	•
0	24/07/18 17:55	Dismantled Parts	1 Load JPG	•
1	24/07/18 17:55	Dismantled Parts	① Load JPG	•
2	24/07/18 17:55	Dismantled Parts	Load JPG	•
3	24/07/18 17:55	Dismantled Parts	Load JPG	•
4	24/07/18 17:55	Dismantled Parts	Load JPG	•
5	24/07/18 17:55	Dismantled Parts	€ Load JPG	•

Pho	otos/Images			•	•
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
36	24/07/18 17:55	Dismantled Parts	0	Load JPG	•
37	24/07/18 17:55	Dismantled Parts	0	Load JPG	•
38	24/07/18 17:55	Dismantled Parts	0	Load JPG	•
39	24/07/18 17:55	Dismantled Parts	0	Load JPG	•
40	24/07/18 17:55	Dismantled Parts	0	Load JPG	•
41	24/07/18 17:55	Dismantled Parts	0	Load JPG	•
42	24/07/18 17:55	Dismantled Parts	0	Load JPG	•
43	24/07/18 17:55	Dismantled Parts	0	Load JPG	•
44	24/07/18 17:55	Dismantled Parts	0	Load JPG	•
45	24/07/18 17:55	Dismantled Parts	0	Load JPG	•
46	24/07/18 17:55	Dismantled Parts	0	Load JPG	•
47	24/07/18 17:55	Dismantled Parts	0	Load JPG	•
48	24/07/18 17:55	Dismantled Parts	0	Load JPG	•
49	24/07/18 17:55	Dismantled Parts	0	Load JPG	•
50	24/07/18 17:55	Dismantled Parts	0	Load JPG	•
51	24/07/18 17:55	Dismantled Parts	0	Load JPG	•
52	24/07/18 17:55	Dismantled Parts	0	Load JPG	•
53	24/07/18 17:55	Dismantled Parts	0	Load JPG	•
54	24/07/18 17:55	Dismantled Parts	0	Load JPG	•
Doc	cumentation		1 per	page ▼	•
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	19/07/18 14:30	OI GIA REPORT	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/AIG18013073/GZ4D3S2

Date:

31/07/2018

REFERENCE

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1700069335

Claimant Vehicle No :

SKS9485U

Insured Vehicle No:

SLS6509T

Date of Loss:

16/07/2018

Nature of Claim:

TP

Claim No: 5624208761SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKS9485U

Make & Model:

TOYOTA HARRIER, 2.0 Premium (A) 15/05/2015 (Man. Year: 2014)

Engine No:

3ZRB443882

Reg. Date: Colour:

White

Chassis No: Odometer:

ZSU600024151 54240 km

Engine Capacity:

1986 cc

Market Value/New Car Price: Sum Insured (S\$):

N/A

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good Yes

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

235/55R18

Rear Tyre Size:

235/55R18

Front Left Side:

Michelin 6 mm

Rear Left Side: Rear Right Side:

Michelin 6 mm Michelin 6 mm

Front Right Side: Michelin 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:

18/07/2018

Date Inspected:

18/07/2018 Inspected At:

N-51 Automotive Pte Ltd (HQ)

BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB

Singapore 417921

Estimated Period of Repair:

6.0 days

XING GUO QIANG Adjuster:

Manager:

Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Re	cor	nm	en	de	d F	ar	te
110				UG	u		

	*REAR BUMPER *REAR BUMPER CLIPS *REAR BUMPER SPONGE *REAR BUMPER REFLECTOR (LOWER) *REVERSE SENSOR	Dented Necessary Cut Broken Damaged	0.00 F 0.00 F 0.00 F 0.00 F	*-F
	*REAR BUMPER SPONGE *REAR BUMPER REFLECTOR (LOWER)	Cut Broken	0.00 F	*-F *-F *-F
	*REAR BUMPER REFLECTOR (LOWER)	Broken		
			0.00 F	*-F
	*REVERSE SENSOR	Damaged		
		Damageu	0.00 F	*-F
	*REAR END PANEL	Buckled	0.00 F	*-F
	*REAR END PANEL TOP GARNISH	Cut	0.00 F	*-F
	*REAR LH TAILLAMP	Broken	0.00 F	*-F
	*REAR RH TAILLAMP	Broken	0.00 F	*- F
	*TAILGATE	Repair	0.00 F	*-F
	*TAILGATE EMBLEM	Necessary	0.00 F	*-F
	*TAILGATE LOCK	Cut	0.00 F	*-F
e part.				
		Total Parts (S\$)	0.00	0.00
•	e part.	*TAILGATE *TAILGATE EMBLEM *TAILGATE LOCK	*TAILGATE Repair *TAILGATE EMBLEM Necessary *TAILGATE LOCK Cut	*TAILGATE

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >