

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7824M**AAD1807-143***Not Notarised
L1 Pay @ 2850h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 7824M

KL1LA69RJB106904

CHEVROLET

EPICA 2.0

16.7.2018

AIG**PART****LIST**

1	1	Front Side View Mirror Assy RH	\$	<i>SL</i>	1,191.00	<i>X</i>
2	1	Rear Door RH (Panel A-RR DR LH)	\$	<i>Ad/way</i>	1,133.00	<i>✓</i>
3	1	Rear door weatherstrip - Inner	\$	<i>SL</i>	41.40	<i>X</i>
4	1	Rear door weatherstrip - 2nd Frame	\$	<i>SL</i>	25.90	
5	1	Rear door top hinge	\$	<i>N</i>	35.00	
6	1	Rear door bottom hinge	\$	<i>N</i>	35.00	
7	1	Rear door inner lock	\$	<i>N</i>	425.00	
8	1	Rear door check / arrestor	\$	<i>SL</i>	65.00	
9	1	Rear door lock striker / latch	\$	<i>N</i>	120.00	
10	1	Rear door outer weatherstrip moulding	\$	<i>SL</i>	85.00	
11	1	Side Rocker Panel Garnish RH	\$	<i>SL</i>	236.40	
12	1	Rear Fender RH	\$	<i>N</i>	1,145.00	
13	1	Rear Fender Inner Trim RH	\$	<i>SL</i>	418.44	<i>X</i>
14	1	Front Side Rocker Panel Garnish RH	\$	<i>SL</i>	236.40	
15	1	Front Side Rocker Panel Outer RH	\$	<i>N</i>	600.00	
16	1	Front Side Rocker Panel Inner RH	\$	<i>N</i>	519.30	
17	1	Rear Bumper	\$	<i>BL</i>	1,202.00	
18	1	Rear Bumper Beam	\$	<i>N</i>	239.94	
19	1	Rear Bumper Centre Absorber	\$	<i>SL</i>	260.00	
20	1	Rear Bumper Side Retainer RH	\$	<i>P.Y</i>	68.76	
21	1	Rear Bumper Side Retainer LH	\$	<i>SL</i>	68.76	
22	1	Rear Bumper Reflectors RH	\$	<i>SL</i>	119.74	
23	1	Rear Bumper Reflectors LH	\$	<i>SL</i>	119.74	
24	1	Rear Bumper Tow Hook Cover	\$	<i>SL</i>	93.00	
25	1	Rear End Panel Outer	\$	<i>N</i>	623.76	<i>X</i>
26	1	Rear End Panel Inner Trim	\$	<i>SL</i>	263.84	

Trans-cab Auto Services Pte Ltd

AAD1807-143

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7824M

TOTAL	\$	9,371.38
10%	\$	937.14
	\$	8,434.24

Special Nett

1 Set Front Bumper Fastener Clip	\$	24.00	✓
1 Set Front licence plate with holder	\$	192.00	X
1 Set Radiator Grille clip	\$	35.00	X
1 Set Front Fender Liner clip	\$	30.00	X
1 Front Fender RR Bracket RH	\$	7.10	X
1 Rear Wheel Rim Hub Cap RH	\$	166.30	X
1 Front right tyre	\$	220.00	X
1 Front Tyre Rim RH	\$	350.00	505m
1 Front door sticker 'Trans-cab'	\$	80.00	X
1Set Rear Fender Inner Trim Clip RH	\$	30.00	X
1 Rear door sticker '6555-3333'	\$	80.00	605m
TOTAL	\$	783.30	
TOTAL PARTS	\$	16,917.10	

LABOUR

To Check Electrical Lighting Concerned.	\$	170.00	201
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	5001
Putty and spray painting of the affected portion.	\$	4,000.00	6001
Towing Fees.	\$	120.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	X

Trans-cab Auto Services Pte Ltd**AAD1807-143**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7824M

To check steering geometry and computer wheel alignment	\$	220.00	601
To transfer of tire, rim and on wheel balancing.	\$	170.00	201
To rust-proofing of the affected areas.	\$	170.00	301
To check steering geometry and computer wheel alignment	\$	na 220.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	601
To transfer of fender fittings, attachment and perform water seepage test.	\$	170.00	601
TOTAL	\$	10,290.00	
Over All Total	\$	25,577.10	

Repair Days (Lump Sum)**15 days****3 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____