

ASS. REC. BY:

REF:

CS/EGI/18013078/Gsd3

n2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGI

Date/Time:

18/7/18 @ 11:08am

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 8573E

Insured:

E559D

at Workshop m/s:

Premier taxis

Tel:

6544 6682

of

23 Changi south Ave 2 #01-02

Policy No:

Claim No:

E559D/SA/p1

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17/07/2018

CA / REV / REP. / REV 24 HRS

cup

H.O.D. Endorsement:

Date/Time:

11:07am @ 18/7/18

Person Contacted:

Gany

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SHB8573E-X

E559D-NS/IN/14005551/K/gbd1

DOA: 23/3/2014

25/07/18 @ 17:41 p.m. revised PI to Pei Li via email.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: E5559/SL/pl

Date: 25 July 2018

Our Ref: CS/EGI18013078/Gsd3

The Motor Claims Department
ERGO INSURANCE PTE LTD

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SHB 8573E .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24/07/2018 at the premises of M/s Premier Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>4,799.20</u> .
Revised Estimate Amount	: S\$ <u>1,634.40</u> .
"Check" Items Amount	: S\$ <u> </u> .
Market Value	: S\$ <u> </u> .
LTA Reimbursement Value	: S\$ <u> </u> .
Nett Value	: S\$ <u> </u> .

Description of Damage:

The vehicle sustained damages at the n/s portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 4 Days

Yours faithfully,
Xing Guo Qiang
Automotive Assessor

Shirley Hiew (LKK Auto)

From: Goh Wee Dek <weedek.goh@premiertaxi.com>
Sent: Monday, 27 August 2018 11:21 AM
To: Shirley Hiew (LKK Auto); guoqiang@lkkauto.com
Cc: 'SUR'; Gary Shi
Subject: RE: SHB8573E- FINALIZE


Ok confirmed at \$1,634.40 4days.

Regards

Goh Wee Dek
Assistant Claims Manager
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 068 | DID: 6544 6682 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Monday, 27 August, 2018 10:37 AM
To: Goh Wee Dek; guoqiang@lkkauto.com
Cc: 'SUR'; Gary Shi
Subject: RE: SHB8573E- FINALIZE

Dear Wee Dek/Gary,

Please re-confirmed P/P \$ 1,634.40 @ 4 repair days.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Goh Wee Dek [mailto:weedek.goh@premiertaxi.com]
Sent: Thursday, 2 August 2018 2:20 PM
To: guoqiang@lkkauto.com
Cc: SUR <sur@lkkauto.com>; Gary Shi <gary.shi@premiertaxi.com>
Subject: SHB8573E- FINALIZE

Dear Quo Qiang

Please confirm PxP \$1,734.40 4days.

Regards

Goh Wee Dek
Assistant Claims Manager
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 068 | DID: 6544 6682 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.



Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 25 July 2018 5:41 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: "SUR"; 'Nivitha (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM
Subject: RE: E559D / TP : SHB8573E/LKK / DOA : 17/07/2018
Attachments: SHB 8573E - Preli Advise.pdf

Dear Pei Li,

Enclosed herewith preliminary advice of SHB 8573E.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 18 July 2018 1:56 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: "SUR" <sur@lkkauto.com>
Subject: RE: E559D / TP : SHB8573E/LKK / DOA : 17/07/2018

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Wednesday, 18 July 2018 11:08 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: 'ASSIGNMENTS@LKKAUTO.COM' <ASSIGNMENTS@LKKAUTO.COM>
Subject: OI : E559D / TP : SHB8573E/LKK / DOA : 17/07/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **PREMIER TAXIS PTE LTD.**

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Wednesday, 18 July 2018 11:08 AM
To: 'admin-d@lkkauto.com'
Cc: 'ASSIGNMENTS@LKKAUTO.COM'
Subject: OI : E559D / TP : SHB8573E/LKK / DOA : 17/07/2018
Attachments: SHB8573E - PRS NOTICE n SAS.pdf; SHB8573E - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **PREMIER TAXIS PTE LTD.**

ADDRESS : 23 CHANGI SOUTH AVE 2
#01-02
SINGAPORE 486443

PERSON TO CONTACT : GOH WEE DEK @ 6544 6682 / 6214 8880 EXT 68

ERGO OFFICER-IN-CHARGE : SITI

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached is TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 18.07.2018
Our Reference: E 559D/SA/pl
Your Reference: SHB 8573E

Sent via Fax ☐

or

Email ☐ weedek.goh@premiertaxi.com /
gary.shi@premiertaxi.com /
vincent.chua@premiertaxi.com

To: PREMIER AUTOMOTIVE SERVICES PTE LTD

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SHB 8573E
Insured's Vehicle: E 559D
Date Of Accident: 17.07.2018

We acknowledge receipt of your request for PRS on: 18.07.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input checked="" type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input checked="" type="checkbox"/>	Our Insured's driver has not reported the accident to us to date.
<input checked="" type="checkbox"/>	Others: <u>OFFICER-IN-CHARGE - SITI</u>

Prepared by:	<u>Pei Li</u>	6829 9194	claims@ergo.com.sg
Signature:	<u>[Signature]</u>		FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

Enquire Transaction History**Transaction History Details**

Log Date/Time:	28 Oct 2013 / 09:25:35	Receipt No.:	AACCK001-AX239-131028-000034
Asset Type:	Vehicle	Transaction Amount:	\$73,800.00
Asset ID:	SHB8573E	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20131028092535913411		
Vehicle No.:	SHB8573E		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	28 Oct 2013		
Original Registration Date:	28 Oct 2013		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414ME5447775		
Engine No.:	D4FDDH308097		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2013		
Open Market Value:	\$19,836.00		
Minimum PARF Benefit:	\$7,401.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	28 Oct 2013 09:25:35		
COE No.:	2013102801001065W		
COE Expiry Date:	27 Oct 2021		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$61,324.00		
Lifespan Expiry Date:	27 Oct 2021		
Owner ID Type:	Company		

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

17-Jul-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8573 E

1 pc	Wheel cover	Cut	\$	116.00
1 pc	Rear bumper	X	\$	696.00
1 pc	Front n/s door	X } repair.	\$	791.00
1 pc	Rear n/s door	X	\$	765.00
			\$	2,368.00
		Less 10%	\$	236.80
			\$	2,131.20

S/NETT

1 set	Rear n/s fender sticker	Smc	\$	60.00
1 pc	n/s door sticker	-	\$	100.00
1 set	Rear bumper clips	X NN	\$	48.00

Sundry	rec	\$	50.00	10
To check wheel alignment - Rear		\$	80.00	60
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00	X
To dismantle and refit the front n/s door inner component into new shell door		\$	150.00	X
To dismantle and refit the Rear n/s door inner component into new shell door		\$	150.00	X

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear n/s fender etc	\$	850.00	400
---	----	--------	-----

To putty and spray painting on Rear bumper, rear n/s fender, rear n/s door, front n/s door	\$	1000	900
To apply rustproofing on the repaired and replaced panels.	\$	200.00	X NN
	\$	4,799.20	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

40 hrs.
Part by part.
After repair photos.
Guo Qiang - 8288 0282
Guo Qiang@lkkauto.com

24/7/18

26/7/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EGI18013078/Gsd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 29-08-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	E 559D	Veh. Inspected	SHB 8573E	
Policy No.		Coverage (\$)	0.00	
Claim No.	E559D/SA/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	18/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	KNAGM414ME5447775	Colour	SILVER	
Odometer	467974	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	ACHILLES	6 mm	
L/H Front Tyre	205/65 R16	ACHILLES	6 mm	
R/H Rear Tyre	205/65 R16	ACHILLES	6 mm	
L/H Rear Tyre	205/65 R16	ACHILLES	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/07/2018	Inspection Date	24/07/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8573E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	WHEEL COVER	CUT	116.00	116.00
1	REAR BUMPER	TO REPAIR SEE LABOUR	696.00	-
1	FRONT N/S DOOR	TO REPAIR SEE LABOUR	791.00	-
1	REAR N/S DOOR	TO REPAIR SEE LABOUR	765.00	-
	LESS 10% DISCOUNT		-236.80	-11.60
			2,131.20	104.40
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR N/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	N/S DOOR STICKER (SN)	NECESSARY	100.00	100.00
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	SUNDRY (SN)	NECESSARY	50.00	10.00
			258.00	170.00
<u>LABOUR</u>				
	TO CHECK WHEEL ALIGNMENT-REAR.		80.00	60.00
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO DISMANTLE AND REFIT THE FRONT N/S DOOR INNER COMPONENT INTO NEW SHELL DOOR.	NOT NECESSARY	150.00	-
	TO DISMANTLE AND REFIT THE REAR N/S DOOR INNER COMPONENT INTO NEW SHELL DOOR.	NOT NECESSARY	150.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE REAR N/S FENDER ETC. INCLUSIVE OF THE REPAIR OF REAR BUMPER, FRONT N/S DOOR AND REAR N/S DOOR.		850.00	400.00
	TO PUTTY AND SPRAY PAINTING ON REAR BUMPER, REAR N/S FENDER, REAR N/S DOOR, FRONT N/S DOOR.		1,000.00	900.00

Report Ref No. CS/EG18013078/Gsd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	200.00	-
			2,610.00	1,360.00
GRAND TOTAL			4,999.20	1,634.40
RECOMMENDED COST OF REPAIRS				1,634.40

Report Ref No. CS/EGI18013078/Gsd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.