

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0019812
Zuraimi Bin Ali

Page 1 of 1
Your ref. TP-SLB 8258T EQ
Job No. 69652
Our ref. 18.07.17
Payment
Date 18/7/2018

Attn

Vehicle No SDX 6173X
Vehicle Model : Hyundai Elantra
Accident on ... 11/7/2018

*Not withanw
Resurvey B4 paint
2 days*

Quantity	Unit	Description	Unit price	Disc. pct	Amount
Supply of Parts:					
1.00	Pc	Front bumper	195.00		195.00 ✓
1.00	Pc	Front bumper side retainer RH	8.00		8.00 X
Total amount of parts supplied - S\$203.00					
1.00		15% of parts supplied:	30.45		30.45
Labour & Misc:					
1.00		To check wheel alignment	60.00		60.00 X
1.00		To remove and renew above parts	300.00		300.00 200
1.00		To spray paint	250.00		250.00 220

Sub-Total
GST 7.00%
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Date:

S\$ 902.49

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大概修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."