

ASS. REC. BY:

REF:

CS/CT118013084/R1td302

Special Instruction:

SULVEY

MEN

From (Person):

Rasu,

Jouny Tay

ASSIGNMENT (Office)

of CTI

Date/Time: 18/7/18 @ 10:20am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLQ 5760A

Insured:

at Workshop m/s:

Sng Ah Tee

Tel: 6268 6183

of

Blk 3 Pioneer Rd North #01-18

Policy No:

DMPCSN2054061700

Claim No:

SNM18D03499C01

Sum Insured:

Excess:

~~\$750.00~~

Make of Veh:

(Client's Record)

D.O.A. 13/07/2018

CA / (REV)

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:00pm @ 18/7/18

Person Contacted:

Samertha

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

SLQ 5760A - X

6/8-

Report via merimen, limit repair \$15k

6/8 @ 6/8pm

authorise repair by Susan Teo

7/8 @ 11:24am

inform Workshop Authorise repair not more than 15k

(08/11/13)

Surrey

REF:

21002

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 49c

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLA 5760 A Yr Regn: 2010 / JanType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MERCEDES Benz E250 c.c. 1796Colour: Black A/C: Insured / Std / NI / NASp. Reading: 172982 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2120472A098103Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/452R17R: 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or KIN FOREST

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 13/07/18 D.O.I. 18/07/18Survey held at SPR AH TEE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRT O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

refer to email: repair 1 unit 15K. repair confirmed

Lump Sum \$15,000 (Red: 15,623.53; 51%)

RECEIVED 28 JAN 2019

Date/Time, File Pass to?



Prel. Report

1) Typist

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 10Resurvey No. of Trip: 1Survey Fee: 200

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

S + RS \$ _____

Photos

Others

TOTAL

Report Format : ODLump Sum / I.B.I: (\$ 15,000)200

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jul 2018 Sendback Est	17 Jul 2018 15:23 \$530,623.53	18 Jul 2018 10:20 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	CHIN KHIN LOONG , ID: S7012100Z, Tel: +6597902227, Email: DANIELCHIN2227@GMAIL.COM		
Vehicle Reg. No.:	SLQ5760A	Date of Loss:	13/07/2018 07:00 - :59 [102 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM18D03499C01	Policy/Cover Note No.:	DMPCSN2054061700 (Comprehensive)
		Excess:	S\$0.00
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/07/2018]		
Driver/Custodian:	CHIN KHIN LOONG (48 / Male), NRIC: S7012100Z, Tel: +6597902227		
Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY & REVERT/CHECK ECONOMICAL FOR REPAIRS. EXCESS OF \$750.00 APPLIES IF CTL, ELSE WILL BE WAIVED (REPAIRABLE).		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18013084/R1td3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 18-07-2018		
		Code : CTI		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		SLQ 5760A	
Policy No.	DMPCSN2054061700	Coverage (\$)	0.00	
Claim No.	SNM18D03499C01	Excess (\$)	750.00	
Assign From	MERIMEN (JOWYN TAY)	Assign Date	18/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/07/2018	Inspection Date	18/07/2018	
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 7 August 2018 11:24 AM
To: 'Sharon Sng'; 'sam@sngahtee.com'; 'admin@sngahtee.com'; 'janice@sngahtee.com'
Cc: SUR
Subject: RE: SLQ5760A / OD / CHINA TAI PING

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLQ 5760A (Excess \$0.00/-)**. Please take note the repair limit is at lump sum **\$15,000/-** which ever lower.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)
Sent: Friday, 27 July 2018 10:29 AM
To: Sharon Sng <sharon@sngahtee.com>; sam@sngahtee.com; admin@sngahtee.com; janice@sngahtee.com
Subject: RE: SLQ5760A / OD / CHINA TAI PING

Dear All,

Any update?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 25 July 2018 2:14 PM
To: 'Sharon Sng' <sharon@sngahtee.com>; 'sam@sngahtee.com' <sam@sngahtee.com>; 'admin@sngahtee.com' <admin@sngahtee.com>; 'janice@sngahtee.com' <janice@sngahtee.com>
Subject: RE: SLQ5760A / OD / CHINA TAI PING

View Received Message

This mail is associated with :

SLQ5760A (SNM18D03499C01)

OD

Jul 13 2018 7:00AM

[CHIN KHIN LOONG]

Sng Ah Tee Motor & Panel Service Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 06/08/2018 18:41 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$15000.00) - SLQ5760A - Claim Handler: Jowyn Tay

Approved:15000.00.

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay

Date: 20 Jul 2018

Preliminary Advice

Vehicle No	: SLQ5760A	Accident Date	: 13/07/2018
Make	: MERCEDES-BENZ E250	Policy No.	: DMPCSN2054061700
Assignment Date	: 18/07/2018	Excess	: S\$0.00
Date of Inspection	: 18/07/2018	Est. Duration of Repair	: 10.00
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	30,623.53
Revised Amount	:S\$	16,562.73
Check Items (Estimated)	:S\$	13,763.20
Total	:S\$	30,325.93

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	46,000.00
COE / PARF Rebate	:S\$	33,132.00
Salvage Value	:S\$	
Margin for Repair	:S\$	12,868.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Pending repair cost from repairer

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/07/2018 11:35
Date Of Accident	13/07/2018 07:15
Exact Location Of Accident	UPP BT TIMAH RD & GOMBAK DRIVE JUNCTION
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ5760A
Insured/Policyholder	
Name Of Registered Owner	CHIN KHIN LOONG
NRIC No	S7012100Z
Email Address	DANIELCHIN2227@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97902227
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E250-1.8 CGI (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN2054061700
Cover Note Number	

Driver

Name of Driver	CHIN KHIN LOONG
NRIC No	S7012100Z
Date Of Birth	21/04/1970
Occupation	INDOOR
Date Of Driving Pass	17/08/1991
Driving Experience	26 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97902227
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	DANIELCHIN2227@GMAIL.COM

Address	606 CLEMENTI WEST ST 1 #14-55
Postcode	120606
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT PANJANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 42 FAJAR ROAD , POSTCODE: 679005 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8929999 - FAX NO: 67673650
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT NO: T/20180713/2055

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	TRAFFIC LIGHT
Vehicle Category	GOVERNMENT
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	RAILING
Vehicle Category	GOVERNMENT
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SGX5364H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM KOK CHUAN
NRIC/Passport Number	S7474045F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AS per police report No. 7/20180713/2055

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

- ☒ Claim own policy
- ☐ Claim third party
- ☐ Claim OD / TP at other works hop
- ☐ For record purpose

Policy No. _____ Veh.No. SLQ5760A
Insurer China

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



1/20180713/2055

1 of 3

Police Station Of Origin
Bukit Panjang N P C
1 Segar Road #01-05 SINGAPORE 677738
Tel No 1800-8929999

→ Report No T/20180713/2055

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 13/07/2018 12 53	Vide Report No J/20180713/0064	Station Diary No 48
---	-----------------------------------	------------------------

Informant's Particulars

Name of Informant CHIN KHIN LOONG			Address. APT BLK 606 CLEMENTI WEST STREET 1 #14-55 SINGAPORE 120606	
ID Type / ID No NRIC NO / S7012100Z			Contact No Home/Office	Mobile 97902227
Nationality SINGAPORE CITIZEN			Email	
Sex Male	Age 48	Date of Birth 21/04/1970	Type of Informant. Driver	
Race Chinese			Language	Institution / School Name
Occupation CONSTRUCTION MANAGER			Driving Licence Information; Class 3 Date of Expiry:	

General information of the Accident

General Information of the Accident				
Type of Accident:	Injury Government Property	Drink Drive: No	Date/Time of Accident: 13/07/2018 07.15	Type of Location: Straight Road
Location Along Road 1 UPPER BUKIT TIMAH ROAD				
Towards Towards Woodlands Road, Junction of Cashew rd and Gombak Dr				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision: Moving Vehicle Against - Road Divider/Kerb/Railings				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGX5364H	Car					0
SLQ5760A	Car	MERCEDES BENZ	E 250CGI	Black	Seriously Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLQ5760A	CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD	DMPCSN30640617 00	11/08/2017	11/01/2019

POLICE REPORT Pg. 2



**SINGAPORE
POLICE FORCE**



1/20180713/2055

2 of 3

Report No: T/20180713/2055

Police Station Of Origin
Bukit Panjang N P C
1 Segar Road #01-05 SINGAPORE 677738
Tel No 1800-8929999

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved No			
No. of Pedestrians Injured NIL		Use of Pedestrian Crossing NA	
Driver			
Name	LIM KOK CHUAN	ID No.	S7474045F
Related Vehicle	SGX5364H (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	CHIN KHIN LOONG	ID No.	S7012100Z
Related Vehicle	SLQ5760A (Car)	Contact No.	97902227
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

Brief Details.

On 13/07/2018 at about 0715hrs, I was driving my car (SLQ5760A, a black mercs) along Upper bukit timah rd towards Woodlands rd at lane 1 (extreme right). As I moved off from the traffic junction of Cashew Rd and Gombak Dr, I saw a car on my left blind spot was very near me, thus I counter steer to the right and it steer too much and hit on to the kerb and standing traffic light. Both of my car front Air bags were deployed. Due to the collision, the traffic light dropped onto a stationary car SGX5364H whom was waiting to make a U turn. That's all.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin
Bukit Panjang N P C
1 Segar Road #01-05 SINGAPORE 677738
Tel No 1600 6929999



1/2018/713/2055

7 of 3

➔ Report No 1/2018/713/2055

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: 117

J /
Sgt 2 CHIA WEI JIE

Signature :

Signature Of Interpreter:

Not applicable Singapore Police Force

Officer In Charge Of Case:

TP / AEIT /

➔ SSI 2 SITIMARSITA BINTE BOHARI

Contact No.: 65476219

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

13/07/2018 12:53

Classification Of Case:

Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company Cert No.: S7012100Z
 Owner ID Type: Singapore NRIC
 Owner Name: CHIN KHIN LOONG
 Registered Address: APT BLK 651 SENJA LINK #12-36 SINGAPORE 670651
 Mailing Address: -
 Birth Date: 21 Apr 1970

Vehicle Particulars

Vehicle No.: SLQ5760A
 Previous Vehicle No.: -
 Effective Date of Ownership: 15 Aug 2017
 Original Regn Date: 12 Jan 2010
 Registration Date: 12 Jan 2010
 Year of Manufacture: 2009
 Vehicle Type: Passenger Motor Car
 Vehicle Scheme: -
 Vehicle Attachment 1: No Attachment
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Make: MERCEDES BENZ
 Vehicle Model: E 250CGI
 Primary Colour: Black
 Secondary Colour: -
 Passenger Capacity: 4
 Chassis No.: WDD2120472A098103
 Engine No.: 27186030009149
 Engine Capacity/Power Rating: 1796 cc / -
 Maximum Power Output: 150.0 kW (201 bhp)
 Propellant: Petrol
 Max Unladen Weight: 1650 kg
 Maximum Laden Weight: 2185 kg
 Open Market Value: \$55,057.00
 PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 11 Jan 2020
 Minimum PARF Benefit: \$27,528.00
 No. of Transfers: 1
 IU Label No.: 1123604125
 COE No.: 2009100103000117M
 COE Expiry Date: 11 Jan 2020
 COE Category: B - Car (1601cc & above)
 COE Registration Category: B - Car (1601cc & above)
 Quota Premium (QP) / Prevailing Quota: \$19,289.00 / -

Rasul (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Thursday, 19 July, 2018 12:47 PM
To: 'Sharon Sng'
Subject: SLQ 5760A doa : 13/07/18

Hi Sharon,

Kindly take note repair limit for this case is 12K only

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner and Details	
Owner ID Type:	Singapore NRIC
Owner ID:	2100Z
Vehicle Details	
Vehicle No.:	SLQ5760A
Vehicle to be Exported:	No
Intended De-registration Date:	19 Jul 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 250CGI
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	27186030009149
Chassis No.:	WDD2120472A098103
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$55,057.00
Original Registration Date:	12 Jan 2010
First Registration Date:	12 Jan 2010
Transfer Count:	1
Actual ARF Paid:	\$55,057.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Jan 2020
PARF Rebate Amount:	\$30,281.00
Intended COE Rebate Details	
COE Expiry Date:	11 Jan 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$19,289.00
COE Rebate Amount:	\$2,851.00
Total Rebate Amount:	\$33,132.00

The information contained herein is correct as at 19 Jul 2018

OK

49,000
 33,132

 15,868
 (15K)

**SNG AH TEE MOTOR &
PANEL SERVICE PTE LTD
3 PIONEER ROAD NORTH
#01-18
SINGAPORE 628457**

Claim Reference:
Assessment Number: DS000513
Version: SNGAHTEE/1
Date Calculated: 17/07/2018 06:48

Full Report - V1
Registration: SLQ5760A
Printed: 17/07/2018 13:48

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	DARREN SNG	Date of Incident:	13/07/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMCPSN2054061700	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	E Class
Sub Model:	E 250 CGI
Model Sheet Number:	3AE 01
Registration:	SLQ5760A
Registration Month:	
Registration Year:	
VIN Number:	WDD2120472A098103
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM A076363/L001354	TECH CHANGES 09/09
HIGH BEAM ASSISTANT	MODEL 2010
PARKTRONIC	LOAD COMPARTMENT BOX
AUDIO 20 CD CHANGER	MULTIMEDIA INTERFACE
LIGHT PACKAGE	DAYTIME LIGHT
HEADLAMP WASHERS	LEATHER TRIM
SUN PROTECTION	EQUIPMENT AVANTGARDE
MEMORY PACKAGE	PEDESTRIAN PROTECT
DIPPING MIRROR	S-WDW ROLLER BLIND
WOOD TRIM ASH TREE	REM RELEASE FUEL CAP
KEYLESS GO	DOUBLE CUP HOLDER
ENGINE PROTECTION	RR SCREEN SUN BLIND
AIR INJECTION	AUTO GEARBOX 5 SPEED
DIRECT STEERING	DIRECT CONTROL SUSP
TYRES 245/45 VR 17	SPACE SAVER S-WHEEL
WHEELS 8J X 17 ALLOY	FUEL TANK 80 LTR
HD COOLING	BI-XENON HEADLAMPS
TWO COAT METALLIC	PREPARE OFF VEHICLE
CLEAR COAT HARD	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on
	Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	13/07/2018
Pre-Accident Damage:	

Tyres Condition:	
Tread Depth LHF:	Tread Depth RHF:

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000513

Version: SNGAHTTE/1

Date Calculated: 17/07/2018 06:48


Full Report - V1

Registration: SLQ5760A

Printed: 17/07/2018 13:48


Tread Depth LHR:

Damage Areas:



Tread Depth RHR:

Direction of Impact:



Addresses

Cost Summary

Total Labour	\$1,990.80
Total Paint/Material	\$301.53
Total Parts	\$26,626.20
Total of Additional Costs	\$1,705.00
Excess:	TBA
Grand Total Exc GST:	\$30,623.53
7 % GST:	\$2,143.65
Grand Total Inc GST:	\$32,767.18

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$0.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
54-1011 01	SHORT TEST INCLUDES: CONNECT + DISCONNECT STAR DIAGNOSIS, PRINT DATA, DELETE ERROR MEMORY	3.0	12.60
54-7989 03	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)	2.0	8.40
61-1086 02	R + R FRONT AND CENTRE ENGINE COMPARTMENT COVERING	3.0	12.60
88-2531 02	REPAIR OF R/FRONT-END DAMAGE INCLUDES: RENEW BUMPER, BONNET, RADIATOR COVER, FRONT WING AND FRONT LAMP UNIT, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	40.0	168.00
88-1348 02	ADDITIONAL FOR RENEW FRONT BUMPER (VEHICLE WITH PARK ASSISTENT)	2.0	8.40
82-4889 02	ADDITIONAL TO RENEW BOTH HEADLAMPS (VEHICLE WITH XENON HEADLAMP)	3.0	12.60
91-2132 01	R + R L/PEDESTRIAN PROTECTION SENSOR	2.0	8.40
91-2133 01	R + R R/PEDESTRIAN PROTECTION SENSOR	2.0	8.40
88-2647 02	R + R L/BONNET HINGE	4.0	16.80
88-2652 02	R + R R/BONNET HINGE	4.0	16.80
91-2125 01	R + R L/BONNET STAY	3.0	12.60
91-2126 01	R + R R/BONNET STAY	3.0	12.60

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000513

Version: SNGAHTEE/1

Date Calculated: 17/07/2018 06:48

Full Report - V1

Registration: SLQ5760A

Printed: 17/07/2018 13:48

60-1331 01	R + R ATTACHED PARTS OF THE ENGINE COMPARTMENT FOR RENEWAL OF THE FRONT MODULE INCLUDES: R + R ALL ATTACHED PARTS IN THE REPAIR SECTION	11.0	46.20
60-3600 01	DO ADD/WORK 1 (VEHICLE WITH HEADLAMP WASHER SYSTEM)	1.0	4.20
62-1269 01	R + R OR RENEW FRONT CROSSMEMBER AND R/TRUSSING BETWEEN WHEELHOUSES INCLUDES: R + R CENTRE TRUSSING, RENEW IF NECESSARY	12.0	50.40
67-1700 02	RENEW WINDSCREEN	32.0	134.40
67-1715 01	ADDITION TO RENEW WINDSCREEN (VEHICLE WITH MULTI FUNCTION CAMERA)	3.0	12.60
88-9950 02	R + R R/DRIP MOULDING	3.0	12.60
68-4605 01	R + R INSTRUMENT PANEL	28.0	117.60
68-4635 02	RENEW INSTRUMENT PANEL (REMOVED)	4.0	16.80
46-7681 01)	R + R INDICATOR SWITCH	1.0	4.20
68-3066 02	R + R SPARE WHEEL WELL COVER	2.0	8.40
68-1052 02	R + R RIGHT A-PILLAR LOWER TRIM	2.0	8.40
68-1092 02	R + R L/UPPER B-PILLAR TRIM	3.0	12.60
68-1092 02	R + R R/UPPER B-PILLAR TRIM	3.0	12.60
91-1520 01)	L/F SEAT BELT LOCK REMOVE + REFIT	3.0	12.60
91-1042 02)	R + R LEFT FRONT SEAT BELT	3.0	12.60
91-3512 01	R + R RIGHT FRONT SEAT	7.0	29.40
91-1516 01)	R/F SEAT BELT LOCK REMOVE + REFIT	3.0	12.60
91-1012 02)	R + R RIGHT FRONT SEAT BELT	3.0	12.60
91-1905 01)	R + R AIRBAG CONT UNIT AND PRETENS SYS	4.0	16.80
20-5410 01	R + R OVERFLOW TANK	6.0	25.20
NO NUMBER	R + R FRONT AIR GUIDE	3.0	12.60
33-1855 02	R + R FRONT AXLE CARRIER	41.0	172.20
33-1859 02)	RENEW FRONT AXLE SUPPORT (REMOVED)	5.0	21.00
33-3570 03)	R + R R/F STEERING KNUCKLE	20.0	84.00
33-1425 02)	DETACH + REFIT R/F TENSION ROD	2.0	8.40
33-1421 03)	R + R RIGHT FRONT TORSION BAR	9.0	37.80
32-1960 03)	R + R R/F STRUT	5.0	21.00
32-1914 02)	DISS/ASS R/F SUSPENSION STRUT	3.0	12.60
32-1920 02)	DIS + ASS FRONT SPRING STRUT/S (REMOVED)	3.0	12.60
46-3610 01)	RENEW POWER STEERING (REMOVED)	1.0	4.20
40-2410 01	R + R LEFT FRONT TYRE	3.0	12.60
40-2410 01	R + R RIGHT FRONT TYRE	3.0	12.60
40-2702 ZAX	ADDITION TO R + R L/F TYRE (TYRE CROSS-SECTION SMALLER THAN 55)	1.0	4.20
40-2702 ZAX	ADDITION TO R + R R/F TYRE (TYRE CROSS-SECTION SMALLER THAN 55)	1.0	4.20
40-2055 01	L/FRONT WHEEL BALANCE	2.0	8.40
40-2055 01	R/FRONT WHEEL BALANCE	2.0	8.40
40-6500 01	ALIGN VEHICLE INCLUDES: ALIGN FRONT AND REAR TOE AND CAMBER, CHECK FRONT AND REAR VEHICLE LEVEL	7.0	29.40
40-6710 01	ADD/WORK FOR VEHICLE WITH BOARDING-/	1.0	4.20

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000513

Version: SNGAHTTE/1

Date Calculated: 17/07/2018 06:48

Full Report - V1

Registration: SLQ5760A

Printed: 17/07/2018 13:48

1112	EXITING SUPPORT		
1156	REPAIR R/F WHEELHOUSE ASSY	10 15.0*	63.00
1000	REPAIR R/UPP W-HOUSE S-MEMB	20 30.0*	126.00
	CHECK WIRING	5 10.0*	42.00
LABOUR COST			
Total Work Units		372.0	
Panel / Mechanical Labour		36.4HRS	\$1,528.80
Visual Alignment Labour		0.8HRS	\$33.60
Corrosion Protection External Labour		0.0HRS	0.00
Corrosion Protection Internal Labour		0.0HRS	0.00
Sub Total		37.2HRS	\$1,562.40
Paint Labour		10.2HRS	\$428.40
Total Labour		47.4HRS	\$1,990.80

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$42.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
LE 0258	FRT NO PLATE REINF PAINTING STAGE I-M	3.0	
98-1731 01	FRONT BUMPER COVER PAINTING STAGE I-M	11.0	
98-1710 ZAX	L/F OUTER SENSOR PAINTING STAGE I-M	1.0	
98-1710 ZAX	R/F OUTER SENSOR PAINTING STAGE I-M	1.0	
98-1710 ZAX	L/F CTR PARKING SENS PAINTING STAGE I-M	1.0	
98-1710 ZAX	R/F CTR PARKING SENS PAINTING STAGE I-M	1.0	
98-1710 ZAX	L/F INNER SENSOR PAINTING STAGE I-M	1.0	
98-1710 ZAX	R/F INNER SENSOR PAINTING STAGE I-M	1.0	
98-2805 01	BONNET PAINTING STAGE I-M	26.0	
98-2615 01	R/F WING PAINTING STAGE I-M	6.0	
LE 0930	CTR FRT REINF PAINTING STAGE I-J	3.0	
LE 1001	FRT LWR CROSSMEMBER PAINTING STAGE I-J	1.0	
LE 2428	R/COVER MOULDING PAINTING STAGE I-M	3.0	
98-8980 ZAX	R/F WHEEL PAINT	4.0	
98-1710 ZAX	L/F OUT SPACER RING PAINTING STAGE II	1.0	
98-1710 ZAX	R/F OUT SPACER RING PAINTING STAGE II	1.0	
98-2416 01	L/F WING PAINTING STAGE II	5.0	
98-3095 01	R/F WHEELHOUSE ASSY PAINTING STAGE I-J	3.0	
98-4316 01	RIGHT FRONT DOOR PAINTING STAGE II	11.0	
98-1340 01	PREPARATION WORK FOR TWO COAT PAINTING OF FITTED BODY PARTS	15.0	
98-1356 01	ADD/WORK FOR PLASTIC PARTS	3.0	
LABOUR COST - PAINT			
TIME(PAINT)		0.0	
Total Work Units (10WU/HR)		102.0	
Total Paintwork Labour		10.2HRS	\$428.40
MATERIAL COST - PAINT			
Total Excluding Pearlescent Uplift			Cost Price
Pearlescent Uplift @ 0.0%			\$301.53
Total Paint Material Cost			\$0.00
			\$301.53

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Price Valid: 01/06/2015
					Bet. Price (\$)

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000513

Version: SNGAHTTE/1

Date Calculated: 17/07/2018 06:48

Full Report - V1

Registration: SLQ5560A

Printed: 17/07/2018 13:48

257	1	FRONT NUMBER PLATE	KNPL3	0%	0.00*
258	1	FRT NO PLATE REINF	212 817 0078	0%	92.00*
283	1	FRONT BUMPER COVER	212 880 1940 9999	0%	860.00*
285	1	L/F SPACER	212 889 1195	0%	20.00*
286	1	R/F SPACER	212 889 1295	0%	20.00*
303	1	L/F OUT BUMP GRILLE	212 885 1723	0%	22.00*
304	1	R/F OUT BUMP GRILLE	212 885 1823	0%	22.00*
305	1	FRONT BUMPER GRILLE	212 885 0523	0%	39.00*
340	1	FRT CTR BUMPER REINF	212 885 2765	0%	58.00*
347	1	L/F IMPACT DAMPER	212 885 0537	0%	29.00*
348	1	R/F IMPACT DAMPER	212 885 0637	0%	29.00*
349	1	FRT/CTR IMPACT DAMP	212 885 1837	0%	58.00*
361	1	L/F OUTER SENSOR	212 542 0118 9999	0%	140.00*
362	1	R/F OUTER SENSOR	212 542 0118 9999	0%	140.00*
363	1	L/F CTR PARKING SENS	212 542 0018 9999	0%	130.00*
364	1	R/F CTR PARKING SENS	212 542 0018 9999	0%	130.00*
365	1	L/F INNER SENSOR	212 542 0018 9999	0%	130.00*
366	1	R/F INNER SENSOR	212 542 0018 9999	0%	130.00*
377	1	FRT BUMPER W/HARNESS	212 540 7313	0%	130.00*
405	1	GRILLE	212 880 1083 9040	0%	570.00*
471	1	BONNET	212 880 0157	0%	1,150.00*
475	1	LEFT BONNET HINGE	204 880 0128	0%	80.00*
476	1	RIGHT BONNET HINGE	204 880 0228	0%	80.00*
477	1	L/BONNET ACTUATOR	212 906 6201	0%	195.00*
478	1	R/BONNET ACTUATOR	212 906 6301	0%	195.00*
481	1	INSULATION CTR COVER	212 682 0126	0%	137.00*
487	1	FRT CVR INSUL MNTG	USE SINGLE PARTS	0%	19.20*
489	1	L/F PEDEST PROT SENS	212 820 4926	0%	61.00*
490	1	R/F PEDEST PROT SENS	212 820 4926	0%	61.00*
493	1	RADIAT GRILLE MOUNTG	212 885 0136	0%	10.00*
494	1	BONNET CATCH	212 880 0064	0%	39.00*
503	1	L/UPPER LATCH	212 880 0060	0%	19.00*
504	1	R/UPPER LATCH	212 880 0060	0%	19.00*
507	1	L/SPRING ELEMENT	204 880 0127	0%	10.00*
508	1	R/SPRING ELEMENT	204 880 0127	0%	10.00*
515	1	L/LOWER LATCH	212 880 0160	0%	37.00*
516	1	R/LOWER LATCH	212 880 0160	0%	37.00*
561	1	LEFT HEADLAMP ASSY	212 820 0939	0%	1,500.00*
562	1	RIGHT HEADLAMP ASSY	212 820 1039	0%	1,500.00*
605	1	L/HEADLAMP WASH TRIM	212 860 0108 9999	0%	36.00*
606	1	R/HEADLAMP WASH TRIM	212 860 0208 9999	0%	36.00*
625	1	L/WASHER JET BRACKET	212 860 0147	0%	108.00*
626	1	R/WASHER JET BRACKET	212 860 0047	0%	108.00*
639	1	L/F DAYTIME RUN LAMP	212 820 0756	0%	290.00*
640	1	R/F DAYTIME RUN LAMP	212 820 0856	0%	290.00*
742	1	R/F WING	212 880 1218	0%	590.00*
784	1	R/F WING MOULDING	212 690 3462	0%	33.00*
786	1	R/F WING BADGE	204 817 7220	0%	20.00*
839	1	L/F W-HOUSE CVR FRT	212 690 4330	0%	103.00*
840	1	R/F W-HOUSE CVR FRT	212 690 0230	0%	103.00*
842	1	R/F W-HOUSE CVR REAR	212 690 6530	0%	94.00*
930	1	CTR FRT REINF	212 620 1100	0%	83.00*

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000513

Version: SNGAHTEE/1

Date Calculated: 17/07/2018 06:48

Full Report - V1

Registration: SLQ5760A

Printed: 17/07/2018 13:48

989	1	FRONT CTR RETAINER	212 898 0232	0%	23.00*
1001	1	FRT LWR CROSSMEMBER	212 620 1500	0%	270.00*
1033	1	FRONT BONNET SEAL	212 887 0098	0%	12.00*
1179	1	L/REINFORCEMENT	212 620 0185	0%	29.00*
1180	1	R/REINFORCEMENT	212 620 0285	0%	29.00*
1188	1	R/F UPP REINF	212 620 0291	0%	133.00*
1320	1	R/PARTITION SEAL	212 628 0098	0%	60.00*
1401	1	WINDSCREEN	212 670 3900 28	0%	0.00*
1411	1	WINDSCREEN REP KIT	000 670 0100	0%	0.00*
1413	4	FRT SCREEN SUPPORTS	210 671 0397	0%	0.00*
1445	1	WASHER JET HOSE	212 860 0992	0%	34.00*
2428	1	R/COVER MOULDING	212 690 0682 9999	0%	175.00*
4325	1	PASSENGER AIRBAG	212 860 3102	0%	980.00*
4331	1	INSTRUMENT PANEL	212 680 2687	0%	2,480.00*
			9G47		
4653	1	L/F SEAT BELT LOCK	212 860 1369 9051	0%	75.00*
4654	1	R/F SEAT BELT LOCK	212 860 1369 9051	0%	75.00*
4661	1	L/F SEAT BELT	212 860 0786	0%	800.00*
			9C94		
4662	1	R/F SEAT BELT	212 860 0886	0%	800.00*
			9C94		
7011	1	FRONT AXLE SUPPORT	212 628 1000	0%	1,156.00*
7048	1	R/F TENSION ROD	212 330 2811	0%	230.00*
7056	1	R/TENSION ROD RUBBER	212 333 0014	0%	50.00*
7072	1	R/F LWR CONTROL ARM	212 330 3011	0%	225.00*
7082	1	R/F STEERING KNUCKLE	212 332 0800	0%	600.00*
7088	1	R/F SHOCK ABSORBER	212 323 6800 64	0%	380.00*
7092	1	R/F STRUT BEARING	212 323 0020	0%	98.00*
7094	1	R/BRG COVER PANEL	172 323 0138	0%	27.00*
7132	1	R/F WHEEL HUB	212 330 0025	0%	410.00*
7202	1	R/F WHEEL	212 401 1000 9765	0%	550.00*
7227	1	L/F TYRE	245/45 R 17 .. V	0%	0.00*
7228	1	R/F TYRE	245/45 R 17 .. V	0%	0.00*
7261	1	FRONT STABILISER	212 323 0965	0%	230.00*
7264	1	R/F STABILISER ARM	212 320 1289	0%	48.00*
7300	1	STEERING GEAR	212 460 3800	0%	3,200.00*
7417	1	COMBI SWITCH MODULE	212 900 7702 9051	0%	520.00*
7445	1	DRIVER AIRBAG	212 860 0102 9116	0%	1,250.00*
7751	1	UPPER AIR GUIDE	212 500 0255	0%	65.00*
7753	1	AIR GUIDE	212 505 1430	0%	38.00*
7787	1	EXPANSION TANK	204 500 0749	0%	70.00*
8777	1	L/BRACKET	204 524 1340	0%	25.00*
8778	1	R/BRACKET	204 524 1440	0%	25.00*
8779	1	FRONT GRILLE PANEL	212 520 2323	0%	115.00*
8780	1	CTR TRIM	204 524 0101	0%	115.00*
9650	1	R/XENON LAMP CU	212 900 7804	0%	580.00*
9686	1	AIRBAG/TENS C-UNIT	212 901 4204	0%	490.00*
1000	1	BUMPER INN PAD X 2	Renew	0%	66.00*
1000	1	R/BONNET STOPPER	Renew	0%	6.00*
f: OEM Parts				Saving	
g: Original				Sub Total	
h: Secondhand				Mark Up From Cost (0 %)	
				\$603.31	
				\$26,526.20	
				\$0.00	

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000513

Version: SNGAHTTE/1

Date Calculated: 17/07/2018 06:48

Full Report - V1

Registration: SLQ5760A

Printed: 17/07/2018 13:48

p: Parallel
x: Exchange

Sundry Parts

(Fixed)

\$100.00

Total Parts

\$26,626.20

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description		Betterment	Price
FRONT NUMBER PLATE	SPECIALIST	0%	\$35.00 <i>350</i>
R/F TYRE	SPECIALIST		\$480.00 <i>480</i>
L/F TYRE	SPECIALIST	0%	\$480.00 <i>480</i>
R/F LAMP BULB(2PCS)	SPECIALIST		\$30.00 <i>300</i>
F/SCREEN GUM	SPECIALIST	0%	\$40.00 <i>40</i>
AIRCON GAS	SPECIALIST		\$50.00 <i>50</i>
COOLANT	SPECIALIST	0%	\$40.00 <i>40</i>
RESET FAULT CODE	SPECIALIST		\$250.00 <i>250</i>
RESET AIR BAG SYSTEM	SPECIALIST	0%	\$300.00 <i>300</i>

Total Extras

\$1,705.00

Final Calculation

Total Parts

\$26,626.20

Labour

Total Panel/Mechanical

Total Paintwork

Total Visual Alignment work

\$1,528.80 *1197*
\$428.40 *386.40*
\$33.60 *33.60*

Total Labour

\$1,990.80

Additional Costs

Corr Prot Materials External

Corr Prot Materials Internal

Cost of Specialist

Acknowledged by Repairer

Signature:

Date:

\$0.00

\$0.00

\$1,705.00

Total of Additional Costs

\$1,705.00

Total Paint/Material Costs

\$301.53 *301.53*

Grand Total Excludes GST

\$30,623.53

GST @ 7 %

\$2,143.65

Grand Total Includes GST

\$32,767.18

Assessment Notes

Summary Information

Vehicle

Manufacturer & Model:

MERCEDES E Class

VIN Number:

WDD2120472A098103

Build Date:

TBA

Software

Calculation Date:

17/07/2018

Software Version:

Valid Part Price Date:

01/06/2015

Registration:

SLQ5760A

Type:

3AE 01

AudaDirect Version:

337

Model Sheet Version:

Claim Reference:

Full Report - V1

Assessment Number: DS000513

Registration: SLQ5760A

Version: SNGAHTTE/1

Printed: 17/07/2018 13:48

Date Calculated: 17/07/2018 06:48

Model Specification

A4	FROM A076363/L001354
C1	TECH CHANGES 09/09
D5	HIGH BEAM ASSISTANT
E1	MODEL 2010
G7	PARKTRONIC
G9	LOAD COMPARTMENT BOX
H1	AUDIO 20 CD CHANGER
H9	MULTIMEDIA INTERFACE
I4	LIGHT PACKAGE
I5	DAYTIME LIGHT
I6	HEADLAMP WASHERS
J4	LEATHER TRIM
K4	SUN PROTECTION
K6	EQUIPMENT AVANTGARDE
L1	MEMORY PACKAGE
L2	PEDESTRIAN PROTECT
L3	DIPPING MIRROR
L8	S-WDW ROLLER BLIND
M9	WOOD TRIM ASH TREE
N5	REM RELEASE FUEL CAP
N7	KEYLESS GO
N9	DOUBLE CUP HOLDER
O1	ENGINE PROTECTION
O6	RR SCREEN SUN BLIND
P6	AIR INJECTION
P8	AUTO GEARBOX 5 SPEED
Q2	DIRECT STEERING
Q5	DIRECT CONTROL SUSP
R7	TYRES 245/45 VR 17
T2	SPACE SAVER S-WHEEL
T5	WHEELS 8J X 17 ALLOY
U7	FUEL TANK 80 LTR
U9	HD COOLING
W5	BI-XENON HEADLAMPS
Y4	TWO COAT METALLIC
Y7	PREPARE OFF VEHICLE
Z1	CLEAR COAT HARD

Guide Numbers**Invalid Guide Numbers**

LE	475	F :	New
LE	476	F :	New
LE	605	F :	New
LE	606	F :	New

***** THIS ASSESSMENT CONTAINS INVALID GUIDE NUMBERS - PLEASE CHECK *****

Eliminated Guide Numbers**Details**

N	283	LO	Labour Overlap	Repair
N	561	LO	Labour Overlap	Repair
N	562	LO	Labour Overlap	Repair
N	839	LO	Labour Overlap	Repair
N	840	LO	Labour Overlap	Repair

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000513

Version: SNGAHTTE/1

Date Calculated: 17/07/2018 06:48

Full Report - V1

Registration: SLQ5760A

Printed: 17/07/2018 13:48

N	4496	LO	Labour Overlap	Repair
N	4995	LO	Labour Overlap	Repair
N	9947	LO	Labour Overlap	Repair
V	9909	LO	Labour Overlap	Alignment
L	1156	EL	Eliminated	Surface

Generated Guide Numbers

Details

E 257	E 1411	E 1413	E 7227	RenewRenewRenewRenewRenewRenew --> Repair
E 7228	E 303	-> N 283		
E 303	-> E 1001	-> N 561		Renew --> Renew --> Repair
E 1001	-> E 1001	-> N 562		Renew --> Renew --> Repair
E 1001	-> E 625	-> N 839		Renew --> Renew --> Repair
E 625	-> E 626	-> N 840		Renew --> Renew --> Repair
E 626	-> E 4654	-> N 4496		Renew --> Renew --> Repair
E 4654	-> E 4653	-> N 4995		Renew --> Renew --> Repair
E 4653	-> E 7088	-> N 9947		Renew --> Renew --> Repair
E 7088	-> E 7011	-> V 9909		Renew --> Renew --> Alignment
E 7011	LE 1188			RenewNewPartPaint

Input Details

Positions Input: 133

Input Data Details

Repair Type	Guide Number	WU	Bet %	Price	Adj
E	257	0	0	\$0.00	
LE	283	0	0	\$0.00	
E	283	0	0	\$0.00	
E	349	0	0	\$0.00	
E	347	0	0	\$0.00	
E	348	0	0	\$0.00	
E	340	0	0	\$0.00	
E	405	0	0	\$0.00	
E	493	0	0	\$0.00	
E	305	0	0	\$0.00	
LE	361	0	0	\$0.00	
E	361	0	0	\$0.00	
LE	365	0	0	\$0.00	
E	365	0	0	\$0.00	
LE	362	0	0	\$0.00	
E	362	0	0	\$0.00	
LE	366	0	0	\$0.00	
E	366	0	0	\$0.00	
LE	363	0	0	\$0.00	
E	363	0	0	\$0.00	
LE	364	0	0	\$0.00	
E	364	0	0	\$0.00	
E	377	0	0	\$0.00	
E	639	0	0	\$0.00	
E	640	0	0	\$0.00	
E	303	0	0	\$0.00	
E	304	0	0	\$0.00	
E	8779	0	0	\$0.00	
E	8777	0	0	\$0.00	
E	8778	0	0	\$0.00	

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000513

Version: SNGAHTEE/1

Date Calculated: 17/07/2018 06:48

Full Report - V1

Registration: SLQ5760A

Printed: 17/07/2018 13:48

E	561	0	0	\$0.00
E	562	0	0	\$0.00
LE	1188	0	0	\$0.00
E	1188	0	0	\$0.00
L	1187	0	0	\$0.00
E	9650	0	0	\$0.00
LE	471	0	0	\$0.00
E	471	0	0	\$0.00
LE	475	0	0	\$0.00
E	475	0	0	\$0.00
LE	476	0	0	\$0.00
E	476	0	0	\$0.00
E	477	0	0	\$0.00
E	478	0	0	\$0.00
E	481	0	0	\$0.00
E	487	0	0	\$0.00
E	1033	0	0	\$0.00
E	494	0	0	\$0.00
E	507	0	0	\$0.00
E	508	0	0	\$0.00
E	626	0	0	\$0.00
LE	606	0	0	\$0.00
E	606	0	0	\$0.00
E	1445	0	0	\$0.00
E	625	0	0	\$0.00
LE	605	0	0	\$0.00
E	605	0	0	\$0.00
LE	258	0	0	\$0.00
E	258	0	0	\$0.00
E	515	0	0	\$0.00
E	516	0	0	\$0.00
E	503	0	0	\$0.00
E	504	0	0	\$0.00
LE	742	0	0	\$0.00
E	742	0	0	\$0.00
E	989	0	0	\$0.00
E	1179	0	0	\$0.00
E	1180	0	0	\$0.00
LE	1001	0	0	\$0.00
E	1001	0	0	\$0.00
E	285	0	0	\$0.00
E	286	0	0	\$0.00
E	1320	0	0	\$0.00
E	786	0	0	\$0.00
E	784	0	0	\$0.00
L	1156	0	0	\$0.00
I	1156	30	0	\$0.00
E	840	0	0	\$0.00
E	842	0	0	\$0.00
E	839	0	0	\$0.00
LE	930	0	0	\$0.00
E	930	0	0	\$0.00

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Claim Reference:

Assessment Number: DS000513

Version: SNGAHTEE/1

Date Calculated: 17/07/2018 06:48

Full Report - V1

Registration: SLQ5760A

Printed: 17/07/2018 13:48

E	7751	0	0	\$0.00
E	7753	0	0	\$0.00
E	7787	0	0	\$0.00
LE	7202	0	0	\$0.00
E	7202	0	0	\$0.00
E	7228	0	0	\$0.00
E	7088	0	0	\$0.00
E	7082	0	0	\$0.00
E	7092	0	0	\$0.00
E	7094	0	0	\$0.00
E	7132	0	0	\$0.00
E	7072	0	0	\$0.00
E	7048	0	0	\$0.00
E	7056	0	0	\$0.00
E	7264	0	0	\$0.00
E	7300	0	0	\$0.00
E	7011	0	0	\$0.00
E	7261	0	0	\$0.00
E	8780	0	0	\$0.00
E	7227	0	0	\$0.00
E	1401	0	0	\$0.00
E	4661	0	0	\$0.00
E	4662	0	0	\$0.00
E	4653	0	0	\$0.00
E	4654	0	0	\$0.00
E	4331	0	0	\$0.00
E	7445	0	0	\$0.00
E	4325	0	0	\$0.00
I	1112	15	0	\$0.00
L	741	0	0	\$0.00
L	1482	0	0	\$0.00
E	9686	0	0	\$0.00
L	355	0	0	\$0.00
L	356	0	0	\$0.00
E	489	0	0	\$0.00
E	490	0	0	\$0.00
E	2428	0	0	\$0.00
LE	2428	0	0	\$0.00
E	7417	0	0	\$0.00
S	1000	0	0	\$0.00
E	1000	0	0	\$0.00
E	1000	0	0	\$0.00
S	1000	0	0	\$0.00
S	1000	0	0	\$0.00
S	1000	0	0	\$0.00
S	1000	0	0	\$0.00
S	1000	0	0	\$0.00
P	1000	10	0	\$0.00
S	1000	0	0	\$0.00
S	1000	0	0	\$0.00
S	1000	0	0	\$0.00

Specialist FRONT NUMBER PLATE
 Renew BUMPER INN PAD x 2
 Renew R/BONNET STOPPER
 Specialist R/F TYRE
 Specialist L/F TYRE
 Specialist R/F LAMP BULB(2PCS)
 Specialist F/SCREEN GUM
 Specialist AIRCON GAS
 WIRING
 Specialist COOLANT
 Specialist RESET FAULT CODE
 Specialist RESET AIR BAG SYSTEM

**CHINA TAIPING
INSURANCE (S) PTE LTD
3 ANSON ROAD
#15-02 SPRINGLEAF
TOWER
079909**

Claim Reference:
Assessment Number: DS000513
Version: SNGAHTTE/2
Date Calculated: 19/07/2018 10:18

Full Report - V1
Registration: SLQ5760A
Printed: 19/07/2018 17:28

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Mr K.K Lau	Date of Incident:	13/07/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMCPSN2054061700	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	E Class
Sub Model:	E 250 CGI
Model Sheet Number:	3AE 01
Registration:	SLQ5760A
Registration Month:	
Registration Year:	
VIN Number:	WDD2120472A098103
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM A076363/L001354	TECH CHANGES 09/09
HIGH BEAM ASSISTANT	MODEL 2010
PARKTRONIC	LOAD COMPARTMENT BOX
AUDIO 20 CD CHANGER	MULTIMEDIA INTERFACE
LIGHT PACKAGE	DAYTIME LIGHT
HEADLAMP WASHERS	LEATHER TRIM
SUN PROTECTION	EQUIPMENT AVANTGARDE
MEMORY PACKAGE	PEDESTRIAN PROTECT
DIPPING MIRROR	S-WDW ROLLER BLIND
WOOD TRIM ASH TREE	REM RELEASE FUEL CAP
KEYLESS GO	DOUBLE CUP HOLDER
ENGINE PROTECTION	RR SCREEN SUN BLIND
AIR INJECTION	AUTO GEARBOX 5 SPEED
DIRECT STEERING	DIRECT CONTROL SUSP
TYRES 245/45 VR 17	SPACE SAVER S-WHEEL
WHEELS 8J X 17 ALLOY	FUEL TANK 80 LTR
HD COOLING	BI-XENON HEADLAMPS
TWO COAT METALLIC	PREPARE OFF VEHICLE
CLEAR COAT HARD	

Vehicle Condition


Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	13/07/2018
Pre-Accident Damage:	

CHINA TAIPING INSURANCE (S) PTE LTD**Claim Reference:****Assessment Number: DS000513****Version: SNGAHTTE/2****Date Calculated: 19/07/2018 10:18****Full Report - V1****Registration: SLQ5760A****Printed: 19/07/2018 17:28****Tyres Condition:**

Tread Depth LHF:


Tread Depth LHR:

Damage Areas:

Tread Depth RHF:

Tread Depth RHR:

Direction of Impact:

**Addresses****Cost Summary**

Total Labour	\$1,906.80
Total Paint/Material	\$301.53
Total Parts	\$26,626.20
Total of Additional Costs	\$1,705.00
Excess:	TBA
Grand Total Exc GST:	\$30,539.53
7 % GST:	\$2,137.77
Grand Total Inc GST:	\$32,677.30

Repair Information**LABOUR****Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR****Price/Dent = \$0.00/HR****Repair /**

Guide Number	Repair Details	WU	Cost Price (\$)
54-1011 01	SHORT TEST INCLUDES: CONNECT + DISCONNECT STAR DIAGNOSIS, PRINT DATA, DELETE ERROR MEMORY	3.0	12.60
54-7989 03	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)	2.0	8.40
61-1086 02	R + R FRONT AND CENTRE ENGINE COMPARTMENT COVERING	3.0	12.60
88-2531 02	REPAIR OF R/FRONT-END DAMAGE INCLUDES: RENEW BUMPER, BONNET, RADIATOR COVER, FRONT WING AND FRONT LAMP UNIT, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	40.0	168.00
88-1348 02	ADDITIONAL FOR RENEW FRONT BUMPER (VEHICLE WITH PARK ASSISTENT)	2.0	8.40
82-4889 02	ADDITIONAL TO RENEW BOTH HEADLAMPS (VEHICLE WITH XENON HEADLAMP)	3.0	12.60
91-2132 01	R + R L/PEDESTRIAN PROTECTION SENSOR	2.0	8.40
91-2133 01	R + R R/PEDESTRIAN PROTECTION SENSOR	2.0	8.40
88-2647 02	R + R L/BONNET HINGE	4.0	16.80
88-2652 02	R + R R/BONNET HINGE	4.0	16.80

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference:

Assessment Number: DS000513

Version: SNGAHTTE/2

Date Calculated: 19/07/2018 10:18

Full Report - V1

Registration: SLQ5760A

Printed: 19/07/2018 17:28

91-2125 01	R + R L/BONNET STAY	3.0	12.60
91-2126 01	R + R R/BONNET STAY	3.0	12.60
60-1331 01	R + R ATTACHED PARTS OF THE ENGINE COMPARTMENT FOR RENEWAL OF THE FRONT MODULE INCLUDES: R + R ALL ATTACHED PARTS IN THE REPAIR SECTION	11.0	46.20
60-3600 01	DO ADD/WORK 1 (VEHICLE WITH HEADLAMP WASHER SYSTEM)	1.0	4.20
62-1269 01	R + R OR RENEW FRONT CROSSMEMBER AND R/TRUSSING BETWEEN WHEELHOUSES INCLUDES: R + R CENTRE TRUSSING, RENEW IF NECESSARY	12.0	50.40
67-1700 02	RENEW WINDSCREEN	32.0	134.40
67-1715 01	ADDITION TO RENEW WINDSCREEN (VEHICLE WITH MULTI FUNCTION CAMERA)	3.0	12.60
88-9950 02	R + R R/DRIP MOULDING	3.0	12.60
68-4605 01	R + R INSTRUMENT PANEL	28.0	117.60
68-4635 02	RENEW INSTRUMENT PANEL (REMOVED)	4.0	16.80
46-7681 01)	R + R INDICATOR SWITCH	1.0	4.20
68-3066 02	R + R SPARE WHEEL WELL COVER	2.0	8.40
68-1052 02	R + R RIGHT A-PILLAR LOWER TRIM	2.0	8.40
68-1092 02	R + R L/UPPER B-PILLAR TRIM	3.0	12.60
68-1092 02	R + R R/UPPER B-PILLAR TRIM	3.0	12.60
91-1520 01)	L/F SEAT BELT LOCK REMOVE + REFIT	3.0	12.60
91-1042 02)	R + R LEFT FRONT SEAT BELT	3.0	12.60
91-3512 01	R + R RIGHT FRONT SEAT	7.0	29.40
91-1516 01)	R/F SEAT BELT LOCK REMOVE + REFIT	3.0	12.60
91-1012 02)	R + R RIGHT FRONT SEAT BELT	3.0	12.60
91-1905 01)	R + R AIRBAG CONT UNIT AND PRETENS SYS	4.0	16.80
20-5410 01	R + R OVERFLOW TANK	6.0	25.20
NO NUMBER	R + R FRONT AIR GUIDE	3.0	12.60
33-1855 02	R + R FRONT AXLE CARRIER	41.0	172.20
33-1859 02)	RENEW FRONT AXLE SUPPORT (REMOVED)	5.0	21.00
33-3570 03)	R + R R/F STEERING KNUCKLE	20.0	84.00
33-1425 02)	DETACH + REFIT R/F TENSION ROD	2.0	8.40
33-1421 03)	R + R RIGHT FRONT TORSION BAR	9.0	37.80
32-1960 03)	R + R R/F STRUT	5.0	21.00
32-1914 02)	DISS/ASS R/F SUSPENSION STRUT	3.0	12.60
32-1920 02)	DIS + ASS FRONT SPRING STRUT/S (REMOVED)	3.0	12.60
46-3610 01)	RENEW POWER STEERING (REMOVED)	1.0	4.20
40-2410 01	R + R LEFT FRONT TYRE	3.0	12.60
40-2410 01	R + R RIGHT FRONT TYRE	3.0	12.60
40-2702 ZAX	ADDITION TO R + R L/F TYRE (TYRE CROSS-SECTION SMALLER THAN 55)	1.0	4.20
40-2702 ZAX	ADDITION TO R + R R/F TYRE (TYRE CROSS-SECTION SMALLER THAN 55)	1.0	4.20
40-2055 01	L/FRONT WHEEL BALANCE	2.0	8.40
40-2055 01	R/FRONT WHEEL BALANCE	2.0	8.40
40-6500 01	ALIGN VEHICLE INCLUDES: ALIGN FRONT AND REAR TOE AND CAMBER,	7.0	29.40

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference:

Assessment Number: DS000513

Version: SNGAHTTE/2

Date Calculated: 19/07/2018 10:18

Full Report - V1

Registration: SLQ5760A

Printed: 19/07/2018 17:28

40-6710 01	CHECK FRONT AND REAR VEHICLE LEVEL		
	ADD/WORK FOR VEHICLE WITH BOARDING-/EXITING SUPPORT	1.0	4.20
1112	REPAIR R/F WHEELHOUSE ASSY	10.0*	42.00
1156	REPAIR R/UPP W-HOUSE S-MEMB	20.0*	84.00
1000	CHECK WIRING	5.0*	21.00
LABOUR COST			
	Total Work Units	352.0	
	Panel / Mechanical Labour	34.4HRS	\$1,444.80
	Visual Alignment Labour	0.8HRS	\$33.60
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	35.2HRS	\$1,478.40
	Paint Labour	10.2HRS	\$428.40
	Total Labour	45.4HRS	\$1,906.80

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$42.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
LE 0258	FRT NO PLATE REINF PAINTING STAGE I-M	3.0	
98-1731 01	FRONT BUMPER COVER PAINTING STAGE I-M	11.0	
98-1710 ZAX	L/F OUTER SENSOR PAINTING STAGE I-M	1.0	
98-1710 ZAX	R/F OUTER SENSOR PAINTING STAGE I-M	1.0	
98-1710 ZAX	L/F CTR PARKING SENSPAINING STAGE I-M	1.0	
98-1710 ZAX	R/F CTR PARKING SENSPAINING STAGE I-M	1.0	
98-1710 ZAX	L/F INNER SENSOR PAINTING STAGE I-M	1.0	
98-1710 ZAX	R/F INNER SENSOR PAINTING STAGE I-M	1.0	
98-2805 01	BONNET PAINTING STAGE I-M	26.0	
98-2615 01	R/F WING PAINTING STAGE I-M	6.0	
LE 0930	CTR FRT REINF PAINTING STAGE I-J	3.0	
LE 1001	FRT LWR CROSSMEMBER PAINTING STAGE I-J	1.0	
LE 2428	R/COVER MOULDING PAINTING STAGE I-M	3.0	
98-8980 ZAX	R/F WHEEL PAINT	4.0	
98-1710 ZAX	L/F OUT SPACER RING PAINTING STAGE II	1.0	
98-1710 ZAX	R/F OUT SPACER RING PAINTING STAGE II	1.0	
98-2416 01	L/F WING PAINTING STAGE II	5.0	
98-3095 01	R/F WHEELHOUSE ASSY PAINTING STAGE I-J	3.0	
98-4316 01	RIGHT FRONT DOOR PAINTING STAGE II	11.0	
98-1340 01	PREPARATION WORK FOR TWO COAT PAINTING OF FITTED BODY PARTS	15.0	
98-1356 01	ADD/WORK FOR PLASTIC PARTS	3.0	
LABOUR COST - PAINT			
	TIME(PAINT)	0.0	
	Total Work Units (10WU/HR)	102.0	
	Total Paintwork Labour	10.2HRS	\$428.40
MATERIAL COST - PAINT			
	Total Excluding Pearlescent Uplift		\$301.53
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$301.53

PARTS

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference:

Assessment Number: DS000513

Version: SNGAHTTE/2

Date Calculated: 19/07/2018 10:18

Full Report - V1

Registration: SLQ5760A

Printed: 19/07/2018 17:28

					Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
257	1	FRONT NUMBER PLATE	KNPL3		0%	0.00F
258	1	FRT NO PLATE REINF	212 817 0078		0%	92.00*
283	1	FRONT BUMPER COVER	212 880 1940 9999		0%	860.00*
285	1	L/F SPACER	212 889 1195		0%	20.00*
286	1	R/F SPACER	212 889 1295		0%	20.00*
303	1	L/F OUT BUMP GRILLE	212 885 1723		0%	22.00*
304	1	R/F OUT BUMP GRILLE	212 885 1823		0%	22.00*
305	1	FRONT BUMPER GRILLE	212 885 0523		0%	39.00*
340	1	FRT CTR BUMPER REINF	212 885 2765		0%	58.00*
347	1	L/F IMPACT DAMPER	212 885 0537		0%	29.00*
348	1	R/F IMPACT DAMPER	212 885 0637		0%	29.00*
349	1	FRT/CTR IMPACT DAMP	212 885 1837		0%	58.00*
361	1	L/F OUTER SENSOR	212 542 0118 9999		0%	140.00*
362	1	R/F OUTER SENSOR	212 542 0118 9999		0%	140.00*
363	1	L/F CTR PARKING SENS	212 542 0018 9999		0%	130.00*
364	1	R/F CTR PARKING SENS	212 542 0018 9999		0%	130.00*
365	1	L/F INNER SENSOR	212 542 0018 9999		0%	130.00*
366	1	R/F INNER SENSOR	212 542 0018 9999		0%	130.00*
377	1	FRT BUMPER W/HARNESS	212 540 7313		0%	130.00*
405	1	GRILLE	212 880 1083 9040		0%	570.00*
471	1	BONNET	212 880 0157		0%	1,150.00*
475	1	LEFT BONNET HINGE	204 880 0128		0%	80.00*
476	1	RIGHT BONNET HINGE	204 880 0228		0%	80.00*
477	1	L/BONNET ACTUATOR	212 906 6201		0%	195.00*
478	1	R/BONNET ACTUATOR	212 906 6301		0%	195.00*
481	1	INSULATION CTR COVER	212 682 0126		0%	137.00*
487	1	FRT CVR INSUL MNTG	USE SINGLE PARTS		0%	19.20*
489	1	L/F PEDEST PROT SENS	212 820 4926		0%	61.00*
490	1	R/F PEDEST PROT SENS	212 820 4926		0%	61.00*
493	1	RADIAT GRILLE MOUNTG	212 885 0136		0%	10.00*
494	1	BONNET CATCH	212 880 0064		0%	39.00*
503	1	L/UPPER LATCH	212 880 0060		0%	19.00*
504	1	R/UPPER LATCH	212 880 0060		0%	19.00*
507	1	L/SPRING ELEMENT	204 880 0127		0%	10.00*
508	1	R/SPRING ELEMENT	204 880 0127		0%	10.00*
515	1	L/LOWER LATCH	212 880 0160		0%	37.00*
516	1	R/LOWER LATCH	212 880 0160		0%	37.00*
561	1	LEFT HEADLAMP ASSY	212 820 0939		0%	1,500.00*
562	1	RIGHT HEADLAMP ASSY	212 820 1039		0%	1,500.00*
605	1	L/HEADLAMP WASH TRIM	212 860 0108 9999		0%	36.00*
606	1	R/HEADLAMP WASH TRIM	212 860 0208 9999		0%	36.00*
625	1	L/WASHER JET BRACKET	212 860 0147		0%	108.00*
626	1	R/WASHER JET BRACKET	212 860 0047		0%	108.00*
639	1	L/F DAYTIME RUN LAMP	212 820 0756		0%	290.00*
640	1	R/F DAYTIME RUN LAMP	212 820 0856		0%	290.00*
742	1	R/F WING	212 880 1218		0%	590.00*
784	1	R/F WING MOULDING	212 690 3462		0%	33.00*
786	1	R/F WING BADGE	204 817 7220		0%	20.00*
839	1	L/F W-HOUSE CVR FRT	212 690 4330		0%	103.00*
840	1	R/F W-HOUSE CVR FRT	212 690 0230		0%	103.00*

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference:

Assessment Number: DS000513

Version: SNGAHTTE/2

Date Calculated: 19/07/2018 10:18

Full Report - V1

Registration: SLQ5760A

Printed: 19/07/2018 17:28

842	1	R/F W-HOUSE CVR REAR	212 690 6530	0%	94.00*
930	1	CTR FRT REINF	212 620 1100	0%	83.00*
989	1	FRONT CTR RETAINER	212 898 0232	0%	23.00*
1001	1	FRT LWR CROSSMEMBER	212 620 1500	0%	270.00*
1033	1	FRONT BONNET SEAL	212 887 0098	0%	12.00*
1179	1	L/REINFORCEMENT	212 620 0185	0%	29.00*
1180	1	R/REINFORCEMENT	212 620 0285	0%	29.00*
1188	1	R/F UPP REINF	212 620 0291	0%	133.00*
1320	1	R/PARTITION SEAL	212 628 0098	0%	60.00*
1401	1	WINDSCREEN	212 670 3900 28	0%	0.00*
1411	1	WINDSCREEN REP KIT	000 670 0100	0%	0.00F
1413	4	FRT SCREEN SUPPORTS	210 671 0397	0%	0.00F
1445	1	WASHER JET HOSE	212 860 0992	0%	34.00*
2428	1	R/COVER MOULDING	212 690 0682 9999	0%	175.00*
4325	1	PASSENGER AIRBAG	212 860 3102	0%	980.00*
4331	1	INSTRUMENT PANEL	212 680 2687	0%	2,480.00*
			9G47		
4653	1	L/F SEAT BELT LOCK	212 860 1369 9051	0%	75.00*
4654	1	R/F SEAT BELT LOCK	212 860 1369 9051	0%	75.00*
4661	1	L/F SEAT BELT	212 860 0786	0%	800.00*
			9C94		
4662	1	R/F SEAT BELT	212 860 0886	0%	800.00*
			9C94		
7011	1	FRONT AXLE SUPPORT	212 628 1000	0%	1,156.00*
7048	1	R/F TENSION ROD	212 330 2811	0%	230.00*
7056	1	R/TENSION ROD RUBBER	212 333 0014	0%	50.00*
7072	1	R/F LWR CONTROL ARM	212 330 3011	0%	225.00*
7082	1	R/F STEERING KNUCKLE	212 332 0800	0%	600.00*
7088	1	R/F SHOCK ABSORBER	212 323 6800 64	0%	380.00*
7092	1	R/F STRUT BEARING	212 323 0020	0%	98.00*
7094	1	R/BRG COVER PANEL	172 323 0138	0%	27.00*
7132	1	R/F WHEEL HUB	212 330 0025	0%	410.00*
7202	1	R/F WHEEL	212 401 1000 9765	0%	550.00*
7227	1	L/F TYRE	245/45 R 17 .. V	0%	0.00F
7228	1	R/F TYRE	245/45 R 17 .. V	0%	0.00F
7261	1	FRONT STABILISER	212 323 0965	0%	230.00*
7264	1	R/F STABILISER ARM	212 320 1289	0%	48.00*
7300	1	STEERING GEAR	212 460 3800	0%	3,200.00*
7417	1	COMBI SWITCH MODULE	212 900 7702 9051	0%	520.00*
7445	1	DRIVER AIRBAG	212 860 0102 9116	0%	1,250.00*
7751	1	UPPER AIR GUIDE	212 500 0255	0%	65.00*
7753	1	AIR GUIDE	212 505 1430	0%	38.00*
7787	1	EXPANSION TANK	204 500 0749	0%	70.00*
8777	1	L/BRACKET	204 524 1340	0%	25.00*
8778	1	R/BRACKET	204 524 1440	0%	25.00*
8779	1	FRONT GRILLE PANEL	212 520 2323	0%	115.00*
8780	1	CTR TRIM	204 524 0101	0%	115.00*
9650	1	R/XENON LAMP CU	212 900 7804	0%	580.00*
9686	1	AIRBAG/TENS C-UNIT	212 901 4204	0%	490.00*
1000	1	BUMPER INN PAD X 2	Renew	0%	66.00*
1000	1	R/BONNET STOPPER	Renew	0%	6.00*
f: OEM Parts			Saving		\$603.31

CHINA TAIPING INSURANCE (S) PTE LTD**Claim Reference:****Assessment Number: DS000513****Version: SNGAHTTE/2****Date Calculated: 19/07/2018 10:18****Full Report - V1****Registration: SLQ5760A****Printed: 19/07/2018 17:28**

2634670

g: Original	Sub Total		\$26,526.20
h: Secondhand	Mark Up From Cost	(0 %)	\$0.00
p: Parallel	Sundry Parts	(Fixed)	\$100.00
x: Exchange	Total Parts		\$26,626.20

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description		Betterment	Price
FRONT NUMBER	SPECIALIST	0%	\$35.00
PLATE			
R/F TYRE	SPECIALIST		\$480.00
L/F TYRE	SPECIALIST	0%	\$480.00
R/F LAMP	SPECIALIST		\$30.00
BULB(2PCS)			
F/SCREEN GUM	SPECIALIST	0%	\$40.00
AIRCON GAS	SPECIALIST		\$50.00
COOLANT	SPECIALIST	0%	\$40.00
RESET FAULT CODE	SPECIALIST		\$250.00
RESET AIR BAG	SPECIALIST	0%	\$300.00
SYSTEM			
Total Extras			\$1,705.00

Final Calculation

Total Parts		\$26,626.20
Labour		
Total Panel/Mechanical	\$1,444.80	
Total Paintwork	\$428.40	
Total Visual Alignment work	\$33.60	
Total Labour		\$1,906.80
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$1,705.00	
Total of Additional Costs		\$1,705.00
Total Paint/Material Costs		\$301.53
Grand Total Excludes GST		\$30,539.53
GST @ 7 %		\$2,137.77
Grand Total Includes GST		\$32,677.30

Assessment Notes**Summary Information**

Vehicle			
Manufacturer & Model:	MERCEDES E Class	Registration:	SLQ5760A
VIN Number:	WDD2120472A098103	Type:	3AE 01
Build Date:	TBA		
Software			
Calculation Date:	19/07/2018	AudaDirect Version:	337

CHINA TAIPING INSURANCE (S) PTE LTD**Claim Reference:****Assessment Number: DS000513****Version: SNGAHTTE/2****Date Calculated: 19/07/2018 10:18****Full Report - V1****Registration: SLQ5760A****Printed: 19/07/2018 17:28**

Software Version:

Valid Part Price Date: 01/06/2015

Model Sheet Version:

Model Specification

A4	FROM A076363/L001354
C1	TECH CHANGES 09/09
D5	HIGH BEAM ASSISTANT
E1	MODEL 2010
G7	PARKTRONIC
G9	LOAD COMPARTMENT BOX
H1	AUDIO 20 CD CHANGER
H9	MULTIMEDIA INTERFACE
I4	LIGHT PACKAGE
I5	DAYTIME LIGHT
I6	HEADLAMP WASHERS
J4	LEATHER TRIM
K4	SUN PROTECTION
K6	EQUIPMENT AVANTGARDE
L1	MEMORY PACKAGE
L2	PEDESTRIAN PROTECT
L3	DIPPING MIRROR
L8	S-WDW ROLLER BLIND
M9	WOOD TRIM ASH TREE
N5	REM RELEASE FUEL CAP
N7	KEYLESS GO
N9	DOUBLE CUP HOLDER
O1	ENGINE PROTECTION
O6	RR SCREEN SUN BLIND
P6	AIR INJECTION
P8	AUTO GEARBOX 5 SPEED
Q2	DIRECT STEERING
Q5	DIRECT CONTROL SUSP
R7	TYRES 245/45 VR 17
T2	SPACE SAVER S-WHEEL
T5	WHEELS 8J X 17 ALLOY
U7	FUEL TANK 80 LTR
U9	HD COOLING
W5	BI-XENON HEADLAMPS
Y4	TWO COAT METALLIC
Y7	PREPARE OFF VEHICLE
Z1	CLEAR COAT HARD

Guide Numbers**Invalid Guide Numbers**

LE	475	F :	New
LE	476	F :	New
LE	605	F :	New
LE	606	F :	New

******* THIS ASSESSMENT CONTAINS INVALID GUIDE NUMBERS - PLEASE CHECK *********Eliminated Guide Numbers**

			Details	
N	283	LO	Labour Overlap	Repair
N	561	LO	Labour Overlap	Repair
N	562	LO	Labour Overlap	Repair

**CHINA TAIPING
INSURANCE (S) PTE LTD
3 ANSON ROAD
#15-02 SPRINGLEAF
TOWER
079909**

Claim Reference:
Assessment Number: DS000513
Version: CHINATAI/2
Date Calculated: 25/01/2019 08:27

Full Report - V1
Registration: SLQ5760A
Printed: 25/01/2019 16:27

Summary Information

Claim			
Location:	Singapore (SG)	Currency:	SGD
Printed by:	Mr K.K Lau	Date of Incident:	13/07/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMCPSN2054061700	Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle		Model Specs	
Manufacturer:	MERCEDES	FROM A076363/L001354	TECH CHANGES 09/09
Model:	E Class	HIGH BEAM ASSISTANT	MODEL 2010
Sub Model:	E 250 CGI	PARKTRONIC	LOAD COMPARTMENT BOX
Model Sheet Number:	3AE 01	AUDIO 20 CD CHANGER	MULTIMEDIA INTERFACE
Registration:	SLQ5760A	LIGHT PACKAGE	DAYTIME LIGHT
Registration Month:		HEADLAMP WASHERS	LEATHER TRIM
Registration Year:		SUN PROTECTION	EQUIPMENT AVANTGARDE
VIN Number:	WDD2120472A098103	MEMORY PACKAGE	PEDESTRIAN PROTECT
Odometer:	Not Known	DIPPING MIRROR	S-WDW ROLLER BLIND
Colour:		WOOD TRIM ASH TREE	REM RELEASE FUEL CAP
Engine Number:		KEYLESS GO	DOUBLE CUP HOLDER
Fuel Level:	%	ENGINE PROTECTION	RR SCREEN SUN BLIND
		AIR INJECTION	AUTO GEARBOX 5 SPEED
		DIRECT STEERING	DIRECT CONTROL SUSP
		TYRES 245/45 VR 17	SPACE SAVER S-WHEEL
		WHEELS 8J X 17 ALLOY	FUEL TANK 80 LTR
		HD COOLING	BI-XENON HEADLAMPS
		TWO COAT METALLIC	PREPARE OFF VEHICLE
		CLEAR COAT HARD	

Vehicle Condition

Vehicle Status	
Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on Inspection:
	Date of Inspection: 13/07/2018
Brakes Pedal Travel:	
Place of Inspection:	
Pre-Accident Damage:	

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference:

Assessment Number: DS000513

Version: CHINATAI/2

Date Calculated: 25/01/2019 08:27

Full Report - V1

Registration: SLQ5760A

Printed: 25/01/2019 16:27

Tyres Condition:

Tread Depth LHF:



Tread Depth LHR:

Damage Areas:

Tread Depth RHF:

Tread Depth RHR:

Direction of Impact:



Addresses

Cost Summary

Total Labour	\$1,617.00
Total Paint/Material	\$274.08
Total Parts	\$18,429.00
Total of Additional Costs	\$1,705.00
Excess:	TBA
Grand Total Exc GST:	\$22,025.08
7 % GST:	\$1,541.76
Grand Total Inc GST:	\$23,566.84

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$0.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
54-1011 01	SHORT TEST INCLUDES: CONNECT + DISCONNECT STAR DIAGNOSIS, PRINT DATA, DELETE ERROR MEMORY	3.0	12.60
54-7989 03	R + R BATTERY EARTH CABLE (WHEN DISCONNECTING ELECTRIC PLUG AND SOCKET CONNECTIONS)	2.0	8.40
88-2531 02	REPAIR OF R/Front-End Damage INCLUDES: RENEW BUMPER, BONNET, RADIATOR COVER, FRONT WING AND FRONT LAMP UNIT, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	40.0	168.00
88-1348 02	ADDITIONAL FOR RENEW FRONT BUMPER (VEHICLE WITH PARK ASSISTENT)	2.0	8.40
82-4790 02)	RENEW L/F LAMP UNIT (BUMPER DETACHED)	4.0	16.80
82-4888 02	ADDITIONAL TO R + R BOTH HEADLAMPS (VEHICLE WITH XENON HEADLAMP)	2.0	8.40
60-1331 01	R + R ATTACHED PARTS OF THE ENGINE COMPARTMENT FOR RENEWAL OF THE FRONT MODULE INCLUDES: R + R ALL ATTACHED PARTS IN	11.0	46.20

CHINA TAIPING INSURANCE (S) PTE LTD

Full Report - V1

Claim Reference:

Assessment Number: DS000513

Registration: SLQ5760A

Version: CHINATAI/2

Printed: 25/01/2019 16:27

Date Calculated: 25/01/2019 08:27

60-3600 01	THE REPAIR SECTION	1.0	4.20
	DO ADD/WORK 1		
62-1269 01	(VEHICLE WITH HEADLAMP WASHER SYSTEM)	12.0	50.40
	R + R OR RENEW FRONT CROSSMEMBER AND		
	R/TRUSSING BETWEEN WHEELHOUSES		
	INCLUDES: R + R CENTRE TRUSSING, RENEW		
	IF NECESSARY	32.0	134.40
67-1700 02	RENEW WINDSCREEN	3.0	12.60
67-1715 01	ADDITION TO RENEW WINDSCREEN		
	(VEHICLE WITH MULTI FUNCTION CAMERA)	28.0	117.60
68-4605 01	R + R INSTRUMENT PANEL	4.0	16.80
68-4635 02	RENEW INSTRUMENT PANEL (REMOVED)	2.0	8.40
68-3066 02	R + R SPARE WHEEL WELL COVER	2.0	8.40
68-1052 02	R + R RIGHT A-PILLAR LOWER TRIM	3.0	12.60
68-1092 02	R + R L/UPPER B-PILLAR TRIM	3.0	12.60
68-1092 02	R + R R/UPPER B-PILLAR TRIM	3.0	12.60
91-1520 01)	L/F SEAT BELT LOCK REMOVE + REFIT	3.0	12.60
91-1042 02)	R + R LEFT FRONT SEAT BELT	7.0	29.40
91-3512 01	R + R RIGHT FRONT SEAT	3.0	12.60
91-1516 01)	R/F SEAT BELT LOCK REMOVE + REFIT	3.0	12.60
91-1012 02)	R + R RIGHT FRONT SEAT BELT	4.0	16.80
91-1905 01)	R + R AIRBAG CONT UNIT AND PRETENS SYS	6.0	25.20
20-5410 01	R + R OVERFLOW TANK	3.0	12.60
NO NUMBER	R + R FRONT AIR GUIDE	3.0	12.60
40-1580 01	R + R FRONT WHEEL	4.0	16.80
32-3332 02)	R + R R/F STABILIZER LINKAGE	20.0	84.00
33-3570 03)	R + R R/F STEERING KNUCKLE	3.0	12.60
33-3630 03)	R + R FRONT STEERING KNUCKLE ASS WORK	2.0	8.40
33-1425 02)	DETACH + REFIT R/F TENSION ROD	9.0	37.80
33-1421 03)	R + R RIGHT FRONT TORSION BAR	5.0	21.00
32-1960 03)	R + R R/F STRUT	3.0	12.60
32-1914 02)	DISS/ASS R/F SUSPENSION STRUT	3.0	12.60
32-1920 02)	DIS + ASS FRONT SPRING STRUT/S (REMOVED)	3.0	12.60
40-2410 01	R + R LEFT FRONT TYRE	3.0	12.60
40-2410 01	R + R RIGHT FRONT TYRE	1.0	4.20
40-2702 ZAX	ADDITION TO R + R L/F TYRE		
	(TYRE CROSS-SECTION SMALLER THAN 55)	1.0	4.20
40-2702 ZAX	ADDITION TO R + R R/F TYRE		
	(TYRE CROSS-SECTION SMALLER THAN 55)	2.0	8.40
40-2055 01	L/FRONT WHEEL BALANCE	2.0	8.40
40-2055 01	R/FRONT WHEEL BALANCE	7.0	29.40
40-6500 01	ALIGN VEHICLE		
	INCLUDES: ALIGN FRONT AND REAR TOE AND		
	CAMBER,		
	CHECK FRONT AND REAR VEHICLE LEVEL	1.0	4.20
40-6710 01	ADD/WORK FOR VEHICLE WITH BOARDING-/		
	EXITING SUPPORT	10.0*	42.00
1112	REPAIR R/F WHEELHOUSE ASSY	20.0*	84.00
1156	REPAIR R/UPP W-HOUSE S-MEMB	5.0*	21.00
1000	CHECK WIRING		
LABOUR COST		293.0	
Total Work Units			

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference:
Assessment Number: DS000513
Version: CHINATAI/2
Date Calculated: 25/01/2019 08:27

Full Report - V1
Registration: SLQ5760A
Printed: 25/01/2019 16:27

Panel / Mechanical Labour	28.5HRS	\$1,197.00
Visual Alignment Labour	0.8HRS	\$33.60
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	29.3HRS	\$1,230.60
Paint Labour	9.2HRS	\$386.40
Total Labour	38.5HRS	\$1,617.00

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$42.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
LE 0258	FRT NO PLATE REINF PAINTING STAGE I-M	3.0	
98-1731 01	FRONT BUMPER COVER PAINTING STAGE I-M	11.0	
98-1710 ZAX	L/F OUTER SENSOR PAINTING STAGE I-M	1.0	
98-1710 ZAX	R/F OUTER SENSOR PAINTING STAGE I-M	1.0	
98-1710 ZAX	R/F CTR PARKING SENS PAINTING STAGE I-M	1.0	
98-1710 ZAX	R/F INNER SENSOR PAINTING STAGE I-M	1.0	
98-2805 01	BONNET PAINTING STAGE I-M	26.0	
98-2615 01	R/F WING PAINTING STAGE I-M	6.0	
LE 1001	FRT LWR CROSSMEMBER PAINTING STAGE I-J	1.0	
LE 1188	R/F UPP REINF PAINTING STAGE I-J	3.0	
98-8980 ZAX	R/F WHEEL PAINT	4.0	
98-1710 ZAX	L/F OUT SPACER RING PAINTING STAGE II	1.0	
98-1710 ZAX	R/F OUT SPACER RING PAINTING STAGE II	1.0	
98-3095 01	R/F WHEELHOUSE ASSY PAINTING STAGE I-J	3.0	
98-4316 01	RIGHT FRONT DOOR PAINTING STAGE II	11.0	
98-1340 01	PREPARATION WORK FOR TWO COAT PAINTING OF FITTED BODY PARTS	15.0	
98-1356 01	ADD/WORK FOR PLASTIC PARTS	3.0	
LABOUR COST - PAINT			
TIME(PAINT)		0.0	
Total Work Units (10WU/HR)		92.0	
Total Paintwork Labour		9.2HRS	\$386.40
MATERIAL COST - PAINT			Cost Price
Total Excluding Pearlescent Uplift			\$274.08
Pearlescent Uplift @ 0.0%			\$0.00
Total Paint Material Cost			\$274.08

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Price (\$)
257	1	FRONT NUMBER PLATE	KNPL3		0.00F
258	1	FRT NO PLATE REINF	212 817 0078		92.00*
283	1	FRONT BUMPER COVER	212 880 1940 9999		860.00*
285	1	L/F SPACER	212 889 1195		20.00*
286	1	R/F SPACER	212 889 1295		20.00*
305	1	FRONT BUMPER GRILLE	212 885 0523		39.00*
340	1	FRT CTR BUMPER REINF	212 885 2765		58.00*
349	1	FRT/CTR IMPACT DAMP	212 885 1837		58.00*
361	1	L/F OUTER SENSOR	212 542 0118 9999		140.00*
362	1	R/F OUTER SENSOR	212 542 0118 9999		140.00*

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference:

Assessment Number: DS000513

Version: CHINATAI/2

Date Calculated: 25/01/2019 08:27

Full Report - V1

Registration: SLQ5760A

Printed: 25/01/2019 16:27

364	1	R/F CTR PARKING SENS	212 542 0018 9999	0%	130.00*
366	1	R/F INNER SENSOR	212 542 0018 9999	0%	130.00*
377	1	FRT BUMPER W/HARNESS	212 540 7313	0%	130.00*
405	1	GRILLE	212 880 1083 9040	0%	570.00*
471	1	BONNET	212 880 0157	0%	1,150.00*
503	1	L/UPPER LATCH	212 880 0060	0%	19.00*
504	1	R/UPPER LATCH	212 880 0060	0%	19.00*
561	1	LEFT HEADLAMP ASSY	212 820 0939	0%	1,500.00*
605	1	L/HEADLAMP WASH TRIM	212 860 0108 9999	0%	36.00*
626	1	R/WASHER JET BRACKET	212 860 0047	0%	108.00*
640	1	R/F DAYTIME RUN LAMP	212 820 0856	0%	290.00*
742	1	R/F WING	212 880 1218	0%	590.00*
784	1	R/F WING MOULDING	212 690 3462	0%	33.00*
786	1	R/F WING BADGE	204 817 7220	0%	20.00*
840	1	R/F W-HOUSE CVR FRT	212 690 0230	0%	103.00*
842	1	R/F W-HOUSE CVR REAR	212 690 6530	0%	94.00*
989	1	FRONT CTR RETAINER	212 898 0232	0%	23.00*
1001	1	FRT LWR CROSSMEMBER	212 620 1500	0%	270.00*
1033	1	FRONT BONNET SEAL	212 887 0098	0%	12.00*
1180	1	R/REINFORCEMENT	212 620 0285	0%	29.00*
1188	1	R/F UPP REINF	212 620 0291	0%	133.00*
1320	1	R/PARTITION SEAL	212 628 0098	0%	60.00*
1401	1	WINDSCREEN	212 670 3900 28	0%	1,250.00*
1411	1	WINDSCREEN REP KIT	000 670 0100	0%	0.00F
1413	4	FRT SCREEN SUPPORTS	210 671 0397	0%	0.00F
4325	1	PASSENGER AIRBAG	212 860 3102	0%	980.00*
4331	1	INSTRUMENT PANEL	212 680 2687	0%	2,480.00*
			9G47		
4653	1	L/F SEAT BELT LOCK	212 860 1369 9051	0%	75.00*
4654	1	R/F SEAT BELT LOCK	212 860 1369 9051	0%	75.00*
4661	1	L/F SEAT BELT	212 860 0786	0%	800.00*
			9C94		
4662	1	R/F SEAT BELT	212 860 0886	0%	800.00*
			9C94		
7048	1	R/F TENSION ROD	212 330 2811	0%	230.00*
7056	1	R/TENSION ROD RUBBER	212 333 0014	0%	50.00*
7072	1	R/F LWR CONTROL ARM	212 330 3011	0%	225.00*
7082	1	R/F STEERING KNUCKLE	212 332 0800	0%	600.00*
7088	1	R/F SHOCK ABSORBER	212 323 6800 64	0%	380.00*
7132	1	R/F WHEEL HUB	212 330 0025	0%	410.00*
7202	1	R/F WHEEL	212 401 1000 9765	0%	550.00*
7227	1	L/F TYRE	245/45 R 17 .. V	0%	0.00F
7228	1	R/F TYRE	245/45 R 17 .. V	0%	0.00F
7264	1	R/F STABILISER ARM	212 320 1289	0%	48.00*
7445	1	DRIVER AIRBAG	212 860 0102 9116	0%	1,250.00*
7753	1	AIR GUIDE	212 505 1430	0%	38.00*
7787	1	EXPANSION TANK	204 500 0749	0%	70.00*
9650	1	R/XENON LAMP CU	212 900 7804	0%	580.00*
9686	1	AIRBAG/TENS C-UNIT	212 901 4204	0%	490.00*
1000	1	BUMPER INN PAD X 2	Renew	0%	66.00*
1000	1	R/BONNET STOPPER	Renew	0%	6.00*
f: OEM Parts					Saving
					\$603.31

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference:
Assessment Number: DS000513
Version: CHINATAI/2
Date Calculated: 25/01/2019 08:27

Full Report - V1
Registration: SLQ5760A
Printed: 25/01/2019 16:27

g: Original	Sub Total		\$18,329.00
h: Secondhand	Mark Up From Cost	(0 %)	\$0.00
p: Parallel	Sundry Parts	(Fixed)	\$100.00
x: Exchange	Total Parts		\$18,429.00

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description		Betterment	Price
FRONT NUMBER	SPECIALIST	0%	\$35.00
PLATE			
R/F TYRE	SPECIALIST		\$480.00
L/F TYRE	SPECIALIST	0%	\$480.00
R/F LAMP	SPECIALIST		\$30.00
BULB(2PCS)			
F/SCREEN GUM	SPECIALIST	0%	\$40.00
AIRCON GAS	SPECIALIST		\$50.00
COOLANT	SPECIALIST	0%	\$40.00
RESET FAULT CODE	SPECIALIST		\$250.00
RESET AIR BAG	SPECIALIST	0%	\$300.00
SYSTEM			
Total Extras			\$1,705.00

Final Calculation

Total Parts		\$18,429.00
Labour		
Total Panel/Mechanical	\$1,197.00	
Total Paintwork	\$386.40	
Total Visual Alignment work	\$33.60	
Total Labour		\$1,617.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$1,705.00	
Total of Additional Costs		\$1,705.00
Total Paint/Material Costs		\$274.08
Grand Total Excludes GST		\$22,025.08
GST @ 7 %		\$1,541.76
Grand Total Includes GST		\$23,566.84

Assessment Notes

Summary Information

Vehicle			
Manufacturer & Model:	MERCEDES E Class	Registration:	SLQ5760A
VIN Number:	WDD2120472A098103	Type:	3AE 01
Build Date:	TBA		
Software			
Calculation Date:	25/01/2019	AudaDirect Version:	337

CHINA TAIPING INSURANCE (S) PTE LTD**Claim Reference:****Assessment Number: DS000513****Version: CHINATAI/2****Date Calculated: 25/01/2019 08:27****Full Report - V1****Registration: SLQ5760A****Printed: 25/01/2019 16:27**

Software Version:

Valid Part Price Date: 01/06/2015

Model Sheet Version:

Model Specification

A4	FROM A076363/L001354
C1	TECH CHANGES 09/09
D5	HIGH BEAM ASSISTANT
E1	MODEL 2010
G7	PARKTRONIC
G9	LOAD COMPARTMENT BOX
H1	AUDIO 20 CD CHANGER
H9	MULTIMEDIA INTERFACE
I4	LIGHT PACKAGE
I5	DAYTIME LIGHT
I6	HEADLAMP WASHERS
J4	LEATHER TRIM
K4	SUN PROTECTION
K6	EQUIPMENT AVANTGARDE
L1	MEMORY PACKAGE
L2	PEDESTRIAN PROTECT
L3	DIPPING MIRROR
L8	S-WDW ROLLER BLIND
M9	WOOD TRIM ASH TREE
N5	REM RELEASE FUEL CAP
N7	KEYLESS GO
N9	DOUBLE CUP HOLDER
O1	ENGINE PROTECTION
O6	RR SCREEN SUN BLIND
P6	AIR INJECTION
P8	AUTO GEARBOX 5 SPEED
Q2	DIRECT STEERING
Q5	DIRECT CONTROL SUSP
R7	TYRES 245/45 VR 17
T2	SPACE SAVER S-WHEEL
T5	WHEELS 8J X 17 ALLOY
U7	FUEL TANK 80 LTR
U9	HD COOLING
W5	BI-XENON HEADLAMPS
Y4	TWO COAT METALLIC
Y7	PREPARE OFF VEHICLE
Z1	CLEAR COAT HARD

Guide Numbers**Invalid Guide Numbers**

LE 605 F : New

******* THIS ASSESSMENT CONTAINS INVALID GUIDE NUMBERS - PLEASE CHECK *********Eliminated Guide Numbers****Details**

N	283	LO	Labour Overlap	Repair
N	561	LO	Labour Overlap	Repair
N	562	LO	Labour Overlap	Repair
N	840	LO	Labour Overlap	Repair
N	4496	LO	Labour Overlap	Repair
N	4995	LO	Labour Overlap	Repair

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference:

Assessment Number: DS000513

Version: CHINATAI/2

Date Calculated: 25/01/2019 08:27

Full Report - V1

Registration: SLQ5760A

Printed: 25/01/2019 16:27

N	9947	LO	Labour Overlap	Repair
V	9909	LO	Labour Overlap	Alignment
L	1156	EL	Eliminated	Surface

Generated Guide Numbers

E 257 E 1411 E 1413 E 7227
 E 7228 E 305 -> N 283
 E 305 -> E 1001 -> N 561
 E 1001 -> E 1001 -> N 562
 E 1001 -> E 626 -> N 840
 E 626 -> E 4654 -> N 4496
 E 4654 -> E 4653 -> N 4995
 E 4653 -> E 7088 -> N 9947
 E 7088 -> E 7048 -> V 9909
 E 7048

Details

RenewRenewRenewRenewRenewRenew --> Repair
 Renew --> Renew --> Repair
 Renew --> Renew --> Repair
 Renew --> Renew --> Repair
 Renew --> Renew --> Repair
 Renew --> Renew --> Repair
 Renew --> Renew --> Repair
 Renew --> Renew --> Alignment
 Renew

Input Details

Positions Input: 85

Input Data Details

Repair Type	Guide Number	WU	Bet %	Price	Adj
E	257	0	0	\$0.00	
E	283	0	0	\$0.00	
LE	283	0	0	\$0.00	
E	349	0	0	\$0.00	
E	340	0	0	\$0.00	
E	405	0	0	\$0.00	
E	305	0	0	\$0.00	
E	361	0	0	\$0.00	
LE	361	0	0	\$0.00	
E	362	0	0	\$0.00	
LE	362	0	0	\$0.00	
E	366	0	0	\$0.00	
LE	366	0	0	\$0.00	
E	364	0	0	\$0.00	
LE	364	0	0	\$0.00	
E	377	0	0	\$0.00	
E	640	0	0	\$0.00	
E	561	0	0	\$0.00	
E	1188	0	0	\$0.00	
LE	1188	0	0	\$0.00	
L	1187	0	0	\$0.00	
E	9650	0	0	\$0.00	
E	471	0	0	\$0.00	
LE	471	0	0	\$0.00	
E	1033	0	0	\$0.00	
E	626	0	0	\$0.00	
E	605	0	0	\$0.00	
LE	605	0	0	\$0.00	
E	258	0	0	\$0.00	
LE	258	0	0	\$0.00	
E	503	0	0	\$0.00	
E	504	0	0	\$0.00	
E	742	0	0	\$0.00	

CHINA TAIPING INSURANCE (S) PTE LTD

Claim Reference:

Assessment Number: DS000513

Version: CHINATAI/2

Date Calculated: 25/01/2019 08:27

Full Report - V1

Registration: SLQ5760A

Printed: 25/01/2019 16:27

LE	742	0	0	\$0.00	
E	989	0	0	\$0.00	
E	1180	0	0	\$0.00	
E	1001	0	0	\$0.00	
LE	1001	0	0	\$0.00	
E	285	0	0	\$0.00	
E	286	0	0	\$0.00	
E	1320	0	0	\$0.00	
E	786	0	0	\$0.00	
E	784	0	0	\$0.00	
I	1156	20	0	\$0.00	
L	1156	0	0	\$0.00	
E	840	0	0	\$0.00	
E	842	0	0	\$0.00	
E	7753	0	0	\$0.00	
E	7787	0	0	\$0.00	
E	7202	0	0	\$0.00	
LE	7202	0	0	\$0.00	
E	7228	0	0	\$0.00	
E	7088	0	0	\$0.00	
E	7082	0	0	\$0.00	
E	7132	0	0	\$0.00	
E	7072	0	0	\$0.00	
E	7048	0	0	\$0.00	
E	7056	0	0	\$0.00	
E	7264	0	0	\$0.00	
E	7227	0	0	\$0.00	
E	1401	0	0	\$0.00	
E	4661	0	0	\$0.00	
E	4662	0	0	\$0.00	
E	4653	0	0	\$0.00	
E	4654	0	0	\$0.00	
E	4331	0	0	\$0.00	
E	7445	0	0	\$0.00	
E	4325	0	0	\$0.00	
I	1112	10	0	\$0.00	
L	1482	0	0	\$0.00	
E	9686	0	0	\$0.00	
L	355	0	0	\$0.00	
L	356	0	0	\$0.00	
S	1000	0	0	\$0.00	Specialist FRONT NUMBER PLATE
E	1000	0	0	\$0.00	Renew BUMPER INN PAD x 2
E	1000	0	0	\$0.00	Renew R/BONNET STOPPER
S	1000	0	0	\$0.00	Specialist R/F TYRE
S	1000	0	0	\$0.00	Specialist L/F TYRE
S	1000	0	0	\$0.00	Specialist R/F LAMP BULB(2PCS)
S	1000	0	0	\$0.00	Specialist F/SCREEN GUM
S	1000	0	0	\$0.00	Specialist AIRCON GAS
P	1000	5	0	\$0.00	WIRING
S	1000	0	0	\$0.00	Specialist COOLANT
S	1000	0	0	\$0.00	Specialist RESET FAULT CODE
S	1000	0	0	\$0.00	Specialist RESET AIR BAG SYSTEM

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jul 2018 Sendback Est.	17 Jul 2018 15:23 \$30,623.53	18 Jul 2018 10:20 Edit Adj Rpt	\$15,000.00 Edit Estimates	\$15,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: CHIN KHIN LOONG , ID: S7012100Z, Tel: +6597902227, Email: DANIELCHIN2227@GMAIL.COM									
Vehicle Reg. No.: SLQ5760A		Date of Loss: 13/07/2018 07:00 - :59 [102 Months and 1 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM18D03499C01		Policy/Cover Note No.: DMPCSN2054061700 (Comprehensive)							
		Excess: \$40.00							
Repairer: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 27/07/2018]									
Driver/Custodian: CHIN KHIN LOONG (48 / Male), NRIC: S7012100Z, Tel: +6597902227									
Adj Asg. Remarks: PLEASE PROCEED TO SURVEY & REVERT/CHECK ECONOMICAL FOR REPAIRS, EXCESS OF \$750.00 APPLIES IF CTL, ELSE WILL BE WAIVED (REPAIRABLE).									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPIING (06/08/2018): Alert - Adj Mandate Approved (\$15000.00) - SLQ5760A - Claim Handler: Jowyn Tay									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLQ5760A (SNM18D03499C01)

OD

Jul 13 2018 7:00AM

[CHIN KHIN LOONG]

Sng Ah Tee Motor & Panel Service Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No.	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	17/07/18 15:23	Repairer Estimates	 Load HTM	
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/08/18 10:54	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	☒
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/07/18 11:10	General View	 Load JPG	☒
2	20/07/18 11:10	General View	 Load JPG	☒
3	20/07/18 11:10	General View	 Load JPG	☒
4	20/07/18 11:10	General View	 Load JPG	☒
5	20/07/18 11:10	General View	 Load JPG	☒
6	20/07/18 11:10	General View	 Load JPG	☒
7	20/07/18 11:10	General View	 Load JPG	☒
8	20/07/18 11:10	General View	 Load JPG	☒
9	20/07/18 11:10	General View	 Load JPG	☒
10	20/07/18 11:10	General View	 Load JPG	☒
11	20/07/18 11:10	General View	 Load JPG	☒
12	20/07/18 11:10	General View	 Load JPG	☒
13	20/07/18 11:10	General View	 Load JPG	☒
14	20/07/18 11:10	General View	 Load JPG	☒
15	20/07/18 11:10	General View	 Load JPG	☒
16	20/07/18 11:10	General View	 Load JPG	☒
17	20/07/18 11:10	General View	 Load JPG	☒
18	20/07/18 11:10	General View	 Load JPG	☒
19	20/07/18 11:10	General View	 Load JPG	☒
20	20/07/18 11:10	General View	 Load JPG	☒
21	20/07/18 11:10	General View	 Load JPG	☒
22	20/07/18 11:10	General View	 Load JPG	☒
23	20/07/18 11:10	General View	 Load JPG	☒
24	20/07/18 11:10	General View	 Load JPG	☒
25	20/07/18 11:10	General View	 Load JPG	☒
26	20/07/18 11:10	General View	 Load JPG	☒
27	20/07/18 11:10	General View	 Load JPG	☒
28	20/07/18 11:10	General View	 Load JPG	☒
29	20/07/18 11:10	General View	 Load JPG	☒
30	20/07/18 11:10	General View	 Load JPG	☒
31	20/07/18 11:10	General View	 Load JPG	☒
32	20/07/18 11:10	General View	 Load JPG	☒
33	20/07/18 11:10	General View	 Load JPG	☒
34	20/07/18 11:10	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
				☒
35	20/07/18 11:10	General View	 Load JPG	☒
36	20/07/18 11:10	General View	 Load JPG	☒
37	20/07/18 11:10	General View	 Load JPG	☒
38	20/07/18 11:10	General View	 Load JPG	☒
39	20/07/18 11:10	General View	 Load JPG	☒
40	20/07/18 11:10	General View	 Load JPG	☒
41	20/07/18 11:10	General View	 Load JPG	☒
42	20/07/18 11:10	General View	 Load JPG	☒
43	20/07/18 11:10	General View	 Load JPG	☒
44	20/07/18 11:10	General View	 Load JPG	☒
45	20/07/18 11:10	General View	 Load JPG	☒
46	20/07/18 11:10	General View	 Load JPG	☒
47	20/07/18 11:10	General View	 Load JPG	☒
48	20/07/18 11:10	General View	 Load JPG	☒
49	20/07/18 11:10	General View	 Load JPG	☒
50	20/07/18 11:10	General View	 Load JPG	☒
51	20/07/18 11:10	General View	 Load JPG	☒
52	20/07/18 11:10	General View	 Load JPG	☒
53	20/07/18 11:10	General View	 Load JPG	☒
54	20/07/18 11:10	General View	 Load JPG	☒
55	20/07/18 11:10	General View	 Load JPG	☒
56	20/07/18 11:10	General View	 Load JPG	☒
57	20/07/18 11:10	General View	 Load JPG	☒
58	20/07/18 11:10	General View	 Load JPG	☒
59	20/07/18 11:10	General View	 Load JPG	☒
60	20/07/18 11:10	General View	 Load JPG	☒
61	20/07/18 11:11	General View	 Load JPG	☒
62	20/07/18 11:11	General View	 Load JPG	☒
63	20/07/18 11:11	General View	 Load JPG	☒
64	20/07/18 11:11	General View	 Load JPG	☒
65	20/07/18 11:11	General View	 Load JPG	☒
66	20/07/18 11:11	General View	 Load JPG	☒
67	20/07/18 11:11	General View	 Load JPG	☒
68	20/07/18 11:11	General View	 Load JPG	☒
69	20/07/18 11:11	General View	 Load JPG	☒
70	20/07/18 11:11	General View	 Load JPG	☒
71	06/08/18 11:16	General View	 Load PDF	
72	25/01/19 16:53	Reinspection Photo	 Load JPG	☒
73	25/01/19 16:53	Reinspection Photo	 Load JPG	☒
74	25/01/19 16:53	Reinspection Photo	 Load JPG	☒
75	25/01/19 16:53	Reinspection Photo	 Load JPG	☒
76	25/01/19 16:53	Reinspection Photo	 Load JPG	☒
77	25/01/19 16:53	Reinspection Photo	 Load JPG	☒
78	25/01/19 16:53	Reinspection Photo	 Load JPG	☒
79	25/01/19 16:53	Reinspection Photo	 Load JPG	☒
80	25/01/19 16:53	Reinspection Photo	 Load JPG	☒
81	25/01/19 16:53	Reinspection Photo	 Load JPG	☒
82	25/01/19 16:53	Reinspection Photo	 Load JPG	☒
83	25/01/19 16:53	Reinspection Photo	 Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
84	25/01/19 16:53	Reinspection Photo	1	Load JPG	☒
85	25/01/19 16:53	Reinspection Photo	1	Load JPG	☒
86	25/01/19 16:53	Reinspection Photo	1	Load JPG	☒
87	25/01/19 16:53	Reinspection Photo	1	Load JPG	☒
88	25/01/19 16:53	Reinspection Photo	1	Load JPG	☒
89	25/01/19 16:53	Reinspection Photo	1	Load JPG	☒
90	25/01/19 16:53	Reinspection Photo	1	Load JPG	☒
91	25/01/19 16:53	Reinspection Photo	1	Load JPG	☒
92	25/01/19 16:53	Reinspection Photo	1	Load JPG	☒
93	25/01/19 16:53	Reinspection Photo	1	Load JPG	☒
94	25/01/19 16:53	Reinspection Photo	1	Load JPG	☒
95	25/01/19 16:53	Reinspection Photo	1	Load JPG	☒
96	25/01/19 16:53	Reinspection Photo	1	Load JPG	☒
97	25/01/19 16:53	Reinspection Photo	1	Load JPG	☒
98	25/01/19 16:53	Reinspection Photo	1	Load JPG	☒
99	25/01/19 16:53	Reinspection Photo	1	Load JPG	☒
100	25/01/19 16:53	Reinspection Photo	1	Load JPG	☒
101	25/01/19 16:53	Reinspection Photo	1	Load JPG	☒
102	25/01/19 16:53	Reinspection Photo	1	Load JPG	☒
103	25/01/19 16:53	Reinspection Photo	1	Load JPG	☒
104	25/01/19 16:53	Reinspection Photo	1	Load JPG	☒
105	25/01/19 16:53	Reinspection Photo	1	Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	17/07/18 15:23	E-filed GIA report	1	Load PDF	
2	17/07/18 15:23	IC,DL,CI	1	Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	06/08/18 11:08	estimate pg 1 - 4	1	Load PDF	
2	06/08/18 11:08	estimate pg 5 - 11	1	Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	16/07/18 09:37	Accident Statement	1	Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	14/07/18 10:02	Accident Photo	1	Load JPG	☒
2	14/07/18 10:02	Accident Photo	1	Load JPG	☒
3	14/07/18 10:02	Accident Photo	1	Load JPG	☒
4	14/07/18 10:02	Accident Photo	1	Load JPG	☒
5	14/07/18 10:02	Accident Photo	1	Load JPG	☒
6	14/07/18 10:02	Accident Photo	1	Load JPG	☒
7	14/07/18 10:02	Accident Photo	1	Load JPG	☒
8	14/07/18 10:02	Accident Photo	1	Load JPG	☒
9	14/07/18 10:02	Accident Photo	1	Load JPG	☒
10	14/07/18 10:02	Accident Photo	1	Load JPG	☒
11	14/07/18 10:02	Accident Photo	1	Load JPG	☒
12	14/07/18 10:02	Accident Photo	1	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
13	14/07/18 10:02	Accident Photo		☒
14	14/07/18 10:02	Accident Photo		☒
15	14/07/18 10:02	Accident Photo		☒
16	14/07/18 10:02	Accident Photo		☒
17	14/07/18 10:02	Accident Photo		☒
18	14/07/18 10:02	Accident Photo		☒
19	14/07/18 10:02	Accident Photo		☒
20	14/07/18 10:02	Accident Photo		☒
21	14/07/18 10:02	Accident Photo		☒
22	14/07/18 10:02	Accident Photo		☒
23	14/07/18 10:02	Accident Photo		☒
24	14/07/18 10:02	Accident Photo		☒
25	14/07/18 10:02	Accident Photo		☒
26	14/07/18 10:02	Accident Photo		☒
27	14/07/18 10:02	Accident Photo		☒
28	14/07/18 10:02	Accident Photo		☒
29	16/07/18 09:37	Accident Photo		☒
30	16/07/18 09:37	Accident Photo		☒
Documentation			1 per page	☒
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	16/07/18 09:37	Sketch Plan		☐
2	16/07/18 09:37	CI,IC,DL		☐
3	16/07/18 09:37	POLICE REPORT		☐

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT118013084/T1TD3E2

Date: 28/01/2019

REFERENCE

Insured/Claimant: CHIN KHIN LOONG Policy No: DMPCSN2054061700
Date of Loss: 13/07/2018 Nature of Claim: OD Claim No: SNM18D03499C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ5760A**
Make & Model: MERCEDES-BENZ E250, 1.8 CGI (A) Engine No: 27186030009149
Reg. Date: 12/01/2010 (Man. Year: 2009) Chassis No: WDD2120472A098103
Colour: Black Odometer: 172982 km
Engine Capacity: 1796 cc
Market Value/New Car Price: S\$49,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45Z R17 Rear Tyre Size: 245/45Z R17
Front Left Side: Kinforest 6 mm Rear Left Side: Kinforest 6 mm
Front Right Side: Kinforest 6 mm Rear Right Side: Kinforest 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,331.20	20,134.00	8,197.20	28.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,292.33	1,891.08	401.25	17.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,623.53	22,025.08	8,598.45	28.08
Approved Total (Overridden) (S\$)		15,000.00		
(S\$)	30,623.53	15,000.00	15,623.53	51.02
+ GST 7.00/7.00% (S\$)	2,143.65	1,050.00	1,093.65	51.02
Nett Amount (S\$)	32,767.18	16,050.00	16,717.18	51.02

INSPECTION

Date of Assignment: 18/07/2018 Present Location: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Date Inspected: 18/07/2018 Inspected At: Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)
Blk 3 Pioneer Road North, #01-18
Singapore 628457
Estimated Period of Repair: 10.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Jan 2019)
Parts: 143	MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLQ5760A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*AIR GUIDE	Cut	38.00 F	*38.00 F
2	1	NA	*AIRBAG/TENS C-UNIT	Activated	490.00 F	*490.00 F
3	1	NA	*BONNET	Buckled	1,150.00 F	*1,150.00 F
4	1	NA	*BONNET CATCH	Serviceable	39.00 F	*- F
5	1	NA	*BUMPER INN PAD X 2	Torn	66.00 F	*66.00 F
6	1	NA	*COMBI SWITCH MODULE	Not Necessary	520.00 F	*- F
7	1	NA	*CTR FRT REINF	Serviceable	83.00 F	*- F
8	1	NA	*CTR TRIM	Serviceable	115.00 F	*- F
9	1	NA	*DRIVER AIRBAG	Activated	1,250.00 F	*1,250.00 F
10	1	NA	*EXPANSION TANK	Distorted	70.00 F	*70.00 F
11	1	NA	*FRONT AXLE SUPPORT	Serviceable	1,156.00 F	*- F
12	1	NA	*FRONT BONNET SEAL	Necessary	12.00 F	*12.00 F
13	1	NA	*FRONT BUMPER COVER	Torn	860.00 F	*860.00 F
14	1	NA	*FRONT BUMPER GRILLE	Deformed	39.00 F	*39.00 F
15	1	NA	*FRONT CTR RETAINER	Necessary	23.00 F	*23.00 F
16	1	NA	*FRONT GRILLE PANEL	Serviceable	115.00 F	*- F
17	1	NA	*FRONT NUMBER PLATE (NPA)	Cracked	0.00 F	*- F
18	1	NA	*FRONT STABILISER	Serviceable	230.00 F	*- F
19	1	NA	*FRT BUMPER W/HARNESS	Cut	130.00 F	*130.00 F
20	1	NA	*FRT CTR BUMPER REINF	Bent	58.00 F	*58.00 F
21	1	NA	*FRT CVR INSUL MNTG	Serviceable	19.20 F	*- F
22	1	NA	*FRT LWR CROSSMEMBER	Bent	270.00 F	*270.00 F
23	1	NA	*FRT NO PLATE REINF	Deformed	92.00 F	*92.00 F
24	1	NA	*FRT SCREEN SUPPORTS (NPA)	Not Necessary	0.00 F	*- F
25	1	NA	*FRT/CTR IMPACT DAMP	Deformed	58.00 F	*58.00 F
26	1	NA	*GRILLE	Cracked	570.00 F	*570.00 F
27	1	NA	*INSTRUMENT PANEL	Torn	2,480.00 F	*2,480.00 F
28	1	NA	*INSULATION CTR COVER	Serviceable	137.00 F	*- F
29	1	NA	*L/BONNET ACTUATOR	Serviceable	195.00 F	*- F
30	1	NA	*L/BRACKET	Serviceable	25.00 F	*- F
31	1	NA	*L/F CTR PARKING SENS	Serviceable	130.00 F	*- F
32	1	NA	*L/F DAYTIME RUN LAMP	Serviceable	290.00 F	*- F
33	1	NA	*L/F IMPACT DAMPER	Serviceable	29.00 F	*- F
34	1	NA	*L/F INNER SENSOR	Serviceable	130.00 F	*- F
35	1	NA	*L/F OUT BUMP GRILLE	Serviceable	22.00 F	*- F
36	1	NA	*L/F OUTER SENSOR	Not Working	140.00 F	*140.00 F
37	1	NA	*L/F PEDEST PROT SENS	Serviceable	61.00 F	*- F
38	1	NA	*L/F SEAT BELT	Activated	800.00 F	*800.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1	NA	*L/F SEAT BELT LOCK	Activated	75.00 F	*75.00 F
40	1	NA	*L/F SPACER	Necessary	20.00 F	*20.00 F
41	1	NA	*L/F TYRE (NPA)	Serviceable	0.00 F	*- F
42	1	NA	*L/F W-HOUSE CVR FRT	Serviceable	103.00 F	*- F
43	1	NA	*L/HEADLAMP WASH TRIM	Cracked	36.00 F	*36.00 F
44	1	NA	*L/LOWER LATCH	Serviceable	37.00 F	*- F
45	1	NA	*L/REINFORCEMENT	Serviceable	29.00 F	*- F
46	1	NA	*L/SPRING ELEMENT	Serviceable	10.00 F	*- F
47	1	NA	*L/UPPER LATCH	Bent	19.00 F	*19.00 F
48	1	NA	*L/WASHER JET BRACKET	Serviceable	108.00 F	*- F
49	1	NA	*LEFT BONNET HINGE	Serviceable	80.00 F	*- F
50	1	NA	*LEFT HEADLAMP ASSY	Broken	1,500.00 F	*1,500.00 F
51	1	NA	*PASSENGER AIRBAG	Activated	980.00 F	*980.00 F
52	1	NA	*R/BONNET ACTUATOR	Serviceable	195.00 F	*- F
53	1	NA	*R/BONNET STOPPER	Necessary	6.00 F	*6.00 F
54	1	NA	*R/BRACKET	Serviceable	25.00 F	*- F
55	1	NA	*R/BRG COVER PANEL	Serviceable	27.00 F	*- F
56	1	NA	*R/COVER MOULDING	Serviceable	175.00 F	*- F
57	1	NA	*R/F CTR PARKING SENS	Not Working	130.00 F	*130.00 F
58	1	NA	*R/F DAYTIME RUN LAMP	Broken	290.00 F	*290.00 F
59	1	NA	*R/F IMPACT DAMPER	Serviceable	29.00 F	*- F
60	1	NA	*R/F INNER SENSOR	Necessary	130.00 F	*130.00 F
61	1	NA	*R/F LWR CONTROL ARM	Bent	225.00 F	*225.00 F
62	1	NA	*R/F OUT BUMP GRILLE	Not Necessary	22.00 F	*- F
63	1	NA	*R/F OUTER SENSOR	Not Working	140.00 F	*140.00 F
64	1	NA	*R/F PEDEST PROT SENS	Serviceable	61.00 F	*- F
65	1	NA	*R/F SEAT BELT	Activated	800.00 F	*800.00 F
66	1	NA	*R/F SEAT BELT LOCK	Activated	75.00 F	*75.00 F
67	1	NA	*R/F SHOCK ABSORBER	Bent	380.00 F	*380.00 F
68	1	NA	*R/F SPACER	Necessary	200.00 F	*20.00 F
69	1	NA	*R/F STABILISER ARM	Bent	48.00 F	*48.00 F
70	1	NA	*R/F STEERING KNUCKLE	Bent	600.00 F	*600.00 F
71	1	NA	*R/F STRUT BEARING	Serviceable	98.00 F	*- F
72	1	NA	*R/F TENSION ROD	Bent	230.00 F	*230.00 F
73	1	NA	*R/F TYRE (NPA)	Serviceable	0.00 F	*- F
74	1	NA	*R/F UPP REINF	Bent	133.00 F	*133.00 F
75	1	NA	*R/F WHEEL	Scratched	550.00 F	*550.00 F
76	1	NA	*R/F WHEEL HUB	Bent	410.00 F	*410.00 F
77	1	NA	*R/F W-HOUSE CVR FRT	Torn	103.00 F	*103.00 F
78	1	NA	*R/F W-HOUSE CVR REAR	Torn	94.00 F	*94.00 F
79	1	NA	*R/F WING	Torn	590.00 F	*590.00 F
80	1	NA	*R/F WING BADGE	Necessary	20.00 F	*20.00 F
81	1	NA	*R/F WING MOULDING	Necessary	33.00 F	*33.00 F
82	1	NA	*R/HEADLAMP WASH TRIM	Serviceable	36.00 F	*- F
83	1	NA	*R/LOWER LATCH	Serviceable	37.00 F	*- F
84	1	NA	*R/PARTITION SEAL	Necessary	60.00 F	*60.00 F
85	1	NA	*R/REINFORCEMENT	Bent	29.00 F	*29.00 F
86	1	NA	*R/SPRING ELEMENT	Serviceable	10.00 F	*- F
87	1	NA	*R/TENSION ROD RUBBER	Bent	50.00 F	*50.00 F
88	1	NA	*R/UPPER LATCH	Bent	19.00 F	*19.00 F
89	1	NA	*R/WASHER JET BRACKET	Missing	108.00 F	*108.00 F
90	1	NA	*R/XENON LAMP CU	Broken	580.00 F	*580.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
91	1	NA	*RADIAT GRILLE MOUNTG	Serviceable	10.00 F	*- F
92	1	NA	*RIGHT BONNET HINGE	Serviceable	80.00 F	*- F
93	1	NA	*RIGHT HEADLAMP ASSY	Serviceable	1,500.00 F	*- F
94	1	NA	*SPECIALIST AIRCON GAS	Necessary	50.00 FS	*50.00 FS
95	1	NA	*SPECIALIST COOLANT	Necessary	40.00 FS	*40.00 FS
96	1	NA	*SPECIALIST F/SCREEN GUM	Necessary	40.00 FS	*40.00 FS
97	1	NA	*SPECIALIST FRONT NUMBER PLATE	Broken	35.00 FS	*35.00 FS
98	1	NA	*SPECIALIST L/F TYRE	Scratched	480.00 FS	*480.00 FS
99	1	NA	*SPECIALIST R/F LAMP BULB(2PCS)	Broken	30.00 FS	*30.00 FS
100	1	NA	*SPECIALIST R/F TYRE	Punctured	480.00 FS	*480.00 FS
101	1	NA	*SPECIALIST RESET AIR BAG SYSTEM	Necessary	300.00 FS	*300.00 FS
102	1	NA	*SPECIALIST RESET FAULT CODE	Necessary	250.00 FS	*250.00 FS
103	1	NA	*STEERING GEAR	Serviceable	3,200.00 F	*- F
104	1	NA	*SUNDRY PARTS	Necessary	100.00 FS	*100.00 FS
105	1	NA	*UPPER AIR GUIDE	Serviceable	65.00 F	*- F
106	1	NA	*WASHER JET HOSE	Serviceable	34.00 F	*- F
107	1	NA	*WINDSCREEN	Cracked	0.00 F	*1,250.00 F
108	1	NA	*WINDSCREEN REP KIT (NPA)	Not Necessary	0.00 F	*- F

F=Franchise part. S=SpcNett.

Total Parts (S\$)	28,331.20	20,134.00
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total Paint Labour	New	428.40	386.40
2	Total Paint Materials	New	301.53	274.08
3	Total Panel/Mechanical Labour	New	1,562.40	1,230.60
Gross Labour Cost (\$\$)			2,292.33	1,891.08

Report was unsubmitted during this print-out.

< END OF ESTIMATES >