

7/03/2002

ASS. REC. BY:

REF: CS/CTI/8013085/ T1rd3<sup>n2</sup>

Special Instruction:

Surveyor:  
Maximen

Tau Hich

ASSIGNMENT (Office)

From (Person): Sanyu Tay

of CTI

Date/Time: 18/7/18 @ 10:21am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: 8GX 5364H

Insured: SLQ 5760A

at Workshop m/s Etho Z

Tel: 8822 8339

of 30 Blk Bafok Crescent

Policy No: DMPC SN 306 4061700

Claim No: SNM18D0349 9C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 13/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS lup

H.O.D. Endorsement:

Date/Time: 11:56am @ 18/7/18

Person Contacted: Mr. Lee

Vehicle-IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	8GX 5364H - CS/AXA/16008496 / Fq h 3c2 DOA: 20/2/2016
	SLQ 5760A - CS/CTI/8013084 / T1rd3 DOA: 13/07/2018
	Confirm with Lee L/S \$2750 @ 6 days
	Red: 82984.04, 52%.

(08/11/13) wef

REF: CTI

ASS. REC. BY: *Taufik*

## ASSIGNMENT

WE 2021 July

From: \_\_\_\_\_ Date: 23/07/18

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGX 5364 Hat Workshop m/s Ethozof 30 Bkt Bahok Crest

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 931K

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SGX 5364 H Yr Regn: 2006 / JulyType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Lexus 13250 c.c. 2500Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 146472 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: ST HSK 262x02014787Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/45R17

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. \_\_\_\_\_

D.O.I. 23/7/18 @ 1230pmSurvey held at Ethoz Bkt BahokDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orFrt o/s, o/s, Rear o/s, Rooftop  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 29 AUG 2018

Date/Time, File Pass to?

1) Print

Date/Time, File Return to?

2) \_\_\_\_\_

Report Format: TPLump Sum / I.B.I: (\$ 2750.00)Days Of Repair: 6Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

220

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jul 2018		18 Jul 2018 10:21 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHIN KHIN LOONG, ID: S7012100Z		
Main Claimant:	KANG SOOL PENG, ID: S7263823I		
Vehicle Reg. No.:	SGX5364H	Date of Loss:	13/07/2018 07:00 - :59
Claim Type:	TP / SNM18D03499C02	Policy/Cover Note No.:	DMPCSN3064061700 (Comprehensive) Coverage: 11/08/2017 - 11/01/2019
Vehicle Reg. No. (Insured):	SLQ5760A	Policy No. (Claimant):	GA052450
		Excess:	S\$0.00
Repairer:	ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent, 658075 Bukit Batok - Tel: 66547750/51		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/07/2018]		
Adj Asg. Remarks:	PLEASE PROCEED TO SURVEY & ARRANGE FOR DIRECT SETTLEMENT.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18013085/T1rd3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 18-07-2018



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLQ 5760A	Veh. Inspected	SGX 5364H
Policy No.	DMPCSN3064061700	Coverage (\$)	0.00
Claim No.	SNM18D03499C02	Excess (\$)	0.00
Assign From	MERIMEN (JOWYN TAY)	Assign Date	18/07/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	13/07/2018	Inspection Date	23/07/2018
Survey held at	ETHOZ GROUP LTD 30 BUKIT BATOK CRESCENT SINGAPORE 658075		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

**From:** Lee Chen Sin <ChenSin.Lee@ethozgroup.com>  
**Sent:** Wednesday, August 01, 2018 3:24 PM  
**To:** Taufikh (LKKAUTO); SUR  
**Subject:** FINALIZATION REPORT OF SGX-5364-H LEXUS IS250 (TP)(CHINA TAIPING)  
**Attachments:** 33\_20180801150551.pdf; PHOTO AFTER PAINT (1).JPG; PHOTO AFTER PAINT (2).JPG; PHOTO AFTER PAINT (3).JPG; PHOTO AFTER PAINT (4).JPG; PHOTO AFTER PAINT (5).JPG; PHOTO AFTER PAINT (6).JPG; PHOTO AFTER PAINT (7).JPG; PHOTO AFTER PAINT (8).JPG; PHOTO AFTER PAINT (9).JPG; PHOTO AFTER PAINT (10).JPG; PHOTO AFTER PAINT (11).JPG

Hi Taufikh,

Attached are the finalization report and photo after paint of above mention vehicle.

Please send acceptance once the COR is confirm.

COR : \$ 2,750.00 (Lump Sum Repair)  
Repair days : 6

Kindly revert.

Thank you.

Warmest Regards,  
Lee Chen Sin  
Motor Claims Operations

**ETHOZ**  
ETHOZ GROUP LTD

30 Bukit Batok Crescent Singapore 658075  
DID: 6654 7520 | FAX: 6654 7542 | Mobile: 8822 8339  
[www.ethozgroup.com](http://www.ethozgroup.com)



Disclaimer: This message may contain confidential information intended only for the use of the addressee named above. If you are not the intended recipient of this message you are hereby notified that any use, dissemination, distribution or reproduction of this message is prohibited. If you received this message by mistake, please notify the sender by reply email immediately. Please conduct your own virus checks before opening any attachment as ETHOZ Group does not guarantee the integrity of this email or attached files has been maintained nor this communication is free of viruses, interceptions or interference. Any views expressed in this message are those of the individual sender and may not necessarily reflect the views of ETHOZ Group. ETHOZ Group shall not be responsible nor liable for the improper and incomplete transmission of the information contained in this communication nor for any delay in its receipt or damage to your system.

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	3823I
<b>Vehicle Details</b>	
Vehicle No.:	SGX5364H
Vehicle to be Exported:	No
Intended De-registration Date:	17 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS IS250 AUTO STD
Primary Colour:	Grey
Manufacturing Year:	2006
Engine No.:	4GR0198476
Chassis No.:	JTHBK262X02014787
Maximum Power Output:	153.0 kW (205 bhp)
Open Market Value:	\$36,638.00
Original Registration Date:	31 Jul 2006
First Registration Date:	31 Jul 2006
Transfer Count:	1
Actual ARF Paid:	\$40,302.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	30 Jul 2021
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$25,815.00
COE Rebate Amount:	\$15,669.00
<b>Total Rebate Amount:</b>	<b>\$15,669.00</b>
<b>Message</b>	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 17 Jul 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	13/07/2018 14:39
Date Of Accident	13/07/2018 07:20
Exact Location Of Accident	UPPER BUKIT TIMAH ROAD AT THE JUNC OF MINDEF
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGX5364H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KANG SOOL PENG
NRIC No	S7263823I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98559786
Alternative Phone No	OFFICE-98559786

### Vehicle Particulars

Manufacturer	LEXUS
Model	IS-2.5 250 STD (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA052450
Cover Note Number	31/07/2018-30/07/2019

### Driver

Name of Driver	LIM KOK CHUAN
NRIC No	S7474045F
Date Of Birth	20/10/1974
Occupation	INDOOR
Date Of Driving Pass	06/03/2007
Driving Experience	11 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84358798
Fax Number	
Contact Number	
EEmail Address	NOEMAIL



Address	15 HUME AVE #04-03
Postcode	598725
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT BY FALLEN TREE / OTHER OBJECTS
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : KANG SOOL PENG GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT BATOK NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 103 BUKIT BATOK CENTRAL , POSTCODE: 650103 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5639999 - FAX NO: 66655794
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO THE POLICE REPORT T/20180713/2026

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLQ5760A
Vehicle Make/Model/Colour	B
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	



Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

13/07/2018

2:10pm

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


13/07/2018

2:10pm

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No:

Kenneth

# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Contents.  
Follow the ~~report~~ of police report


### **Important:**

You have been advised by the workshop that in the event that you wish to claim against your own policy (OD CLAIM), There is a **FOURTEEN (14) DAYS CLAUSE WHEREBY MUST BE MADE** within the stipulated time frame from the day of the occurrence.


- Reporting Only
- Claim OD
- Claim TP
- Claim OD/ TP at other workshop

### DECLARATION

I/WE declare the foregoing particulars are true in every respect.

  
Policyholder's signature  
Date & Time

13/07/2018  
2:10pm

  
Driver's Signature  
(if driver not the policyholder)  
Date & Time

13/07/2018  
2:10pm

  
Reporting Centre Personnel's Signature  
Name: **Kenneth**  
Nric/Fin No.



Police Station Of Origin:  
Bukit Batok N.P.C  
21 Bukit Batok East Avenue 4 SINGAPORE  
659840  
Tel No: 1800-6659999

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/07/2018 10:28	Vide Report No.: J/20180713/0065	Station Diary No.: 35
--	-------------------------------------	--------------------------

Informant's Particulars				
Name of Informant: LIM KOK CHUAN		Address: 15 HUME AVENUE #04-03 SINGAPORE 598725		
ID Type / ID No.: NRIC NO / S7474045F		Contact No.: Home/Office:                      Mobile: 84358798		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 43	Date of Birth: 20/10/1974	Type of Informant: Driver	
Race: Chinese		Language:	Institution / School Name:	
Occupation: UNEMPLOYED		Driving Licence Information: Class: 3                      Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 13/07/2018 07:20	Type of Location: Straight Road
Location: Along Road 1 UPPER BUKIT TIMAH ROAD  At the junction of Mindef entrance				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Debris from traffic light hit car				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGX5364H	Car				Slightly Damaged	1
SLQ5760A	Car				Seriously Damaged	0



**POLICE FORCE**



T/20180713/2026

Police Station Of Origin:

2 of 3

Bukit Batok N.P.C

Report No. T/20180713/2026

21 Bukit Batok East Avenue 4 SINGAPORE

659840

CONTINUATION OF REPORT

Tel No: 1800-6659999

**Brief Details.**

On 13/6/18 at around 0720hrs, I was at Upper Bt Timah Road, at the junction of Gombak Drive. While I was waiting to turn into Gombak Drive, a black Mercedes (Registration number: SLQ5760A) travelling at high speed crashed into a traffic light. As a result, the driver of the vehicle (Chin Khin Loong, IC:S7012100Z, HP:97902227) suffered scratches on his left arm. Debris from the traffic light fell onto my vehicle (Registration number: SGX5364H), and as a result there were dents on my vehicle at the bonnet area, near the driver door, roof of the vehicle, the boot area and rear door of driver side. The traffic light had toppled over and the divider was also damaged. Both my wife and I who were in my vehicle were not injured



POLICE FORCE



T/20180713/2026

3 of 3

Police Station Of Origin:  
Bukit Batok N.P.C  
21 Bukit Batok East Avenue 4 SINGAPORE  
659840  
Tel No: 1800-6659999


Report No. T/20180713/2026


CONTINUATION OF REPORT


**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J/ NEVIN R NAIR 
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt NOR FAIZAL BIN YAHYA Contact No.: 65476202 SN 114

Authentication Stamp  
NP168  
  
Singapore Police Force

Signature Of Informant: 
Date/Time: 13/07/2018 10:28
Classification Of Case:

(LKK AUTO CONSULTANTS)

PLEASE ARRANGE TO SURVEY  
VEHICLE AT 30 BUKIT BATOK  
CRESCENT (S 658075)

Lee Chen Sin  
CLAIM DEPARTMENT  
DID : 66547520  
FAX :

Date : 17/07/2018

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.  
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : KANG SOOL PENG

: AXA INSURANCE PTE LTD

Certificate No : GA052450

Accident Date : 13/07/2018

Vehicle No : SGX-5364-H

Make & Model : TOYOTA LEXUS IS250C AUTO STD

## ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
-----	-------------	-------------------	---------------

### List Item

- 1 FRONT FENDER RH
- 1 FRONT FENDER INNER SHIELD RH
- 10 FRONT FENDER INNER SHIELD CLIP
- 1 FRONT BONNET HINGE RH
- 1 FRONT BONNET
- 1 CENTRE PILLAR RH
- 1 ROOF PANEL
- 1 FRONT DOOR RH
- 1 FRONT DOOR OUTER GARNISH RH

RESTORE RY  
RESTORE RY  
RESTORE RY  
RESTORE RY

922.15

397.48

25.00

85.06

60.76

922.15  
X nn  
X nn  
RY  
X  
60.76



Date : 17/07/2018

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.  
ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : KANG SOOL PENG

: AXA INSURANCE PTE LTD

Certificate No : GA052450

Accident Date : 13/07/2018

Vehicle No : SGX-5364-H

Make & Model : TOYOTA LEXUS IS250C AUTO STD

## ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	RESTORE R		
1	REAR DOOR RH	455.30	Ry } x
1	REAR DOOR HANDLE OUTER RH	243.50	Ry } x
1	REAR DOOR LOCK CAP RH	966.40	bt 966.40
1	REAR BOOTLID	95.60	ne 95.60
1	REAR BOOTLID EMBLEM CENTRE	75.40	ne 75.40
1	REAR BOOTLID EMBLEM "IS 250"	96.40	ne 96.40
1	REAR BOOTLID EMBLEM "LEXUS"	1,657.20	Ry x
1	ROOF PANEL		

Date : 17/07/2018  
 To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.  
**ESTIMATION**  
 Attn : Motor Claim Department FAX :

Owner : KANG SOOL PENG  
 : AXA INSURANCE PTE LTD  
 Certificate No : GA052450 Accident Date : 13/07/2018  
 Vehicle No : SGX-5364-H Make & Model : TOYOTA LEXUS IS250C AUTO STD

## ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	5080.25	
	Discount 25% On Parts	(1270.06)	
	<u>Labour &amp; Misc</u>		
	LABOUR TO FACILIATE REPAIR	600.00	500 500
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	✓ 35
	TO SPRAY PAINT ON AFFECTED AREAS	1,300.00	1100 1100
	TO REMOVE & REINSTALL ROOF LINING TO FACILIATE REPAIR	180.00	100 100
	TO REMOVE & INSTALL ALL REAR BOOT LID COMPONENT TO FACILITATE REPAIRS	100.00	60 60

5734.04

6025.19

Date : 01/08/2018

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : KANG SOOL PENG

Insured By : AXA INSURANCE PTE LTD

Certificate No : GA052450 Accident Date : 13/07/2018

Vehicle No : SGX-5364-H Make & Model : TOYOTA LEXUS IS250C AUTO STD

**FINAL ESTIMATED REPAIR COST DETAILS** Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
<b>List Item</b>			
1	FRONT FENDER RH	922.15	922.15
1	FRONT FENDER INNER SHIELD RH	397.48	0.00
10	FRONT FENDER INNER SHIELD CLIP	25.00	0.00
1	FRONT BONNET HINGE RH	85.06	0.00
1	FRONT BONNET RESTORE	0.00	0.00
1	CENTRE PILLAR RH RESTORE	0.00	0.00
1	ROOF PANEL RESTORE	0.00	0.00
1	FRONT DOOR RH RESTORE	0.00	0.00
1	FRONT DOOR OUTER GARNISH RH	60.76	60.76
1	REAR DOOR RH RESTORE	0.00	0.00
1	REAR DOOR HANDLE OUTER RH	455.30	0.00
1	REAR DOOR LOCK CAP RH	243.50	0.00
1	REAR BOOTLID	966.40	966.40
1	REAR BOOTLID EMBLEM CENTRE	95.60	95.60

PAGE : 1

Date : 01/08/2018

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : KANG SOOL PENG

Insured By : AXA INSURANCE PTE LTD

Certificate No : GA052450

Accident Date : 13/07/2018

Vehicle No : SGX-5364-H

Make & Model : TOYOTA LEXUS IS250C AUTO STD

**FINAL ESTIMATED REPAIR COST DETAILS** Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	REAR BOOTLID EMBLEM "IS 250"	75.40	75.40
1	REAR BOOTLID EMBLEM "LEXUS"	96.40	96.40
1	ROOF PANEL	1657.20	0.00
	<b>Sub Total</b>	<b>5080.25</b>	<b>2216.71</b>
	<b>Discount 25% On Parts</b>	<b>(0.00)</b>	<b>(554.18)</b>
<b>Labour &amp; Misc</b>			
	LABOUR TO FACILITATE REPAIR	600.00	500.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	35.00	35.00
	TO SPRAY PAINT ON AFFECTED AREAS	1300.00	1100.00
	TO REMOVE & REINSTALL ROOF LINING TO FACILITATE REPAIR	180.00	100.00
	TO REMOVE & INSTALL ALL REAR BOOT LID COMPONENT TO FACILITATE REPAIRS	100.00	60.00

Date : 01/08/2018

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : KANG SOOL PENG

Insured By : AXA INSURANCE PTE LTD

Certificate No : GA052450 Accident Date : 13/07/2018

Vehicle No : SGX-5364-H Make & Model : TOYOTA LEXUS IS250C AUTO STD

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	Sub Total	2215.00	1795.00

Sub Total	6,025.19	3,457.53
GST 7.0 %	421.76	242.03
Total	6,446.95	3,699.56

COR: \$ 2,750.00 (45 REPAIR)

6 DAYS REPAIR

Surveyor Name : TAUFIK - LKK

Date & Time : 23/07/2018 12:15:00 PM

Lee Chen Sin

CLAIM DEPARTMENT

DID : 66547520

FAX :

PARTS - \$ 2,216.71 - 25%

- \$ 1,662.53

S/W - \$ 1,795.00

\$ 3,457.53

- 20% (45 REPAIR)

\$ 2,766.02

PAGE: 3

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18013085/T1RD3N2

Date: 31/08/2018

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3064061700
Claimant Vehicle No :	SGX5364H	Insured Vehicle No :	SLQ5760A
Date of Loss:	13/07/2018	Nature of Claim:	TP
		Claim No:	SNM18D03499C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SGX5364H	Engine No:	4GR0198476
Make & Model:	LEXUS IS, 2.5 250 STD (A)	Chassis No:	JTHBK262X02014787
Reg. Date:	31/07/2006 (Man. Year: 2006)	Odometer:	146472 km
Colour:	Grey		
Engine Capacity:	2500 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	245/45R17	Rear Tyre Size:	245/45R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,810.19	1,662.53	2,147.66	56.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,215.00	1,795.00	420.00	18.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,025.19</b>	<b>3,457.53</b>	<b>2,567.66</b>	<b>42.62</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,750.00</b>		
(S\$)	6,025.19	2,750.00	3,275.19	54.36
<b>+ GST 7.00/7.00% (S\$)</b>	<b>421.76</b>	<b>192.50</b>	<b>229.26</b>	<b>54.36</b>
<b>Nett Amount (S\$)</b>	<b>6,446.95</b>	<b>2,942.50</b>	<b>3,504.45</b>	<b>54.36</b>

## INSPECTION

Date of Assignment:	18/07/2018	
Date Inspected:	23/07/2018	Inspected At: ETHOZ Protect Pte Ltd (Bukit Batok) 30 Bukit Batok Crescent Singapore 658075
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	<b>Version:</b> 1.0 (Last Synchronised: 30 Aug 2018)
<b>Parts:</b> 143	LEXUS IS 2.5 250 STD (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SGX5364H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Bent	922.15 FL	*922.15 FL
2	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	397.48 FL	*- FL
3	10		*FRONT FENDER INNER SHIELD CLIP	Not Necessary	25.00 FL	*- FL
4	1		*FRONT BONNET HINGE RH	Repair	85.06 FL	*- FL
5	1		*FRONT BONNET (NPA)	Repair	0.00 FL	*- FL
6	1		*CENTRE PILLAR RH (NPA)	Repair	0.00 FL	*- FL
7	1		*ROOF PANEL (NPA)	Repair	0.00 FL	*- FL
8	1		*FRONT DOOR RH (NPA)	Repair	0.00 FL	*- FL
9	1		*FRONT DOOR OUTER GARNISH RH	Cut	60.76 FL	*60.76 FL
10	1		*REAR DOOR RH (NPA)	Repair	0.00 FL	*- FL
11	1		*REAR DOOR HANDLE OUTER RH	Repair	455.30 FL	*- FL
12	1		*REAR DOOR LOCK CAP RH	Repair	243.50 FL	*- FL
13	1		*REAR BOOTLID	Bent	966.40 FL	*966.40 FL
14	1		*REAR BOOTLID EMBLEM CENTRE	Necessary	95.60 FL	*95.60 FL
15	1		*REAR BOOTLID EMBLEM IS250	Necessary	75.40 FL	*75.40 FL
16	1		*REAR BOOTLID EMBLEM LEXUS	Necessary	96.40 FL	*96.40 FL
17	1		*ROOF PANEL	Repair	1,657.20 FL	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,080.25</b>	<b>2,216.71</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>1,270.06</b>	<b>554.18</b>
<b>Total Parts (\$\$)</b>	<b>3,810.19</b>	<b>1,662.53</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO FACILITATE REPAIR	New	600.00	500.00
2	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	35.00	35.00
3	TO SPRAY PAINT ON AFFECTED AREAS	New	1,300.00	1,100.00
4	TO REMOVE & REINSTALL ROOF LINING TO FACILITATE REPAIR	New	180.00	100.00
5	TO RMEOVE & INSTALL ALL REAR BOOT LID COMPONENT TO FACILITATE REPAIRS	New	100.00	60.00
Gross Labour Cost (\$\$)			<b>2,215.00</b>	<b>1,795.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >