

ASS. REC. BY:

REF:

CS/EGT18013090/Avd3⁰²

Special Instructions:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGI

Date/Time:

18/7/18 @ 3:55pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLZ 5769D

Insured:

GBB 562K

at Workshop m/s

United SG Automobile

Tel:

6747 4454

of

53 Ubi Ave 1 #01-56

Policy No:

Claim No:

GBB 562K / SL / p

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 10/07/2018

CA / REV / REP. / REV 24 HRS

Cup?

19/7/18 @ After 1pm

H.O.D. Endorsement:

Date/Time:

5:10pm @ 18/7/18

Person Contacted:

Chris

Vehicle-IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLZ 5769D -X

GBB 562K - CC6 / AXA / 14009822 / Kh 26392 DOA: 24/5/2014

20/7/18

Informed Pei Li pending workshop est by merimen

8/8/18

Adrian confirmed LS \$1300 (Red 2330.53, 64%)

8/8/18

Email preli revised to Pei Li



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|---|---------------------------|---|
| ERGO INSURANCE PTE LTD | | Ref : CS/EGI18013090/Avd3 | |
| 5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985 | | Date : 18-07-2018 |  |
| | | Code : EGI | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | GBB 562K | Veh. Inspected | SLZ 5769D |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | GBB562K/SL/pl | Excess (\$) | 0.00 |
| Assign From | YEE PEI LI | Assign Date | 18/07/2018 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | |
| | | | |
| 5. General Information | | | |
| Accident Date | 10/07/2018 | Inspection Date | |
| Survey held at | UNITED SG AUTOMOBILE PTE LTD 53 UBI AVENUE 1 #01-56 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 8 August 2018 10:33 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: GBB562K / TP : SLZ5769D/LKK / DOA : 10/07/2018
Attachments: SLZ 5769D PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle SLZ 5769D
Date of survey: 19/7/2018
Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Friday, 20 July 2018 1:23 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GBB562K / TP : SLZ5769D/LKK / DOA : 10/07/2018

Dear Pei Li,

Please be informed that we have inspected the vehicle SLZ 5769D on 19/7/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 18 July 2018 5:13 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GBB562K / TP : SLZ5769D/LKK / DOA : 10/07/2018

Dear Sir/Mdm,



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: GBB562K/SL/pl

Our ref: CS/EGI18013090/Avd3

The Motor Claims Department
M/s: ERGO Insurance Pte Ltd

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SLZ 5769D


We thank you for your instruction on 18/7/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 19/7/2018 at the premises of M/s UNITED SG AUTOMOBILE PTE LTD

| | |
|--------------------------|--------------------------|
| Workshop Estimate Amount | : S\$3,630.53 |
| Revised Estimate Amount | : S\$1,300.00 (LUMP SUM) |
| "Check" Items Amount | : S\$ |
| Market Value | : S\$ |
| LTA Reimbursement Value | : S\$ |
| Nett Value | : S\$ |

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer arrange on 19/07/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]

Sent: Wednesday, 18 July 2018 3:55 PM

To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>

Cc: 'ASSIGNMENTS@LKKAUTO.COM' <ASSIGNMENTS@LKKAUTO.COM>

Subject: OI : GBB562K / TP : SLZ5769D/LKK / DOA : 10/07/2018

Dear Catherine / Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD – MR ADRIAN** to be the "Single Joint Expert".

Please conduct this survey request from **UNITED SG AUTOMOBILES PTE LTD.**

ADDRESS : 53 UBI AVENUE 1
#01-56 PAYA UBI INDUSTRIAL PARK
SINGAPORE 408934

PERSON TO CONTACT : CHRIS @ 6747 4454

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached is TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID: +65 6829 9194
Tel: +65 6829 9199
Fax: +65 6829 9247

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers



AVG

This email has been checked for viruses by AVG antivirus software.

www.avg.com

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 20 July 2018 1:23 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: GBB562K / TP : SLZ5769D/LKK / DOA : 10/07/2018

Dear Pei Li,

Please be informed that we have inspected the vehicle SLZ 5769D on 19/7/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 18 July 2018 5:13 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GBB562K / TP : SLZ5769D/LKK / DOA : 10/07/2018

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer arrange on 19/07/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Wednesday, 18 July 2018 3:55 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: 'ASSIGNMENTS@LKKAUTO.COM' <ASSIGNMENTS@LKKAUTO.COM>
Subject: OI : GBB562K / TP : SLZ5769D/LKK / DOA : 10/07/2018

Dear Catherine / Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD – MR ADRIAN** to be the "Single Joint Expert".

Please conduct this survey request from **UNITED SG AUTOMOBILES PTE LTD.**

ADDRESS : 53 UBI AVENUE 1
#01-56 PAYA UBI INDUSTRIAL PARK
SINGAPORE 408934

PERSON TO CONTACT : CHRIS @ 6747 4454

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached is TP's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
Tel : +65 6829 9199
Fax : +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Wednesday, 18 July 2018 3:55 PM
To: 'admin-d@lkkauto.com'
Cc: 'ASSIGNMENTS@LKKAUTO.COM'
Subject: OI : GBB562K / TP : SLZ5769D/LKK / DOA : 10/07/2018
Attachments: SLZ5769D - SAS.pdf; SLZ5769D - PRS FORM.pdf; RE: PRI SURVEY FOR SLZ5769D HYUNDAI ELANTRA / DOA: 10 JULY 2018 / YOUR RE... (431 KB)

Dear Catherine / Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD – MR ADRIAN** to be the "Single Joint Expert".

Please conduct this survey request from **UNITED SG AUTOMOBILES PTE LTD,**

ADDRESS : 53 UBI AVENUE 1
#01-56 PAYA UBI INDUSTRIAL PARK
SINGAPORE 408934

PERSON TO CONTACT : CHRIS @ 6747 4454

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached is TP's SAS (**note: reports not to be released to any Third Party**).

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
Tel. : +65 6829 9199
Fax : +65 6829 9247

www.ergo.com.sg

ERGO

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 18.07.2018
Our Reference: GBB 562K/SL/pl
Your Reference: USG-201807-12

Sent via Fax ☐
or
Email ☐ chris@unitedsg.com.sg

To: UNITED SG AUTOMOBILE PTE LTD

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLZ 5769D
Insured's Vehicle: GBB 562K
Date Of Accident: 10.07.2018


We acknowledge receipt of your request for PRS on: 18.07.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK.

| | | | |
|-----|--|-----|--------------------------------|
| AIS | Automobile Inspection Services Pte Ltd | LBS | L.B.S Auto Consultants Pte Ltd |
| FTA | FormTeam Consultancy Pte Ltd | LKK | LKK Auto Consultants Pte Ltd |
| IAS | Infiniti Appraisal Service | PS | Priority Services |
| JPK | JP Knights Pte Ltd | VAC | Vicom Ltd |
| | | | |

| | |
|-------------------------------------|--|
| <input checked="" type="checkbox"/> | Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy. |
| <input type="checkbox"/> | Your request for inspection does not have your client's GIA report, kindly forward a copy. |
| <input type="checkbox"/> | We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate. |
| <input checked="" type="checkbox"/> | Our Insured's driver has not reported the accident to us to date. |
| <input checked="" type="checkbox"/> | Others: <u>OFFICER-IN-CHARGE - STEVE LIM</u> |

| | | | |
|--------------|---|-----------|---------------------------|
| Prepared by: | <u>Pei Li</u> | 6829 9194 | <u>claims@ergo.com.sg</u> |
| Signature: |  | | <u>FAX : 6829 9247</u> |

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

United SG Automobile Pte Ltd

"We are always in your journey"....

53 Ubi Avenue 1 #01-56 Paya Ubi Industrial Park Singapore 408934
Tel : 6747 4454 | Fax : 6747 7752 | Email: claims@unitedsg.com.sg
UEN No. 201729521C | GST No: 201729521C

TP Ergo KMHD841CMJ4686081
Vacon

ESTIMATION QUOTE

ERGO INSURANCE PTE LTD
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
ATTN: MOTOR CLAIMS DEPARTMENT

VEHICLE NO : SLZ5769D
MAKE MODEL : HYUNDAI ELANTRA
REFERENCE : USG-201807-12
DOA : 10-Jul-18
CLAIM TYPE : TP CLAIM

PAGE 1 OF 1

| LIST ITEMS | QTY | LIST PRICE (\$) | REMARKS |
|---|-----|-----------------|---------------|
| REAR BUMPER <i>Deband</i> | 1 | \$ 693.50 | <i>495</i> |
| REAR BUMPER RETAINER <i>new</i> | 2 | \$ 139.20 | <i>✓</i> |
| REAR BUMPER BRACKET <i>new</i> | 2 | \$ 158.42 | <i>x</i> |
| REAR BUMPER REINFORCEMENT <i>Bent</i> | 1 | \$ 390.00 | <i>328</i> |
| REAR BUMPER SPONGE <i>new</i> | 1 | \$ 139.00 | <i>x</i> |
| REAR BUMPER LOWER GARNISH <i>Deband</i> | 1 | \$ 490.20 | <i>280.10</i> |
| REAR BUMPER REFLECTOR <i>new</i> | 2 | \$ 190.34 | <i>x</i> |

1242.30

993.84

\$ 2,200.66
LESS 20% \$ 440.13
SUBTOTAL \$ 1,760.53
BALANCE C/F \$ 1,760.53

| SPECIAL NETT ITEMS | QTY | LIST PRICE (\$) | REMARKS |
|--------------------|-----|-----------------|---------|
|--------------------|-----|-----------------|---------|

BALANCE B/F \$ 1,760.53

| | | | |
|--------------------------------|-------|-----------|------------|
| REAR BUMPER CLIP <i>new</i> | 1 SET | \$ 60.00 | <i>50</i> |
| REAR REVERSE SENSOR <i>new</i> | 1 SET | \$ 400.00 | <i>200</i> |

230

SUBTOTAL \$ 460.00
BALANCE C/F \$ 2,220.53

| LABOUR | S/NO | LIST PRICE (\$) | REMARKS |
|--------|------|-----------------|---------|
|--------|------|-----------------|---------|

BALANCE B/F \$ 2,220.53

| | | | |
|--|---|-----------|------------|
| CHECK REAR WIRING AND LIGHTNING SYSTEM | 1 | \$ 60.00 | <i>30</i> |
| REMOVE AND RENEW REAR REVERSE SENSOR | 2 | \$ 150.00 | <i>50</i> |
| PANEL BEARTING ON AFFECTED AREAS | 3 | \$ 500.00 | <i>200</i> |
| SPRAY PAINTING ON AFFECTED AREAS | 4 | \$ 600.00 | <i>200</i> |
| APPLY ANTI RUST ON AFFECTED AREAS | 5 | \$ 100.00 | <i>x</i> |

SUBTOTAL \$ 1,410.00

480

GRAND TOTAL \$ 3,630.53

total: 1703.84
2/c 1.3K
0.30 days

- LKK Auto Consultants hence notify
- To resurvey before and after repair
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|---|-----------------------------|------------|---|
| ERGO INSURANCE PTE LTD | | Ref : CS/EGI18013090/Avd3n2 | | |
| 5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985 | | Date : 14-08-2018 | |  |
| | | Code : EGI | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | GBB 562K | Veh. Inspected | SLZ 5769D | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | GBB562K/SL/pl | Excess (\$) | 0.00 | |
| Assign From | YEE PEI LI | Assign Date | 18/07/2018 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | HYUNDAI ELANTRA | c.c | 1591 | |
| Engine No. | HIDDEN | Year of Reg. | 2018 | |
| Chassis No. | KMHD841CMJU686081 | Colour | GREY | |
| Odometer | 5822 | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 195/65 R15 | NEXEN | 6 mm | |
| L/H Front Tyre | 195/65 R15 | NEXEN | 6 mm | |
| R/H Rear Tyre | 195/65 R15 | NEXEN | 6 mm | |
| L/H Rear Tyre | 195/65 R15 | NEXEN | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 10/07/2018 | Inspection Date | 19/07/2018 | |
| Survey held at | UNITED SG AUTOMOBILE PTE LTD 53 UBI AVENUE 1 #01-56 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 3 Working Days | | |

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 5769D

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|--|---------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | REAR BUMPER | DEFORMED | 693.50 | 495.00 |
| 2 | REAR BUMPER RETAINER | NECESSARY | 139.20 | 139.20 |
| 2 | REAR BUMPER BRACKET | NOT NECESSARY | 158.42 | - |
| 1 | REAR BUMPER REINFORCEMENT | BENT | 390.00 | 328.00 |
| 1 | REAR BUMPER SPONGE | NOT NECESSARY | 139.00 | - |
| 1 | REAR BUMPER LOWER GARNISH | DEFORMED | 490.20 | 280.10 |
| 2 | REAR BUMPER REFLECTOR | NOT NECESSARY | 190.34 | - |
| | LESS 20% DISCOUNT | | -440.13 | -248.46 |
| | | | 1,760.53 | 993.84 |
| SPECIAL NETT ITEMS | | | | |
| 1 | SET REAR BUMPER CLIP (SN) | NECESSARY | 60.00 | 30.00 |
| 1 | SET REAR REVERSE SENSOR (SN) | DAMAGED | 400.00 | 200.00 |
| | | | 460.00 | 230.00 |
| LABOUR | | | | |
| | CHECK REAR WIRING AND LIGHTING SYSTEM. | | 60.00 | 30.00 |
| | REMOVE AND RENEW REAR REVERSE SENSOR. | | 150.00 | 50.00 |
| | PANEL BEATING ON AFFECTED AREAS. | | 500.00 | 200.00 |
| | SPRAY PAINTING ON AFFECTED AREAS. | | 600.00 | 200.00 |
| | APPLY ANTI-RUST ON AFFECTED AREAS. | NOT NECESSARY | 100.00 | - |
| | | | 1,410.00 | 480.00 |
| GRAND TOTAL | | | 3,630.53 | 1,703.84 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 1,300.00 |

Report Ref No. CS/EG118013090/Avd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.