

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : GX 4292 MMake & Model : KIA PREGIOYear of Manufacture : Chassis No. : KNCTB241247151986Unit : Engine No. : Vehicle Type : Policy No. : Suggested Days of Repair : 10Time of Accident : Contractor : INDECO**Repair Estimates**Parts (a) Cost / List Price Items \$ 7,145.20Plus/Less 10% \$ 714.52Total of Cost / List \$ 6,430.68(b) Nett Price Items \$ -Less \$ -Total of Nett Item \$ -(c) Special Nett Items \$ 710.00Total Parts Cost (Appendix A) \$ 7,140.68Labour (Appendix B) \$ 4,850.00Total Repair Cost \$ 11,990.68

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Guo Qiang - 82880282Company : UtkSurvey conducted on : 19/7/18 at Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 6 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ (e) Signature of surveyor : Date:

*Lumpsum Repair
After repair photos.*



VEHICLES & EQUIPMENT DIVISION

No. 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736

ANSON 85114276 FAX:62860908

ESTIMATED REPAIR COST DETAILSVehicle No : GX 4292 MCase Owner : 0Make & Model : KIA PREGIOYear Manufacture : 0Chassis No : KNCTB241247151986Engine No : TP

Date & Time : _____

Supplier : JAE KOW

Order By : _____

Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N
1	REAR WINDSCREEN MOULDING / <i>ML</i>	1		\$ 758.00		
2	SEALANT / <i>ML</i>	1				\$ 40.00
3	LOGO KIA / <i>ML</i>	1		\$ 42.00		
4	70 KM STICKER / <i>ML</i>	1				\$ 20.00
5	GREEN SPOT STICKER / <i>ML</i>	1				\$ 20.00
6	INDECO STICKER / <i>ML</i>	1				\$ 80.00
7	COMPANY ART WORK STICKER / <i>ML</i>	1				\$ 150.00
8	TAILGATE / <i>Buc</i>	1		\$ 1,356.00		
9	TAILGATE DAMPER RH X <i>SMV</i>	1		\$ 122.00		
10	TAILGATE DAMPER LH X <i>SMV</i>	1		\$ 122.00		
11	TAILGATE LOCK X <i>OM</i>	1		\$ 121.00		
12	TAILGATE LOCK CATCH X <i>NV</i>	1		\$ 29.00		
13	TAILGATE LAMP LH / <i>scr</i>	1		\$ 144.00		
14	TAILGATE LAMP RH / <i>scr</i>	1		\$ 144.00		
15	REAR NUMBER PLATE / <i>mis</i>	1				\$ 45.00
16	REAR BUMPER / <i>re</i>	1		\$ 595.00		
17	REAR BUMPER RETAINER RH / <i>re</i>	1		\$ 56.10		
18	REAR BUMPER RETAINER LH / <i>re</i>	1		\$ 56.10		
19	REAR BUMPER REINFORCMENT ?	1		\$ 350.00		
20	REVERSE SENSOR <i>DM</i>	1				\$ 250.00
21	REAR END PANEL X <i>repair</i>	1		\$ 762.00		
22	BONNET / <i>Buc</i>	1		\$ 285.00		
23	BONNET HINGE RH X <i>SMV</i>	1		\$ 39.00		
24	BONNET HINGE LH X <i>SMV</i>	1		\$ 39.00		
25	BONNET LOCK / <i>BT</i>	1		\$ 54.00		
26	BONNET LOCK CATCH X <i>NV</i>	1		\$ 36.00		
27	FRT GRILLE / <i>Cut</i>	1		\$ 338.00		
28	HEADLAMP RH / <i>CMA</i>	1		\$ 314.00		
29	SIDE RH X <i>NV</i>	1		\$ 91.00		
30	HEADLAMP LH / <i>CMA</i>	1		\$ 314.00		

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL

\$ - \$ 6,167.20 \$ - \$ 605.00



VEHICLES & EQUIPMENT DIVISION

No . 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

Vehicle No : GX 4292 MCase Owner : 0Make & Model : KIA PREGIOYear Manufacture : 0Chassis No : KNCTB241247151986Engine No : TPDate & Time : 0Supplier : JAE KOWOrder By : 0Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N
31	SIDE LAMP LH <i>X NN</i>	1		\$ 91.00		
32	FRT BUMPER <i>/ RC</i>	1		\$ 365.00		
33	FRT BUMPER RETAINER RH <i>X NN</i>	1		\$ 17.00		
34	FRT BUMPER RETAINER LH <i>X NN</i>	1		\$ 17.00		
35	FRT BUMPER REINFORCEMENT <i>X NN</i>	1		\$ 488.00		
36	FRT NUMBER PLATE <i>/ Cust</i>	1				\$ 45.00
37	RHF DOOR ROC STICKER <i>X NN</i>	1				\$ 20.00
38	LHF DOOR ROC STICKER <i>X NN</i>	1				\$ 20.00
39	BONNET GREEN SPOT STICKER <i>/ RC</i>	1				\$ 20.00
40	0	1				
41	0	1				
42	0	1				
43	0	1				
44	0	1				
45	0	1				
46	0	1				
47	0	1				
48	0	1				
49	0	1				
50	0	1				
51	0	1				
52	0	1				
53	0	1				
54	0	1				
55	0	1				
56	0	1				
57	0	1				
58	0	1				
59	0	1				
60	0	1				

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL

\$ - \$ 978.00 \$ - \$ 105.00



Tel: (65) 382 2736 FAX: (65) 6382 2817

Vehicle No.	:	<u>GX 4292 M</u>
Make & Model	:	KIA PREGIO

Case Owner	0
:	0

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.