



**AIG Asia Pacific Insurance Pte. Ltd.**  
78 Shenton Way  
AIG Building, #07-16  
Singapore 079120

Joy

**Attn : Motor Claims Department**

# ESTIMATE

VEHICLE NO. : **SKZ8078G**  
CHASSIS NO : KPTV0B1TSGP109461 /2016  
MAKE / MODEL : SSANGYONG STAVIC 7-SEATER  
DATE OF ACCIDENT : 21/04/2018 @ 22:55HRS  
YOUR INSURED VEHICLE NUMBER : SLF8365X

**PARTS DISCRPTION**

	<u>QTY</u>	<u>Cost Price</u>	<u>Total Cost Price</u>
FRONT BONNET	1	\$ 2,950.00	\$ 2,950.00 X
FRONT GRILLE	1	\$ 1,241.33	\$ 1,241.33 X
FRONT GRILLE "LOGO" EMBLEM	1	\$ 105.00	\$ 105.00 X
FRONT HEADLAMP LH & RH @ 1050	2	\$ 1,580.00	\$ 3,160.00 CA - 2100
FRONT HEADLAMP CLIPS LH & RH	1SET	\$ 40.00	\$ 80.00 ne -
FRONT BUMPER	1	\$ 1,580.00	\$ 1,580.00 repair
FRONT BUMPER CLIPS	1SET	\$ 30.00	\$ 30.00 X
FRONT BUMPER NUMBER PLATE WITH HOLDER	1	\$ 30.00	\$ 30.00 X
FRONT BUMPER LOWER GRILLE	1	\$ 397.95	\$ 397.95 X
FRONT BUMPER CHROME MOULDING LH & RH	2	\$ 251.70	\$ 503.40 X
FRONT BUMPER INNER SPONGE	1	\$ 299.85	\$ 299.85 X
FRONT BUMPER REINFORCEMENT LH & RH	2	\$ 67.00	\$ 134.00 X

2180  
10%  
1962

Total	\$ 7,561.53
LESS 10%	\$ 756.15
<b>TOTAL PARTS</b>	<b>\$ 6,805.38</b>

**LABOUR CHARGES**

TO REMOVE, REPLACE & REPAIR ALL DAMAGES ITEMS  
TO SPRAY PAINT ON THE AFFECTED AREAS DUE TO ACCIDENT

	\$ 750.00	300
	\$ 600.00	250
<b>TOTAL LABOUR</b>	<b>\$ 1,350.00</b>	550

Rasul

Hp 90010068

3 days

4/5

24/07/18 @ 0930

Recy after repair-

**SUB TOTAL \$8,155.38**

1962  
550  
2512  
20%  
2009.60  
4/5 - 2,000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: