

ASS. REC. BY:

REF:

TP /

CS/TP18013102/KHb12

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

G/A / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1. B. 1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Screen

Date / Time

Action / Instruction

19/7 File pass to Catherine

SLW 820M - CS/TP18013102/KHb12

Dof: 190518

23/10 @ 3917-60 Confirm (Red: 4393-72) 52%

RECEIVED 20 OCT 2010

Date/Time, File Pass to?

11/26/10 Typist

Date/Time, File Return to?



: Prell. Report



: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

3917-60

160
50
30
14
80
354

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/07/2018 16:04
Date Of Accident	05/07/2018 14:15
Exact Location Of Accident	PIE TOWARDS LORNIE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW8290M
Insured/Policyholder	
Name Of Registered Owner	KOH LI WEI (XU LIWEI)
NRIC No	S7233594E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84442424
Alternative Phone No	OFFICE-84442424
Vehicle Particulars	
Manufacturer	HONDA
Model	SHUTTLE
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5098339662
Cover Note Number	
Driver	
Name of Driver	KOH LI WEI (XU LIWEI)
NRIC No	S7233594E
Date Of Birth	22/09/1972
Occupation	OUTDOOR
Date Of Driving Pass	07/10/1992
Driving Experience	25 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84442424
Fax Number	
Contact Number	OFFICE-84442424
E Mail Address	NOEMAIL

Address BLK 302B ANCHORVALE LINK #02-186
 Postcode 542302
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? YES
 Foreign Vehicle Registration Number MAM9102 (PRIVATE CAR)
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 3
 Passenger 1 NAME: : GRAB PASSENGER 1
 GENDER: : FEMALE
 Passenger 2 NAME: : GRAB PASSENGER 2
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name THOMSON NPP 25 SIN MING ROAD
 Police Station Address ROAD: 25 SIN MING ROAD #01-180 , POSTCODE: 570025 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: CANNOT BE UPLOADED
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number MAM9102
 Vehicle Make/Model/Colour PROTON /GREEN
 Details Of Properties
 Vehicle Category PRIVATE CAR

Name of Driver
NRIC/Passport Number
Contact Number

NG KEONG LAI
831011-106079
91808498

Address

NO 112 JALAN 022 OZANA IMPIAH 75450 MELAKA

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

05 JUL 2018

Driver's Signature

(If driver is not the policyholder)

Date & Time:

05 JUL 2018



Reporting Centre Personnel's Signature

Name:


NG WING KIN JAMES

NRIC/FIN No.:

S7927881E

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer as police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 05 JUL 2018

Driver's Signature
(If driver is not the policyholder)
Date & Time: 05 JUL 2018



Reporting Centre Personnel's Signature
Name: NG WING KIN JAMES
NRIC/FIN No.: S7927881E



**SINGAPORE
POLICE FORCE**



T/20180705/2104

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

1 of 4

Report No. T/20180705/2104

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/07/2018 15:21	Vide Report No.:	Station Diary No.: 25
--	------------------	--------------------------

Informant's Particulars

Name of Informant: KOH LI WEI			Address: APT BLK 302B ANCHORVALE LINK #02-186 SINGAPORE 542302		
ID Type / ID No.: NRIC NO / S7233594E			Contact No.: Home/Office: Mobile: 84442424		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 45	Date of Birth: 22/09/1972	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class: 3,4,5 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 05/07/2018 14:15	Type of Location: Flyover
Location: Along Road 1 PAN ISLAND EXPRESSWAY towards to Lornie Road Destination trip: 9. Leedon Heights				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Between Moving Vehicles - Head On				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
MAM9102	Car					0
SLW8290M	Car	HONDA	SHUTTLE HYBRID 1.5 AUTO	Silver		2

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
-------------	-------------------	---------------	-----------	-------------



**SINGAPORE
POLICE FORCE**



T/20180705/2104

2 of 4

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

Report No. T/20180705/2104

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SLW8290M	NTUC Income Insurance Co-Operative Limited	5098339662	02/03/2018	01/03/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	Ng Keong Lai		ID No.	831011-10-6079
Related Vehicle	MAM9102 (Car)		Contact No.	91608496
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	KOH LI WEI		ID No.	S7233594E
Related Vehicle	SLW8290M (Car)		Contact No.	84442424
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3,4,5 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details.

On 05th July 2018 at about 2.15pm, I was driving my vehicle registration number: SLW8290M with my 2 female passengers (from Airport T3 arrivals and destinations to 9, Leedon Heights) along PIE towards to Jurong. I was driving on the 1st lane.

While I was driving, there was ahead vehicle making a sudden brake. I managed to apply brake and was in the stationary position. Then, there was an impact from my rear vehicle.

I realised that there was another vehicle registration number: MAM9102 had collided to my rear portion of my vehicle.

The AETOS officers came shortly and my insurance company staffs also at scene. We shifted to the road shoulder. The AETOS officers notified Traffic Police who came shortly to the scene.

I was not injured but I'm not sure whether my passengers are injured. I had reported to GRAB company



**SINGAPORE
POLICE FORCE**



T/20180705/2104

3 of 4

Police Station Of Origin:

Thomson NPP

25 Sin Ming Road #01-180 SINGAPORE

570025

Tel No: 1800-4529999

Report No. T/20180705/2104

CONTINUATION OF REPORT

regarding the occurrences and will check whether the passengers are injured.

I am lodging this report. I wished to state that there are inbuilt cameras (front and rear camera) installed in my vehicle. It captured the occurrences.

Grab Job details: ADR-4559123-5-001



**SINGAPORE
POLICE FORCE**



T/20180705/2104

4 of 4

Police Station Of Origin:
Thomson NPP
25 Sin Ming Road #01-180 SINGAPORE
570025
Tel No: 1800-4529999

Report No. T/20180705/2104

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /
Sr Staff Sgt MOHAMAD FARID BIN JAMAL

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

05/07/2018 15:21

Officer In Charge Of Case:

TP / GIT /
Staff Sgt YAN MINGSHENG DANIEL
Contact No.: 65476252

Classification Of Case:



SINGAPORE
POLICE FORCE

SN 070

Authentication Stamp

NP188

SIGNATURE



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

W
SL# 8290 M

Finalised

Not No hair
1-B.1
Pulley B4 pain

Parts (a) Cost / List Price Items	\$	4,782.90
Plus/Less 20%	\$	956.58
Total of Cost / List	\$	3,826.32
(b) Nett Price Items		
Less		
Total of Nett Item		
(c) Special Nett Items	\$	830.00
Total Parts Cost	\$	4,656.32
Labor	\$	3,660.00
Total	\$	8,316.32

2772
554.40
2217.60

40
2257.60
1760
4017.60 3917.60

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Company

Survey conducted on

Kenneth

CRK

18/7/18

at 12:15pm

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 4-5 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : _____

Date:

18/7/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Parts

No. : **SLQ 8290 M**
Model : **HONDA SHUTTLE**
No : **GP71201626**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :
Cost / List

Part Description	Qty	Unit Price	Price	Disposition by Surveyor
Rear windscreen moulding	1	\$55.00	✓	✓
Rear windscreen sealant	1	\$50.00	✓ S.N	✓
✓ Reverse sensor	1	\$200.00	✓ S.N	✓
Reverse Camera	1	\$580.00	S.N	✗
✓ Rear bumper	1	\$1,150.60	✓	✓
Rear bumper clip	10	\$40.00	✓	✓
Rear bumper side retainer LH	1	\$26.50		✗
Rear bumper side retainer RH	1	\$26.50		✗
Rear bumper sponge	1	\$89.50		✗
Rear bumper reflector LH	1	\$58.00		✗
Rear bumper reflector RH	1	\$58.00		✗
Rear bumper reflector cover LH	1	\$58.00		✗
Rear bumper reflector cover RH	1	\$58.00		✗
✓ Tail door	1	\$1,193.00	✓	✓
Tail door lock	1	\$157.70	✓	✓
Tail door emblem	1	\$38.00	✓	✓
Wording "HYBRID"	1	\$66.20	✓	✓
Wording "SHUTTLE"	1	\$55.00	✓	✓
Tail door chrome	1	\$383.10		✗
Taildoor inner trim	1	\$385.00		✗
Taildoor inner trim clip	8			
Tail end panel	1	\$560.80		✗
Tail end panel garnish	1	\$155.50		✗

If any of the quoted parts are recommended to be repaired, then an additional labour charge is charged accordingly under supplementary.

18 Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Reg No. 200005485N / GST No. 20-0005485-N

2755.50
40 (S.N.)

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SLQ 8290 M

HONDA SHUTTLE

GP71201626

Submit By :
Year Manufacture :
Engine No. :
Cost / List

Carmen Lim

2017

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Boot weatherstrip	1	\$168.50		X
25					
26					
27	Supplementary :-				
29	Rear tow cover RH	1	16.50	✓	
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 6093 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7629 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLQ 8290 M**
Make & Model : **HONDA SHUTTLE**

Submit By : **Carmen Lim**
Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,600.00	500 800?
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,200.00	660
3	To check wiring	\$50.00	20
4	To remove & refit reverse sensor	\$120.00	50
5	To tuff coat	\$180.00	30
6	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. <i>nr</i>	\$150.00	X
7	To remove & refit rear windscreen.	\$120.00	✓
8	To transfer boot mechanism to new boot	\$120.00	60
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20
10			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

1760



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLØ 8290 M

Not Notified
I.B.I
Resurvey By painter

Parts	(a) Cost / List Price Items	\$	4,782.90
	Plus/Less 20%	\$	956.58
	Total of Cost / List	\$	3,826.32
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	830.00
Total Parts Cost		\$	4,656.32
Labour		\$	3,660.00
Total		\$	8,316.32

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

8329.52

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 18/7/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 4-5 day(s)

(c) Resurvey : Required / ~~Not~~ Required

(d) Excess : \$ _____

(e) Signature of surveyor : De

Date: 18/7/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLQ 8290 M**
Make & Model : **HONDA SHUTTLE**
Chassis No : **GP71201626**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding	1	\$55.00		✓
2	Rear windscreen sealant	1	\$50.00	S.N	4020
3	Reverse sensor	1	\$200.00	S.N	✓
4	Reverse Camera	1	\$580.00	S.N	?
5	Rear bumper	1	\$1,150.60		✓
6	Rear bumper clip	10	\$40.00		✓
7	Rear bumper side retainer LH	1	\$26.50		X
8	Rear bumper side retainer RH	1	\$26.50		X
9	Rear bumper sponge	1	\$89.50		?
10	Rear bumper reflector LH	1	\$58.00		X
11	Rear bumper reflector RH	1	\$58.00		X
12	Rear bumper reflector cover LH	1	\$58.00		?
13	Rear bumper reflector cover RH	1	\$58.00		X
14	Tail door	1	\$1,193.00		✓
15	Tail door lock	1	\$157.70		✓
16	Tail door emblem	1	\$38.00		✓
17	Wording "HYBRID"	1	\$66.20		✓
18	Wording "SHUTTLE"	1	\$55.00		✓
19	Tail door chrome	1	\$383.10		X
20	Taildoor inner trim	1	\$385.00		?
21	Taildoor inner trim clip	8			
22	Tail end panel	1	\$560.80		?
23	Tail end panel garnish	1	\$155.50		?

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : SLQ 8290 M
Make & Model : HONDA SHUTTLE
Chassis No : GP71201626

Submit By : Carmen Lim
Year Manufacture : 2017
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Boot weatherstrip	1	\$168.50		X
25					
26					
27					
28					
29					
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLQ 8290 M** Submit By : **Carmen Lim**
Make & Model : **HONDA SHUTTLE** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,600.00	?
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL)	\$1,200.00	8601
3	To check wiring	\$50.00	201
4	To remove & refit reverse sensor	\$120.00	501
5	To tuff coat	\$180.00	301
6	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	?
7	To remove & refit rear windscreen.	\$120.00	✓
8	To transfer boot mechanism to new boot	\$120.00	601
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	201
10			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ESTEEM PERFORMANCE PL *

Ref : CS/TP18013102/Ktbn2

BLK 5033, #01-259, ANG MO KIO INDUSTRIAL PARK 2, SINGAPORE 569536

Date : 05-11-2018



ON BEHALF OF KOH LI WEI (XU LIWEI)

Code : TP053

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SLW 8290M
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	18/07/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	GP71201626	Colour	METALLIC GREY
Odometer	41753	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/45 R16	YOKOHAMA	8 mm
L/H Front Tyre	205/45 R16	YOKOHAMA	8 mm
R/H Rear Tyre	205/45 R16	YOKOHAMA	8 mm
L/H Rear Tyre	205/45 R16	YOKOHAMA	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	05/07/2018	Inspection Date	18/07/2018
Survey held at	385 SIN MING DRIVE		
Repairer	ESTEEM PERFORMANCE PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 8290M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR WINDSCREEN MOULDING	NECESSARY	55.00	55.00
1	REAR BUMPER	BENT	1,150.60	1,150.60
10	REAR BUMPER CLIP	NECESSARY	40.00	40.00
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	26.50	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	26.50	-
1	REAR BUMPER SPONGE	SERVICEABLE	89.50	-
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	58.00	-
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	58.00	-
1	REAR BUMPER REFLECTOR COVER LH	SERVICEABLE	58.00	-
1	REAR BUMPER REFLECTOR COVER RH	SERVICEABLE	58.00	-
1	TAIL DOOR	BENT	1,193.00	1,193.00
1	TAIL DOOR LOCK	DENTED	157.70	157.70
1	TAIL DOOR EMBLEM	NECESSARY	38.00	38.00
1	WORDING "HYBRID"	NECESSARY	66.20	66.20
1	WORDING "SHUTTLE"	NECESSARY	55.00	55.00
1	TAIL DOOR CHROME	SERVICEABLE	383.10	-
1	TAIL DOOR INNER TRIM }	SERVICEABLE	385.00	-
8	TAIL DOOR INNER TRIM CLIP }	SERVICEABLE	-	-
1	TAIL END PANEL	TO REPAIR SEE LABOUR	560.80	-
1	TAIL END PANEL GARNISH	SERVICEABLE	155.50	-
1	REAR TOW COVER RH	MISSING	16.50	16.50
1	BOOT WEATHERSTRIP	SERVICEABLE	168.50	-
	LESS 20% DISCOUNT		-959.88	-554.40
			3,839.52	2,217.60
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REVERSE SENSOR (SN)	DENTED	200.00	200.00
1	REVERSE CAMERA (SN)	SERVICEABLE	580.00	-
			830.00	240.00

Report Ref No. CS/TP18013102/Ktbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL, SPARE TYRE WELL PANEL) INCLUSIVE OF THE REPAIR OF TAIL END PANEL.		1,600.00	500.00
	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR, END PANEL, SPARE TYRE WELL PANEL)		1,200.00	660.00
	TO CHECK WIRING.		50.00	20.00
	TO REMOVE & REFIT REVERSE SENSOR.		120.00	50.00
	TO TUFF COAT.		180.00	30.00
	TO REMOVE & REFIT SPARE TYRE, SPARE TYRE BOARD, CARPET TRIM TO ASSIST WORK LOAD.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT REAR WINDSCREEN.		120.00	120.00
	TO TRANSFER BOOT MECHANISM TO NEW BOOT.		120.00	60.00
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PREPER AIR AND SEALING.		120.00	20.00
			3,660.00	1,460.00
	GRAND TOTAL		8,329.52	3,917.60
	RECOMMENDED COST OF REPAIRS			3,917.60

Report Ref No. CS/TP18013102/Ktbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.