

ASS. REC. BY:

REF

CS3/CTI18013109/R124d3⁴²

Special Instruction:

Surveyor

Mennen

Rasul

ASSIGNMENT (Office)

From (Person)

Elaine Cheong

of

CTI

Date/Time

19/7/18 @ 9.22am

Estimated Cost

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGW 3437A

Insured:

SJP 2198Y

at Workshop m/z

Hwa peng Auto

Tel:

9688 5655

of

70 woodlands Ind. park E9

Policy No:

DMPCSN3024301800

Claim No:

8NM18D03507C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13/7/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

10:16am @ 19/7/18

Person Contacted:

Francis

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SGW 3437A - CTI / AIG 12010611 / C pup 1 DOA: 27/05/2012
	SJP 2198Y - X
20/7/18	Dismantled.

(08/11/13) Wef

ASS. REC. BY: P. Ram

REF: CTI

ASSIGNMENT

From:

Date: 19/7/2018

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SGW 3437A

at Workshop m/s

of

Hwa Peng Auto
70 Woodlands Ind. Park E9

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


Make of Veh:

Francis @ 9688 5655

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6 days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS ^{1 up}

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGW 3437A

Yr Regn:

JUL / 2007Type: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA VIOS

C.C.

1497

Colour:

GLD

A/C:

Insured / Std / NI / NA

Sp. Reading

265697

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR053HY9305013522Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

19/07/18

Survey held at

Hwa PengDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/8Estimated repair range \$4500 - \$5000
Submit PRS report.1/8/18

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format : PRS

Lump Sum / I.B.I: (\$




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS3/CTI18013109/R1z4d3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 19-07-2018	
		Code : CTI	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SJP 2198Y	Veh. Inspected	SGW 3437A
Policy No.	DMPCSN3024301800	Coverage (\$)	0.00
Claim No.	SNM18D03507C02	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE CHEONG)	Assign Date	19/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	13/07/2018	Inspection Date	19/07/2018
Survey held at	HWA PENG AUTO SERVICE (1996) 70 WOODLAND INDUSTRIAL PARK E SINGAPORE 757836		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jul 2018		19 Jul 2018 09:22 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	DRAGON WORLD INVESTMENT PTE LTD		
Vehicle Reg. No.:	SGW3437A	Date of Loss:	13/07/2018 00:00 - :59
Claim Type:	TP / SNM18D03507C02	Policy/Cover Note No.:	DMPCSN3024301800
Vehicle Reg. No. (Insured):	SJP2198Y	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Hwa Peng Auto Service (1996) (HQ) 70 WOODLANDS INDUSTRIAL PARK E9, 757836 Woodlands - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/07/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

From: Cheong Hoh Lee <mail@cheonghoh.sg>
Sent: Wednesday, 18 July, 2018 3:12 PM
To: Lucas Lee
Subject: Re: PRS FOR SGW3437A (CTI: SNM18D03507C02) (Yr Ref: LCH.my/W1HP-80639.18)

Dear Lucas,

We refer to the above matter and your email.

Pursuant to the NIMA protocol of the Practice Directions Amendment No. 1 of 2016, we have our client's instructions to reject your list of appointed surveyors as stated in your aforesaid letter.

We are further instructed to append below our client's 10 proposed surveyors as follows :-

- (1) Jeffery Ong Leng Kiat
- (2) Fong Kok Heng
- (3) Chang Fuh Keong
- (4) T Rajan
- (5) Ng Soon Chuan Louis
- (6) Ng Soon Aik Francis
- (7) Jayson Liaw Leong San
- (8) Lee Kok Weng
- (9) Loi Boon Juan
- (10) How Andrew

If you are not agreeable to our list of surveyors above, kindly appoint your surveyor to proceed with the pre-repair survey ("PRS") of our client's vehicle no. SGW 3437 A at our client's repairer workshop as follows :-

Hwa Peng Auto Service (1996)
Blk 70 Woodlands Industrial Park E
Singapore 757836

Person to contact : Francis (mobile no. 9688 5655)

Regards,
Melody
Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 6337 8700
Fax: 6337 3700

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SGW3437A
Vehicle Type:	Z10 - Private Hire (Chauffeur) Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Chassis No.:	MR053HY9305013522
Propellant:	Petrol
Engine No.:	1NZX581690
Engine Capacity:	1497 cc
Maximum Power Output:	80.0 kW (107 bhp)
Maximum Laden Weight:	1505 kg
Unladen Weight:	1095 kg
Year Of Manufacture:	2007
Original Registration Date:	13 Jul 2007
Lifespan Expiry Date:	-
COE Category:	A - Car (1600cc & below)
PQP Paid:	\$24,100.00
COE Expiry Date:	12 Jul 2022
Road Tax Expiry Date:	12 Jan 2019
Inspection Due Date:	12 Jul 2019
Intended Transfer Date:	23 Jul 2018
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Jul 2018		19 Jul 2018 09:22 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -			[Created by Insurer]	
Main Claimant:	DRAGON WORLD INVESTMENT PTE LTD				
Vehicle Reg. No.:	SGW3437A		Date of Loss:	13/07/2018 00:00 - :59 [132 Months From LTA Reg Date (Man Yr)]	
Claim Type:	TP / SNM18D03507C02		Policy/Cover Note No.:	DMPCSN3024301800	
Vehicle Reg. No. (Insured):	SJP2198Y		Policy No. (Claimant):		
			Excess:	S\$0.00	
Repairer:	Hwa Peng Auto Service (1996) (HQ) 70 WOODLANDS INDUSTRIAL PARK E9, 757836 Woodlands - Tel:				
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 30/07/2018]				
Adj Asg. Remarks:	NO EST, CASE W/O SJE.				

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

*SGW3437A (SNM18D03507C02)
[SJP2198Y]

TP

DRAGON WORLD INVESTMENT PTE LTD
Jul 13 2018 12:00AM

[-]

Hwa Peng Auto Service (1996)

[Upload Documents](#) [Upload Photos](#) [Compose New Letter](#)

View [View in Browser](#) ▼

Documentation				1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	19/07/18 09:21	PRS		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/07/18 10:38	LKKPhotosIn6-1.pdf		Load PDF	
2	23/07/18 10:38	LKKPhotosIn6-2.pdf		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18013109/R1Z4D3S2

Date: 02/08/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN3024301800

Claimant Vehicle No: SGW3437A Insured Vehicle No: SJP2198Y

Date of Loss: 13/07/2018 Nature of Claim: TP Claim No: SNM18D03507C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGW3437A**

Make & Model: TOYOTA VIOS, 1.5 (A) Engine No: 1NZX581690

Reg. Date: 13/07/2007 (Man. Year: 2007) Chassis No: MR053HY9305013522

Colour: Gold Odometer: 265097 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15

Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 19/07/2018

Date Inspected: 19/07/2018 Inspected At: Hwa Peng Auto Service
70 WOODLANDS INDUSTRIAL PARK E9
Singapore 757836

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500.00 - \$5,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Aug 2018)

Parts: 143 TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGW3437A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >