

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 23 Jul 2018

Preliminary Advice

Insured Vehicle No	: SJU7370G	Accident Date	: 10/06/2018
TP Vehicle No	: SLH2958P	Assignment Date	: 18/07/2018
Make	: MAZDA MAZDA5	Est. Duration of Repair	: 2.00
Date of Inspection	: 20/07/2018		
Inspection At	: TRANS EUROKARS PTE LTD (HQ) 5 UBI CLOSE SINGAPORE 408605		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,896.16
Revised Amount	:S\$	2,719.43
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,719.43

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.