

610, Serangoon Road S(218216)
Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

ASSESSMENT FOR REPAIR: HONDA CB400 - FBJ3478J

Engine No.: NC42E1126504

[illegible]

Less discount 10%

\$1,319.90

\$11,879.10

Special nett items

1 pc	Front sport rim	\$790.00 <i>Rp</i>
3 pcs	Engine oil @ \$35.00	\$105.00 <i>X hn</i>
1 pc	Box rack	\$195.00 <i>bt ✓</i>
1 pc	Top case	\$350.00 <i>out ✓</i>
1)	Towing charges	\$100.00 <i>80</i>
	Replace, realign and adjust above	
	damaged parts, check wiring and	
2)	lighting system	\$700.00 <i>400</i>
	To replace and balance front and	
3)	rear wheel rim	\$150.00 <i>30</i>
	To knock, straighten chassis & body	
4)	balancing	\$450.00 <i>250 photo</i>
	To remove/refit, replace (if damage) check and	
5)	straighten front fork tubes.	\$180.00 <i>140</i>
6)	Spray painting	\$480.00 <i>300</i>
7)	Antirust application	\$80.00 <i>30</i>

Total Estimate

\$15,459.10

Note: The above estimate is subjected to the prevailing GST of 7%

17,560.60



For Bike Production Pte Ltd

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Kah 97495749
62563561

'WP' 20/7/18 R 1515

Lumpsum

Resurvey after repair

6 days.

Suo@lkkauto.com

Signature
25/7/18