

John

REF:

C9/KC118013122/KHd3e2


1345N

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

Veh No: **SLQ 9260A** Yr Regn: **2017 July**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **MAZDA 3** C.C. **1496**
 Colour: **Brown** A/C: Insured / Std / NI / NA
 Sp Reading: **47184** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **3M 66N 22A 846152928**
 Gen. Cond: Good / **Fair** / Poor / Burnt
 Steering: **In order** / Jammed / Leaked / Burnt or
 Brake: **In order** / Jammed / Leaked / Burnt or
 Modi: Nil / **S/Ren** / STD A/Rim or
 Tyre Size: F: **205/60R16**
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **WISDOM**
 Front **6** mm Rear **6** mm
 R/Bal. **6** mm L/Bal. **6** mm
 D.O.A. **18/07/18** D.O.I. **20/07/18**
 Survey held at **PEGANUS**
 Des. of Damages: Frt / **Rear** / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 25 MAR 2019

re submit final figure to \$8072.04 *Celene* 3/5/19

6/5/19 184 D02 16/3/19 / 180000 net only ↓

Date/Time, File Pass to?

☐ : Preli. Report
☒ : Final Report

12/3 Typist
 Date/Time, File Return to?

Days Of Repair: **9**

Resurvey No. of Trip: **3**

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech Invs (\$)
☐ : Weekend (\$)

Survey Fee:
 Transportation:

) S + RS \$

) Photos

) Others

)

TOTAL

3x152.4

170 + 45
 50
 50 + 50 + 50
 105

520

Report Format :

Lump Sum / I.B.I. (\$ **6368.84**)

8072.04

TP

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No :
---	--

Quotation No. : QO18/07-1235	Quotation Date : 18/07/2018	Terms : 30 DAYS
Vehicle No. : SLQ9260A	Chassis No. : JM6BN22A8H0152924	Third Party Insurer : FIRST CAPITAL
Model : MAZDA 3	Date of Accident : 18/07/2018	
Remarks : INSURED'S VEH NO: SH6880U		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	BOOTLID	1	958.0000	958.00
2	BOOTLID MAZDA 3 BADGE	1	54.0000	54.00
3	BOOTLID SKYACTIV BADGE	1	64.0000	64.00
4	BOOTLID CENTRE EMBLEM BADGE	1	75.0000	75.00
5	BOOTLID REFLECTORS	2	265.0000	530.00
6	BOOTLID INNER TRIM	1	121.0000	121.00
7	BOOTLID INNER TRIM CLIPS	4	5.0000	20.00
8	BOOTLID RUBBER STOPPERS	2	13.0000	26.00
9	BOOTLID LOCK	1	153.0000	153.00
10	BOOTLID STRIKER BOTTOM	1	35.0000	35.00
11	BOOTLID WEATHERSTRIP	1	130.0000	130.00
12	BOOTLID HINGES	2	146.0000	292.00
13	BOOTLID KEYLESS SENSOR	1	78.0000	78.00
14	REAR END PANEL	1	506.0000	506.00
15	REAR END PANEL INNER TRIM	1	86.0000	86.00
16	REAR END PANEL INNER TRIM CLIPS	4	5.0000	20.00
17	REAR LAMPS	2	504.0000	1,008.00
18	REAR LAMP PANEL	2	358.0000	716.00
19	REAR LAMP HOLDER CLIPS	8	26.7000	213.60
20	REAR BUMPER	1	1,075.0000	1,075.00
21	REAR BUMPER REFLECTORS	2	51.0000	102.00
22	REAR BUMPER END SPLASHIELD COVER	1	80.0000	80.00
23	REAR BUMPER CLIPS	10	5.0000	50.00

2018 Bumper Centre bracket (Plastic) - CR4 / 35

C/F 0.00

PEGASUS **ENGINEERING & TRADING PTE LTD**

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :

Customer : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No :
--

Quotation No. : QO18/07-1235	Quotation Date : 18/07/2018	Terms : 30 DAYS
Vehicle No. : SLQ9260A	Chassis No. : JM6BN22A8H0152924	Third Party Insurer : FIRST CAPITAL
Model : MAZDA 3	Date of Accident : 18/07/2018	
Remarks : INSURED'S VEH NO: SH6880U		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	REAR BUMPER REINFORCEMENT	1	538.0000 <i>TH</i>	538.00
25	REAR BUMPER SIDE RETAINERS	2	37.0000 <i>an</i>	74.00
26	REAR BUMPER SIDE HOLDERS	2	46.0000 <i>an</i>	92.00
27	REAR BUMPER SIDE HOLDER RIVETS	4	9.0000 <i>an</i>	36.00
28	REAR BUMPER TOW COVER	2	18.0000 <i>an</i>	36.00
29	REAR BUMPER SCREW SPACER	4	8.0000 <i>an</i>	32.00
30	REAR LUGGAGE FLOOR PANEL TRIMBOARD	1	350.0000 <i>X</i>	350.00
31	REAR LUGGAGE FLOOR FOAM COMPARTMENT TOOL	1	166.0000 <i>X</i>	166.00
32	REAR LICENSE PLATE LAMP	2	72.0000 <i>X</i>	144.00
33	REAR LICENSE PLATE GARNISH	1	50.0000 <i>X</i>	50.00
34	REAR FENDER	2	1,175.0000 <i>repair</i>	2,350.00
35	REAR FENDER INNER COWLING	2	235.0000 <i>X</i>	470.00
36	REAR FENDER INNER COWLING CLIPS	8	5.0000 <i>X</i>	40.00
37	REAR FENDER LOWER PANEL	2	356.0000 <i>repair</i>	712.00
38	LESS 20% ON ITEM 1 - 36	1	-2,296.5200	-2,296.52
39	REAR BUMPER PARKING SENSOR	1	450.0000 <i>200 an</i>	450.00
40	REAR LICENSE PLATE	1	80.0000 <i>35 an</i>	80.00
41	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	120.0000 <i>30</i>	120.00
42	TO RUST-PROOFING OF THE AFFECTED AREAS.	1	120.0000 <i>60</i>	120.00
43	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	1	150.0000 <i>80 60</i>	150.00
44	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	1	160.0000 <i>60</i>	160.00

C/F 0.00
Page 2 of 3

11087.60

PEGASUS **ENGINEERING & TRADING PTE LTD**

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : WEE TZE FAH Tel : Email :

Customer : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No :
--

Quotation No. : QO18/07-1235	Quotation Date : 18/07/2018	Terms : 30 DAYS
Vehicle No. : SLQ9260A	Chassis No. : JM6BN22A8H0152924	Third Party Insurer : FIRST CAPITAL
Model : MAZDA 3	Date of Accident : 18/07/2018	
Remarks : INSURED'S VEH NO: SH6880U		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
45	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	1	120.0000 60	120.00
46	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	1,200.0000 800	1,200.00
47	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	1	1,400.0000 1000	1,400.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Repair
Hp 900 10068
9 days
P/P
20/07/18 @ 1716
Resurvey by paint

24/7/2018

Sub Total	12,986.08
GST(7.00%)	909.03
Total (SGD)	13,895.11

Please conduct the survey at
 Pegasus Engineering @ 74 Kian Teck Road Singapore 628800

13010.08

14212.28

PEGASUS
ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :

Customer : GRAB RENTALS 2 PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :

Quotation No. : QO18/08-1033	Quotation Date : 01/08/2018	Terms : 30 DAYS
Vehicle No. : SLQ9260A	Chassis No. : JM8BN22A8H0152924	Third Party Insurer : FIRST CAPITAL
Model : MAZDA 3		Date of Accident : 18/07/2018
Remarks : SUPPLEMENTARY ITEM		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	RH FRONT SEAT	1	2,129.0000	2,129.00
2	LESS 20% ITEM (1)	1	-425.8000	-425.80


Rahul
02/08/18

Sub Total	1,703.20
GST(7.00%)	119.22
Total (SGD)	1,822.42



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 9260A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOTLID	BENT	958.00	958.00
1	BOOTLID MAZDA 3 BADGE	NECESSARY	54.00	54.00
1	BOOTLID SKYACTIV BADGE	NECESSARY	64.00	64.00
1	BOOTLID CENTRE EMBLEM BADGE	NECESSARY	75.00	75.00
2	BOOTLID REFLECTORS @\$265.00	SERVICEABLE	530.00	-
1	BOOTLID INNER TRIM	SERVICEABLE	121.00	-
4	BOOTLID INNER TRIM CLIPS @\$5.00	NECESSARY	20.00	20.00
2	BOOTLID RUBBER STOPPERS @\$13.00	NECESSARY	26.00	26.00
1	BOOTLID LOCK	BENT	153.00	153.00
1	BOOTLID STRIKER BOTTOM	SERVICEABLE	35.00	-
1	BOOTLID WEATHERSTRIP	NECESSARY	130.00	130.00
2	BOOTLID HINGES @\$146.00	SERVICEABLE	292.00	-
1	BOOTLID KEYLESS SENSOR	SERVICEABLE	78.00	-
1	REAR END PANEL	BENT	506.00	506.00
1	REAR END PANEL INNER TRIM	CUT	86.00	86.00
4	REAR END PANEL INNER TRIM CLIPS @\$5.00	NECESSARY	20.00	20.00
2	REAR LAMPS @\$504.00	O/S CRACKED	1,008.00	504.00
2	REAR LAMP PANEL @\$358.00	N/S BENT / O/S TO REPAIR SEE LABOUR	716.00	358.00
8	REAR LAMP HOLDER CLIPS @\$26.70	NECESSARY-4PCS ONLY	213.60	106.80
1	REAR BUMPER	DEFORMED	1,075.00	1,075.00
2	REAR BUMPER REFLECTORS @\$51.00	O/S CRACKED	102.00	51.00
1	REAR BUMPER END SPLASHIELD COVER	SERVICEABLE	80.00	-
10	REAR BUMPER CLIPS @\$5.00	NECESSARY	50.00	50.00
1	REAR BUMPER CENTRE BRACKET (PLASTIC)	CRACKED	35.00	35.00
1	REAR BUMPER REINFORCEMENT	BENT	538.00	538.00
2	REAR BUMPER SIDE RETAINERS @\$37.00	NECESSARY	74.00	74.00
2	REAR BUMPER SIDE HOLDERS @\$46.00	NECESSARY	92.00	92.00
4	REAR BUMPER SIDE HOLDER RIVETS @\$9.00	NECESSARY	36.00	36.00
2	REAR BUMPER TOW COVER @\$18.00	MISSING	36.00	36.00

Report Ref No. CS/FCI18013122/R1td3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
4	REAR BUMPER SCREW SPACER @\$8.00	NECESSARY	32.00	32.00
1	REAR LUGGAGE FLOOR PANEL TRIMBOARD	SERVICEABLE	350.00	-
1	REAR LUGGAGE FLOOR FOAM COMPARTMENT TOOL	SERVICEABLE	166.00	-
2	REAR LICENSE PLATE LAMP @\$72.00	SERVICEABLE	144.00	-
1	REAR LICENSE PLATE GARNISH	SERVICEABLE	50.00	-
2	REAR FENDER @\$1175.00	TO REPAIR SEE LABOUR	2,350.00	-
2	REAR FENDER INNER COWLING @\$235.00	SERVICEABLE	470.00	-
8	REAR FENDER INNER COWLING CLIPS @\$5.00	SERVICEABLE	40.00	-
2	REAR FENDER LOWER PANEL @\$356.00	TO REPAIR SEE LABOUR	712.00	-
1	RH FRONT SEAT (ADDITIONAL)	BENT	2,129.00	2,129.00
	LESS 20% DISCOUNT		-2,729.32	-1,441.76
			10,917.28	5,767.04
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER PARKING SENSOR (SN)	NECESSARY	450.00	200.00
1	REAR LICENSE PLATE (SN)	SCRATCHED	80.00	35.00
			530.00	235.00
	<u>LABOUR</u>			
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		120.00	30.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		120.00	60.00
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.		150.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		160.00	60.00
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		120.00	60.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF O/S REAR LAMP PANEL, REAR FENDER AND REAR FENDER LOWER PANEL.		1,200.00	800.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,400.00	1,000.00
			3,270.00	2,070.00
	GRAND TOTAL		14,717.28	8,072.04

Report Ref No. CS/FCI18013122/R1td3e2



RECOMMENDED COST OF REPAIRS				8,072.04
-----------------------------	--	--	--	----------

Report Ref No. CS/FCI18013122/R1td3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.