

INS CASE OWNER

1cc

cc 4, Asm 130

13123,

P. Waz

LKK:
IDAC

58322

Surveyor:

P. Anu

DOI:

ASSIGNMENT

30/7/18

Date / Time:

18/07/2018

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SK6 22U

Name of Insured:

EuroAutomobiles PLC

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

14/7/2008

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Edison Tan Keng Hin

Driver Tel No.:

91154254

(V/L: YES / NO)

Claim No.:

S8M000MS

Policy No.:

VLX/P1344719

Make / Model:

Alfa Romeo

Place of Accident:

CCK S1 S2

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

S6T 6820Y



INSRS:

WSP:

Tel:

Liability:

RMKS:

PML



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

19/7/18

S6T 6820Y - X; SK6 22U - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

19/7/18

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time: 05-03-19

Confirm with: CAROLINE

Confirm by: PMS

Repair Cost:

P/P \$54,050.99

(7 days)

Reduction:

36 %

Email

Call

FINAL SETTLEMENT

Date/Time: 08-04-19

Confirm with: CAROLINE

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

G/GT: \$57,776.16

OLD BEATS RED LIGHT.

Loss of Rental (LOR):

\$5,750.00

(5 days)

x \$950

Loss of Use (LOU):

\$5 -

(\$ x days)

Loss of Income (LOI):

\$5 -

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

\$52.00

Medical

\$5 -

Disbursement:

\$5 -

(e.g. Tow/ Independent)

Legal Cost

\$5 -

Total:

\$57,928.16

Global Sum \$5:

FINAL PAYMENT

Date/Time: 08-04-19

Confirm with: CAROLINE

Email

Call

Payee 1:

\$57,928.16

Name 1:

PERFORMANCE MOTOR LIMITED

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

ASSIGNMENT

From: Date: 30/07/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 967 6820Y
at Workshop m/s: Performane
of: 303 Alexandra Rd

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Kevin

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est Repairs: 7 days Res: Yes or No

Lum Sum: - % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle IN / OUT

Veh No: SGT 6820Y Yr Regn: 2016 / Jun

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.M.W 520I AT cc 1997

Colour: WHITE A/C: Insured / Std / NI / NA

Sp Reading: 78146 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBA5A3204007A2564

Gen. Cond: Good / Fair / Poor / Burnt

Steering: No order / Jammed / Leaked / Burnt or

Brake: No order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45R18

R: 1.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 14/07/18 D.O.I: 30/07/18

Survey held at PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRS O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

P/p: +16,032.49 (RED) + 8,919.61 36%

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1) \$ = RE. 50

1) Photos

1) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

BMW Dealer

Performance Motors Limited
A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

288, Kampong Arang Road
East Coast Centre
Singapore 438380
Tel. 63190888 (AfterSales)
Fax. 63449773

318, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motocrad)
Fax. 64796601 (AfterSales)
64796624 (Motocrad)

GST REG. NO : M2 - 0020081 - X

18 JUL 2018

E S T I M A T E

Estimate No.	: b1 47723	Page No. :	1 of 5
Date Estimated	: 18/07/2018		
Prepared By	: Kevin Leong Wai Kit		

- ESTIMATE REPAIR FOR - Tang Chong Ming 66C ENG NEO AVENUE SINGAPORE 289545	- ACCOUNT - 238 AXA Insurance Pte Ltd 8 Shenton Way #24-01 AXA Tower Singapore 068811
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGT6820Y	D792564	01/06/2016	520iA	0

DESCRIPTION	VALUE
To replace frt bumper, frt RH side panel, bonnet, RH headlamp bracket, air ducts & all attachments cause by accident.	2550 4,250.00 3095
Painting on frt bumper, frt RH side panel & bonnet	2326 2,787.00 2463.30
To check electrical wiring systems for proper function.	150 177.00 135
To replace left or right headlight including program and conduct tests for proper function.	451 531.00 405.90
To carry out body cavity preservation. (Per panel).	100 118.00 90
To supply front emboss number plate.	500 83.00
Sundries. <i>NA</i>	? 150.00
Total Labour 1: 8,046.00	

DESCRIPTION	QTY	PRIC	VALUE
FRT RH FENDER	1	863.35	<i>Repair</i> 863.35
BONNET	1	2,224.70	<i>PA</i> 2,224.70
SET MOUNTS PDC SENSOR FRT (PDC)	1	31.65	<i>XAN?</i> 31.65
FRT LH BOTTOM DEFORMATION ELEMENT	1	101.70	<i>SVC</i> 101.70
FRT RH BOTTOM DEFORMATION ELEMENT	1	101.70	<i>BT</i> 101.70
FRT BUMPER CARRIER	1	684.75	<i>CHA</i> 684.75
FRT BUMPER FLAP COVER SPRING	1	5.25	<i>XVI?</i> 5.25
FRT BUMPER BOTTOM MOUNT	1	157.50	<i>CHA?</i> 157.50
BRACKET RH	1	13.90	<i>X17</i> 13.90
FRT BUMPER RH SPACER	1	9.45	<i>u</i> 9.45
GRILLE AIR INLET MIDDLE	1	80.65	<i>u</i> 80.65
LH GRILLE AIR INLET PARTLY CLOSED	1	74.25	<i>X17</i> 74.25
RH GRILLE AIR INLET PARTLY CLOSED	1	68.65	<i>DB?</i> 68.65
FRT SHOCK ABSORBER	1	48.00	<i>CRA?</i> 48.00



101, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 62190888 (AfterSales)
Fax. 63449777

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533 (Motorrad)
64796501 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47723
Date Estimated : 18/07/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGT6820Y	D792564	01/06/2016	520iA	0

DESCRIPTION

LEVER RH
DUMMY PLUG RH
FRT BUMPER LH PROTECTIVE RUBBER STR
FRT BUMPER RH PROTECTIVE RUBBER STR
FRT BUMPER RH PROTECTIVE RUBBER STR
FRT BUMPER PANEL PRIMED (PDC)
FRT TOWING LUG COVER PRIMED
RH COVERING PRIMEND
Support
FINISHER SIDE PANEL FRT RH
FRT LH GRILLE (BASIS)
FRT RH GRILLE (BASIS)
EMBLEM GROMMET
BMW EMBLEM
CONNECTION TOP FRT
RH HEADLAMP SUPPORT
COVER RIGHT
AIR DUCT
AIR DUCT BRAKE RH
SEAL BONNET REAR
FRT RH LOCATOR SEAL
SEAL ENGINE BONNET FRT
LH HEADLIGHT LED TECHNOLOGY
RH HEADLIGHT LED TECHNOLOGY
RH FOG LIGHT LED

QTY

PRIC

VALUE

1 7.20
1 7.75
1 22.30
1 22.30
1 22.30
1 1,277.55
1 46.45
1 46.45
1 20.95
1 75.15
1 120.50
1 120.50
1 0.80
1 69.50
1 155.35
1 128.45
1 10.95
1 293.50
1 51.50
1 29.35
1 56.80
1 42.30
1 4,201.60
1 4,201.60
1 391.10

Total Parts : 15,887.70

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized by Repairer

Labour 1	:	8,046.00
Parts	:	15,887.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,675.36
Grand Total	:	25,609.06

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. b1 47723
Date Estimated 18/07/2018
Prepared By Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Tang Chong Ming
66C ENG NEO AVENUE

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

SINGAPORE 289545

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SGT6820Y	D792564	01/06/2016	520iA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
# To replace front PDC wire harness include resetting and conducting checks for function	226.00	10.00	203.40	✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT	
# BLIND RIVET *	1.25	2.00	3.00	2.42	✓
# FRT BUMPER RH CONNECTOR *	54.75	1.00	3.00	53.11	✓
# STABILIZATION PIN *	1.00	1.00	3.00	0.97	✓
# RH COVER BOTTOM *	71.30	1.00	3.00	69.16	✓
# WIRING SET PDC FRT *	105.25	1.00	3.00	102.09	✓
# RH HIGH PRESSURE NOZZLE *	179.30	1.00	3.00	173.92	✓
# GASKET SET *	43.95	1.00	3.00	42.63	✓
# DECOUPLING RING PDC TORQUE CONVERTE *	5.05	1.00	3.00	4.90	✓
# BUMPER PDC SENSOR (A96 MINERALWEIS) *	368.80	1.00	3.00	357.74	✓
# NOTICE SAFETY CATCH *	23.80	1.00	3.00	23.09	✓

Total Labour : 203.40
Total Parts : 830.03
Total Labour & Parts : 1,033.43

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 47723
Date Estimated : 18/07/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Tang Chong Ming
66C ENG NEO AVENUE

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

SINGAPORE 289545

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SGT6820Y	D792564	01/06/2016	5201A	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments, bonnet and attachments, RH covering, RH bottom cover, RH head lamp support, front air duct, RH high pressure nozzle include making good the front RH fender and knocking out dents caused by the accident	2550.00	10.00	2,295.00	
* To spray paint front bumper, front RH fender and bonnet	2737.00	10.00	2,463.30	
To check electrical wiring systems and lightings at the front section for proper function	150.00	10.00	135.00	
To replace RH LED technology headlight include programming and conducting tests for proper function	451.00	10.00	405.90	
To carry out body cavity preservation (Per panel)	100.00	10.00	90.00	
To supply front emboss number plate	83.00	0.00	83.00	
# To replace front PDC wire harness include resetting and conducting checks for function	226.00	10.00	203.40	
Sundries	150.00	0.00	150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET *	1.25	2.00	3.00	2.42
BONNET	2,224.70	1.00	3.00	2,157.96
FRT RH BOTTOM DEFORMATION ELEMENT	101.70	1.00	3.00	98.65
# FRT BUMPER RH CONNECTOR *	54.75	1.00	3.00	53.11
FRT BUMPER CARRIER	684.75	1.00	3.00	664.21
FRT BUMPER BOTTOM MOUNT	157.49	1.00	3.00	152.77
FRT BUMPER RH SPACER	9.45	1.00	3.00	9.17
# STABILIZATION PIN *	1.00	1.00	3.00	0.97
SUPPORT	16.60	1.00	3.00	16.10
GRILLE AIR INLET MIDDLE	80.65	1.00	3.00	78.23
RH GRILLE AIR INLET PARTLY CLOSED	68.65	1.00	3.00	66.59
FRT SHOCK ABSORBER	48.00	1.00	3.00	46.56

Performance Motors Limited

A member of the Sims Derby Group
Co. Reg. No. 1974015500W, GST Reg. No. M2-0030081-X



FINAL REPORT

LEVER RH	7.20	1.00	3.00	6.98
FRT BUMPER RH PROTECTIVE RUBBER STR	22.30	1.00	3.00	21.63
FRT BUMPER PANEL PRIMED (PDC)	1,277.55	1.00	3.00	1,239.22
RH COVERING PRIMEND	46.45	1.00	3.00	45.06
FRT RH GRILLE (BASIS)	120.49	1.00	3.00	116.88
BMW EMBLEM	69.49	1.00	3.00	67.41
RH HEADLAMP SUPPORT	128.45	1.00	3.00	124.60
AIR DUCT	293.49	1.00	3.00	284.69
# RH COVER BOTTOM *	71.30	1.00	3.00	69.16
SEAL BONNET REAR	29.35	1.00	3.00	28.47
FRT RH LOCATOR SEAL	56.80	1.00	3.00	55.10
SEAL ENGINE BONNET FRT	42.30	1.00	3.00	41.03
# WIRING SET PDC FRT *	105.25	1.00	3.00	102.09
# RH HIGH PRESSURE NOZZLE *	179.30	1.00	3.00	173.92
# GASKET SET *	43.95	1.00	3.00	42.63
RH HEADLIGHT LED TECHNOLOGY	4,201.60	1.00	3.00	4,075.55
# DECOUPLING RING PDC TORQUE CONVERTE *	5.05	1.00	3.00	4.90
# BUMPER PDC SENSOR (A96 MINERALWEIS) *	368.80	1.00	3.00	357.74
# NOTICE SAFETY CATCH *	23.80	1.00	3.00	23.09

SUPPLEMENTARY ITEMS

Total Labour :	5,825.60
Total Parts :	10,226.89
Total Labour & Parts :	16,052.49
Deduction for Excess :	0.00
Total Repair Costs less Excess:	16,052.49
GST @7%:	1,123.67
Grand Total :	17,176.16



RE: Re:MANDATE IA (S8M00OMS)

Type

 Question

Message

Liability: Insured beats the red light and hit third party vehicle. Spoken to Insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost w/GST : \$17,176.16 Loss of Rental : \$750 (5days x \$150) LTA Search: \$2.00 Total: \$17,928.16 Revised Immediate Advice with Mandate and relevant document uploaded for your easy reference. Please kindly let us have your approval / instruction if any.
Thank you - Asher Sng (29/03/2019)

Reply



Re:RE: Re:MANDATE IA (S8M00OMS)

Type

🔔 Question

Message

PLS PROCEED AS RECOMMENDED

Reply

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) (Singapore) (the "Act")
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 (Singapore)
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)


This document forms part of your contract with us and should be read together with your Policy Schedule and your Policy Details. Do let us know if any of the details shown here need to be amended or updated.

Certificate No.	: MT/00485152
Type of Coverage / Driver Plan	: Car Comprehensive (Value Plus Plan)
1) Vehicle Registration No.	: SGT6820Y
Chassis No.	: WBA5A32040D792564
2) Name of Policy Holder	: Tang, Chong Ming
3) Effective Date / Time of Commencement of Insurance for the Purpose of the Act	: 01/06/2018 00:00
4) Date/Time of Expiry of Insurance	: 31/05/2019 23:59
5) Persons or Classes of Persons Entitled to Drive	
(a) The Insured	
(b) Any named person under the policy who is driving on the Insured's order or with his permission.	
(c) Any authorised person, provided such person is aged 30 and above and holds a valid driving licence of 2 years or more, who is driving on the Insured's order or with his permission	
The person driving must have a valid driving licence to drive in Singapore and must not be under suspension or disqualification from driving.	
6) Limitations as to use*	
Use only for private purposes, in accordance with the declared car usage stated on your Policy Schedule. The policy does not cover use for hire or reward, tuition, driving test, racing, pace-making, reliability trials, speed tests, the carriage of goods for payment or for any purpose in connection with the motor trade business.	
*Limitations rendered inoperative by Section 8 of the Act and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under this heading.	
Sum Insured	: Market Value
Own Damage Excess	: S\$ 300.00 (before any applicable GST)
Windscreen Excess	: S\$ 100.00 (before any applicable GST)
Choice of workshop	: My Workshop/ My Authorised Distributor Workshop
Finance company / Hire Purchase	:
Main driver	: Tang, Chong Ming
Named driver	: None
Important Note: This policy does not cover drivers below the age of 30 and drivers who hold a valid driving licence of less than 2 years with the exception of the named drivers above.	

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and the Road Transport Act, 1987 (Malaysia).

Issued on: 30/05/2018

Direct Asia Insurance (Singapore) Pte. Ltd.



Edip Okur
Chief Underwriting Officer

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S2504949G



Name

TANG CHONG MING

鄧仲敏

Race

CHINESE

Date of Birth

29-05-1947

Sex

M

Country of Birth

MALAYSIA

REPUBLIC OF SINGAPORE DRIVING LICENC.



Licence Number S2504949G

Holder

TANG CHONG MING

Birth Date 29 May 1947

Issue Date 23 Apr 2004



8226750



SPIC No. S2504949G

Nationality

MALAYSIAN

Blood Group

A+

Date of issue

07-09-1999

Address

66C ENG NEO AVENUE
SINGAPORE 289545

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 2B	Motorcycles not exceeding 200 cc	15 Apr 1986
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	15 Apr 1986

NP 426A





PAI

AXA Insurance Pte Ltd
8 Shenton Way
#27-01
Singapore 068811
Attention: Motor Claims

"Without Prejudice"

Your Ref

Our Ref

Date

Subject

06 March 2019

ACCIDENT INVOLVING VEHICLES SGT6820Y & SKG22U ON 14.07.2018

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of Repair	:	S\$	17176.16
Car Rental	:	S\$	750.00
GIA search fee	:	S\$	2.00
Total	:	S\$	17928.16

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill & GIA search slip
3. Copy of Car Rental bill & Car Rental Agreement & Insurance of Certificate
4. Copy of Identification Card & Driving License
5. Copy of Letter of Authorisation & Discharge Voucher

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@sime-darby.com.sg.

Yours sincerely

Teng Wai Khan
Customer Service Manager, Body & Paint

Performance Motors
Limited
1800-Call-BMW
(1800-2255-269)

www.pml.com.sg

303 Alexandra Road
Sime Darby
Performance Centre
Singapore 159941
Tel Sales 6319 0100
Tel AfterSales:
6319 0111
Fax 6474 7770

315 Alexandra Road
#01-01
Sime Darby
Business Centre
Singapore 159944
Tel Sales 6319 0511
Tel AfterSales:
6319 0527
Fax 6479 6624

280
Kampong Arang Rd
East Coast Centre
Singapore 438180
Tel AfterSales:
6319 0868
Fax 6344 1332

Registered office
305 Alexandra Road
#02-01
Vantage
Automotive Centre
Singapore 159942

Co. Reg. No:
197401559W



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

20 July 2018

Euroautomobile Pte Ltd

24 Leng Kee Rd
#01-03
Singapore 159096

Dear Sir/ Mdm

OUR REF : CC4/ASM18013123/wa3
YOUR REF : SKG 22U

ACCIDENT INVOLVING SKG 22Y & SGT 6820Y ALONG CCK ST 52 ON 14/07/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from **Performance Motors Limited** acting on behalf of the owner of SGT 6820Y against your motor insurance policy.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to Vivianlau@lkkauto.com within 7 days if not provided at our reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us 6841 8625 or email us at Vivianlau@lkkauto.com

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Vivian Lau
Case Handler
DID: 6841 8625
FAX: 6741 4108
EMAIL: Vivianlau@lkkauto.com

c.c. AXA Insurance Pte Ltd
(Motor Claims Dept)

Performance Motors Limited

A member of the Sime Darby Group



LETTER OF AUTHORISATION

ACCIDENT INVOLVING SGT 68204 & SK6224 ON 14/7/2018.

I, TAN CHONG MING owner of Vehicle Registration No. SGT 68204
hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and
settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all
documents whatsoever in relation to this matter and to accept and receive any payment
due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation
on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if
the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement
amount in respect of such claim shall constitute the full discharge of my claim in respect of
such loss and damage.

Signed by:

Name: Tan Chong Ming (Date) 15/7/18
NRIC No.: S25049499

In the presence of:

KEVIN LEONG WAI KIT
 Performance Motors Limited
 303 Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941

Name: Kevin Leong (Date) 15/7/18
NRIC No.: _____



redefining / insurance

CLAIM REF : 38M000MS
INSURED : EUROAUTOMOBILE PTE LTD

DISCHARGE VOUCHER

We/I Tang Chong Ming, NRIC NO. S25 049496 hereby agree to accept the sum of dollars [SEVENTEEN THOUSAND NINE HUNDRED TWENTY EIGHT AND CENTS SIXTEEN ONE] (\$\$ 17,928.16) paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. [SK6224] as a result of an accident along [Junction of CCK North 5 / CCK STR 51/52] on [14/7/18] of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. [SGT 6830Y].

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. [SK6224] in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. [SK6224].

Dated this 8 day of APRIL 2017

Claimant's Signature

[Signature]

NRIC no./ Company Stamp

S25049496

Occupation/ Business

Address

666 Eng Neo Avenue S (289545)

Telephone No.

Witness's Name

Kevin Leong

Witness's Signature

[Signature]

Witness's NRIC No.



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438380
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1287407

Date IN : 30/07/2018

Cust. Svc. Advisor: Kevin Leong Wai Kit

Page No. : 1 of 3

Invoice Number : 2072970 / WSB

Invoice Date : 05/03/2019

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Mr Tang Chong Ming
66C ENG NEO AVENUE

SINGAPORE 289545

- INVOICE TO - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.
SGT6820Y

CHASSIS NO.
D792564

REGN. DATE
01/06/2016

MODEL
520IA

MILEAGE
74146

- - - - LABOUR 1 - - - -

To replace front bumper and attachments, front bonnet and attachments, right grille and air duct etc including to make good the front right

fender and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job. -

To respray front bumper, front right fender and front bonnet etc.

To check electrical wiring systems and lighting at the front section for proper function.

To replace right Technology LED headlight including program and conduct tests for proper function.

To carry out body cavity preservation.

To replace front PDC wire harness including reset and checks for proper function.

Sundries.

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 14.7.2018. 3RD PARTY CAR : SKG22U.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR RASUL FROM LKK AUTO CONSULTANTS PTE LTD ON 30.7.2018 AT 3.00 PM. AUTHORISED REPAIR BY MS VIVIAN LAU FROM LKK ON 19.7.2018 VIA E-MAIL.

PROPOSE CAR RENTAL = \$750.00. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.

GIA SEARCH FEE = \$2.00.

Retail

Price

DISC%

NETT

2,550.00 10.00 2,295.00

2,737.00 10.00 2,463.30

150.00 10.00 135.00

451.00 10.00 405.90

100.00 10.00 90.00

226.00 10.00 203.40

150.00 0.00 150.00

0.00 0.00 0.00

0.00 0.00 0.00

0.00 0.00 0.00

Total Labour 1: 5,742.60

- - - - PARTS - - - -

Retail

Qty

Price

DISC%

NETT

BONNET 1 2,224.70 3.00 2,157.96

FRT BUMPER RH SPACER 1 9.45 3.00 9.17

FRT BUMPER PANEL PRIMED (PDC) 1 1,277.55 3.00 1,239.22

RH COVERING PRIMEND 1 46.45 3.00 45.06

FRT RH GRILLE (BASIS) 1 120.50 3.00 116.88

BMW EMBLEM 1 69.50 3.00 67.41

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449772

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190538 (AfterSales)
63190533/539 (Motorrad)
Fax. 64786601 (AfterSales)
64786624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1287407

Date IN : 30/07/2018

Cust. Svc. Advisor: Kevin Leong Wai Kit

Page No. : 2 of 3

Invoice Number : 2072970 / WSB

Invoice Date : 05/03/2019

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

AIR DUCT	1	293.50	3.00	284.69
SEAL BONNET REAR	1	29.35	3.00	28.47
SEAL ENGINE BONNET FRT	1	42.30	3.00	41.03
RH HEADLIGHT LED TECHNOLOGY	1	4,201.60	3.00	4,075.55
RH GRILLE AIR INLET PARTLY CLOSED	1	68.65	3.00	66.59
WIRING SET PDC FRT	1	105.25	3.00	102.09
FRT BUMPER RH CONNECTOR	1	54.75	3.00	53.11
STABILIZATION PIN	1	1.00	3.00	0.97
SUPPORT	1	16.60	3.00	16.10
LEVER RH	1	7.20	3.00	6.98
RH HIGH PRESSURE NOZZLE	1	179.30	3.00	173.92
RH COVER BOTTOM	1	71.30	3.00	69.16
DECOUPLING RING PDC TORQUE CONVERTE	1	5.05	3.00	4.90
NOTICE SAFETY CATCH	1	23.80	3.00	23.09
FRT RH BOTTOM DEFORMATION ELEMENT	1	101.70	3.00	98.65
FRT BUMPER CARRIER	1	684.75	3.00	664.21
FRT BUMPER BOTTOM MOUNT	1	157.50	3.00	152.77
FRT SHOCK ABSORBER	1	48.00	3.00	46.56
RH HEADLAMP SUPPORT	1	128.45	3.00	124.60
FRT RH LOCATOR SEAL	1	56.80	3.00	55.10
BUMPER PDC SENSOR (A96 MINERALWEIS)	1	368.80	3.00	357.74
GRILLE AIR INLET MIDDLE	1	80.65	3.00	78.23
FRT BUMPER RH PROTECTIVE RUBBER STR	1	22.30	3.00	21.63
BLIND RIVET	2	1.25	3.00	2.42
GASKET SET	1	43.95	3.00	42.63

Total Parts : 10,226.89

- - - - LABOUR 2 - - - -

To supply front silver emboss lettering black base number
plate with bracket.

Retail		
Price	DISC%	NETT
83.00	0.00	83.00

Total Labour 2: 83.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401339W GST Reg. No M2-0020001-a



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

298, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449771

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1287407	Page No. : 3 of 3
Date IN : 30/07/2018	Invoice Number : 2072970 / WSB
Cust. Svc. Advisor: Kevin Leong Wai Kit	Invoice Date : 05/03/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

Labour Charges : 5,675.60	Total Labour & Parts Charges : S\$ 16,052.49
Parts Charges : 10,226.89	Less Insurance Excess : S\$ 0.00
Lubricant/Misc : 150.00	Invoice Total Amount Exclude GST : S\$ 16,052.49
	GST @ 7% : S\$ 1,123.67
	Invoice Total Amount Include GST : S\$ 17,176.16

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 17,176.16**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



RENTAL AGREEMENT

29.05.1947

HA 201807-0285

Hirer's Name MR. TANG CHONG MING	Date of Birth 07.04.1947	Passport/ Nric No. S2504949G	Nationality MA
Address 66C ENG NEO XIE	Occupation	Driving Licence No.	Date of Expiry
Postal Code 289545	Contact No.	Mobile Phone No. 9679 7989	
Joint Hirer's / Guarantor's Name	Date of Birth	Passport/ Nric No.	Nationality
Address	Occupation	Driving Licence No.	Date of Expiry
Postal Code	Contact No.	Mobile Phone No.	

CHECK OUT

CHECK IN

Date 30.07.2018	Time 0945	Mileage KM	E	1/4	1/2	3/4	F
Date 3-8.18	Time 6pm	Mileage KM	Remarks 5	N			

IMPORTANT NOTES:

- Car is restricted to SINGAPORE use. See clause 1(f) for non-compliance.
- No refund will be given for vehicle that returns early.
- Own Damage Liability - First \$1500 for damage to vehicle plus loss of earnings while damaged vehicle is under repair.
- Third Party Liability - First \$2000 for any Third Party Accident Claim.
- Additional Excess of \$3000 for drivers under 24yrs old or above 70yrs and/or less than 2yrs driving experience.
- Hirer is responsible for all parking fines & traffic summons.
- Extension: One day's advance notice is required otherwise no extension will be allowed.
- Vehicle should be returned at the same time as collection except on Saturday where return time is before 10am.
- Vehicle returned after office hour will be charged to the next working day.
- Hourly extension is charged at 1/5 of the daily rate.
- As preventive maintenance, please check water & engine oil daily.
- Please check that you have not left any of your personal belongings in the vehicle. Our company and staff will not be responsible for any loss of belongings after the vehicle is returned.
- For the comfort of other users, please refrain from smoking, eating or carrying of pets in the car. A cleaning charge of \$200 will be imposed for smoky, smelly or dirty vehicle.
- Carrying of PASSENGERS in commercial vehicle is strictly prohibited. Only WORKERS covered under hirer's workmen compensation are allowed.

Additional \$30/day

	UNIT	RATE (\$)	TOTAL (\$)
RATE	5	@ \$150	
DISCOUNT			
GST @ 7%			
TOTAL			750/-
EXTENSION			
Kern/DML = ekam TP			
SGT 6820Y			
DEPOSIT (refundable) S\$			
CHANGED OVER FROM VEH. DATE			

I/We have read and agree to the terms and conditions of the rental agreement above and as set overleaf.
I/We declare that all information given on this form is true and accurate.

Hirer's Signature

Joint Hirer's/ Guarantor's Signature

for CHAN'S & SONS ENTERPRISE

VEHICLE NO. **S5V1779X**

MODEL **CAMP 2.0**

FROM **30.07.2018**

RETURN

Estimate Date. For actual return see CHECK IN

CHAN'S & SONS ENTERPRISE

363 Sembawang Road
Singapore 758379
Tel: 67532536 Fax: 67567565
GST Reg No: 51-936900-M

chan's
www.chans.com.sg

TAX INVOICE

TANG CHONG MING

NO. 66C
ENG NEO AVENUE
SINGAPORE 289545

ATTN : TANG CHONG MING

INVOICE : AR1808-0122
DATE : 06/08/2018
TERMS : C.O.D
STAFF ID : AINI
AGREEMENT NO. : HA201807-0285

DESCRIPTION	AMOUNT (SGD)
-------------	--------------

Vehicle Reg No : SJV1779X 700.93
Make / Model :
Rental Dates : Rental Billing From 30/07/2018 To 03/08/2018 (incl)
Period : 5 days
Rental Rate : S\$ 150.00 Per Day (Including GST)
Reference No : SGT6820Y

AMOUNT : S\$

SEVEN HUNDRED FIFTY DOLLARS ONLY

NON-TAXABLE VALUE : 0.00
TAXABLE VALUE : 700.93
GST 7% : 49.07
TOTAL S\$: 750.00

Please make your cheques payable to : **CHAN'S & SONS ENTERPRISE**



For Official Use Only

Payment Date :	F / Amt
CS / CC / CH :	
CS / CC / CH :	

CHANS & SONS ENTERPRISE

363 Sembawang Road, Goodlink Park,
Singapore 758379
Tel: 67532536 Fax: 67567565
GST Reg No: 51-936900-M

chan's
www.chans.com.sg

Hirer:

TANG CHONG MING

OFFICIAL RECEIPT

DESCRIPTION		AMOUNT (SGD)	
Official Receipt No	: 201808-0044		
Account of	: TANG CHONG MING		
Date Issued	: 06/08/2018		
Vehicle Reg No.	: SJV1779X		
Rental Dates	: 30/07/2018		
Amount Received	: S\$ 750.00		
Payment Type:	: MASTER	M100259	S\$ 750.00
Payment for Invoice	: AR1808-0122		
Comments	:		
TOTAL AMOUNT RECEIVED		S\$	750.00

* This is a computer generated document. No signature is required.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-108245

Date of Request: 16/07/2018

Your Ref No:

Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 16/07/2018
Enquiry By Caroline Tan Shirui
TP Vehicle No. SKG22U
Accident Date 14/07/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKG22U	AXA Insurance Pte Ltd	30/01/2018-29/01/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-108245

Date of Request: 16/07/2018

Your Ref No:

Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 16/07/2018
Enquiry By Caroline Tan Shirui
TP Vehicle No. SKG22U
Accident Date 14/07/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKG 22U (Insd veh)	Model:	B.M.W. 520i AT
	SGT 6820Y (TP veh)		
Date of Accident:	14/07/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	26,714.83
Final Repair Cost	:	\$	17,176.16
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	750.00 5 days
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	17,928.16

Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
	_____ NIL _____
BOLA Liability: _____ 100 _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____ _____	

Payment Instruction: Payee's Breakdown			
1)	PERFORMANCE MOTORS LIMITED	:	\$ 17,928.16

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

23/04/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18013123/R1ea3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN			Date : 23-04-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKG 22U	Veh. Inspected	SGT 6820Y	
Policy No.	VCX/PI1344719	Coverage (\$)	0.00	
Claim No.	S8M00OMS	Excess (\$)	0.00	
Assign From		Assign Date	18/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 520I AT	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WBA5A32040D792564	Colour	WHITE	
Odometer	78146	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/45 R18	CONTINENTAL	6 mm	
L/H Front Tyre	245/45 R18	CONTINENTAL	6 mm	
R/H Rear Tyre	245/45 R18	CONTINENTAL	6 mm	
L/H Rear Tyre	245/45 R18	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/07/2018	Inspection Date	30/07/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGT 6820Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT EMBOSS NUMBER PLATE (SN) (CONSISTENT)	SCRATCHED	83.00	83.00
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	150.00	150.00
1	FRT RH FENDER (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	863.35	-
1	BONNET (SN) (CONSISTENT)	BENT	2,224.70	2,157.96
1	SET MOUNTS PDC SENSOR FRT (PDC) (SN) (CONSISTENT)	NOT NECESSARY	31.65	-
1	FRT LH BOTTOM DEFORMATION ELEMENT (SN) (CONSISTENT)	SERVICEABLE	101.70	-
1	FRT RH BOTTOM DEFORMATION ELEMENT (SN) (CONSISTENT)	BENT	101.70	98.65
1	FRT BUMPER CARRIER (SN) (CONSISTENT)	CRACKED	684.75	664.21
1	FRT BUMPER FLAP COVER SPRING (SN) (CONSISTENT)	NOT NECESSARY	5.25	-
1	FRT BUMPER BOTTOM MOUNT (SN) (CONSISTENT)	CRACKED	157.50	152.77
1	BRACKET RH (SN) (CONSISTENT)	NOT NECESSARY	13.90	-
1	FRT BUMPER RH SPACER (SN) (CONSISTENT)	NECESSARY	9.45	9.17
1	GRILLE AIR INLET MIDDLE (SN) (CONSISTENT)	CRACKED	80.65	78.23
1	LH GRILLE AIR INLET PARTLY CLOSED (SN) (CONSISTENT)	NOT NECESSARY	74.25	-
1	RH GRILLE AIR INLET PARTLY CLOSED (SN) (CONSISTENT)	DEFORMED	68.65	66.59
1	FRT SHOCK ABSORBER (SN) (CONSISTENT)	CRACKED	48.00	46.56
1	LEVER RH (SN) (CONSISTENT)	CRACKED	7.20	6.98
1	DUMMY PLUG RH (SN) (CONSISTENT)	SERVICEABLE	7.75	-
1	FRT BUMPER LH PROTECTIVE RUBBER STR (SN) (CONSISTENT)	SERVICEABLE	22.30	-
1	FRT BUMPER RH PROTECTIVE RUBBER STR (SN) (CONSISTENT)	NECESSARY	22.30	21.63
1	FRT BUMPER RH PROTECTIVE RUBBER STR (SN) (CONSISTENT)	NOT NECESSARY	22.30	-
1	FRT BUMPER PANEL PRIMED (PDC)(SN) (CONSISTENT)	DEFORMED	1,277.55	1,239.22
1	FRT TOWING LUG COVER PRIMED (SN) (CONSISTENT)	NOT NECESSARY	46.45	-
1	RH COVERING PRIMEND (SN) (CONSISTENT)	MISSING	46.45	45.06
1	SUPPORT (SN) (CONSISTENT)	CRACKED	20.95	16.10

Report Ref No. CC4/ASM18013123/R1ea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FINISHER SIDE PANEL FRT RH (SN) (CONSISTENT)	NOT NECESSARY	75.15	-
1	FRT LH GRILLE (BASIS) (SN) (CONSISTENT)	NOT NECESSARY	120.50	-
1	FRT RH GRILLE (BASIS) (SN) (CONSISTENT)	SCRATCHED	120.50	116.88
1	EMBLEM GROMMET (SN) (CONSISTENT)	NOT NECESSARY	0.80	-
1	BMW EMBLEM (SN) (CONSISTENT)	NECESSARY	69.50	67.41
1	CONNECTION TOP FRT (SN) (CONSISTENT)	NOT NECESSARY	155.35	-
1	RH HEADLAMP SUPPORT (SN) (CONSISTENT)	BENT	128.45	124.60
1	COVER RIGHT (SN) (CONSISTENT)	NOT NECESSARY	10.95	-
1	AIR DUCT (SN) (CONSISTENT)	CRACKED	293.50	284.69
1	AIR DUCT BRAKE RH (SN) (CONSISTENT)	NOT NECESSARY	51.50	-
1	SEAL BONNET REAR (SN) (CONSISTENT)	NECESSARY	29.35	28.47
1	FRT RH LOCATOR SEAL (SN) (CONSISTENT)	NECESSARY	56.80	55.10
1	SEAL ENGINE BONNET FRT (SN) (CONSISTENT)	NECESSARY	42.30	41.03
1	LH HEADLIGHT LED TECHNOLOGY (SN) (CONSISTENT)	SERVICEABLE	4,201.60	-
1	RH HEADLIGHT LED TECHNOLOGY (SN) (CONSISTENT)	BROKEN	4,201.60	4,075.55
1	RH FOG LIGHT LED (SN) (CONSISTENT))	SERVICEABLE	391.10	-
2	BLIND RIVET (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	2.42	2.42
1	FRT BUMPER RH CONNECTOR (SN) (CONSISTENT) (ADDITIONAL)	CRACKED	53.11	53.11
1	STABILIZATION PIN (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	0.97	0.97
1	RH COVER BOTTOM (SN) (CONSISTENT) (ADDITIONAL)	CRACKED	69.16	69.16
1	WIRING SET PDC FRT (SN) (CONSISTENT) (ADDITIONAL)	CUT	102.09	102.09
1	RH HIGH PRESSURE NOZZLE (SN) (CONSISTENT) (ADDITIONAL)	CRACKED	173.92	173.92
1	SET GASKET (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	42.63	42.63
1	DECOUPLING RING PDC TORQUE CONVERTE (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	4.90	4.90
1	BUMPER PDC SENSOR (A96 MINERALWEIS)(SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	357.74	357.74
1	NOTICE SAFETY CATCH (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	23.09	23.09
			16,950.73	10,459.89

Report Ref No. CC4/ASM18013123/R1ea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REPLACE FRONT PDC WIRE HARNESS INCLUDE RESETING AND CONDUCTING CHECKS FOR FUNCTION.(ADDITIONAL)		203.40	203.40
	TO REPLACE FRT BUMPER ,FRT RH SIDE PANEL,BONNET ,RH HEADLAMP BRACKET ,AIR DUCTS & ALL ATTACHMENTS CAUSE BY ACCIDENT.		4,250.00	2,295.00
	PAINTING ON FRT BUMPER ,FRT RH SIDE PANEL & BONNET .		2,737.00	2,463.30
	TO CHECK ELECTRICAL WIRING SYSTEMS FOR PROPER FUNCTION .		177.00	135.00
	TO REPLACE LEFT OR RIGHT HEADLIGHT INCLUDING PROGRAM AND CONDUCT TESTS FOR PROPER FUNCTION .		531.00	405.90
	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL).		118.00	90.00
			8,016.40	5,592.60
	GRAND TOTAL		24,967.13	16,052.49
RECOMMENDED COST OF REPAIRS				16,052.49

Report Ref No. CC4/ASM18013123/R1ea3q2

MOHAMMED RASUL BIN MOHD YUNUS















Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 BENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 April 2019
 payment breakdown.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 April 2019
 LOD.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 April 2019
 LKKInspection (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 April 2019
 LKKAdjustment1a.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 April 2019
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 April 2019
 DISCHARGE VOUCHER.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	26 April 2019
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	26 April 2019
 WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (TP)	26 April 2019
 LETTER TO OJ.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	26 April 2019
 Immediate Advice with Mandate - REVISED.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	29 March 2019
 SUPPLEMENTARY.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	29 March 2019
 FINAL REPORT.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	29 March 2019
 Immediate Advice with Mandate.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 March 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKK Survey Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	3 March 2019
 LKK Recovery Photo.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 March 2019
 TP ESTIMATE-MAIBED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	5 August 2018
 SGT 6820Y.jpg	Evidence	Videos	LKK AUTO CONSULTANTS PTE LTD (TP)	19 July 2018
 SMC22U INSD GIA REPORT.PDF	Reports & Statement	GIA Report	RATAN BHOSALE Pragasli	18 July 2018
 EMAIL RECIEVED FROM WORKSHOP WITH TP GIA REPORT & ESTIMATE.mie	Letters and Correspondence	Workshop	RATAN BHOSALE Pragasli	18 July 2018