

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

18 JUL 2018

E S T I M A T E

Estimate No. : b1 47723
Date Estimated : 18/07/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Tang Chong Ming
66C ENG NEO AVENUE

SINGAPORE 289545

- ACCOUNT - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGT6820Y	D792564	01/06/2016	520iA	0

DESCRIPTIONVALUE

To replace frt bumper, frt RH side panel, bonnet, RH headlamp bracket, air ducts & all attachments cause by accident.

2550 4,250.00

Painting on frt bumper, frt RH side panel & bonnet

2326 2,787.00

To check electrical wiring systems for proper function.

150 177.00

To replace left or right headlight including program and conduct tests for proper function.

451 531.00

To carry out body cavity preservation.
(Per panel).

100 118.00

To supply front emboss number plate.

SCA 83.00

Sundries.

? 150.00

Total Labour 1: 8,046.00

DESCRIPTIONQTY PRICVALUE

FRT RH FENDER

1 863.35

Repair 863.35

BONNET

1 2,224.70

Rt 2,224.70

SET MOUNTS PDC SENSOR FRT (PDC)

1 31.65

? 31.65

FRT LH BOTTOM DEFORMATION ELEMENT

1 101.70

EX 101.70

FRT RH BOTTOM DEFORMATION ELEMENT

1 101.70

? 101.70

FRT BUMPER CARRIER

1 684.75

? 684.75

FRT BUMPER FLAP COVER SPRING

1 5.25

? 5.25

FRT BUMPER BOTTOM MOUNT

1 157.50

? 157.50

BRACKET RH

1 13.90

M 13.90

FRT BUMPER RH SPACER

1 9.45

M 9.45

GRILLE AIR INLET MIDDLE

1 80.65

? 80.65

LH GRILLE AIR INLET PARTLY CLOSED

1 74.25

? 74.25

RH GRILLE AIR INLET PARTLY CLOSED

1 68.65

DGT 68.65

FRT SHOCK ABSORBER

1 48.00

? 48.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 47723**
Date Estimated : **18/07/2018**
Prepared By : **Kevin Leong Wai Kit**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGT6820Y	D792564	01/06/2016	520ia	0

DESCRIPTION	QTY	PRIC	VALUE
LEVER RH	1	7.20	7.20
DUMMY PLUG RH	1	7.75	7.75
FRT BUMPER LH PROTECTIVE RUBBER STR	1	22.30	22.30
FRT BUMPER RH PROTECTIVE RUBBER STR	1	22.30	22.30
FRT BUMPER RH PROTECTIVE RUBBER STR	1	22.30	22.30
FRT BUMPER PANEL PRIMED (PDC)	1	1,277.55	1,277.55
FRT TOWING LUG COVER PRIMED	1	46.45	46.45
RH COVERING PRIMEND	1	46.45	46.45
Support	1	20.95	20.95
FINISHER SIDE PANEL FRT RH	1	75.15	75.15
FRT LH GRILLE (BASIS)	1	120.50	120.50
FRT RH GRILLE (BASIS)	1	120.50	120.50
EMBLEM GROMMET	1	0.80	0.80
BMW EMBLEM	1	69.50	69.50
CONNECTION TOP FRT	1	155.35	155.35
RH HEADLAMP SUPPORT	1	128.45	128.45
COVER RIGHT	1	10.95	10.95
AIR DUCT	1	293.50	293.50
AIR DUCT BRAKE RH	1	51.50	51.50
SEAL BONNET REAR	1	29.35	29.35
FRT RH LOCATOR SEAL	1	56.80	56.80
SEAL ENGINE BONNET FRT	1	42.30	42.30
LH HEADLIGHT LED TECHNOLOGY	1	4,201.60	4,201.60
RH HEADLIGHT LED TECHNOLOGY	1	4,201.60	4,201.60
RH FOG LIGHT LED	1	391.10	391.10

Total Parts : 15,887.70

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 30/07/18 @ 1500 Excess S\$ _____Surveyor's Name RPM Sign _____Surveyor's No. 9006068 Authorised Yes / No _____

Authorised Date _____ Time _____

Please FIVE PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Labour 1	:	8,046.00
Parts	:	15,887.70

Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,675.36

Grand Total : 25,609.06

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **