1990000	l la	nine, le 2 abs	() LKK:
INS. CASE OWNER:	CC V /AIG1801	Hind Intally	IDAC:
R-019	ASSIGNI	MENT	18/7/18
Surveyor:	DOE BY	Date / Time :	(2 (4 (5)
	2	Registered in	Merimen: 10 Y 18
Pre-ussign / CCU / FTE			
Insured Vehicle No. 5 B	,C 33770 -	Claim No. 6+C	049756754
mounted vehicle (vo.		seas w	701400668-02.
A Name of Insured : MBK4V		Concy 1995	
Insured Tel No.	HIT A BAGGAID	Septime 1 September	MADA
Excess Sec II :SS	DOY 30/18/18	Place of Accident : 7WW	
Is driver the owner? (YES) / N	O ) Nature of Accident :	R	o E DEDIK RO. "
If NO. Driver Name / Age :	ATTENDED ATTENDED TO A TO A STATE OF THE STA	OLGIA REPORT: VEST NO	TP GIA REPORT: (ES NO
Driver Tel No.	(V/L, ATS\$ / NO )	Insured Liability	
Proposition (SPE)		5-317	
5128115T			<b></b>
INSRS:	INSRS:	INSRS:	INSRS:
WSP: DEPASHS	WSP:	WSP.	WSP
H H Tel: Y W H H	Tel: A A	Tel:	H Tel:
Embility: RMKS:	Liability : RMKS:	Liability:	Liability: RMKS:
TEA 1	RMKS: 14	RMKS:	RSIKS:
Date/ Time			116-11-11-11
212/8 1916 8/19	1-4 (817)33		DATE/PIC
24/1/10		Non-Reporting Non-Reporting	
MM		Non-Reporting	CANADA LANCE
		Notification ltr	if non-pickup)
2010 10 10	I d . N . In al. ca	Call Ot	v 281744
Exercises File pass	to shu Pei to close	After call itr to	Oleck List: Handler Typist
Bracherson		Nonfication ltr	
		After call lit to	
		Authorisation 1	
		Release Voucho	Y
		Final Repair Bi	1000
		Car Rental Inve	ice:
		Towing Invoice	
		LTA/GIA:	
		Medical Hill:	
		PIR:	
		Mundate/Reje	of Instruction
		LOD	7
		Payment Brea	kdown Form:
PRELIMINARY ADVICA: Date/Time:	Sent By:	Post-Repair P	
		Others:	
FINALIZATION Date/Time:	Confirm with:	Confirm by:	
Repair Cost: 411 SS 1/819.60		5 %	Email Cull
FINAL SETTLEMENT Date/Time: Vol 4			Cal
	(Agreed / Assessed) BOLA S/N No.: 2		Ass. Laa
Repair Cost: (W/457) 55 1,946-9	7		EAR END TP)
Loss of Rental (LOR): SS 550-0			
Less of Use (LOU): 5\$ - (5	- x - days)		
Loss of Income (LOI): SS (S	x days)	24	101.0
LOR only LOU only LOR + LOU	LOR + LO Tick only or	ne]	al allo
GIA/LTA Search SS 7-49		DESCRIPTION OF THE PROPERTY OF	ο `
Medical: 55 -			s: Nemal/Reject/Private Settle
Dishursement: SS =	(e.g. Towl Independen		nat: TP
Legal Cost SS - Total: SS 2, 504.	46 Global Sum SS:	3) Survey fee	\$320
FINAL PAYMENT Date/Time:	Confirm with:	Provide 1	Cif
Payer 1: 55 2, 504		MGINEEKIAG &	
Payer 1: SS 3, 30 4 -	Name 2:	MUINEERING &	KUDING LIBERT
Payer 3: (Strike if N.A.) SS	Name 3:		
Tallet of Families II (41/47) 1945	147900106 475		

Royau ATLY	( 7200h)
	aboto NME x I
SIOCFOFT Sweet PROTOCOLS	Type: (Cor / M.Cycle / Bes / Van / Lorry / Taxi / Prime Mover.)
DD TP WS / TP RES / OD RES / EVA / INV / MV	Truck (Trailer or
Tal Inspect Vehicle No. SLA 8115T	Makes M42D9 3 00 1496
at Workshop rate Pagasus	Golden BLUG AG Insured / Std / NI / NA
74 KDBH TOCK RU	Sp Reading 87 668 THadio Insured / Std / NT / NA
Improd	Engifile:
Policy No.	JM 6BN 22A8HO153198
Claims No.	Gen. Cond. Good / Caly / Poor / Burnt
Sum Insured Excess	Steering   Corder / Jammed / Leaked / Burnt or
(Client's Record)	Brake horder / Jammed / Leaked / Burnt or
Make of Veh.	Modi Nil / ZROn / STD A/Rim or
	Tyre Size F. 205 60R16
(Policy Condition)	R A-
Remark: The veh had commenced its N/S	G/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	> TOYO / YOKO OF WISTLAKE
Bal. or Market Value	Front A Rest (
IDAC Accident Rport: Consistent? : Yes or No	R/Bal & mm R/Bal & mm
GIA / FR Seen: Consistent? : Yes or No	L/Bal. C mm L/Bal. C mm
Est Repairs 3 stays Res: Yes or No	DOA 206 18 DOI (7/67/18
Limi Sum 6 /6 % 3 Val. Yes or No	Survey held at PEGNAN
CA / REV / REP. / 24 HRS	Des. of Damages Frt   Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN	
Date: Ferson Contacted:	The U/C / Chassis frame / Body Structure affected due to collision
	1.60   Red \$ 5,575 60   75 %)
Complete Factor Pass to President Report	Days Of Repair:
	Days Of Repair:  Resurvey No. of Trip: Survey Fee
Complete File Pass to T : Prefi. Report  Final Report  Cultivities File Return to T	per la company de la company d
CutoTies. Fix Return to?	Resurvey No. of Trip: Survey Fee
CussTurse File Return to 7	Resurvey No. of Trip: Survey Fee Transportation
CussTurse File Return to 7	Resurvey No. of Trip: Survey Fee Transportmon  d Fee: Site fresp (\$ 1 1 - Pl 1 2 4



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Inter	rnationale Des Experts En Autor	nobile	
AIG	ASIA PACIFIC INS	SURANCE PTE LTD	Ref : CC6/AIG18013	3124/R1ub3	
CH/	SHENTON WAY #0 ARTIS BUILDING GAPORE 079120	8-16	Date: 19-07-2018		
		Policy Parties	Code: AIG	IM	
1.	Insured Veh.	SBC 3377D	Veh. Inspected	SLQ 8115T	
	MARKET PRESIDENCE	SBC 3377D		0.00	
	Policy No.		Coverage (\$)	0.00	
	Claim No.		Excess (\$)	19/07/2018	
	Assign From		Assign Date	19/0/12010	
2.		Vehicle F	Particulars & Condition		
	Make & Model	1000-207-207	c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer - Steering		Steering		
	Brakes		Modification		
	General				
3.		Co	nditions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre			mm	
4.		Desc	ription of Damages		
5.		Ga	neral Information		
-	Accident Date	20/06/2018	Inspection Date	17/07/2018	
	Survey held at	PEGASUS ENGINEERING		CONTRACTOR STATE	
	Surrey mana at	51 DEFU LANE 10 SINGAPORE 539216			
5a.			Remarks		
			"WITHOUT PREJUDICE" BAS IS, WE HAVE NOT AUTHORIS		



GST / ROC COMPANY NO: 201101753C

#### Quotation

PEGASUS ENGINEERING & TRADING PTE LTD

74 KIAN TECK ROAD SINGAPORE 628800

Officer In Charge: WEE TZE FAH

Tel: Email: Customer:

GRAB RENTALS 2 PTE LTD 18 SIN MING LANE

#01-08 MIDVIEW CITY SINGAPORE 573960

Attn: : Tel : Fax No. :

Quotation No.: QO18/08-1385	Quotation Date : 20/06/2018	Terms: 30 DAYS
Vehicle No.: SLQ8115T	Chassis No.: JM6BN22A8H0153198	Third Party Insurer : AIG
Model: MAZDA 3		Date of Accident : 20/06/2018

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	REAR BUMPER	1	1,075.0000 D	1,075.00
2	REAR BUMPER REINFORCEMENT	1	538.0000	538.00
3	REAR BUMPER REFLECTOR	2	51.0000	102.00
4	REAR BUMPER SIDE RETAINER	2	92.0000 X	184.00
5	REAR BUMPER SIDE HOLDER	2	74.0000 🗡	148.00
6	REAR BUMPER SIDE HOLDER RIVETS	4	6.0000 🗙	24.00
7	REAR BUMPER TOW COVER	FIL	C 17.0000 PA	45/ 34.00
8	REAR BUMPER CLIPS	10	5.0000 🕏	/ 1-50.00
9	REAR BUMPER SCREW SPACER	2	1 4.5 10.0000 A	1 JUL 20.00
10	REAR BUMPER SPACER SCREW	2	PWN 3 15.0000 ~	30.00
11	BOOTLID	1	958.0000 >	958.00
12	BOOTLID WEATHERSTRIP	1	130.0000 >	130.00
13	BOOTLID REFLECTOR	2	265.0000 >	530,00
14	BOOTLID MAZDA 3 BADGE	1)	130.0000 🗙	130.00
15	BOOTLID SKYACTIV BADGE	1	64.0000	64.00
16	BOOTLID LOCK TOP	1	153.0000	153.00
17	BOOTLID LOCK STRIKER BOTTOM	1	35.0000 >	35.00
18	BOOTLID HINGE	2	145.0000 >	296,00
19	BOOTLID HINGE COVER	2	34.0000 /	MU 68.00
20	BOOTLID HINGE COVER CLIPS	6	5.0000	30.00
21	BOOTLID RUBBER STOPPER	2	16.0000	32.00
22	BOOTLID INNER TRIM COVER	<sub>1</sub> , ) 1	121.0000 >	121.00
23	BOOTLID INNER TRIM COVER CLIPS	4 W W 6	5.0000 >	30.00
	V-	1162.40	C	7F 0.00
	X /	113.10 -		Page 1 of 2



GST / ROC COMPANY NO: 201101753C

#### Quotation

From :

PEGASUS ENGINEERING & TRADING PTE LTD
74 KIAN TECK ROAD
SINGAPORE \$28800

Officer in Charge : WEE TZE FAH
Tel :
Email :

Customer:

GRAB RENTALS 2 PTE LTD

18 SIN MING LANE

#01-08 MIDVIEW CITY

SINGAPORE 573960

Attn::
Tel:
Fax No.:

Quotation No. : QO18/05-1365	Quotation Date: 20/06/2018	Terms: 30 DAYS
Vehicle No. : SLQ8115T	Chassis No. : JM6BN22A8H0153198	Third Party Insurer : AIG
Model: MAZDA 3		Date of Accident : 20/06/2018

DESCRIPTION		Qty	UNI	PRICE	AMOUN	
- M				75.0000	B/F	75.00
		ė.		70.0000	anal-	
		1				
REAR END PANEL INNER TRIM		1				86,00
REAR END PANEL INNER TRIM CLIPS		4		5,0000	M- /	20.00
LESS 20% ITEM (1-27)		1	-1		-	1,093,80
REAR BUMPER PARKING SENSOR		1	NW	450,0000	200 .	450.00
TO CHECK ELECTRICAL LIGHTING CONCERNED.		1	per	80.0000	X	80.00
TO RUST-PROOFING OF AFFECTED AREAS.		1		220,0000	20	220.00
TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS GARNISH AND OTHER, TO ENABLE REPAIR.	k:	1		150,0000	60	150.00
TO TRANSFER OF BOOTLID FITTING, ATTACHMENTS, AND PERFORM WATER SEEPAGE TEST.	D	1		120,0000	×	120.00
TO REINSTALL OF REAR BUMPER PARKING SENSOR.		1		120,0000	60	120.00
PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST A	ND	1		980,8000	350	980.00
n Respond of the tellisming in sense of helmostics spary positives in sense of helmostics spary positives in desplay domography positives and the positive sense of the sense of the positive sense of the sense of t	17-4	1 68 1	890	900-0000	400	900.00
is subject to man apparatus Acknowledged by Repairor	7/18 P	SII	GST(	7.00%)	10	,395.20 517.66 ,912.88
	BOOTLID CENTRE LOGO BADGE REAR END PANEL REAR END PANEL INNER TRIM REAR END PANEL INNER TRIM CLIPS LESS 20% ITEM (1-27) REAR BUMPER PARKING SENSOR TO CHECK ELECTRICAL LIGHTING CONCERNED. TO RUST-PROOFING OF AFFECTED AREAS. TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS GARNISH AND OTHER, TO ENABLE REPAIR. TO TRANSFER OF BOOTLID FITTING, ATTACHMENTS, AN PERFORM WATER SEEPAGE TEST. TO REINSTALL OF REAR BUMPER PARKING SENSOR. PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECL PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST A REALIGN THE SAME.  PUTTY-AND-SPRAY PAINTINGS OF THE AFFECTED PORT K Artles Consultable spray property in the Consultable spray property is a Subject to book approved to the Indian Indianance Company Septimentally itself to a Confinencial Indianance Company Septimentally itself in the Indianance Company Septimental Indianance Comp	BOOTLID CENTRE LOGO BADGE  REAR END PANEL  REAR END PANEL INNER TRIM  REAR END PANEL INNER TRIM CLIPS  LESS 20% ITEM (1-27)  REAR BUMPER PARKING SENSOR  TO CHECK ELECTRICAL LIGHTING CONCERNED.  TO RUST-PROOFING OF AFFECTED AREAS.  TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.  TO TRANSFER OF BOOTLID FITTING, ATTACHMENTS, AND PERFORM WATER SEEPAGE TEST.  TO REINSTALL OF REAR BUMPER PARKING SENSOR.  PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.  PUTTY-AND SPRAY PAINTINGS OF THE AFFECTED PORTION.  K Ands Georsill and a photosy is on a "Sufficient Proposition" in the control of the following is positively included that the plant of the control of the c	BOOTLID CENTRE LOGO BADGE  REAR END PANEL  REAR END PANEL INNER TRIM  REAR END PANEL INNER TRIM  1  REAR END PANEL INNER TRIM  1  REAR END PANEL INNER TRIM CLIPS  4  LESS 20% ITEM (1-27)  1  REAR BUMPER PARKING SENSOR  1  TO CHECK ELECTRICAL LIGHTING CONCERNED.  1  TO RUST-PROOFING OF AFFECTED AREAS.  1  TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.  10  TO TRANSFER OF BOOTLID FITTING, ATTACHMENTS, AND PERFORM WATER SEEPAGE TEST.  10  TO REINSTALL OF REAR BUMPER PARKING SENSOR.  11  PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.  PUTTY-AND-SPRAY PAINTINGS OF THE AFFECTED PORTION.  1  K Anths Controllables belong positively an active by belongible for the Controllables  10  TO THE AFFECTED PORTION.  1  TO SULL  1  1  1  1  1  1  1  1  1  1  1  1	BOOTLID CENTRE LOGO BADGE  REAR END PANEL  REAR END PANEL INNER TRIM  REAR END PANEL INNER TRIM CLIPS  LESS 20% ITEM (1-27)  REAR BUMPER PARKING SENSOR  TO CHECK ELECTRICAL LIGHTING CONCERNED.  TO RUST-PROOFING OF AFFECTED AREAS.  TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.  TO TRANSFER OF BOOTLID FITTING, ATTACHMENTS, AND PERFORM WATER SEEPAGE TEST.  TO REINSTALL OF REAR BUMPER PARKING SENSOR.  1  PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.  PUTTY-AND-SPRAY PAINTINGS OF THE AFFECTED PORTION.  A rise Consultants Information Indicated the reliable of the Consultance of the	BOOTLID CENTRE LOGO BADGE  REAR END PANEL  REAR END PANEL INNER TRIM  REAR END PANEL INNER TRIM  REAR END PANEL INNER TRIM CLIPS  LESS 20% ITEM (1-27)  REAR BUMPER PARKING SENSOR  TO CHECK ELECTRICAL LIGHTING CONCERNED.  TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS,  TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS,  TO TRANSFER OF BOOTLID FITTING, ATTACHMENTS, AND  TO REINSTALL OF REAR BUMPER PARKING SENSOR.  PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY  PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND  REALIGN THE SAME.  BUTTY-AND-SPRAY PAINTINGS OF THE AFFECTED PORTION.  K Antis Consultants innocent from the innomed Guing tog  To display during of control of the following town of your positions of the Research of the following in the control of the following in the	BOOTLID CENTRE LOGO BADGE  REAR END PANEL  REAR END PANEL  REAR END PANEL INNER TRIM  REAR END PANEL INNER TRIM CLIPS  LESS 20% ITEM (1-27)  REAR BUMPER PARKING SENSOR  TO CHECK ELECTRICAL LIGHTING CONCERNED.  TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS,  GARNISH AND OTHER, TO ENABLE REPAIR.  TO TRANSFER OF BOOTLID FITTING, ATTACHMENTS, AND  PERFORM WATER SEEPAGE TEST.  TO REINSTALL OF REAR BUMPER PARKING SENSOR.  PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY  PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND  REALIGN THE SAME.  PULTTY-AND-SPRAY PAINTINGS OF THE AFFECTED PORTION.  K Antic Constitution setup of politics of the Control of the Contro



GST / ROC COMPANY NO: 201101753C

#### Quotation

From:

PEGASUS ENGINEERING & TRADING PTE LTD

74 KIAN TECK ROAD SINGAPORE 628800

Officer in Charge: WEE TZE FAH

Tel: Email: Customer:

GRAB RENTALS 2 PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960

Attn:: Tel:

Fax No.:

Quotation No.: QO18/06-1365	Quotation Date: 20/06/2018	Terms: 30 DAYS
Vehicle No. : SLQ8115T	Chassis No.: JM6BN22A8H0153198	Third Party Insurer : AIG
Model: MAZDA 3	Date of Accident: 20/06/2018	

ITEM	DESCRIPTION	Qty	UNIT PRICE AMO	UNT (SGD)
1	REAR BUMPER	1	1,075.0000 <b>DE</b> /	1,075.00
2	REAR BUMPER REINFORCEMENT	1	538.0000 ?	538.00
3	REAR BUMPER REFLECTOR	2	51.0000 🔀	102.00
4	REAR BUMPER SIDE RETAINER	2	92.0000 ★	184.00
5	REAR BUMPER SIDE HOLDER	2	74.0000 🗶	148.00
6	REAR BUMPER SIDE HOLDER RIVETS	4	6.0000	24.00
7	REAR BUMPER TOW COVER	FIL	C 17.0000 MS	34.00
8	REAR BUMPER CLIPS	10	5.0000 Re	50.00
9	REAR BUMPER SCREW SPACER	2	115 10.0000 AL	20.00
10	REAR BUMPER SPACER SCREW	2	pwn 3 15.0000 ~ -	30.00
11	BOOTLID	1	958.0000 🗶	958.00
12	BOOTLID WEATHERSTRIP	1	130.0000 🗶	130.00
13	BOOTLID REFLECTOR	2	265.0000 🗶	530.00
14	BOOTLID MAZDA 3 BADGE	1	130.0000 🗙	130.00
15	BOOTLID SKYACTIV BADGE	1	64.0000	64.00
16	BOOTLID LOCK TOP	1	153.0000	153.00
17	BOOTLID LOCK STRIKER BOTTOM	1	35.0000 🗡	35.00
18	BOOTLID HINGE	2	148.0000 🗡	296.00
19	BOOTLID HINGE COVER	2	34.0000 🗡	68.00
20	BOOTLID HINGE COVER CLIPS	6	5.0000	30.00
21	BOOTLID RUBBER STOPPER	2	16.0000	32.00
22	BOOTLID INNER TRIM COVER	1	121.0000	121.00
23	BOOTLID INNER TRIM COVER CLIPS	6	5.0000 🗡	30.00



GST / ROC COMPANY NO: 201101753C

#### Quotation

From:

PEGASUS ENGINEERING & TRADING PTE LTD

Remarks: INSURED'S VEH NO: SBC3377D

74 KIAN TECK ROAD SINGAPORE 628800

Officer in Charge: WEE TZE FAH

Tel: Email: Customer:

GRAB RENTALS 2 PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960

Attn:: Tel:

Fax No.:

Quotation No.: QO18/06-1365 Quotation Date: 20/06/2018 Terms: 30 DAYS Third Party Insurer: AIG Vehicle No.: SLQ8115T Chassis No.: JM6BN22A8H0153198 Date of Accident: 20/06/2018 Model: MAZDA 3

ITEM	DESCRIPTION	Qty	UNIT PRICE AMO	DUNT (SGD)
			B/F	0.00
24	BOOTLID CENTRE LOGO BADGE	-1	75.0000 🗡	75.00
25	REAR END PANEL	1	506.0000 Rego	506.00
26	REAR END PANEL INNER TRIM	1	86.0000 🗶	86.00
27	REAR END PANEL INNER TRIM CLIPS	4	5.0000	20.00
28	LESS 20% ITEM (1-27)	1	-1,093.8000	-1,093.80
29	REAR BUMPER PARKING SENSOR	1	450,0000 200	450.00
30	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	80.0000 🗶	80.00
31	TO RUST-PROOFING OF AFFECTED AREAS.	1	220,0000 20	220.00
32	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	1	150,0000 60	150.00
33	TO TRANSFER OF BOOTLID FITTING, ATTACHMENTS, AND PERFORM WATER SEEPAGE TEST.	1	120.0000 🗙	120.00
34	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	1	120,0000 6 0	120.00
35	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	980,8000 7	980.00
36	PUTTY AND SPRAY PAINTINGS OF THE AFFECTED PORTION.	1	90,0000 40	900.00
in a	LL 900	8000		

. To display consume 1 per sale Parts poots and publicants confirmations Third poffs survey is not a "Afficiant Fingurer" 4 mile. · lig days — the service service Substantial participant on converged and
 It substantials approved from the substantial Contemp

Administrated by Registral

3 days

P/P

17/07/18 P/S/10 Sub Total
GST(7.00%)
Total (SGD)

Resy L4 part

7,395.20 517.66 7,912.86

Please conduct the survey at Pegasus Engineering @ 74 Kian Teck Road Singapore 628800

## > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID: Vehicle Details	1345N
Vehicle No.:	SLQ8115T
Vehicle to be Exported:	Yes
Intended De-registration Date:	23 Jun 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	P520444876
Chassis No.:	JM6BN22A8H0153198
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,761.00
Original Registration Date:	24 Jul 2017
First Registration Date:	24 Jul 2017
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$9,761.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jul 2027
PARF Rebate Amount: Intended COE Rebate Details	\$7,320.00
COE Expiry Date:	23 Jul 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$34,240.00
Total Rebate Amount:	\$41,560.00

The information contained herein is correct as at 23 Jun 2018

## Khanchna (LKK Auto)

From: Sent:	Pauline Ngu <pauline.pegasusengrg@gmail.com> Thursday, 5 September 2019 4:10 PM</pauline.pegasusengrg@gmail.com>				
To: Cc:	Khanchna (LKK Auto) Shu Pei (LKKAuto); Soon Tat Ng; Pegasus Engineering; xianchern.pegasusengrg; lionelchua@pegasusengrg.com.sg; Admin A				
Subject:	Re: LOD - Third party claim - Our ref: SLQ8115T Your ref: SBC3377D on 20/06/2018				
Without Prejudice					
Dear Khanchna,					
We refer to above mentioned of	laim.				
We agree with the repair costs and Loss of income as below:-	and LTA search fee. But we would like to counter propose for Loss of rental				
LOR @ 5 days x \$66.95 = \$33	4.75				
LOE @ 5 days x \$120.00 = \$6					
FOUNDE CEX &	NO ):				
Kindly consider to revise your	offer.				
We look forward to hearing from	n you soon.				
Have a nice day!					
Many thanks.					
Best Regards,					

#### Khánchna (LKK Auto)

From:

Khanchna (LKK Auto)

Sent:

Thursday, 5 September 2019 5:30 PM

To:

Pauline Ngu

Cc:

Shu Pei (LKKAuto); Soon Tat Ng; Pegasus Engineering; xianchern.pegasusengrg;

lionelchua@pegasusengrg.com.sg; Admin A

Subject:

RE: LOD - Third party claim - Our ref: SLQ8115T Your ref: SBC3377D on 20/06/2018

Tracking:

Recipient

Delivery

Pauline Ngu

Shu Pei (LKKAuto)

Delivered: 5/9/2019 5:30 PM

Soon Tat Ng

Pegasus Engineering xianchern.pegasusengrg

lionelchua@pegasusengrg.com.sq

Admin A

olivialau@lkkauto.com

Delivered: 5/9/2019 5:30 PM

Meikwan@lkkauto.com

Delivered: 5/9/2019 5:30 PM

Without Prejudice

Our Ref: CC6/AIG18013124/R1kb3

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows:

x \$110)	
2. Loss of Rental/ Loss of Income (5 days x \$110)	\$ 550.00
. Cost of Repair (w/GST)	\$ 1,946.97

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

#### Khanchna (LKK Auto)

From:

Khanchna (LKK Auto)

Sent:

Monday, 26 August 2019 3:29 PM

To:

Shu Pei (LKKAuto); pauline.pegasusengrg@gmail.com

Cc:

Soon Tat Ng; Pegasus Engineering; xianchern.pegasusengrg;

lionelchua@pegasusengrg.com.sg; Admin A

Subject:

RE: LOD - Third party claim - Our ref: SLQ8115T Your ref: SBC3377D on 20/06/2018

Without Prejudice

Our Ref: CC6/AIG18013124/R1kb3

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows:

1. Cost of Repair (w/GST)	\$ 1,946.97
2. Loss of Rental/ Loss of Income (4 days x \$100)	\$ 400.00
3.LTA Search Fee	\$ 7.49
Total	\$ 2,354.46

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: <u>Khanchna@lkkauto.com</u> Fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



MSIG Insurance (Singapore) Pts. Ltd. 4 Shemton Way, #21-01, SGX Centre 2, Singapore 068607 Tel +55 6827 7888, Fax +65 6827 7800 Co. Reg. No. 200412212G GST Reg. No. 20-041221G

## Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)

THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE) OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.2.400 Cars for Hire COMMERCIAL VEHICLE - FLEET Comprehensive

Certificate No.

A 29069774 MKF

Excess: SGD2,000

1. Index Mark and Registration Number of Vehicle

SLQB115T

2. Name of Policyholder

Grab Rentals 2 Pte. Ltd.

3. Effective Date of the Commencement of Insurance for the purposes of the Act

01/02/2018

4. Date of Expiry of Insurance

31/01/2019

5. Persons or Classes of Persons entitled to drive

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

\* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use\*

Use for the carriage of passengers or goods in connection with the Policyholder's business.

Use for social domestic and pleasure purposes.

The Policy does not cover

- (1) Use for racing pace-making reliability trial or speed-testing.
- (2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act. 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.

Approved Insurers

Chief Executive Officer

<sup>\*</sup> Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.



No.1, Sunview Road #08-15 Eco-Tech@Sunview Singapore 627615 Tel: 6513 7748 / HP 9628 6508

.....

Fax: 6251 3161

Our F	Ref: VSR18-23278 for SLQ8115T	Da	te: _15.07.201	9
Your	Ref: SBC3377D			
		WIT	HOUT PREJU	UDICE
Claim	s Department - Executive In Charge			
AIG	ASIA PACIFIC INSURANCE PTE LTD			
Dear	Sin/Madam,			
ACC	IDENT INVOLVING SLQ8115T AND SBC3377D ON 20	/06/2018		
Refe	r to the above accident and please acknowledge receipt of t	his letter within 14 days		
	pears that the accident was caused by your insured. Enclos as our client had authorized us to quantify, to act and to re			
- <del>0</del> Or	iginal Tax-invoice number IV19/07-1101 0	police report / police res	sult	
-O Cer	rtificate Of Insurance MSIG OV	ehicle search result		
0 Let	tter from Grab — A	uthorization To Act - H	rer / Owner	
O-RE	NTAL TARIFF			
*Surv	vey under insurance instruction - RASUL			
a)	Cost of repair (inclusive GST)	s	1,946.97	
b)	Vehicle Search Fees / GIA fees / Police Report Fees / R	Reporting fees S	7.49	
c)	Loss of rental 5 days @ \$66.95	() s	334,75	
d)	Loss of earnings/ rental fee 5 days @ \$150.00	\$	750.00	
€) (Waiv	Administrative charges to negotiate settlement ie if 100% offer made within acknowledge timeframe)	\$	107.00	
	Total	\$	3,146.21	

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Pegasus Engineering & Trading Pte Ltd" within 28 days.

Yours faithfully,

Lionel Chua

Email: lionelchua@pegasusengrq.com.sg



<sup>\*</sup> Driver's injury and other losses exclude in this claim.



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Our Ref: CC6/AIG18013124/R1kb3

8 JULY 2019

MARIA LI SUK MEE

23A NALLUR ROAD SINGAPORE 456644

Dear Sir/Madam.

#### ACCIDENT INVOLVING SBC3377D & SLQ 8115T ALONG NEW UPPER CHANGI RD & BEDOK RD ON 20/06/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SLQ 8115T against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

KHANCHNA Case Handler DID: 6841-2360

FAX: 6741 4108

Email: khanchna@lkkauto.com

AIG Asia Pacific Insurance Pte Ltd C.C. (Motor Claims Dept)

# AUTHORIZATION TO ACT

US ENGINEERING & TRADING PTE LTD
ER OF VEHICLE NUMBER SLQ 8115 T
INVOLVING SBC 3377 D
New Upper Changi Road and Badok Road
authorize you to act on my behalf in pursuance of my claim for loss of rental , ring the repair arising out of the above accident.
serve as the "AUTHORITY TO ACT".
eby authorize all agreed settlement payment be made in favour to PEGASUS ING & TRADING PTE LTD.
: Grab Rentals 2 Pte Ltd
: 201701345N
: 18 Sin Ming Lane #01-08 Midview City Singapore 573960
: 6655 0005
:

Owner

WITHOUT PREJUDICE TO:

(a) Insurance Subrogated Claim and/or

(b) Any Claims
[Note: This Notice supersedes any inconsistencies found in this Discharge Voucher]

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

# RELEASE VOUCHER (AIG Asia Pacific - Express Third Party Claim)

"We/I, PEGASUS ENGINEERING & TRADING PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$1,946.97 (Repair Cost), S\$550.00(Loss of Use/Rental), S\$7.49(Disbursement) for vehicle no. SLO8115T that was damaged pursuant to the accident which occurred on 20/06/2018 (date) along JUNCTION ROAD OF NEW UPPER CHANGI ROAD (location) involving vehicle no/s SBC3377D. This is pursuant to the inspection conducted on 17/07/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner GRAB RENTALS PTE LTD (the third party claimant") of vehicle no. SLQ8115T make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to <a href="SLQ8115T">SLQ8115T</a>(vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this \_\_\_\_\_\_\_ (day) of \_\_\_\_\_\_ Saptember (month) 20\_\_\_\_\_ (year)

| Signed by appointed surveyor | Signed by "the workshop" (with chop)



GST / ROC COMPANY NO: 201101753C

#### Tax Invoice

From:

PEGASUS ENGINEERING & TRADING PTE LTD

74 KIAN TECK ROAD SINGAPORE 628800

Officer in Charge: WEE TZE FAH

Tel: Email: Customer:

**GRAB RENTALS 2 PTE LTD** 

18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960

Attn:: Tel:

Fax No.:

Model: MAZDA 3

Remarks: TP INSURER: AIG, INSURED'S VEHICLE NO: SBC3377D, DATE OF ACCIDENT: 20/06/2018

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	TO PART BY PART REPAIR AS RECOMMENDED BY SURVEYOR -	1	1,819.6000	1,819.60

Cheques should be crossed & made payable to PEGASUS ENGINEERING & TRADING PTE LTD

Sub Total GST(7.00%) Total (SGD) 1,819.60 127.37 1,946.97

PEGASUS ENGINEERING & TRADING PTE LTD

Pauline Pauline



Our Ref: GR-ACC-2017-02

01 June 2017

Pagasus Engineering & Trading Pte Ltd No. 51 Defu Lane 10 Singapore 539218 Mailing Address 18 Sin Ming Lane, #01-08 Midview City, Singapore 573960 Co. No. 201617200G

To whom it may concern,

Re: Vehicle Rental Rates for Loss of Rental Claims.

With regards to the above subject matter, we are pleased to inform you our Grab Rental sate for our various vehicles which are as follows:

S/No.	Make & Model	Daily Rental Rates (S\$)
01	Toyota Prius 1,798cc, 90kw, 120bhp, Automatic	\$ 79.95
02	Mezde 3 1.5 (A) Sedan	\$ 66,95
03	Nissan Qashqal 1.2L	\$78.95
04	Honda Vezel 1.5L	\$77.95
05	Honda Vezel 1.5L Hybrid	\$84.95
06	Toyota Vios 1.5L	\$86.95 .

Please note that the above stated rate is our daily rental rate to our drivers. For your necessary actions on third party accident cialms on less of rental.

Yours fall fully,

Tay Chee Wee Grab Rental Pte Ltd

Vehicle Hub 7/16/2018

# Enquire Vehicle & Owner Information ( Vehicle No. SBC3377D As At 20 Jun 2018 / 08:30:00 )

#### Law Firm Search Details

Search Reason:

Insurance claim in relation to traffic accident

Law Firm Case No.:

SLQ8115T

#### **Current Owner Details**

Owner ID Type:

Singapore NRIC

Owner ID:

525966271

Owner Name:

MARIA LI SUK MEE

Registered Address Type:

Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 23A

Registered Street Name:

NALLUR ROAD

Registered Unit No.:

#10-01

Registered Building Name: -

Registered Postal Code:

456644

#### **Current Vehicle Details**

Vehicle No.:

SBC3377D

Make Description/Model: MAZDA / MAZDA6 WAGON 2.5 A/T ABS D/AIRBAG 2WD SR

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.



Lee Ming Hui Kelvin has successfully logged out.

Your last login date and time was 16 Jul 2018, 14:31:10.

To return to ONE MOTORING, please click here

For security reasons, please CLEAR YOUR CACHE after each session.

#### Session Transaction History

5/No.35	Asset Type:	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(3\$)
1	Vehicle	5BC3377D		18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49
2	Vehicle	5DD908M		18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

AIM SUE	FOLDER TRA	A STATE OF THE PARTY OF THE PAR	Two was a const	FACILITIES OF		Taran e	CATALOGE	Trans. Acceptant	Evan	110		
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt		Ad) S	ubmitted	Ins Auth'ed	Status			
Main	20 Jul 2018 Edit Rag		17 Jul 2018 00:00 Edit Adj Rpt	S\$1,819	0.00	100.00	819.60 w Apt		Pending for Survey Report Cancel Case			
	Main	R	eference	l c	aim Det	alls		Documen	ts	1	Show All	
CLAIM S	UBFOLDER D	ETAILS		46			[Created	by adjuster]				
insured:	Li Suk M	ee Maria, ID: 52	5966271									
Main Claimant:	GRAB RE	NTALS PTE LTD,	Co. Reg. No.: 20	1617200G								
Vehicle Re No.:	9. SLQ811	.5T			Date of	Loss:		18 08:00 - :59 na and <b>27</b> Days Fr	rom LTA	Reg Date	(Man Yr)]	
Claim Typ	e: TP / 6756497563SG Policy/Cover Note No.: (Comprehensive)											
Vehicle Re No. (Insured):	SBC3377D (Claimant): A29069766MKF											
400100000000000000000000000000000000000					Excess:							
Repairer:			rading Pte Ltd (Ki									
Handling Insurer:		Pacific Insuranc Qian Ler@aig.com	e Pte. Ltd. (Expre	ess) - Tel: 6	-6419-3	000	. [Handled	by Ler, Bernard-	-JQ]			
Claimant's Insurer:	MSIG In		ore) Pte. Ltd. (HQ									
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 6	256-3561	[Handle	t by M	OHD RASI	JL] [Final R	pt due :	30/07/20	018]	
ASSOCIA	TED MAIL R	ECEIVED						V	lew All	Compos	se Case Mai	
There are	no mail for this	s case.										
ALL ASS	OCIATED TA	sks=				_ Y	View All	Search Tasks	Create N	ew Task	Complet	
Due De	to Delevite	Type Tool	Group Subje	ct Hand	or .	_	ned By	Completed Or		reated Or	Done	
No results		Type Task	oroup subje	et mana		425191	and by	Campieced Of		Lacea O		

#### Claim Documents

\*SLQ8115T (6756497563SG)

[SBC3377D]

TP

GRAB RENTALS PTE LTD

Jun 20 2018 8:00AM

[Li Suk Mee Maria]

Pegasus Engineering & Trading Pte Ltd

Let	ters/Corresponder	ces	1 per p	age 🔻	80
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	6	Edit	
				1771	12
Pho	tos/Images	The state of the s	3 per p		₩.
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	-	Thumbnail	-
1_	08/07/19 10:38	General View	0	Load JPG	8
2	08/07/19 10:38	Chassis Number	0	Load JPG	8
3	08/07/19 10:38	General View	0	Load JPG	2
4	08/07/19 10:38	General View	0	Load JPG	2
5	08/07/19 10:38	General View	0	Load JPG	N
6	08/07/19 10:38	General View	0	Load JPG	100
7	08/07/19 10:38	General View	0	Load JPG	Ø
8	08/07/19 10:38	General View	0	Load JPG	Ø
9	08/07/19 10:38	General View	0	Load JPG	12
10	08/07/19 10:38	General View	0	Load JPG	Ø
	WEIGHT COSC HIGH VAN	COUNTRY CONTRACTOR	0	Load 3PG	Ø
11	08/07/19 10:38	General View	0	Load 3PG	Ø
17	08/07/19 10:38	General View			+
13	08/07/19 10:38	General View	0	Load JPG	8
14	08/07/19 10:38	General View	0	Load JPG	₩.
15	06/07/19 10:38	General View	0	Load JPG	8
16	08/07/19 10:38	General View	0	Load JPG	8
17	08/07/19 10:38	General View	0	Load JPG	2
18	08/07/19 10:38	General View	0	Load JPG	2
19	08/07/19 10:38	General View	0	Load JPG	80
20	08/07/19 10:38	General View	6	Load JPG	120
21	08/07/19 10:38	General View	0	Load JPG	100
	10012219211222	General View	0	Load JPG	M
22	08/07/19 10:38	TEXTS (ACCUSED)	0	Load JPG	12
23	08/07/19 10:38	General View			8
24	08/07/19 10:38	General View	0	Load JPG	DEC)
Da	cumentation		1 per	page V	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	- Louis tinti	Thumbnail	-
1	19/07/18 17:53	TP ESTIMATE- MARKED	0	Load PDF	
2	19/07/18 17:53	TP GIA REPORT	0	Load FDF	
3	08/07/19 10:45	LETTER TO OI	0	Load PDF	
4	27/09/19 08:31	WORKSHOP INVOICE	0	Load PDF	
5	27/09/19 08:31	AUTHORISATION TO ACT FORM	0	Load PDF	
6	27/09/19 08:31	Release Voucher	0	Load PDF	
7	27/09/19 08:31	RENTAL RATES	0	Load PDF	
8	27/09/19 08:31	LTA SEARCH	0	Load PDF	
9	27/09/19 08:31	LOD	0	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	20/07/18 09:48	OI GIA REPORT	0	Load PDF	

#### **Documents Checklist**

DOCUMENTS CHECKLIST

	Reset   Save   Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Hendling Insurer Note: Remarks are private unless you show it to other parties.	

NOTE:	TO BE	COMP	ETED	RV	SURVEYOR
NO IE:	100	CONP	LEIED	D 1	SURVETUR

TEAM					
	_	_	_		_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehi	cle No:	SBC3377D (Insd veh)		Model:	MAZDA 3 1.5 SEDAN EU6	
		SLQ81	15T (TP veh	)		(A)
Date	Date of Accident: 20/06/2018					
Glob	al Sum Settlen	nent :	[ ] Yes		[X] No	
Rep	air Estimate			: \$	7,912.86	
Fina	Repair Cost			: \$	1,946.97	
Loss	of Use			: \$		days at \$0.00 per day
Ren	tal (if any)			: \$	550.00	5 days
LTA / GIA Search Fee			: \$	7.49		
Othe	ers:			: \$	0.00	
CO. 14 C. 2. 2.			: \$			
Final Settlement Sum			: \$	2,504.46		
	hird Party Wor	kshop (	GIA Register	ed?	[ ] YES [	X ] NO (Kindly indicate
belov					- 1889-24WW	200
A)	For Non GIA F	tegister	ed Worksho	p:	Agreed Liability _	
B)	For GIA Regis	tered W	orkshop:		BOLA Applicable:	Yes/ No BOLA Scenario No:
	BOLA Liability:		(%)		Assessed Liability	/ (*):(%)
	* Assessed Lie	bility to I	be filled only	for cha	in collisions and for co	ases where BOLA does not apply
Ren	narks					
_						
Pay	ment Instructi	on: Pay	ee's Breakdo	own		
1)	Pegasus Engineering & Trading Pte Ltd			: \$	2,504.46	
2)					: S	
3)					: \$	
~/					: \$	

 JOANNE LEE KHANG MIN
 27 Sep 2019

 LKK Auto Consultants Pte Ltd
 Date

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

#### LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC6/AIG18013124/R1KB3Q2

Date:

Insured Vehicle No: SBC3377D

27/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant

Policy No:

Vehicle No: Date of Loss:

SLQ8115T 20/06/2018

Nature of Claim:

Claim No: 6756497563SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

**SLQ8115T** 

Make & Model:

MAZDA 3, 1.5 SEDAN EU6 (A)

Engine No:

P520444876

Reg. Date:

24/07/2017 (Man. Year: 2017)

Chassis No:

JM6BN22A8H0153198

Colour:

1496 cc

Odometer:

87008 km

Engine Capacity:

Market Value/New Car

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable):

Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side:

West Lake 6 mm

Rear Left Side:

West Lake 6 mm

Front Right Side:

West Lake 6 mm

Rear Right Side:

West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,825.20	929.60	3,895.60	80.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,570.00	890.00	1,680.00	65.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	3,895.60 0.00 1,680.00	
Gross Total (S\$)	7,395.20	1,819.60		75.39 75.40
+ GST 7.00/7.00% (S\$)	517.66	127.37		
Nett Amount (S\$)	7,912.86	1,946.97	5,965.89	75.39
+ Car Rental (5.0 x SS	\$110.00/day) (S\$)	550.00		
+ Doc	/Search Fee (S\$)	7.49		

Nett Liability (S\$)

INSPECTION

Date of Assignment:

17/07/2018

Date Inspected:

17/07/2018 Inspected At:

Pegasus Engineering & Trading Pte

Ltd (Kian Teck) 74 Kian Teck Road Singapore 628800

2,504.46

Estimated Period of Repair:

3.0 days

Adjuster: MOHD RASUL Manager: Khanchna Pothuraj

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=g... 27/9/2019

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

Recomm	nended	Parts
110001111		I GILO

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,075.00 FL	*1,075.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Not Necessary	538.00 FL	*-FL
3	2		*REAR BUMPER REFLECTOR	Not Necessary	102.00 FL	*-FL
4	2		*REAR BUMPER SIDE RETAINER	Not Necessary	184.00 FL	*-FL
5	2		*REAR BUMPER SIDE HOLDER	Not Necessary	148.00 FL	*-FL
6	4		*REAR BUMPER SIDE HOLDER RIVETS	Not Necessary	24.00 FL	*-FL
7	2		*REAR BUMPER TOW COVER	Missing (1 PCS ONLY)	34.00 FL	*17.00 FL
8	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
9	2		*REAR BUMPER SCREW SPACER	Not Necessary	20.00 FL	*- FL
10	2		*REAR BUMPER SPACER SCREW	Not Necessary	30.00 FL	*-FL
11	1		*BOOTLID	Not Necessary	958.00 FL	*-FL
12	1		*BOOTLID WEATHERSTRIP	Not Necessary	130.00 FL	*-FL
13	2		*BOOTLID REFLECTOR	Not Necessary	530.00 FL	*-FL
14	1		*BOOTLID MAZDA 3 BADGE	Not Necessary	130.00 FL	*-FL
15	1		*BOOTLID SKYACTIV BADGE	Not Necessary	64.00 FL	*-FL
16	1		*BOOTLID LOCK TOP	Not Necessary	153.00 FL	*-FL
17	1		*BOOTLID LOCK STRIKER BOTTOM	Not Necessary	35.00 FL	*-FL
18	2		*BOOTLID HINGE	Not Necessary	296.00 FL	*-FL
19	2		*BOOTLID HINGE COVER	Not Necessary	68.00 FL	*- FL
20	6		*BOOTLID HINGE COVER CLIPS	Not Necessary	30.00 FL	*-FL
21	2		*BOOTLID RUBBER STOPPER	Not Necessary	32.00 FL	*-FL
22	1		*BOOTLID INNER TRIM COVER	Not Necessary	121.00 FL	*-FL
23	6		*BOOTLID INNER TRIM COVER CLIPS	Not Necessary	30.00 FL	*- FL
24	1		*BOOTLID CENTRE LOGO BADGE	Not Necessary	75.00 FL	*-FL
25	1		*REAR END PANEL	Repair	506.00 FL	*- FL
26	1		*REAR END PANEL INNER TRIM	Not Necessary	86.00 FL	*-FL
27	4		*REAR END PANEL INNER TRIM CLIPS	Necessary	20.00 FL	*20.00 FL
28	1		*REAR BUMPER PARKING SENSOR	Not Necessary	450.00 FS	*-F8
F=Fr	anchise	part. S=Spo	Nett. L=ListItemDisc.	E 2012 P 2012		4 400 00
Sub Total (S\$)				1,162.00		
	- List Item Discount on L Items 20.00/20.00% (S\$)			1,093.80	232.40	
				Total Parts (S\$)	4,825.20	929.60

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	80.00	0.00
2	TO RUST -PROOFING OF AFFECTED AREAS	New	220.00	20.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR	New	150.00	60.00
4	TO TRANSFER OF BOOTLID FITTING ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	120.00	0.00
5	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	120.00	60.00
6	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	980.00	350.00
7	PUTTY AND SPRAY PAINTINGS OF THE AFFECTED PORTION	New	900.00	400.00
	Gross Labo	ur Cost (S\$)	2,570.00	890.00

< END OF ESTIMATES >