

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9357X**AAD1807-156***Not Notified
1/1/18*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9357X

KL1LA69RJB072798

CHEVROLET

EPICA 2.0

16.7.2018

AIG

		PART		LIST
1	1	Front Bumper	\$	<i>CM</i> 1,202.00 ✓
2	1	Front Bumper Reinforcement	\$	295.25 ?
3	1	Front Bumper Lower Absorber	\$	180.00 ?
4	1	Front Bumper Lower Grille	\$	<i>RM</i> 78.00 ✓
5	1	Front Bumper Retainer RH	\$	<i>RM</i> 102.00 X
6	1	Front Bumper Retainer LH	\$	<i>RM</i> 102.00 X
7	1	Front Bumper Lower Stiffener	\$	<i>RM</i> 134.37 X
8	1	Front Headlamp RH	\$	<i>RM</i> 816.00 X
9	1	Front Headlamp LH	\$	<i>RM</i> 816.00 X
10	1	Front Support Panel Assy (Panel A-Frt)	\$	<i>RM</i> 1,222.32 X
11	1	Bonnet (Panel A-Hood)	\$	<i>RM</i> 1,250.00 X
12	1	Centre 'CHEVROLET' Logo Badge	\$	<i>RM</i> 144.30 X
13	1	Bonnet Moulding	\$	<i>RM</i> 257.00 X
14	1	Radiator Grille (Grille A-Rad)	\$	<i>CM</i> 367.00 ✓
15	1	Radiator Assembly (Radiator A)	\$	<i>RM</i> 618.00 X
16	1	Aircon Condenser (Condenser A)	\$	<i>RM</i> 600.00 X
17	1	Air Intercooler	\$	<i>RM</i> 652.00 X
18	1	Fan Blade (Small)	\$	<i>RM</i> 536.00 X
19	1	Fan Blade (Big)	\$	<i>RM</i> 634.00 X
20	1	Front Fender LH	\$	<i>RM</i> 837.60 X
21	1	Front Fender RH	\$	<i>RM</i> 837.60 X
22	1	Rear Bumper	\$	<i>RM</i> 1,202.00 ✓
23	1	Rear Bumper Beam	\$	<i>RM</i> 239.94 ✓
24	1	Rear Bumper Centre Absorber	\$	<i>CM</i> 260.00 ✓
25	1	Rear Bumper Side Retainer RH	\$	<i>CM</i> 68.76 ✓
26	1	Rear Bumper Side Retainer LH	\$	<i>CM</i> 68.76 ✓
27	1	Rear Bumper side support RH	\$	<i>RM</i> 25.00 ✓

Trans-cab Auto Services Pte Ltd**AAD1807-156**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9357X

28	1	Rear Bumper side support LH	\$	Sh 25.00 X
29	1	Rear Bumper Reflectors RH	\$	Bo 119.74 —
30	1	Rear Bumper Reflectors LH	\$	cm 119.74 —
31	1	Rear Bumper Tow Hook Cover	\$	h1 93.00 —
32	1	Rear Luggage Floor Panel	\$	R 973.00 X
33	1	Rear Luggage Floor Panel Insulator	\$	Sh 63.50 X
34	1	Rear Luggage Floor Panel Trim Board	\$	Sh 378.00 X
35	1	Rear End Panel Inner	\$	B 336.84 —
36	1	Rear End Panel Outer	\$	R 623.76 —
37	1	Rear End Panel Inner Trim	\$	D1 263.84 —
38	1	Bootlid	\$	R 973.00 X
39	1	Bootlid inner trim board	\$	Sh 400.00 X
40	1	Bootlid Weatherstrip	\$	Sh 344.28 X
41	1	Bootlid Lock - Top	\$	R 466.56 X
42	1	Bootlid lock - bottom	\$	R 39.40 X
43	1	Bootlid 'CHEVROLET' Badge	\$	Sh 120.62 —
44	1	Bootlid Logo	\$	Sh 138.84 —
45	1	Bootlid 'EPICA LT' Badge	\$	Sh 119.84 —
46	1	Bootlid inner handle	\$	Sh 45.55
47	1	Bootlid Reflector Centre	\$	Sh 217.97
48	1	Bootlid Reflector RH	\$	Sh 128.40
49	1	Bootlid Reflector LH	\$	Sh 128.40
50	1	Bootlid Hinge RH	\$	R 120.00
51	1	Bootlid Hinge LH	\$	R 120.00
52	1	Rear Tail Lamp RH	\$	Sh 479.30
53	1	Rear Tail Lamp Panel RH	\$	R 359.00
54	1	Rear Tail Lamp LH	\$	Sh 479.30
55	1	Rear Tail Lamp Panel LH	\$	R 359.00
56	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	R 1,110.00
57	1	Rear Fender RH	\$	R 1,145.00
58	1	Rear Fender Inner Cowling RH	\$	Sh 298.00
59	1	Rear Fender Inner Trim RH	\$	Sh 418.44
60	1	Rear Fender LH	\$	R 1,145.00
61	1	Rear Fender Inner Cowling LH	\$	Sh 298.00
62	1	Rear Fender Inner Trim LH	\$	Sh 418.44

Trans-cab Auto Services Pte Ltd**AAD1807-156**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9357X

TOTAL	\$	26,414.66
10%	\$	2,641.47
	\$	23,773.19

Special Nett

1	1Set	Front Bumper Fastener Clip	\$	<i>na</i> 24.00 ✓
2	1Set	Front Licence Plate With Holder	\$	<i>B</i> 192.00 <i>25na</i>
3	1Set	Bonnet Insulator Clip	\$	<i>na</i> 40.00 X
4	1Set	Radiator Grille Clip	\$	<i>na</i> 18.00 ✓
5	1Set	Bootlid inner trim board Clip	\$	<i>na</i> 40.00 X
6	1Set	Radiator Grille Top Cover Clip	\$	<i>na</i> 10.00 X
7	1Set	Front Fender Liner Clip	\$	<i>na</i> 40.00 X
8	1Set	Rear Bumper Parking Sensor	\$	<i>CD</i> 300.00 ✓
9	1Set	Rear Bumper Fastener Clip	\$	<i>na</i> 30.00 ✓
10	2Set	Rear Fender inner cowling clip	\$	<i>na</i> 30.00 X
11	1Set	Rear Fender Inner Trim Clip RH	\$	<i>na</i> 30.00 X
12	1Set	Rear Fender Inner Trim Clip LH	\$	<i>na</i> 30.00 X
13	1Set	Rear Bumper End Dust Cover Clip	\$	<i>na</i> 30.00 X
14	1	Rear Boot Sticker 'Trans-cab'	\$	<i>na</i> 30.00 ✓
15	1	Rear Boot Sticker '6555-3333'	\$	<i>na</i> 30.00 ✓
16	1	Rear Exhaust Mounting	\$	<i>na</i> 10.00 X
17	1	Rear Bumper End Sealant	\$	<i>na</i> 80.00 X
18	2	Rear Windscreen Sealant	\$	<i>na</i> 80.00 X
19	1	Rear Windscreen Inner Sponge Seal	\$	<i>na</i> 100.00 X

TOTAL	\$	1,144.00
--------------	-----------	-----------------

TOTAL PARTS	\$	24,917.19
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 6,000.00 *1000*

To Check Electrical Lighting Concerned.

\$ 170.00 *40*

Trans-cab Auto Services Pte Ltd**AAD1807-156**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9357X

To Rust-Proofing Of The Affected Areas.	\$	170.00	601
Putty And Spray Painting Of The Affected Portion.	\$	4,800.00	10001
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	601
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of end panel fittings and conduct water seepage test.	\$	170.00	X
Towing fees	\$	na 120.00	X
To transfer of boot fittings and conduct water seepage test.	\$	na 170.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	na 170.00	X
To check steering geometry and computer wheel alignment	\$	na 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	na 170.00	X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	na 170.00	X
To check ABS brake efficiency, final checking and testing.	\$	na 380.00	X

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Repair Days

Acknowledged by Repairer

Signature:

Date:

\$	13,050.00
TOTAL	\$ 37,967.19

20-DAYS

6 days