

15/02/2010

INS. CASE OWNER:

JACWIN

CC 6/AIG1801 7120, A h6b52

LKK:

IDAC:

Surveyor:

Admin

DOI:

ASSIGNMENT

18/3/18

Date / Time:

18/3/18

Registered in Merimen:

19/3/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SL6 9168K

Name of Insured:

VEE WEE KIM

Insured Tel No.:

HP: 90118878

Excess Sec II :SS

D.O.A: 18/3/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

970663505154

Policy No.:

70150705-01

Make / Model:

Toyota

Place of Accident:

Turn off mow highway 1
middle rd.

If NO, Driver Name / Age:

WEE WEE KIM

OI GIA REPORT: YES NO : TP GIA REPORT: YES NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

% Final ? Yes / No

SKF 25524

INSRS:
WSP:
Tel:
Liability:
RMKS:

Zero Gravity

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
28/3/18	Non-Reporting ltr (1st):	
10/09/18	Non-Reporting ltr (2nd):	
10/09/18	Non-Reporting ltr (Final):	
10/09/18	Notification ltr (if non-pickup):	
10/09/18	Call OI:	
10/09/18	After call ltr to OI:	
10/09/18	Documentation Check List:	
10/09/18	Notification ltr (if non-pickup):	
10/09/18	After call ltr to OI:	
10/09/18	Authorisation To Act:	
10/09/18	Release Voucher:	
10/09/18	Final Repair Bill:	
10/09/18	Car Rental Invoice:	
10/09/18	Towing Invoice:	
10/09/18	LTA / GIA:	
10/09/18	Medical Bill:	
10/09/18	PIR:	
10/09/18	Mandate/Reject Instruction:	
10/09/18	LOD:	
10/09/18	Payment Breakdown Form:	
10/09/18	Post-Repair Photos:	
10/09/18	Others:	

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

6,100.00

(6 days)

Reduction:

51

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

TIPANY

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

SS

6,100.00

Loss of Rental (LOR):

SS

1,260.00

(7 days)

x

4180.00

Loss of Use (LOU):

SS

-

(S

x

days)

Loss of Income (LOI):

SS

-

(S

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

7.45

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

4500.00

Total:

SS

7,367.45

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

7,367.45

Name 1:

ZERO GRAVITY

Payee 2: (Strike if N.A.)

SS

-

Name 2:

=

Payee 3: (Strike if N.A.)

SS

-

Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18013130/Ahb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 19-07-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLL 9168K	Veh. Inspected	SKK 2553U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	19/07/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	17/07/2018	Inspection Date	18/07/2018
Survey held at	ZERO GRAVITY 2 KAKI BUKIT AVE 2 #01-25 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67412845 Fax No: +65 67412170

Email: zero_gravity@singnet.com.sg

Buss.Reg.No.: 52888887X

Attn: Adrian

QUOTATION

No : QT-000141

AIG ASIA PACIFIC INSURANCE PTE. LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attention: Motor Claim Department

TEL : 64193000

FAX :

Your Ref. : SLL9168K
 Vehicle No. : SKK2553U
 Make & Model : TOYOTA ALPHARD
 Chasis No. : AGH300012486
 Engine No. : 2AR1273538
 Accident Date : 17-07-2018
 Policy No. : GA247767
 Date : 18-07-2018
 Page : 1 of 2

Vic

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	1575 S\$
1	REAR BUMPER <i>Deformed</i>	1.0 FCS	1,954.00	<u>1,954.00</u>
2	BUMPER CAP (R/H) <i>sehand</i>	1.0 FCS	50.30	50.30 ✓
3	BUMPER CLIP <i>new</i>	9.0 FCS	14.90	<u>134.10</u> 30
4	REAR BUMPER REFLECTOR (R/H) <i>new</i>	1.0 FCS	96.00	96.00 ✓
5	BUMPER SIDE RETAINER (R/H/R) <i>new</i>	1.0 FCS	83.30	83.30 ✓
6	REAR BUMPER SIDE RETAINER (SHORT) <i>new</i>	1.0 FCS	76.00	76.00 ✓
7	GARNISH (EXHAUST) <i>new</i>	1.0 FCS	126.10	126.10 ✓
8	REAR BOOT WEATHERSTRIP <i>new</i>	1.0 FCS	439.15	439.15 ✓
9	REAR END PANEL <i>Dented</i>	1.0 FCS	745.00	745.00 ✓
10	REAR END PANEL GARNISH <i>Dehand</i>	1.0 FCS	270.00	270.00 ✓
11	SENSOR (REAR BOOT) <i>new</i>	1.0 FCS	509.10	509.10 ✓
12	LAMP (REAR) R/H <i>new</i>	1.0 FCS	1,175.00	1,175.00 ✓
13	WINDSCREEN MOULDING (REAR) <i>new</i>	1.0 FCS	115.00	115.00 ✓
14	REAR BOOT ABSORBER <i>new</i>	2.0 FCS	233.00	466.00 ✓
15	REAR BOOT <i>Dented</i>	1.0 FCS	2,152.00	<u>2,152.00</u> 1956
16	REAR BOOT INNER TRIM BOARD <i>sehand</i>	1.0 FCS	701.00	701.00 ✓
17	REAR BOOT INNER TRIM BOARD CLIPS <i>new</i>	16.0 FCS	6.00	96.00 30
18	REAR BOOT INNER LOCK <i>new</i>	1.0 FCS	845.00	<u>845.00</u> 481
19	REAR BOOT LOCK STRIKER <i>new</i>	1.0 FCS	33.00	33.00 ✓
20	EMBLEM "ALPHARD" <i>new</i>	1.0 FCS	63.00	63.00 ✓
21	REVERSE SENSOR <i>Damaged</i>	2.0 FCS	489.35	978.70 560.
22	Discount 25 %			-2,776.94
23	SubTotal (L)			8,330.81
24	REVERSE CAMERA <i>new</i>	1.0 FCS	450.00	450.00 ✓
25	REAR BOOT LOWER CHROME MOULDING <i>new</i>	1.0 FCS	450.00	<u>450.00</u> 350
26	REAR END PANEL SEALANT <i>new</i>	1.0 ETL	50.00	50.00 ✓

6735.60

5051.70



ZERO GRAVITY

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67412845 Fax No: +65 67412170

Email: zero_gravity@singnet.com.sg

Buss.Reg.No.: 5288887X

Attn: Adrian

QUOTATION

No : QT-000141

AIG ASIA PACIFIC INSURANCE PTE. LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attention: Motor Claim Department

TEL : 64193000

FAX :

Your Ref. : SLL9168K
 Vehicle No. : SKK2553U
 Make & Model : TOYOTA ALPHARD
 Chasis No. : AGH300012486
 Engine No. : 2AR1273538
 Accident Date : 17-07-2018
 Policy No. : GA247767
 Date : 18-07-2018
 Page : 2 of 2

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/ Price	Amount
			S\$	S\$
27	SEALANT (WINDSCREEN) <i>NEW</i>	1.0 PCS	35.00	35.00 ✓
28	POLISHING OF VEHICLE (PAINT COATING)	1.0 X	400.00	400.00 300
29	STICKER (VELLIRE/ALPHARD) <i>NEW</i>	1.0 PCS	50.00	50.00 30
30	SubTotal (S)			1,435.00
31	PANEL BEAT & REPAIR REAR DAMAGE	1.0 X		1,200.00 700
32	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1.0 X		750.00 700
33	TO PROVIDE UNDER TURFCODE	1.0 X		150.00 40
34	TO REMOVE REVERSE SENSOR/CAMERA	1.0 X		150.00 100
35	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	1.0 X		150.00 120
36	TO REMOVE AND REFIT COMPONENTS / FACILITATE THE REPAIR	1.0 X		180.00 60
37	TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS	1.0 X		50.00 30
38	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT	1.0 X		80.00 x
39	TO TRANSFER REAR BOOT FITTING	1.0 X		120.00 60
40	SubTotal (LABOUR)			2,830.00

total 7626.70

h/s. 6.1K

06 Days.

SINGAPORE DOLLAR TWELVE THOUSAND FIVE HUNDRED NINETY FIVE AND CENTS EIGHTY ONE ONLY

E. & O.E

Total S\$ 12,595.81

Discount S\$ 0.00

Net Total S\$ 12,595.81

Terms: C.O.D.

6.1K

LKK Auto Consultants hence notify the Repairer of the following:

Customer's Signature/Co. Stamp

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation

ZERO GRAVITY

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Jul 2018 Edit Reg		18 Jul 2018 00:00 Edit Adj Rpt	S\$6,100.00 Edit Estimates	S\$6,100.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Lee Wee Chong (Li Weizhong), ID: S73198251		
Main Claimant:	CHAN CHEW MUN, ID: S7701487Z		
Vehicle Reg. No.:	SKK2553U	Date of Loss:	17/07/2018 07:00 - :59 [11 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9701635052SG	Policy/Cover Note No.:	2100502205 (Comprehensive)
Vehicle Reg. No. (Insured):	SLL9168K	Policy No. (Claimant):	GA247767
		Excess:	
Repairer:	Zero Gravity (Kaki Bukit) 2 Kaki Bukit Ave 2, #01-25 Kaki Bukit Autohub, 417921 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 30/07/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

***SKK2553U (9701635052SG)**
[SLL9168K]
TP
CHAN CHEW MUN
Jul 17 2018 7:00AM
[Lee Wee Chong (Li Weizhong)]
Zero Gravity

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

[View](#)
[View in Browser](#)

Letters/Correspondences					1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit		

Photos/Images					3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	07/09/18 10:20	General View		Load JPG	☒	
2	07/09/18 10:20	General View		Load JPG	☒	
3	07/09/18 10:20	General View		Load JPG	☒	
4	07/09/18 10:20	General View		Load JPG	☒	
5	07/09/18 10:20	General View		Load JPG	☒	
6	07/09/18 10:20	General View		Load JPG	☒	
7	07/09/18 10:20	General View		Load JPG	☒	
8	07/09/18 10:20	General View		Load JPG	☒	
9	07/09/18 10:20	General View		Load JPG	☒	
10	07/09/18 10:20	General View		Load JPG	☒	
11	07/09/18 10:20	General View		Load JPG	☒	
12	07/09/18 10:20	General View		Load JPG	☒	
13	07/09/18 10:20	General View		Load JPG	☒	
14	07/09/18 10:20	General View		Load JPG	☒	
15	07/09/18 10:20	General View		Load JPG	☒	
16	07/09/18 10:20	General View		Load JPG	☒	
17	07/09/18 10:20	General View		Load JPG	☒	
18	07/09/18 10:20	General View		Load JPG	☒	
19	07/09/18 10:20	General View		Load JPG	☒	
20	07/09/18 10:20	General View		Load JPG	☒	
21	07/09/18 10:20	General View		Load JPG	☒	
22	07/09/18 10:20	General View		Load JPG	☒	
23	07/09/18 10:20	General View		Load JPG	☒	
24	07/09/18 10:20	General View		Load JPG	☒	
25	07/09/18 10:20	General View		Load JPG	☒	
26	07/09/18 10:20	General View		Load JPG	☒	
27	07/09/18 10:20	General View		Load JPG	☒	
28	07/09/18 10:20	Reinspection Photo		Load JPG	☒	
29	07/09/18 10:20	Reinspection Photo		Load JPG	☒	
30	07/09/18 10:20	Reinspection Photo		Load JPG	☒	
31	07/09/18 10:20	Reinspection Photo		Load JPG	☒	
32	07/09/18 10:20	Reinspection Photo		Load JPG	☒	

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	07/09/18 10:20	Reinspection Photo	Load JPG	☒
34	07/09/18 10:20	Reinspection Photo	Load JPG	☒
35	07/09/18 10:20	Reinspection Photo	Load JPG	☒
36	07/09/18 10:20	Reinspection Photo	Load JPG	☒
37	07/09/18 10:20	Reinspection Photo	Load JPG	☒
38	07/09/18 10:20	Reinspection Photo	Load JPG	☒
39	07/09/18 10:20	Reinspection Photo	Load JPG	☒
40	07/09/18 10:20	Reinspection Photo	Load JPG	☒
41	07/09/18 10:20	Reinspection Photo	Load JPG	☒
42	07/09/18 10:20	Reinspection Photo	Load JPG	☒
43	07/09/18 10:20	Reinspection Photo	Load JPG	☒
44	07/09/18 10:20	Reinspection Photo	Load JPG	☒
45	07/09/18 10:20	Reinspection Photo	Load JPG	☒
46	07/09/18 10:20	Reinspection Photo	Load JPG	☒
47	07/09/18 10:20	Reinspection Photo	Load JPG	☒
48	07/09/18 10:20	Reinspection Photo	Load JPG	☒
49	07/09/18 10:20	Reinspection Photo	Load JPG	☒
50	07/09/18 10:20	Reinspection Photo	Load JPG	☒
51	07/09/18 10:20	Reinspection Photo	Load JPG	☒
52	07/09/18 10:20	Reinspection Photo	Load JPG	☒
53	07/09/18 10:20	Reinspection Photo	Load JPG	☒
54	07/09/18 10:20	Reinspection Photo	Load JPG	☒
55	07/09/18 10:20	Reinspection Photo	Load JPG	☒

Documentation			1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/07/18 17:46	TP GIA REPORT.	Load PDF	
2	10/09/18 17:27	TP ESTIMATE - MARKED	Load PDF	
3	10/09/18 17:48	EMAIL TO OI	Load PDF	
4	10/09/18 17:48	LETTER TO OI	Load PDF	
5	23/01/19 10:48	AUTHORISATION TO ACT	Load PDF	
6	23/01/19 10:48	LTA SEARCH	Load PDF	
7	23/01/19 10:48	RELEASE VOUCHER	Load PDF	
8	23/01/19 10:48	RENTAL RECEIPT	Load PDF	
9	23/01/19 10:48	WORKSHOP INVOICE	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	20/07/18 09:31	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLL9168K (Insd veh)	Model:	TOYOTA ALPHARD 2.5 S CVT
	SKK2553U (TP veh)		ABS D/AIRBAG 2WD 5DR (A)
Date of Accident:	17/07/2018		

Global Sum Settlement	:	[]	Yes	[X]	No	
Repair Estimate	:	\$				12,595.81
Final Repair Cost	:	\$				6,100.00
Loss of Use	:	\$				days at \$0.00 per day
Rental (if any)	:	\$				7 days
LTA / GIA Search Fee	:	\$				7.45
Others:	:	\$				
	:	\$				
Final Settlement Sum	:	\$				7,367.45
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)						
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)				
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____				
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)				
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.						
Remarks _____						

Payment Instruction: Payee's Breakdown			
1)	Zero Gravity	:	\$ 7,367.45
2)		:	\$
3)		:	\$
4)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

23 Jan
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18013130/AHB3S2

Date: 23/01/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100502205

Claimant Vehicle No: SKK2553U

Insured Vehicle No: SLL9168K

Date of Loss: 17/07/2018

Nature of Claim: TP

Claim No: 9701635052SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKK2553U

Make & Model: TOYOTA ALPHARD, 2.5 S CVT ABS D/AIRBAG 2WD 5DR (A)

Engine No: 2AR1273538

Reg. Date: 21/07/2017 (Man. Year: 2015)

Chassis No: AGH300012486

Colour: Black

Odometer: 12694 km

Engine Capacity: 2493 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50R18

Rear Tyre Size:

235/50R18

Front Left Side: Toyo 6 mm

Rear Left Side:

Toyo 6 mm

Front Right Side: Toyo 6 mm

Rear Right Side:

Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,365.81	5,516.70	3,849.11	41.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,230.00	2,110.00	1,120.00	34.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,595.81	7,626.70	4,969.11	39.45
Approved Total (Overridden) (S\$)		6,100.00		
Nett Amount (S\$)	12,595.81	6,100.00	6,495.81	51.57
+ Car Rental (7.0 x S\$180.00/day) (S\$)		1,260.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,367.45		

INSPECTION

Date of Assignment: 18/07/2018

Date Inspected: 18/07/2018 Inspected At:

Zero Gravity (Kaki Bukit)

2 Kaki Bukit Ave 2, #01-25 Kaki Bukit Autohub
Singapore 417921

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,954.00 FL	*1,575.00 FL
2	1		*BUMPER CAP (R/H)	Deformed	50.30 FL	*50.30 FL
3	1		*BUMPER CLIP	Necessary	134.10 FL	*30.00 FL
			9pcs			
4	1		*REAR BUMPER REFLECTOR (R/H)	Not Necessary	96.00 FL	*- FL
5	1		*BUMPER SIDE RETAINER (R/H/R)	Necessary	83.30 FL	*83.30 FL
6	1		*REAR BUMPER SIDE RETAINER (SHORT)	Necessary	76.00 FL	*76.00 FL
7	1		*GARNISH (EXHAUST)	Not Necessary	126.10 FL	*- FL
8	1		*REAR BOOT WEATHERSTRIP	Not Necessary	439.15 FL	*- FL
9	1		*REAR END PANEL	Dented	745.00 FL	*745.00 FL
10	1		*REAR END PANEL GARNISH	Deformed	270.00 FL	*270.00 FL
11	1		*SENSOR (REAR BOOT)	Not Necessary	509.10 FL	*- FL
12	1		*LAMP (REAR) R/H	Not Necessary	1,175.00 FL	*- FL
13	1		*WINDSCREEN MOULDING (REAR)	Necessary	115.00 FL	*115.00 FL
14	2		*REAR BOOT ABSORBER	Not Necessary	466.00 FL	*- FL
15	1		*REAR BOOT	Dented	2,152.00 FL	*1,956.00 FL
16	1		*REAR BOOT INNER TRIM BOARD	Deformed	701.00 FL	*701.00 FL
17	1		*REAR BOOT INNER TRIM BOARD CLIPS	Necessary	96.00 FL	*30.00 FL
			16pcs			
18	1		*REAR BOOT INNER LOCK	Damaged	845.00 FL	*481.00 FL
19	1		*REAR BOOT LOCK STRIKER	Not Necessary	33.00 FL	*- FL
20	1		*EMBLEM ALPHARD	Necessary	63.00 FL	*63.00 FL
21	2		*REVERSE SENSOR	Damaged	978.70 FL	*560.00 FL
22	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
23	1		*REAR BOOT LOWER CHROME MOULDING	Cracked	450.00 FS	*350.00 FS
24	1		*BTL REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
25	1		*SEALANT	Necessary	35.00 FS	*35.00 FS
26	1		*STICKER (VELLFIRE/ALPHARD)	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,142.75	7,200.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,776.94	1,683.90
Total Parts (\$\$)	9,365.81	5,516.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	POLISHING OF VEHICLE (PAINT COATING)	New	400.00	300.00
2	PANEL BEAT & REPAIR REAR DAMAGE.	New	1,200.00	700.00
3	TO PUTTY AND RE-SPRAY AFFECTED PORTION.	New	750.00	700.00
4	TO PROVIDE UNDER TURFCODE.	New	150.00	40.00
5	TO REMOVE REVERSE SENSOR / CAMERA.	New	150.00	100.00
6	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	New	150.00	120.00
7	TO REMOVE AND REFIT COMPONENTS / FACILITATE THE REPAIR.	New	180.00	60.00
8	TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS.	New	50.00	30.00
9	TO CHECK WIRING SYSTEM & ENSURE FUNCTION OF COMPONENT.	New	80.00	0.00
10	TO TRANSFER REAR BOOT FITTING.	New	120.00	60.00
Gross Labour Cost (\$\$)			3,230.00	2,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >