

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

16 November, 2018

To Whom It May Concern

Dear Sir / Madam,

Accident on 16/07/18 10:30 PM at BUKIT BATOK WEST AVENUE 6

1. We refer to the above-mentioned accident and wish to inform that Trans-Cab Services Pte Ltd is the registered owner of the taxi bearing vehicle registration no. SHD9839Y. The taxi was hired to TANG SIAW HOCK a registered hirer-operator of Trans-Cab Services Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$99.32 per day (inclusive of GST).
2. Please be advised that the Taxi is insured with AXA INSURANCE PTE LTD on a third party basis at the material time of the accident.
3. Please liaise with us directly for any settlement of claims in respect of the said accident.

Yours faithfully,

Jasmine Tan
General Manager

Trans-Cab Services Pte Ltd

No. 2 Ang Mo Kio Street 63

Tel No.: 6287 6666 Fax No. 6281 1400

Co./GST Reg. No. 200303878K

16-07-2018

Dear Sir/Madam,

Please be informed that the taxi was undergo accident repair in the workshop as follow:

Date In	Date Out	Vehicle No.	
Accident No.	AAD1807-151		Accident Date 16-07-2018
7/16/2018 22:30	8/6/2018 15:30	SHD9839Y	
8/6/2018 15:31	8/28/2018 18:00	SHD9839Y	

Yours Faithfully,

Trans-Cab Services Pte Ltd**Jasmine Tan****General Manager**

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Monday, 11 March 2019 2:28 PM
To: 'Ng Wai Yin'; 'Jasmine Tan'
Cc: 'claims'; Admin A
Subject: RE: Your Ref: to be advised (SHD 9839Y); Our Ref : CC3/III18013134/Kfb3
Attachments: Video - Accident (OID).MP4

Importance: High

WITHOUT PREJUDICE

Your Ref: to be advised (SHD 9839Y)(DOA: 16.07.2018)
Our Ref : CC3/III18013134/Kfb3

Dear Sir/Madam,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SHD 3331J AND SHD 9839Y ON 16/07/2018

We refer to the above matter.

We have reviewed the circumstances of the incident and we are of the opinion that your driver is more liable as our video footage show Traffic Light is in our OI favor. This is evidenced of video footage from our Insured. Below is a copy of our insured's accident report statement for your perusal.

Brief Details.

On 16/07/2018 at about 2230 hours, I was driving my Comfort Taxi bearing vehicle registration number SHD3331J along Bukit Batok West Ave 3 towards Bukit Batok East Ave 5. I had a passenger sitting at the front left passenger seat and two other passengers sitting at the rear passenger seat. I had stopped my vehicle at the junction of Bukit Batok West Ave 3 and Bukit Batok West Ave 6 as the traffic light was red. After the traffic light had turned green in my favor, I proceeded to drive forward. Out of a sudden, there was a strong impact on the left side of my vehicle. The impact was caused by a red Transcab taxi which was unable to stop in time. Despite the impact, my vehicle was still moving forward and I only managed to stop my vehicle about 5 meters away. As my passengers complained of pain, I called for ambulance and police.

Subsequently after ambulance had arrived, the three passenger from my vehicle were conveyed. I am unsure which hospital they were conveyed to. I would like to add that the passenger from the Transcab taxi was conveyed as well. There is an in car camera in my vehicle and I had handed over the memory card to Traffic Police.

I would like to state that I feel pain at my chest area but I have yet to seek medical attention. I would also like to state that I did not manage to take down the vehicle registration number of the Transcab taxi. I also did not manage to take down the particulars of the driver and the passengers involved.

I was then instructed to lodge a report under TP IO Shahrul Nizam (tel: 65476904)

In view of this, we regret to inform you that we are unable to look into your claim.

Should you have further evidence to prove otherwise, please send us a copy for our review.

Thank you.

Note: This videos are solely for investigation and shall not be reproduced. You undertake to preserve its confidentiality and will not disclose, provide or make available the video footage in whole or in part, to any third party.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK
Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Poh Kin (LKKAuto)

Sent: Monday, 22 October 2018 4:59 PM

To: 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>

Subject: RE: Your Ref: to be advised (SHD 9839Y); Our Ref : CC3/III18013134/Kfb3

Importance: High

WITHOUT PREJUDICE

Your Ref: to be advised (SHD 9839Y)

Our Ref : CC3/III18013134/Kfb3

Dear Wai Yin,

RE: ROAD TRAFFIC ACCIDENT INVOLVING SHD 3331J AND SHD 9839Y ON 16/07/2018

Any update for video footage?

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK
Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Print Received Message

This mail is associated with :

***SHD9839Y (MCT18070471)**
[SHD3331J]

TP

TRANS-CAB SERVICES PTE LTD
Jul 16 2018 10:00PM
[COMFORT TRANSPORTATION PTE LTD]
Trans-cab Auto Services Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 11/03/2019 10:59 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SHD9839Y - Claim Handler: Zuhaidah Bte Samsuri

Approved:0.00:Please proceed to reject TP claim

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	19 Jul 2018 15:03	Clim Veh Model Changed	(204383) RENAULT LATITUDE 2.0 L (A).	[A] Lau Shu Pei
2	19 Jul 2018 15:03	Clim Created	Reg No: SHD9839Y. Acct Date: 2018/07/16. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). TP Insurer: AXA Insurance Pte Ltd (HQ). Workshop: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)	[A] Lau Shu Pei
3	19 Jul 2018 15:03	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
4	19 Jul 2018 15:03	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/07/30	[A] Lau Shu Pei
5	19 Jul 2018 15:03	Adj Mandate Set	Approved:0.00,Reinsp:Adj decides.	[A] Lau Shu Pei
6	19 Jul 2018 15:03	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pei
7	19 Jul 2018 15:03	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] Lau Shu Pei
8	23 Jul 2018 10:18	Clim Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
9	23 Jul 2018 10:18	Clim Dtl Modified	Claimant's Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pei
10	25 Jul 2018 17:48	Adj Mandate Request	Cur.Req:0.00:PODS Liability: TBA Kindly upload the OI video footage to Merimen in order for us to seek Liability mandate from you. Thank you	[A] Chong Poh Kin
11	26 Jul 2018 08:59	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/07/30. Mandate Remarks: We will only receive OID video footage next week. In the meantime, please request TP for their video footage.	[I] Zuhaidah Bte Samsuri
12	26 Jul 2018 08:59	Adj Mandate Set	Maintained:We will only receive OID video footage next week. In the meantime, please request TP for their video footage.	[I] Zuhaidah Bte Samsuri
13	31 Jul 2018 14:28	Video Downloaded	Downloaded Video - Accident (OID)	[I] Lalitha Krishnan
14	31 Jul 2018 14:30	Video Downloaded	Downloaded Video - Accident (OID)	[I] Lalitha Krishnan
15	31 Jul 2018 14:48	Video Downloaded	Downloaded Video - Accident (OID)	[I] Lalitha Krishnan
16	31 Jul 2018 14:49	Video Downloaded	Downloaded Video - Accident (OID)	[I] Lalitha Krishnan
17	01 Aug 2018 09:16	Video Downloaded	Downloaded Video - Accident (OID)	[A] Chong Poh Kin
18	08 Nov 2018 11:37	Video Downloaded	Downloaded Video - Accident (OID)	[I] Zuhaidah Bte Samsuri
19	08 Nov 2018 11:38	Video Downloaded	Downloaded Video - Accident (OID)	[I] Zuhaidah Bte Samsuri
20	11 Mar 2019 09:50	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 100% against TP. Remarks: we have e-mail to TP request Video footage, however no reply from them since October 2018 till todote. we hereby seek approval to reject TP claim as OI video footage show traffic light is in ou	[A] Chong Poh Kin
21	11 Mar 2019 10:59	Video Downloaded	Downloaded Video - Accident (OID)	[I] Zuhaidah Bte Samsuri
22	11 Mar 2019 10:59	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2018/07/30. Mandate Remarks: Please proceed to reject TP claim	[I] Zuhaidah Bte Samsuri
23	11 Mar 2019 10:59	Adj Mandate Set	Approved:0.00:Please proceed to reject TP claim	[I] Zuhaidah Bte Samsuri

Date From



Date To



Audit Type

None

Go

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jul 2018 Edit Reg		18 Jul 2018 00:00 Edit Adj Rpt	S\$30,150.00 Edit Estimates	S\$30,150.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by adjuster\]](#)

Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHD9839Y	Date of Loss:	16/07/2018 22:00 - :59 [50 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18070471	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHD3331J	Policy No. (Claimant):	VPX/P1680520
		Excess:	
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 30/07/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (11/03/2019): Alert - Adj Mandate Approved (S\$0.00) - SHD9839Y - Claim Handler: Zuhaidah Bte S...
- III_SG (30/07/2018): Video footage uploaded
- III_SG (26/07/2018): Alert - Adj Mandate Maintained - SHD9839Y - Claim Handler: Zuhaidah Bte Samsuri

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SHD9839Y (MCT18070471)**
[SHD3331J]
TP
TRANS-CAB SERVICES PTE LTD
Jul 16 2018 10:00PM
[COMFORT TRANSPORTATION PTE LTD]
Trans-cab Auto Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Video				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	30/07/18 11:37	Video - Accident (OID)		Load MP4	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
2	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
3	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
4	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
5	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
6	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
7	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
8	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
9	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
10	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
11	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
12	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
13	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
14	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
15	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
16	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
17	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
18	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
19	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
20	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
21	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
22	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
23	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
24	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
25	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
26	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
27	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
28	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
29	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
30	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
31	11/03/19 09:44	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
32	11/03/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>

Video			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
33	11/03/19 09:44	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
34	11/03/19 09:44	General View	Load JPG	<input checked="" type="checkbox"/>
35	11/03/19 09:44	General View	Load JPG	<input checked="" type="checkbox"/>
36	11/03/19 09:44	General View	Load JPG	<input checked="" type="checkbox"/>
37	11/03/19 09:44	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/07/18 17:42	TP ESTIMATE- MARKED	Load PDF	
2	19/07/18 17:42	TP GIA REPORT	Load PDF	
3	11/03/19 09:50	e-mail to request video footage	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	20/07/18 09:03	Singapore Accident Statement	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18013134/KFB3S2

Date: 14/03/2019

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SHD9839Y	Insured Vehicle No :	SHD3331J
Date of Loss:	16/07/2018	Nature of Claim:	TP
		Claim No:	MCT18070471

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD9839Y		
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Engine No:	M9R8839C001334
Reg. Date:	25/04/2014 (Man. Year: 2014)	Chassis No:	VF1ABL15AUC277497
Colour:	Metallic White/Red	Odometer:	403928 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Falken 7 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Falken 7 mm	Rear Right Side:	Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	79,442.49	33,726.70	45,715.79	57.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	20,000.00	3,970.00	16,030.00	80.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	99,442.49	37,696.70	61,745.79	62.09
Approved Total (Overridden) (S\$)		30,150.00		
(S\$)	99,442.49	30,150.00	69,292.49	69.68
+ GST 7.00/7.00% (S\$)	6,960.97	2,110.50	4,850.47	69.68
Nett Amount (S\$)	106,403.46	32,260.50	74,142.96	69.68

INSPECTION

Date of Assignment:	18/07/2018	
Date Inspected:	18/07/2018	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	16.0 days	

Adjuster: KENNETH KONG

Manager: Chong Poh Kin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printprt&caseid=726600&extid=277897&CFID=49765848&C... 1/6

any other liability under any other circumstances is hereby expressly excluded.

20

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Mar 2019)
Parts:	143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD9839Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Missing	1,259.42 FL	*1,259.42 FL
2	1		*BUMPER SPOILER FRT	Missing	181.75 FL	*181.75 FL
3	1		*BUMPER ABSORBER FRT	Broken	394.68 FL	*394.68 FL
4	1		*BUMPER RETAINER FRT LH	Cracked	151.41 FL	*151.41 FL
5	1		*BUMPER SUPPORT FRT	Missing	123.88 FL	*123.88 FL
6	1		*BUMPER RETAINER FRT RH	Cracked	150.77 FL	*150.77 FL
7	1		*BUMPER SUPPORT FRT	Missing	123.88 FL	*123.88 FL
8	1		*BUMPER UNDERTRAY FRT	Missing	472.83 FL	*472.83 FL
9	1		*BUMPER GRILLE LOWER FRT	Missing	266.80 FL	*266.80 FL
10	1		*BUMPER FOG LAMP GRILLE LH	Missing	207.21 FL	*207.21 FL
11	1		*BUMPER FOG LAMP GRILLE RH	Missing	207.21 FL	*207.21 FL
12	1		*BUMPER BEAM FRT	Bent	914.08 FL	*914.08 FL
13	1		*TOW COVER FRT	Missing	28.61 FL	*28.61 FL
14	1		*RADIATOR GRILLE	Missing	1,707.78 FL	*1,707.78 FL
15	1		*RADIATOR GRILLE BADGE RENAULT	Missing	225.36 FL	*225.36 FL
16	1		*RADIATOR GRILLE FRAME	Cracked	1,353.75 FL	*1,353.75 FL
17	1		*FRAME FULL SUPPORT PANEL	Cracked	615.90 FL	*615.90 FL
18	1		*FRAME FULL SUPPORT BRACKET	Bent	89.79 FL	*89.79 FL
19	1		*FRONT BRACE PANEL	Bent	177.22 FL	*177.22 FL
20	1		*HORN	Damaged	314.17 FL	*314.17 FL
21	1		*HORN BRACKET	Damaged	40.45 FL	*40.45 FL
22	1		*HEADLAMP LH	Missing	1,184.43 FL	*1,184.43 FL
23	1		*HEADLAMP HARNESS	Not Necessary	928.29 FL	*- FL
24	1		*HEADLAMP RH	Cracked	1,184.43 FL	*1,184.43 FL
25	1		*HEADLAMP HARNESS	Not Necessary	928.29 FL	*- FL
26	1		*HEADLAMP PANEL FRT LH	Bent	152.15 FL	*152.15 FL
27	1		*HEADLAMP PANEL FRT RH	Distorted	152.15 FL	*152.15 FL
28	1		*BONNET	Bent	1,941.63 FL	*1,941.63 FL
29	1		*BONNET INSULATOR	Deformed	405.73 FL	*405.73 FL
30	1		*BONNET STRUT LH	Punctured	88.61 FL	*88.61 FL
31	1		*BONNET STRUT RH	Punctured	88.61 FL	*88.61 FL
32	1		*BONNET HINGE LH	Bent	348.31 FL	*348.31 FL
33	1		*BONNET HINGE RH	Distorted	348.31 FL	*348.31 FL
34	1		*BONNET LOCK	Bent	305.48 FL	*305.48 FL
35	1		*BONNET CABLE	Jammed	119.19 FL	*119.19 FL
36	1		*BONNET CABLE COVER	Cracked	161.03 FL	*161.03 FL
37	1		*BONNET SEAL OUTER	Cut	92.36 FL	*92.36 FL
38	1		*BONNET SEAL INNER	Serviceable	157.28 FL	*- FL
39	1		*FENDER PANEL FRT LH	Buckled	783.83 FL	*783.83 FL
40	1		*FENDER PANEL FRT RH	Bent	783.83 FL	*783.83 FL
41	1		*WHEELARCH FRT LH	Cracked	278.84 FL	*278.84 FL
42	1		*WHEELARCH FRT RH	Cracked	278.84 FL	*278.84 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FENDER BRACKET LOWER LH	Bent	15.79 FL	*15.79 FL
44	1		*FENDER BRACKET LOWER RH	Repair	15.79 FL	*- FL
45	1		*FENDER INSULATOR LH	Serviceable	130.84 FL	*- FL
46	1		*FENDER INSULATOR RH	Serviceable	130.84 FL	*- FL
47	1		*WIPER RESERVOIR	Dented	348.25 FL	*348.25 FL
48	1		*WIPER RESERVOIR NECK	Dented	136.11 FL	*136.11 FL
49	1		*WIPER RESERVOIR MOTOR	Not Necessary	270.06 FL	*- FL
50	1		*AIR CLEANER LOWER	Dented	271.26 FL	*271.26 FL
51	1		*AIR CLEANER HOSE	Not Necessary	76.14 FL	*- FL
52	1		*ENGINE TOP COVER 2.0	Serviceable	555.12 FL	*- FL
53	1		*ENGINE OIL SUMP	Serviceable	484.67 FL	*- FL
54	1		*BASE BATTERY TRAY	Not Necessary	363.40 FL	*- FL
55	1		*AIR CLEANER BOX	Not Necessary	464.20 FL	*- FL
56	1		*TURBO DUCT	Not Necessary	1,027.80 FL	*- FL
57	1		*A/C HEATER VALVE	Not Necessary	484.50 FL	*- FL
58	1		*SUBFRAME OUTER FRT	Not Necessary	2,652.45 FL	*- FL
59	1		*SUBFRAME BRACKET OUTER LH	Not Necessary	92.36 FL	*- FL
60	1		*SUBFRAME BRACKET OUTER RH	Not Necessary	92.36 FL	*- FL
61	1		*ENGINE UNDERTRAY	Not Necessary	564.98 FL	*- FL
62	1		*A/C CONDENSER	Bent	2,020.37 FL	*2,020.37 FL
63	1		*A/C CONDENSER GARNISH LH UPPER	Missing	39.67 FL	*39.67 FL
64	1		*A/C CONDENSER GARNISH RH UPPER	Missing	39.67 FL	*39.67 FL
65	1		*A/C CONDENSER GARNISH LH	Missing	58.81 FL	*58.81 FL
66	1		*A/C CONDENSER GARNISH RH	Missing	59.60 FL	*59.60 FL
67	1		*A/C PIPE CONDENSER TO COMPRESSOR	Serviceable	208.39 FL	*- FL
68	1		*A/C PIPE CONDENSER TO EXPENSION VALVE	Serviceable	658.72 FL	*- FL
69	1		*A/C PIPE COMPRESSOR	Serviceable	334.29 FL	*- FL
70	1		*A/C PIPE	Not Necessary	658.72 FL	*- FL
71	1		*A/C COMPRESSOR	Serviceable	2,684.61 FL	*- FL
72	1		*AIR COOLER	Punctured	792.60 FL	*792.60 FL
73	1		*AIR INTERCOOLER HOSE (LONG)	Not Necessary	1,014.13 FL	*- FL
74	1		*AIR INTERCOOLER HOSE (SHORT)	Not Necessary	375.14 FL	*- FL
75	1		*TRANSMISSION COOLER	Not Necessary	1,219.30 FL	*- FL
76	1		*TRANSMISSION COOLER PAD	Not Necessary	17.96 FL	*- FL
77	1		*RADIATOR	Bent	1,202.20 FL	*1,202.20 FL
78	2		*RADIATOR STUD UPPER	Serviceable	14.41 FL	*- FL
79	2		*RADIATOR BUSH UPPER	Serviceable	50.12 FL	*- FL
80	2		*RADIATOR MTG LOWER	Serviceable	55.85 FL	*- FL
81	1		*RADIATOR FAN COWLING	Not Necessary	820.54 FL	*- FL
82	1		*RADIATOR FAN MOTOR LH	Not Necessary	967.36 FL	*- FL
83	1		*RADIATOR FAN MOTOR RH	Not Necessary	1,479.46 FL	*- FL
84	1		*RADIATOR TANK	Not Necessary	324.62 FL	*- FL
85	1		*RADIATOR HOSE UPPER	Not Necessary	240.56 FL	*- FL
86	1		*RADIATOR HOSE LOWER	Not Necessary	491.18 FL	*- FL
87	1		*RADIATOR TANK HOSE	Not Necessary	61.18 FL	*- FL
88	1		*WINDSCREEN FRT	Serviceable	1,364.06 FL	*- FL
89	1		*AUTO COMPUTER	Serviceable	5,032.17 FL	*- FL
90	1		*INJECTION COMPUTER	Not Necessary	4,706.30 FL	*- FL
91	1		*RHD HYDRAULIC POWER (ROCK & PINION)	Not Necessary	5,154.52 FL	*- FL
92	1		*STEERING PUMP ELECTRIC	Not Necessary	2,306.90 FL	*- FL
93	1		*STEERING PINION RACK	Serviceable	4,413.11 FL	*- FL
94	1		*ENGINE HARNESS	Not Necessary	4,084.54 FL	*- FL
95	1		*SEAT BELT LH L70Y	Jammed	2,937.80 FL	*2,937.80 FL
96	1		*SEAT BELT RH L70Y	Jammed	2,925.37 FL	*2,925.37 FL
97	1		*SEAT BELT BUCKLE LH L70Y	Not Necessary	984.13 FL	*- FL
98	1		*SEAT BELT BUCKLE RH L70Y	Not Necessary	949.80 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
99	1		*PASSENGER AIRBAG L70Y	Burst	3,412.40 FL	*3,412.40 FL
100	1		*STEERING AIRBAG L70Y	Burst	2,525.75 FL	*2,525.75 FL
101	1		*AIRBAG COMPUTER L70Y	Necessary	1,259.82 FL	*1,259.82 FL
102	1		*AIRBAG SENSOR L70Y	Necessary	724.63 FL	*724.63 FL
103	1		*AIRBAG SENSOR L70Y	Necessary	289.30 FL	*289.30 FL
104	1		*SET RADIATOR GRILLE FRAME CLIP	Not Necessary	52.00 FS	*- FS
105	1		*SET BUMPER CLIP FRT	Not Necessary	66.00 FS	*- FS
106	1		*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
107	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
108	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	*- FS
109	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*- FS
110	1		*TOW COVER FRT	Not Necessary	14.50 FS	*- FS
111	1		*SET RADIATOR GRILLE SCREW	Necessary	16.00 FS	*16.00 FS
112	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
113	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
114	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
115	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
116	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
117	1		*SET FRONT LICENCE PLATE WITH HOLDER	Missing	80.00 FS	*45.00 FS
118	1		*FRONT LEFT TYRE (60%)	Dented	330.00 FS	*198.00 FS
119	1		*FRONT LEFT TYRE RIM	Punctured	380.00 FS	*380.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	88,128.05	37,403.11
- List Item Discount on L Items 10.00/10.00% (\$)	8,685.56	3,676.41
Total Parts (\$)	79,442.49	33,726.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	New	9,000.00	1,200.00
2	TOWING FEES.	New	120.00	50.00
3	TO APPLY PAINT PROTECTION SYSTEM (PPS) MAINTAIN AND ENHANCEMENT.	New	380.00	0.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	6,000.00	1,540.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	170.00	120.00
6	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	New	380.00	0.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	220.00	60.00
8	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	New	170.00	20.00
9	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	170.00	30.00
10	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK. }	New	380.00	250.00
11	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR. }	New	380.00	0.00
12	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT.	New	440.00	300.00
13	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	New	440.00	0.00
14	TO REMOVE AND REFIT AIR BAG SYSTEM AND RESET.	New	480.00	200.00
15	TO DROP DIESEL TANK, PIPES, HOSES TO FACILITATE BODYWORK REPAIR, FINAL CHECKING AND TESTING.	New	380.00	0.00
16	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR CONDENSER.	New	380.00	100.00
17	TO REPLACE, REFIX AND TOP UP COOLANT FOR RADIATOR.	New	170.00	50.00
18	TO VACUUM, REPLACE, REFIX AND RECHARGE AIR INTERCOOLER.	New	170.00	50.00
19	TO TRANSFER OF FENDER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
Gross Labour Cost (S\$)			20,000.00	3,970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >