

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 3104D

DATE 18/7/2018 10:04

MAKE :

MODEL : HYUNDAI i40

Change

A01A

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Door (RH) ✓			\$ 1,403.00
	Front Door Rubber ✓			\$ 290.50
	Front Door Glass (RH) ✓			\$ 379.55
	Front Door Gear / Regulator (RH) ?			\$ 785.50
	Front Door Hinge Upper (RH) ?			\$ 53.40
	Front Door Hinge Lower (RH) ?			\$ 53.40
	Front Door Check (RH) ?			\$ 110.15
	Front Door Key Lock Set (RH) ?			\$ 186.50
	Front Door Outer Handle (RH) X			\$ 53.00
	Front Door Outer Moulding (RH) ✓			\$ 63.70
	Front Door Mirror(RH) ✓			\$ 980.50
	Front Door Power Motor ?			\$ 530.50
	Front Door Trim Board (RH) ✓			\$ 1,196.90
	Front Door Protector (RH) ?			\$ 78.25
	Rear Door (RH) ✓			\$ 1,351.00
	SUB TOTAL			\$ 7,515.85
	LESS 20%			\$ 1,503.17
	DISCOUNTED TOTAL			\$ 6,012.68
	Front Door Comfort Logo (RH) ✓			\$ 75.00 Nett
	Front Door Advertisement Logo (RH) ✓			\$ 100.00 Nett
	Rear Door Advertisement Logo (RH) ✓			\$ 100.00 Nett
	Rear Door Comfortdelgro & Apps Sticker (RH) ✓			\$ 80.00 Nett
				\$ 355.00
	Labour Charge			200
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 650.00 600
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 50.00 20
	Transfer of Door		\$ 120.00	\$ 240.00 100
	TOTAL LABOUR			\$ 1,340.00
	ESTIMATE TOTAL			\$ 7,707.68
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

K. L. K. (LKK)

18/7/18 15:20hr

3 Days

L/S

After Repair p Lh