

# SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg\_motor\_enterprise@yahoo.com.sg

Date: 20 July 2018

To : LKK

By Fax: 6256-4315

Attn: Bryan Ong

Tel :

VEHICLE NO : JSR 5263

Honda RS 150R

ACCIDENT DATE: 13 July 2018

| <u>Description</u>                     | <u>Qty</u> | <u>Quotation \$</u> |
|----------------------------------------|------------|---------------------|
| 1 Rear Tail Lamp <del>crack</del>      | 1          | 150.00 ✓            |
| 2 Rear Mudguard cut                    | 1          | 180.00 ✓            |
| 3 Side Reflector crack                 | 1          | 190.00 - 65/-       |
| 4 Exhaust Guard scratched              | 1          | 250.00 ✓            |
| 5 Mirror LH cut                        | 1          | 78.00 ✓             |
| 6 Front Side Panel LH <del>crack</del> | 1          | 125.00 ✓            |
| 7 Front Signal LH broken               | 1          | 75.00 ✓             |
| 8 Handle Bar <del>crack</del>          | 1          | 135.00 X            |
| 9 Front Visor broken                   | 1          | 150.00 ✓            |
|                                        |            | <del>1508.00</del>  |
|                                        |            | 1073.00             |
|                                        | Sub-Total  | 965.70              |
|                                        | Less 10%   | 1,333.00            |
|                                        | Sub-Total  | 133.30              |
|                                        |            | 1,199.70            |

1) Rear foot peg bracket & ~~crack~~  
change  
2) ~~crack~~ reflector - crack

23/07/18  
Re-Survey on

VEHICLE NO : JSR 5263

Honda RS 150R

Nett items

|   |                                       |                         |
|---|---------------------------------------|-------------------------|
| 1 | Rear box <del>cut</del> cut NC        | 280.00 <del>220</del> X |
| 2 | Box rack <del>cut</del> cut NC        | 130.00 <del>100</del> X |
| 3 | Towing fee NC                         | 40.00 ✓                 |
| 4 | Remove & replace parts, align & etc   | 250.00 200/-            |
| 5 | To check & repress front fork tube NC | 150.00 80/-             |
| 6 | Supply body decal sticker NC          | 160.00 100/-            |
| 7 | Rear number plate cut                 | 15.00 ✓                 |

435.00

Sub-Total 1,025.00

Nett Total 2,224.70

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion  
Thank you

20/07/2018 @ 1300h

Hot Antenna

2/5mm 4 days

Riya

2kk Auto

1400.70

Supp 234.00

1634.70

2/5 1300/-

SG 98 MOTOR PTE LTD

:LG

Photo after repair

Dismantle LH side fairing

+ tail lamp to take photo

20/7/2018.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg\_motor\_enterprise@yahoo.com.sg

Date: 23 July 2018

To : LKK

By Fax: 6256-4315

Attn: *Bryan Ong*  
Tel :

VEHICLE NO : JSR 5263  
ACCIDENT DATE: 13 July 2018

Honda RS 150R

## SUPPLEMENTARY ITEMS

| <u>Description</u>                                 | <u>Qty</u> | <u>Quotation \$</u> |
|----------------------------------------------------|------------|---------------------|
| 1 Rear - LH Pillion Footrest Complete <i>crack</i> | 1          | 180.00 ✓            |
| 2 Centre Reflector <i>crack</i>                    | 1          | 80.00 ✓             |
|                                                    | Sub-Total  | 260.00              |
|                                                    | Less 10%   | <del>26.00</del>    |
|                                                    | Total      | 234.00              |

*Tyuan*

23/07/2018

*LKK Auto*

*[Signature]*

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion  
Thank you

*[Signature]*

SG 98 MOTOR PTE LTD

:LG