

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Jul 2018 Edit Reg		19 Jul 2018 00:00 Edit Adj Rpt	S\$1,401.50 Edit Estimates	S\$1,401.50 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: -									
Main Claimant: MOHAMED SULAIMAN BIN MOHAMED ALI SINA , ID: S7804192G									
Vehicle Reg. No.:	SKC8453C	Date of Loss:	09/07/2018 19:00 - :59 [81 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18070282	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHD4512Y	Policy No. (Claimant):	PCPV2017-00008018						
		Excess:							
Repairer:	Charn's Customcraft (HQ) Block 1010 Bukit Merah Lane 3, #01-105, 159724 Bukit Merah - Tel: 62717054								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]								
Claimant's Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 30/07/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (30/07/2018): Alert - Adj Mandate Approved (S\$0.00) - SKC8453C - Claim Handler: Sherini Pillai - III_SG (26/07/2018): Alert - Adj Mandate Maintained - SKC8453C - Claim Handler: Sherini Pillai - III_SG (24/07/2018): Alert - Adj Mandate Maintained - SKC8453C - Claim Handler: Sherini Pillai									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKC8453C (MCT18070282)**
[SHD4512Y]
TP
MOHAMED SULAIMAN BIN MOHAMED ALI SINA
Jul 9 2018 7:00PM
[COMFORT TRANSPORTATION PTE LTD]
Charn's Customcraft

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Video 1 per page ▼ ☒

No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	24/07/18 15:17	Video - Insured		Load MP4	

Photos/Images 3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/04/20 09:02	General View		Load JPG	☒
2	21/04/20 09:02	General View		Load JPG	☒
3	21/04/20 09:02	General View		Load JPG	☒
4	21/04/20 09:02	General View		Load JPG	☒
5	21/04/20 09:02	General View		Load JPG	☒
6	21/04/20 09:02	General View		Load JPG	☒
7	21/04/20 09:02	General View		Load JPG	☒
8	21/04/20 09:02	General View		Load JPG	☒
9	21/04/20 09:02	General View		Load JPG	☒
10	21/04/20 09:02	General View		Load JPG	☒
11	21/04/20 09:02	General View		Load JPG	☒
12	21/04/20 09:02	General View		Load JPG	☒
13	21/04/20 09:02	General View		Load JPG	☒
14	21/04/20 09:02	General View		Load JPG	☒
15	21/04/20 09:02	General View		Load JPG	☒
16	21/04/20 09:02	General View		Load JPG	☒
17	21/04/20 09:02	General View		Load JPG	☒
18	21/04/20 09:02	General View		Load JPG	☒

Documentation 1 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/07/18 15:14	EMAIL FROM III DD 18072018		Load PDF	
2	19/07/18 15:14	TP EST & GIA REPORT		Load PDF	
3	13/08/18 18:38	TP ESTIMATE- MARKED		Load PDF	
4	21/04/20 09:04	EMAIL FROM WSP DD 200420		Load PDF	
5	21/04/20 09:04	EMAIL TO III DD 210420		Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	20/07/18 08:55	Singapore Accident Statement		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III18013138/R1EA3S2**Date:** 04/05/2020**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SKC8453C	Insured Vehicle No :	SHD4512Y
Date of Loss:	09/07/2018	Nature of Claim:	TP
		Claim No:	MCT18070282

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKC8453C	Engine No:	10FJBW1281504
Make & Model:	PEUGEOT 3008, 1.6 (A)	Chassis No:	VF30U5FVABS230751
Reg. Date:	06/10/2011 (Man. Year: 2011)	Odometer:	228176 km
Colour:	Brown		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/50ZR17	Rear Tyre Size:	225/50ZR17
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,021.50	1,021.50	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	380.00	220.00	36.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,621.50	1,401.50	220.00	13.57
+ GST 7.00/7.00% (S\$)	113.51	98.11	15.40	13.57
Nett Amount (S\$)	1,735.01	1,499.61	235.40	13.57

INSPECTION

Date of Assignment:	19/07/2018		
Date Inspected:	07/08/2018	Inspected At:	Charn's Customcraft (HQ) Block 1010 Bukit Merah Lane 3, #01-105 Singapore 159724
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

5/4/2020

Adjuster Report

THE VEHICLE HAS NOT SEND IN FOR REPAIR

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 May 2020)
Parts:	144	PEUGEOT 3008 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKC8453C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Scratched	1,135.00 FL	*1,135.00 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	1,135.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	113.50
					Total Parts (\$\$)	1,021.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE / REPLACE / REINSTALL ALL NECESSARY PARTS: JACKING, PANEL BEATING, REPAIR AND STRAIGHTEN REAR INNER PANEL AND REAR BUMPER.	New	300.00	200.00
2	PUTTY AND RESPRAY REAR INNER PANEL AND REAR BUMPER.	New	300.00	180.00
Gross Labour Cost (\$\$)			600.00	380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >