



創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

FWD/III(SHD4512Y)
DOA:09/07/2018@1900

INDIA INTERNATIONAL INSURANCE PTE LTD 17/7/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM
ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SKC 8453 C - PEUGEOT 3008 TURBO 1.6 ADVENTURE
CHASSIS NO: VF30U5FVABS230751 (2011)

1 pc	Rear bumper	\$ 1,135.00	<i>scr /</i>
	LESS 10%	\$ 113.50	
		<u>\$ 1,021.50</u>	
	Remove/replace/reinstall all necessary parts: jacking, panel beating, repair and straightne rear inner panel and rear bumper.	\$ 300.00	<i>200</i>
	Putty and respray rear inner panel and rear bumper.	\$ 300.00	<i>180</i>
		\$ 1,621.50	
	ADD 7% GST	\$ 113.51	
		<u>\$ 1,735.01</u>	

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....

*Rasul
Hp 90010068
2 days
P/P
07/08/18 @1420
Resin by paint*