

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4752X

DATE 18/7/2018 14:32

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover — Detail			\$ 562.30
	Front Bumper Bracket Top (LH/RH) X su		\$ 22.40	\$ 44.80
	Front Bumper Retainer Mounting X su		\$ 9.20	\$ 18.40
	Front Fender (LH/RH) — Detail			\$ 619.00
	Front Fender Shield (LH) X su			\$ 169.80
	Front Fender Retainer X su			\$ 9.20
	Frt Wheel Hub Cap, LH X su			\$ 150.70
	SUB TOTAL			\$ 1,574.20
	LESS 20%			\$ 314.84
	DISCOUNTED TOTAL			\$ 1,259.36
	Frt Fender Advertisement Logo (LH) — su			\$ 100.00
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 560.00
	Spray Painting Charge			\$ 500.00
	Tuff Kote			\$ 50.00
	Frt Wheel Alignment			\$ 80.00
	TOTAL LABOUR			\$ 1,190.00
	ESTIMATE TOTAL			\$ 2,549.36

Kake 11/11/18

18/7/18 15:10h

2 Days.

L/s

After Repair p lls

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.