



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Lion City Rentals Pte Ltd 60 Anson Road #11-01 Mapletree Anson Singapore 079914 Contact No Mobile: 67420984	Cust No/Name	LL000015/Lion City Rentals Pte Ltd
	Reg No/Reg Date	SLF6928K / 06/09/201
	Date In/Mileage	/ 0
	Chassis No	KNAFX411MH5665278
	Engine No	G4FGGH657321
	Make/Model	KIA/FORTE K3 1.6 A EX BRQ
	Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	18/07/2018/ 18:32	TLC	442 / CocoLu	32328			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2200 2750.00
TO RENEW FRT DOOR RH, REAR DOOR RH, REAR BUMPER								
REPAIR REAR FENDER RH, CENTRE PILLAR RH,								120 200.00
E PNT88000								120 200.00
TO TRANSFER FRT DOOR TRIMS & FACILITATE REPAIR								
E PNT88000								
TO REMOVE & INSTALL REAR DOOR TRIMS AND GLASS								✓ 120.00
B WHEELALIGNMENT								
To Conduct Computerize Full Wheel Alignment								1680 2520.00
E PNT98000								
TO SPRAY PAINT FOR FRT DOOR RH, REAR DOOR RH, CENTRE PILLAR RH								?
REAR FENDER RH, REAR BUMPER								300.00
A 90000001								✓ 200.00
TO RENEW REAR UNDER CARRIAGE								✓ 80.00
A 90000001								✓ 20.00
TO CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM								
M SUNDRY								
TO APPLY SEALANT FOR ACCIDENT PORTION								
M SUNDRY								
Sundry								
M	PANEL ASSY-FRONT DOOR,RH				1.00	1277.00	00.00	bt ✓ 1277.00
M	HINGE ASSY-DOOR UPPER,RH				1.00	26.00	00.00	R ✓ 26.00
M	HINGE ASSY-REAR DOOR UPPER,RH				1.00	33.00	00.00	R ✓ 33.00
M	PANEL ASSY-REAR DOOR,RH				1.00	1309.00	00.00	bt ✓ 1309.00
M	HINGE ASSY-REAR DOOR UPPER,RH				1.00	33.00	00.00	? 33.00
M	HINGE ASSY-DOOR UPPER,RH				1.00	26.00	00.00	? 26.00
M	HANDLE ASSY-DOOR OUTSIDE				1.00	58.00	00.00	aut ✓ 58.00
M	COVER-FR DR O/S HDL,DRIVER				1.00	22.00	00.00	WA ✓ 22.00
M	BASE ASSY-FR DR O/S HANDLE RH				1.00	52.00	00.00	? 52.00
M	LATCH ASSY-FRONT DOOR,RH				1.00	253.00	00.00	? 253.00
M	HANDLE ASSY-DOOR OUTSIDE				1.00	58.00	00.00	R ✓ 58.00
M	COVER-FR DR O/S HDL,PASSENGER				1.00	22.00	00.00	R ✓ 22.00
M	BASE ASSY-FR DR O/S HANDLE RH				1.00	52.00	00.00	? 52.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Lion City Rentals Pte Ltd 60 Anson Road #11-01 Mapletree Anson Singapore 079914 Contact No Mobile: 67420984	Cust No/Name	LL000015/Lion City Rentals Pte Ltd
	Reg No/Reg Date	SLF6928K / 06/09/201
	Date In/Mileage	/ 0
	Chassis No	KNAFX411MH5665278
	Engine No	G4FGGH657321
	Make/Model	KIA/FORTE K3 1.6 A EX BRQ
	Colour/Trim	4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	18/07/2018/ 18:32	TLC	442 / CocoLu	32328
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M LATCH ASSY-REAR DOOR,RH		1.00	309.00	00.00	? 309.00
M PANEL ASSY-FRONT DR MODULE,RH		1.00	324.00	00.00	? 324.00
M MOTOR ASSY-FRONT POWER WDW,RH		1.00	362.00	00.00	? 362.00
M REGULATOR ASSY-RR DR WDO RH		1.00	467.00	00.00	? 467.00
M MOTOR ASSY-POWER WDO REG RR,RH		1.00	155.00	00.00	? 155.00
M BLACK TAPE-FR DR FRAME UPR,RH		1.00	13.00	00.00	new 13.00
M BLACK TAPE-FR DR RR,RH		1.00	12.00	00.00	new 12.00
M TAPE-RR DR FRAME BLACK RR,RH		1.00	8.00	00.00	new 8.00
M BLACK TAPE-RR DR FRAME UPR,RH		1.00	11.00	00.00	new 11.00
M COVER-RR BUMPER		1.00	688.00	00.00	del 688.00
M COVER-RR BUMPER,CTR		1.00	347.00	00.00	x 347.00
M BRACKET-RR BUMPER SIDE MTG,RH		1.00	29.00	00.00	new 29.00
M BRACKET-RR BUMPER SIDE MTG,LH		1.00	29.00	00.00	x 29.00

SURVEYOR NAME: Tan Jie 97495747
SURVEYOR SIGNATURE: [Signature]
DATE: 19/7/18 @ 1515
REMARKS: Resurvey before paint
8 days
sur e lka auto.com.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

7% GST on	Nett	12,365.00
	12365.00	865.55
	Total Payable	13,230.55

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.