

ASS. REC. BY:

REF: CS/FCI18013148/Urbn2 Special Instruction:

Surveyor:

Marius

ASSIGNMENT (Office)

CWS

From (Person):

Karen Tan

of

FCS

Date/Time:

19/7/18 @ 3-01pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

S1B 1224L

Insured:

SHD 66764

at Workshop m/s

Pusheh Auto

Tel:

67465405

of

1 kerli Bkt Ave 6 #01-46

Policy No:

Claim No:

D18005553MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18/07/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

Imp

H.O.D. Endorsement:

Date/Time:

3:00pm @ 20/7/18

Person Contacted:

Nancy

Vehicle:

IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

Revert thru email.

(08/11/13) wef

ASS. REC. BY: MORIS

REF:

fe1/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLB 1224Cat Workshop m/s ft.

of _____

Insured: SH/D 66760

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS MA62131

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

28/8/18 1/5 @ 13.00 confirmed with Alan.Red: \$28,636.90, 69%.

RECEIVED 05 SEP 2018

Date/Time, File Pass to?

1) typed

Date/Time, File Return to?

2) _____

Report Format :

TP

Lump Sum / LB: (\$) 13,000.00☐ : Preli. Report☒ : Final ReportDays Of Repair: 8Resurvey No. of Trip: 2

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS: \$ _____

Photos: 500Others: 500TOTAL: 61918

31x15=465

130+4655050+50184500500969Veh No: SLB 1224C Yr Regn: 3.16Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Toyota Estima c.c. 2362Colour: Black A/C: Insured / Std / NI / NASp. Reading: 27606 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ACR50019.4208Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 225/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front 7 mm Rear 7 mmR/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 18/7/18 D.O.I. 19/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S & ft.

The U/C / Chassis frame / Body Structure affected due to collision.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18013148/Urb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 19-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6676U	Veh. Inspected	SLB 1224L	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	19/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	18/07/2018	Inspection Date	19/07/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005553MFSH

Our Ref: CS/FCI18013148/urb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLB 1224L.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 19.07.2018 at the premises of M/s FASTECH AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>41,636.90</u> .
Revised Estimate Amount	: S\$ <u>16,250.43</u> .
"Check" Items Amount	: S\$ _____ .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:
The vehicle sustained damages
at rear o/s & front portion.



Yours faithfully
MARCUS
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	19-07-2018	Our Ref No. D18005553MFSH
Accident Date	18-07-2018	Claim Type. Third Party
Insured Vehicle	SHD6676U	Third Party Vehicle. SLB1224L
Survey Location	1 KAKI BUKIT AVENUE 6 #01-46/48/50AUTOBAY	
Contact Person.	NANCY LAM	
Contact No.	67465405/ 0	Fax No. 67458520
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	FASTECH AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 9849J

Vehicle Details

Vehicle No.: SLB1224L

Vehicle to be Exported: No

Intended De-registration Date: 19 Jul 2018

Vehicle Make: TOYOTA

Vehicle Model: ESTIMA AERAS PREMIUM 2.4 A

Primary Colour: Black

Manufacturing Year: 2015

Engine No.: 2AZ4A16601

Chassis No.: ACR500194208

Maximum Power Output: 125.0 kW (167 bhp)

Open Market Value: \$30,809.00

Original Registration Date: 04 Mar 2016

First Registration Date: 04 Mar 2016

Transfer Count: 0

Actual ARF Paid: \$35,133.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 03 Mar 2026

PARF Rebate Amount: \$26,349.00

Intended COE Rebate Details

COE Expiry Date: 03 Mar 2026

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$46,970.00

COE Rebate Amount: \$35,782.00

Total Rebate Amount: \$62,131.00

The information contained herein is correct as at 19 Jul 2018

OK



Inchcape
Pre-Owned

**WIDE RANGE OF PRE-OWNED
TOYOTA AND OTHER MAKES
AVAILABLE**

VISIT OUR NEW SHOWROOM FOR A PREMIUM PRE-OWNED EXPERIENCE @ 2 PANDAN CRES

Post an Advertisement


Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Coe Renewal Toyota Vios 1.5A



\$2000 Downpayment Monthly
From \$488 Onwards. Lowest
3.68%P.A@GV Cars Financing
GV Credit Pte Ltd StarAd



Browse by Category ▼

Sort b

9 vehicles

TOYOTA ESTIMA

Advanc

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mile

Search Selection

TOYOTA ESTIMA

Any

Any

2016

Any



**Toyota Estima 2.4A Aeras
Premium Moonroof**

\$135,998

\$15,920 /yr

12-Jan-2016

2,362 cc

15

Be Our Next Happy Buyer To Own This Well-kept Vehicle At Most Reasonable And Affordable Price! Full Ice Blue LED Int Surround System & 3M Soundproof. C2 Titanium Coating Wit...

Posted: 19-Jul-2018

Tags: 2016 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota



**Toyota Estima 2.4A Aeras
Premium Moonroof**

\$129,800

\$13,720 /yr

25-Oct-2016

2,362 cc

32

\$2000 Republic Auto Service Credits. Premium Model With Twin Moonroof And Power Tailgate, Condition Almost New. O Powerful And Smooth Engine. Well Maintained Exterior And Interior...

Republic Auto

Posted: 19-Jul-2018

Tags: 2016 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota



**Toyota Estima 2.4A Aeras
Premium Moonroof**

\$139,888

\$14,820 /yr

18-Aug-2016

2,362 cc

27

Latest Arrival. Elegant White MPV, Premium Model With Twin Moonroof And Power Tailgate, Condition Almost New. Own Kept And Maintained Both Interior And Exterior. No Repair...

Euro Performance Asia Pte Ltd

Posted: 18-Jul-2018

Tags: 2016 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota



**Toyota Estima 2.4A Aeras
Premium Moonroof**

\$136,800

\$14,840 /yr

08-Sep-2016

2,362 cc

31

Nissan Certified Pre-Owned Unit.100% Loan Available! Excellently Maintained And Polished. Original Paintwork And Accic Required. Trade In Are Welcome. Price Can Negotiable! Call Ou...

Hua Yang Credit Pte Ltd

Posted: 16-Jul-2018

Tags: 2016 Toyota Estima, Toyota Estima, Toyota, Estima, Used Toyota

Compare

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 18/7/2018 at 1850 hrs, I was driving my vehicle A along
PIE towards Changi Airport. vehicle C stop, I follow suit
suddenly vehicle B hit on my rear portion and cause my
car to push forwards and hit on vehicle C. There
were 3 cars involved in a chain collision.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Date of Accident : 18/7/18 Accident Time: 1850 (24-HR-Format)
Accident Place : along PIE toward Changi Airport
Vehicle No. (Car Plate No.) : SLB 1224L Make/Model: Toyota Estima
Insurance Company : NTUC Policy No: 5088242938-01
Owner or Company Name / IC No. : Lim Seow Tien / 570098493
Owner or Company Contact No. : _____ Owner's Hp _____ Company Tel _____
DRIVER'S Name / IC No. : Tan Lee Keng / 573274721
DRIVER'S Date Of Birth : 26/7/1973 DRIVER'S License Pass Date 7/10/1995
Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: _____
DRIVER'S Address : B1K 407 Bedok North Ave 3 #04-183
DRIVER'S Contact No. / Alt No. : 1) 96372455 2) 5460407
DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)
Email Address : _____
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance
Number of Passengers (Including Driver): 1 driver
Was there any video Captured by car camera: YES \ NO
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose
Any Injury (If YES, Pls state): yes

Other Party Driver's Particular (if any)

Vehicle No: SHD 66764 (1st car)	Vehicle No: SLA 68625
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: _____	IC No. Driver/Contact: _____

* NEW - Passenger's name & gender:

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6

#01-46,48,50 Autobay

SINGAPORE 417883

Not Advised
1/s # 13.000
19/7/18

VEHICLE NO:SLB 1224L

QTY	PARTICULAR		
1 PCS	TAILGATE	11	\$1,866.10 X
1 PCS	TAILGATE REAR LOGO	11	\$68.60 X
1 PCS	TAILGATE 'ESTIMA' EMBLEM	11	\$82.90 X
1 PCS	TAILGATE 'AERAS' EMBLEM	11	\$80.50 X
1 PCS	TAILGATE INNER LOCK	11	\$499.10 X
1 PCS	TAILGATE WEATHERSTRIP	11	\$392.30 X
1 PCS	TAILGATE INNER TRIM BORAD	11	\$845.10 X
1 PCS	REAR BUMPER	11	\$1,553.10
1 PCS	REAR BUMPER TOW COVER O/S	11	\$65.00
2 PCS	REAR BUMPER RETAINERS @\$125.10	11	\$250.20
1 PCS	REAR BUMPER REFLECTOR O/S	11	\$48.50
1 PCS	REAR BUMPER INNER SPONGE O/S	11	\$119.10
1 SET	REAR BUMPER CLIPS	11	\$50.00
1 PCS	REAR END PANEL	11	\$899.20
1 PCS	REAR END PANEL TOP GARNISH	11	\$455.10 X
1 PCS	REAR FLOOR PANEL	11	\$1,266.10 X
1 PCS	REAR FLOOR PANEL TOP BORAD	11	\$820.10 X
2 PCS	TAILLAMPS @\$650.00	11	\$1,300.00 X
1 PCS	FRONT BUMPER	11	\$1,510.10
1 PCS	FRONT BUMPER CENTRE GRILLE	11	\$822.50
1 PCS	FRONT BUMPER CENTRE GRILLE CHROME MOULDING	11	\$355.10
2 PCS	FRONT BUMPER SIDE RETAINERS @\$125.00	11	\$250.00
1 PCS	FRONT BUMPER REINFORCEMENT	11	\$439.10
1 PCS	FRONT BUMPER TOW COVERS @\$68.00	11	\$136.00 X
1 PCS	FRONT GRILLE	11	\$1,018.10
2 PCS	FRONT FENDERS @\$991.10	11	\$1,982.20 X
1 PCS	BONNET	11	\$866.50 X
1 PCS	BONNET INNER LOCK	11	\$155.10 X
1 PCS	BONNET RUBBER	11	\$48.50 X
2 PCS	HEADLAMP HIDS @\$2410.10	11	\$4,820.20
1 PCS	FRONT SUPPORT PANEL	11	\$1,145.50
1 PCS	FRONT SUPPORT PANEL TOP GARNISH	11	\$368.30
1 SET	FRONT SUPPORT PANEL TOP GARNISH CLIPS	11	\$50.00
1 PCS	FRONT HORN UNIT	11	\$185.00
1 PCS	AIR CON CONDENSER	11	\$2,110.10
1 PCS	FRONT BRACE PANEL	11	\$108.50

257

1 PCS	AIRCON LIQUID PIPE	11	\$211.30X
1 PCS	AIRCON DISCHARGE HOSE	11	\$655.10x
1 PCS	AIRCON SUCTION HOSE	11	\$688.10x
1 PCS	RADIATOR 22/0.10	22/0.10	\$2,668.10 ✓
1 PCS	RADIATOR TOP RETAINER	one	\$265.50 ✓
2 PCS	FRONT FOG LAMPS @\$389.10	11	\$778.20 X
1 PCS	FRONT BUMPER SPONGE	11	\$168.80 ✓
1 PCS	AIR CON COMPRESSOR	11	\$2,450.00 X
			\$34,916.90
	S.NETT		
1 PCS	FRONT LICENCE PLATE	one	\$50.00 40
1 BOT	RADIATOR COOLANT	one	\$50.00 ✓
1 SET	REAR BUMPER REVERSE SENSOR	short	\$300.00 200
1 PCS	REAR END PANEL SEALANT	one	\$50.00 ✓
	LABOUR CHRAGES:		
	TO CHECK WIRING		\$80.00 30
	TO DISMENTLE & REPLACING REVERSE SENSOR		\$80.00 50
	TO DISMENTLE & REFIX REAR WINDSCREEN	11	\$150.00 X
	TO TRANSFER TAILGATE MECHANISM	11	\$150.00 X
	TO REFILL AIR CON GAS		\$150.00 100
	TO DISMENTLE & REFIX SEAT,CUSHION,UPHOLSTREY		\$180.00 80
	TO SPRAY RUST PROOFING		\$180.00 80
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTENED		\$2,800.00 1300
	& REPLACING PARTS		
	TO PUTTY & SPRAY PAINTING		\$2,500.00 1600
	TOTAL		\$41,636.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

16883.9

12670.42

16250.42




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18013148/Urbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 11-09-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6676U	Veh. Inspected	SLB 1224L	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005553MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	19/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ESTIMA (A)	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ACR500194208	Colour	BLACK	
Odometer	27606	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R18	DUNLOP	7 mm	
L/H Front Tyre	225/50 R18	DUNLOP	7 mm	
R/H Rear Tyre	225/50 R18	DUNLOP	7 mm	
L/H Rear Tyre	225/50 R18	DUNLOP	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/07/2018	Inspection Date	19/07/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 1224L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	NOT NECESSARY	1,866.10	-
1	TAILGATE REAR LOGO	NOT NECESSARY	68.60	-
1	TAILGATE "ESTIMA" EMBLEM	NOT NECESSARY	82.90	-
1	TAILGATE "AERAS" EMBLEM	NOT NECESSARY	80.50	-
1	TAILGATE INNER LOCK	NOT NECESSARY	499.10	-
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	392.30	-
1	TAILGATE INNER TRIM BOARD	NOT NECESSARY	845.10	-
1	REAR BUMPER	DISTORTED	1,553.10	681.10
1	REAR BUMPER TOW COVER O/S	TORN	65.00	65.00
2	REAR BUMPER RETAINERS @\$125.10	O/S BENT	250.20	125.10
1	REAR BUMPER REFLECTOR O/S	CRACKED	48.50	48.50
1	REAR BUMPER INNER SPONGE O/S	TORN	119.10	119.10
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR END PANEL	BADLY DENTED	899.20	899.20
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	455.10	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,266.10	-
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	820.10	-
2	TAILLAMPS @\$650.00	NOT NECESSARY	1,300.00	-
1	FRONT BUMPER	DENTED / DEFORMED	1,510.10	1,315.10
1	FRONT BUMPER CENTRE GRILLE	DENTED / DEFORMED	822.50	822.50
1	FRONT BUMPER CENTRE GRILLE CHROME MOULDING	CRACKED	355.10	355.10
2	FRONT BUMPER SIDE RETAINERS @\$125.00	BENT	250.00	250.00
1	FRONT BUMPER REINFORCEMENT	DENTED	439.10	439.10
2	FRONT BUMPER TOW COVERS @\$68.00	NOT NECESSARY	136.00	-
1	FRONT GRILLE	CRACKED	1,018.10	1,018.10
2	FRONT FENDERS @\$991.10	TO REPAIR SEE LABOUR	1,982.20	-
1	BONNET	TO REPAIR SEE LABOUR	866.50	-

Report Ref No. CS/FCI18013148/Urbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET INNER LOCK	NOT NECESSARY	155.10	-
1	BONNET RUBBER	NOT NECESSARY	48.50	-
2	HEADLAMP HIDS @\$2410.10	CRACKED	4,820.20	4,730.20
1	FRONT SUPPORT PANEL	BENT	1,145.50	1,145.50
1	FRONT SUPPORT PANEL TOP GARNISH	TORN	368.30	368.30
1	SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	NECESSARY	50.00	50.00
1	FRONT HORN UNIT	CRACKED	185.00	185.00
1	AIR CON CONDENSER	BENT / PUNCTURE	2,110.10	1,474.10
1	FRONT BRACE PANEL	TWISTED	108.50	108.50
1	AIRCON LIQUID PIPE	NOT NECESSARY	211.30	-
1	AIRCON DISCHARGE HOSE	NOT NECESSARY	655.10	-
1	AIRCON SUCTION HOSE	NOT NECESSARY	688.10	-
1	RADIATOR	BENT / PUNCTURE	2,668.10	2,210.10
1	RADIATOR TOP RETAINER	CRACKED	265.50	265.50
2	FRONT FOG LAMPS @\$389.10	NOT NECESSARY	778.20	-
1	FRONT BUMPER SPONGE	TORN	168.80	168.80
1	AIR CON COMPRESSOR	NOT NECESSARY	2,450.00	-
	LESS 25% DISCOUNT		-	-4,223.48
			34,916.90	12,670.42
	SPECIAL NETT ITEMS			
1	FRONT LICENCE PLATE (SN)	CRACKED	50.00	40.00
1	BOT RADIATOR COOLANT (SN)	NECESSARY	50.00	50.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	300.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
			450.00	340.00
	LABOUR			
	TO CHECK WIRING.		80.00	30.00
	TO DISMENTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMENTLE & REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO TRANSFER TAILGATE MECHANISM.	NOT NECESSARY	150.00	-
	TO REFILL AIR CON GAS.		150.00	100.00
	TO DISMENTLE & REFIX SEAT,CUSHION,UPHOLSTERY.		180.00	80.00

Report Ref No. CS/FCI18013148/Urbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY RUST PROOFING.		180.00	80.00
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTENED & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL,FRONT FENDERS AND BONNET.		2,800.00	1,300.00
	TO PUTTY & SPRAY PAINTING.		2,500.00	1,600.00
			6,270.00	3,240.00
GRAND TOTAL			41,636.90	16,250.42
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				13,000.00

Report Ref No. CS/FCI18013148/Urbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.