

15/5/2018

INS. CASE OWNER:

CC 4/AXA1801

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

SKQ 2463P

TAN HOR Kiang

HP: 86089833

D.O.A: 18/7/18

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

58M0UP03 / 58543

P1562921

VOLKSWAGEN

KUNOS LINK ENTERING PIE

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

INSRS:
WSP:
Tel:
Liability:
RMKS:

performance

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

20/7/18
vian

SKQ 637P-X

SKQ 2463P-X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

27/7/18

Hear to repair.

25/7/18

email w/ shop liability clear.

26/9/18

file pass to typist type report

14/11/18

Seek model via SMART

15/11/18

Spoken to cythia she say for the

call submit pre sign DW.

15/11/18

Please close BY this week.

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

SS 8507.01

Loss of Rental (LOR):

SS 1344.00

(

8

days)

x 168.00

Loss of Use (LOU):

SS

(

5

x

days)

Loss of Income (LOI):

SS

(

5

x

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GLA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS 9851.01

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 9851.01

Name 1:

Performance Motors Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

Signature

Taufik

REF:

AXA

W

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

8144K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res:

Yes or No

Lump Sum:

2.8~

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

WP

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SDX 637P

Yr Regn: 2016 / March

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Dep:

Make:

BMW 520i

c.c 1997

Colour

Colour

Black

A/C: Insured / Std / NI / NA

Sp. Reading

45/74

T/Radio: Insured / Std / NI / NA

Eng/No:

45

C/No:

WBA 5A 32 0100829232

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

19/7/18 @ 5pm

Survey held at

PML

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/5/18 Confirm 2.8~ \$7950.48 with 5 working days

(200) - \$3614.56
31.1)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18013154/wb3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 19-07-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKQ 2463P	Veh. Inspected	SDX 637P	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	19/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	18/07/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

BMW Dealer:

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559M GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 47737
Date Estimated : 18/07/2018
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Tan I-Lin Tammy (Chen Ailing Tammy)
205 Bradell Road
ComfortDelGro East Wing 7 Floor

Singapore 579701

- ACCOUNT - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDX637P	D829232	02/03/2016	520iA	0

DESCRIPTIONVALUE

Replace rear boot lid, rear bumper and remove attachment
etc include knock on accident dent

1530.00 1,700.00 ✓

Spray painting rear boot lid rear bumper

1587.60 1,764.00 ✓

To check electrical wiring systems and lightings at the
rear section for proper function.

135.00 150 177.00 ✓

To remove and install boot compartment carpet and garnish
to facilitate repairs.

207.00 230 271.00 ✓

To carry out body cavity preservation.
(Per panel).

90 100 118.00 ✓

To tow accident vehicle to PML workshop.

✓ 195.00

Sundries.

111 80 150.00 ✓

Total Labour 1: **4,375.00**DESCRIPTIONQTYPRICVALUE

LH BOOTLID HINGE

1 113.65

113.65

RH BOOTLID HINGE

1 113.65

113.65

BOOTLID

1 1,602.40

1,602.40

SET MOUNTS PDC SENSOR REAR

1 62.95

62.95

RR BUMPER BOTTOM CENTRE GUIDE

1 58.95

58.95

PROTECTION FOIL L=55MM

2 4.75

9.50

REAR BUMPER CENTRE GUIDE

1 60.05

60.05

RR LH MOUNT

1 198.30

198.30

RR RH MOUNT

1 198.30

198.30

REAR BUMPER PRIMED (PDC)

1 1,467.20

1,467.20

REAR BUMPER TOWING EYE COVER PRIMED

1 46.45

46.45

EMBLEM GROMMET

2 0.80

1.60

BMW EMBLEM

1 69.50

69.50

MODEL LETTERING 520I

1 62.55

62.55

1534.33

51.18

58.15

1428.18

45.06

61.41

60.67



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63445773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X**E S T I M A T E**

Estimate No. : **b1 47737**
Date Estimated : **18/07/2018**
Prepared By : **Chua Kee Sin**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDX637P	D829232	02/03/2016	520iA	0

DESCRIPTION

TRIGGER CONTACT
LH SPINDLE DRIVE
RR RH LIGHT IN SIDE PANEL
RR RH LIGHT IN TRUNK LID

QTY	PRIC	VALUE
1	131.95	131.95
1	522.65	522.65
1	572.25	572.25
1	338.00	338.00

Total Parts : **5,629.90**

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
 Date & Time **19/7/18 e** Excess S\$ _____
 Surveyor's Name **Taufik** Sign **Taufik**
 Surveyor's Tel **97495749** Authorised Yes / No _____
 Authorised Date _____ Time _____
 RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____
 Surveyor's E-mail **taufik@lkkauto.com**
 Recommended Working Days Recommend **5-6 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey without "repairs" basis
- No illegal modifications allowed
- Supplementary work to the resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	4,375.00
Parts	:	5,629.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	700.34
Grand Total	:	10,705.24

THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY

PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE

10864.70

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0620081-X



SUPPLEMENTARY

Estimate No. : b1 47737
Date Estimated : 18/07/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Tan I-Lin Tammy (Chen Ailing Tammy)
205 Bradell Road
ComfortDelGro East Wing 7 Floor

Singapore 579701

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SDX637P	D829232	02/03/2016	520iA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RR BUMPER CARRIER *	714.25	1.00	3.00	692.82 <i>bf</i>
# ADAPTOR *	68.45	1.00	3.00	66.40 <i>de</i>
# PLUG *	1.05	10.00	3.00	10.18 <i>nei</i>
# REAR RIGHT COVERING *	84.20	1.00	3.00	81.67 <i>de</i>
# PLUG BLACK D=5MM *	0.90	10.00	3.00	8.73 <i>nei</i>

Total Labour :
Total Parts : 859.80
Total Labour & Parts : 859.80

11565-01

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 47737
Date Estimated : 18/07/2018
Prepared By : Chua Kee Sin

Page No. :

REPAIR FOR -
Tan I-Lin Tammy (Chen Ailing Tammy)
205 Braddell Road
ComfortDelGro East Wing 7 Floor
Singapore 579701

- ACCOUNT - 238
AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SDX637P	D829232	02/03/2016	520iA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments, boot lid, rear RH covering include knocking out dents caused by the accident	1700.00	10.00	1,530.00	
To spray paint boot lid and rear bumper	1764.00	10.00	1,587.60	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	10.00	135.00	
To remove and install boot compartment carpet and garnish to facilitate repairs	230.00	10.00	207.00	
* To carry out body cavity preservation, (Per panel).	100.00	10.00	90.00	
To tow accident vehicle to PML workshop.	195.00	0.00	195.00	
Sundries.	80.00	0.00	80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BOOTLID	1,602.40	1.00	3.00	1,554.33
RR BUMPER BOTTOM CENTRE GUIDE	58.95	1.00	3.00	57.18
# RR BUMPER CARRIER *	714.25	1.00	3.00	692.82
# ADAPTOR *	68.45	1.00	3.00	66.40
REAR BUMPER CENTRE GUIDE	60.05	1.00	3.00	58.25
REAR BUMPER PRIMED (PDC)	1,467.20	1.00	3.00	1,423.18
REAR BUMPER TOWING EYE COVER PRIMED	46.45	1.00	3.00	45.06
BMW EMBLEM	69.49	1.00	3.00	67.41
MODEL LETTERING 520i	62.55	1.00	3.00	60.67
# PLUG *	1.05	10.00	3.00	10.18
# REAR RIGHT COVERING *	84.20	1.00	3.00	81.67
# PLUG BLACK D=5MM *	0.90	10.00	3.00	8.73

SUPPLEMENTARY ITEMS

Total Labour :	3,824.60
Total Parts :	4,125.88
Total Labour & Parts :	7,950.48
Deduction for Excess :	
Total Repair Costs less Excess:	7,950.48
GST @7%:	556.53
Grand Total :	8,507.01



Service Request Details

Claim

S8M00P03

Reference

None 

TawAlah.

Loss Date

July 18, 2018

Request Date

July 19, 2018

Due Date

July 26, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SDX637P

Make

TPVD BMW

Model

520I

Service Address

...

Primary Contact/Insured

TAN CHOR KIANG

224 TELOK KURAU ROAD, #03-03 UNI BUILDING, 423836, Singapore
86081833Claim Handler

LOH Cynthia

6568804843

cynthia.loh@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



Re:S8M00P03- Mandate approval

Type

🔗 Question

Message

Mandate approved

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKQ 2463P (Insd veh)	Model:	B.M.W. 520I
	SDX 637P (TP veh)		
Date of Accident:	18/07/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	11,625.23
Final Repair Cost	:	\$	8,507.01
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	1,344.00 8 days
LTA / GIA Search Fee	:	\$	0.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	9,851.01

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____
 BOLA Liability: _____100_____(%) Assessed Liability (*): _____(%)
 * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	PERFORMANCE MOTORS LTD	:	\$ 9,851.01

NUR SHAQILAH BTE ABDOL
WAHAB

16/11/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18013154/T1wb3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CYNTHIA LOH		Date : 16-11-2018 Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKQ 2463P	Veh. Inspected	SDX 637P
Policy No.	P1563931	Coverage (\$)	0.00
Claim No.	S8M00P03	Excess (\$)	0.00
Assign From	CYNTHIA LOH	Assign Date	19/07/2018
2. Vehicle Particulars & Condition			
Make & Model	B.M.W. 520i	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WBA5A32010D829232	Colour	BLACK
Odometer	45174	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/55R17	PIRELLI	6 mm
L/H Front Tyre	225/55R17	PIRELLI	6 mm
R/H Rear Tyre	225/55R17	PIRELLI	6 mm
L/H Rear Tyre	225/55R17	PIRELLI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/07/2018	Inspection Date	19/07/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDX 637P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	LH BOOTLID HINGE (SN) (CONSISTENT)	NOT NECESSARY	113.65	-
1	RH BOOTLID HINGE (SN) (CONSISTENT)	NOT NECESSARY	113.65	-
1	BOOTLID (SN) (CONSISTENT)	BENT	1,602.40	1,554.33
1	SET MOUNTS PDC SENSOR REAR (SN) (CONSISTENT)	NOT NECESSARY	62.95	-
1	RR BUMPER BOTTOM CENTRE GUIDE (SN) (CONSISTENT)	DEFORMED	58.95	57.18
2	PROTECTION FOIL L=5MM (SN) (CONSISTENT)	NOT NECESSARY	9.50	-
1	REARV BUMPER CENTRE GUIDE (SN) (CONSISTENT)	NECESSARY	60.05	58.25
1	RR LH MOUNT (SN) (CONSISTENT)	NOT NECESSARY	198.30	-
1	RR RH MOUNT (SN) (CONSISTENT)	NOT NECESSARY	198.30	-
1	REAR BUMPER PRIMED (PDC) (SN) (CONSISTENT)	DEFORMED	1,467.20	1,423.18
1	REAR BUMPER TOWING EYE COVER PRIMED (SN) (CONSISTENT)	DEFORMED	46.45	45.06
2	EMBLEM GROMMET (SN) (CONSISTENT)	NOT NECESSARY	1.60	-
1	BMW EMBLEM (SN) (CONSISTENT)	NECESSARY	69.50	67.41
1	MODEL LETTERING 520I (SN) (CONSISTENT)	NECESSARY	62.55	60.67
1	TRIGGER CONTACT (SN) (CONSISTENT)	NOT NECESSARY	131.95	-
1	LH SPINDLE DRIVE (SN) (CONSISTENT)	NOT NECESSARY	522.65	-
1	RR RH LIGHT IN SIDE PANEL (SN) (CONSISTENT)	NOT NECESSARY	572.25	-
1	RR RH LIGHT IN TRUNK LID (SN) (CONSISTENT)	NOT NECESSARY	338.00	-
1	SUNDRIES (SN)	NECESSARY	150.00	80.00
1	RR BUMPER CARRIER (SN) (CONSISTENT) (ADDITIONAL)	BENT	692.82	692.82
1	ADAPTOR (SN) (CONSISTENT) (ADDITIONAL)	DEFORMED	66.40	66.40
10	PLUG (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	10.18	10.18
1	REAR RIGHT COVERING (SN) (CONSISTENT) (ADDITIONAL)	DEFORMED	81.67	81.67
10	PLUG BLACK D=5MM (SN) (CONSISTENT) (ADDITIONAL)	NECESSARY	8.73	8.73
			6,639.70	4,205.88
LABOUR				
REPLACE REAR BOOT LID, REAR BUMPER AND REMOVE ATTACHMENT ETC INCLUDE KNOCK ON ACCIDENT DENT.			1,700.00	1,530.00

Report Ref No. CC4/ASM18013154/T1wb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINTING REAR BOOT LID REAR BUMPER.		1,764.00	1,587.60
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	135.00
	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS.		271.00	207.00
	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL).		118.00	90.00
	TO TOW ACCIDENT VEHICLE TO PML WORKSHOP.		195.00	195.00
			4,225.00	3,744.60
	GRAND TOTAL		10,864.70	7,950.48
RECOMMENDED COST OF REPAIRS				7,950.48

Report Ref No. CC4/ASM18013154/T1wb3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.