

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47737
Date Estimated : 18/07/2018
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Tan I-Lin Tammy (Chen Ailing Tammy)
205 Bradell Road
ComfortDelGro East Wing 7 Floor
Singapore 579701

- ACCOUNT - 238

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDX637P	D829232	02/03/2016	520ia	0

DESCRIPTIONVALUE

Replace rear boot lid, rear bumper and remove attachment
etc include knock on accident dent

1,700.00 ✓

Spray painting rear boot lid rear bumper

~~1,500~~ 1,764.00 ✓

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

To remove and install boot compartment carpet and garnish
to facilitate repairs.

230 271.00

To carry out body cavity preservation.
(Per panel).

100? 118.00

To tow accident vehicle to PML workshop.

✓ 195.00

Sundries.

? 150.00

Total Labour 1: **4,375.00**

DESCRIPTIONQTYPRICVALUE

LH BOOTLID HINGE

1 113.65

? 113.65

RH BOOTLID HINGE

1 113.65

? 113.65

BOOTLID

1 1,602.40

bt ✓ 1,602.40

SET MOUNTS PDC SENSOR REAR

1 62.95

? 62.95

RR BUMPER BOTTOM CENTRE GUIDE

1 58.95

? 58.95

PROTECTION FOIL L=55MM

2 4.75

? 9.50

REAR BUMPER CENTRE GUIDE

1 60.05

? 60.05

RR LH MOUNT

1 198.30

? 198.30

RR RH MOUNT

1 198.30

? 198.30

REAR BUMPER PRIMED (PDC)

1 1,467.20

de ✓ 1,467.20

REAR BUMPER TOWING EYE COVER PRIMED

1 46.45

de ✓ 46.45

EMBLEM GROMMET

2 0.80

new ✓ 1.60

BMW EMBLEM

1 69.50

new ✓ 69.50

MODEL LETTERING 520I

1 62.55

new ✓ 62.55

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 47737**
Date Estimated : **18/07/2018**
Prepared By : **Chua Kee Sin**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDX637P	D829232	02/03/2016	520iA	0

DESCRIPTION	QTY	PRIC	VALUE
TRIGGER CONTACT	1	131.95	131.95
LH SPINDLE DRIVE	1	522.65	522.65
RR RH LIGHT IN SIDE PANEL	1	572.25	572.25
RR RH LIGHT IN TRUNK LID	1	338.00	338.00
Total Parts :			5,629.90

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 19/7/18 e Excess S\$ _____

Surveyor's Name Taufik Sign Taufik

Surveyor's Tel 97495749 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No Yes PML Yes / No _____

Surveyor's E-mail taufik@lkkauto.com

No. of Working Days Recommend 5-6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on "without prejudice" basis
- No illegal modification is allowed
- Supplementary claims must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Labour 1	:	4,375.00
Parts	:	5,629.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	700.34
Grand Total	:	10,705.24