

# WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03  
Halcyon 2, S'pore 577200  
Tel No. : 6451 3933 Fax No. : 6455 7576  
E-Mail : worldaut@singnet.com.sg  
Website : www.worldauto.com.sg  
Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD  
143 Cecil Street #01-01 GB Building  
069542

Attention : Motor Claim Department  
Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000234

Date : 18/07/2018  
Vehicle Num. : SLJ 4027C (LCR)  
Make/Model : HONDA VEZEL HYBRID  
Chassis/Eng# :  
Accident Date : 12/07/2018  
Claim No. :  
Reference :  
Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

- |    |   |                                 |  |                  |
|----|---|---------------------------------|--|------------------|
| 1. | 1 | LIST ITEMS :                    |  |                  |
| 2. | 1 | REAR BUMPER                     |  | 900.00 DE        |
| 3. | 1 | REAR SIDE BUMPER - RH           |  | 250.00 DE        |
| 4. | 1 | REAR BUMPER TAIL LAMP RH        |  | 700.00 X         |
| 5. | 1 | REAR WHEEL ARCH MOULDING - RH   |  | 250.00 Repair DE |
| 6. | 1 | REAR COMPARTMENT BOX            |  | 280.00 X         |
| 7. | 1 | REAR BUMPER RETAINER RH         |  | 89.00 ?          |
| 8. | 1 | REAR FENDER INNER TRIM BOARD RH |  | 345.00 X         |

List Total S\$ :

20.00% Discount S\$ :

2,814.00

562.80

2,251.20

- |    |   |                                    |  |             |
|----|---|------------------------------------|--|-------------|
| 1. | 1 | SPECIAL NETT ITEMS :               |  |             |
| 2. | 1 | REAR BUMPER CLIP                   |  | 40.00 DE    |
| 3. | 1 | REAR TAILLAMP CLIPS                |  | 40.00 X     |
| 4. | 1 | REAR WHEEL ARCH MOULDING CLIPS     |  | 20 40.00 DE |
| 5. | 1 | REVERSE SENSOR                     |  | 280.00 X    |
| 6. | 1 | REAR FENDER INNER TRIM BOARD CLIPS |  | 40.00 X     |

Special Nett Total S\$ :

440.00

LABOUR :

LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER  
REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN  
PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.

850.00 3000 400

PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER)

1,000.00 400

Labour Total S\$ :

1,850.00

E. & O.E.

Total S\$ : 4,541.20

for WORLD AUTO PTE LTD

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair  
HP 90010068  
3 days  
4/5  
20/07/18 @ 1500  
Repair after repair