

ASS. REC. BY:

REF:

CS/CT18013157/Atd3

Special Instructions:

Surveyor:
Meimen

Adrian

ASSIGNMENT (Office)

From (Person):

Huang Shiang Yi

of

CT1

Date/Time:

19/7/18 @ 10:22am

Estimated Cost:

Bill to:

OD / ☒ FIP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF 7430R

Insured:

GBH 1982T

at Workshop n/o:

Vision Autowork

Tel:

9856 4815

of

8 keki Bkt Ave 4 # 08-09 Premier

Policy No:

DMCVSN18 06661800

Claim No:

SNM18 D03 54 0C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17/07/2018

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

3:33pm @ 19/7/18

Person Contacted:

Aby

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate	
	GBF 7430R - NA/EQT 18013061/24	D.O.A: 17/7/2018
	GBH 1982T - NA/EQT 18013061/24	D.O.A: 17/07/2018
	Submit preli report, owner withdraw claim	

REF:

ASS. REC. BY: Adrian Ling

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBF7430R

Yr Regn: 2017 / Feb.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan Cabstar.

C.C. 2953

Colour:

Silver.

A/C: Insured / Std / NI / NA

Sp. Reading

54948

T/Radio: Insured / Std / NI / NA

Eng/No:

JN1562FJ420859241.

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nif / S/Rim / STD A/Rim or

Tyre Size:

F: 185 R15C Wanli

R: 155 R12C Dunlop

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Wanli

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

19/07/18.

Survey held at

Vision.

Des. of Damages: Fit / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Check.

MV: 73K (Paper tailgate)
 JV: 39K
 Net: 34K.

RECEIVED 23 JUL 2018

Date/Time, File Pass to?



Preli. Report

23/7 Typist



Final Report

Date/Time, File Return to?

Days Of Repair: 14

Resurvey No. of Trip: -

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Report Format:

TP

Lump Sum / U.B.I: (\$)

Survey Fee:

220

Transportation:

S + RS: \$

Photos

Others:

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jul 2018		19 Jul 2018 10:22 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	KANG JIE TECHNOLOGY LLP		
Vehicle Reg. No.:	GBF7430R	Date of Loss:	17/07/2018 00:00 - :59
Claim Type:	TP / SNM18D03540C02	Policy/Cover Note No.:	DMCVSN1806661800
Vehicle Reg. No. (Insured):	GBH1982T	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4,, #08-09 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 6341 6789		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Hwang Shiang Yi - 63896541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/07/2018]		
Adj Asg. Remarks:	NO EST, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: Admin-D (LKKAuto)
Sent: Monday, 23 July 2018 10:43 AM
To: Denise Tay (LKKAuto)
Subject: FW: PRS FOR GBF7430R (CTI: SNM18D03540C02)

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Vision Autowork [<mailto:visionautowork@gmail.com>]
Sent: Friday, 20 July 2018 4:57 PM
To: Lucas Lee <lucas.lee@sg.cntaiping.com>; Hwang Shiang Yi <shiangyi.hwang@sg.cntaiping.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: Re: PRS FOR GBF7430R (CTI: SNM18D03540C02)

Dear Sir / Madam,

We refer to the above mentioned accident.

As informed by our client (GBF7430R) have do the private settlement with GBH1982T, please withdraw the claim from our workshop.

We apologies for any inconvenience and appreciate your assist.

Thank You

Yours faithfully,

Michelle
Hp: 9856 4815

8 Kaki Bukit Avenue 4,
#08-09,Premier @ Kaki Bukit,
Singapore 41875
Tel: 6341 6789
Fax: 6341 6778

On Thu, Jul 19, 2018 at 10:14 AM, Lucas Lee <lucas.lee@sg.cntaiping.com> wrote:

Dear Sirs,

VISION AUTOWORK PTE. LTD.

8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, S'PORE 415875

Tel: 6341 6789 Fax: 6341 6778

Co. Reg. No.: 201500371E

Date: 18/07/18

By Fax & Email

To: China Taiping

Attn: Motor Claims Department

Re: Accident involving motor vehicle Nos. GBF 7430R and GBH 1982T
along Woodlands Avenue 12 towards Gambas (After Woodlands Ave 5) on 17/07/2018

We refer to the above matter.

We are instructed by Kang Jie Technology LLP to notify you of a road traffic accident on 17/07/2018 at about 16:20 at Woodlands Avenue 12 towards Gambas (After Woodlands Ave 5), involving our client's/customer's vehicle registration number GBF 7430R and vehicle registration number GBH 1982T driven by you at the material time.

As a result of the accident, our client's /customer's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client/we shall proceed to repair the vehicle without further reference to you.

Thank You

Yours faithfully



Abby

Hp : 9856 4815



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18013157/Atd3

3 ANSON ROAD #16-00

SPRINGLEAF TOWERS SINGAPORE 079909

Date : 19-07-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 1982T	Veh. Inspected	GBF 7430R
Policy No.	DMCVSN1806661800	Coverage (\$)	0.00
Claim No.	SNM18D03540C02	Excess (\$)	0.00
Assign From	MERIMEN (HWANG SHIANG YI)	Assign Date	19/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	17/07/2018	Inspection Date	19/07/2018
Survey held at	VISION AUTOWORK PTE LTD 8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/07/2018 15:10
Date Of Accident	17/07/2018 16:20
Exact Location Of Accident	WOODLANDS AVE 12 TWDS GAMBAS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF7430R
Insured/Policyholder	
Name Of Registered Owner	KANG JIE TECHNOLOGY LLP
Co Reg No	T10LL0938L
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999

Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCPHQ18-001290
Cover Note Number	

Driver

Name of Driver	ZHAO XINGSHUANG
Passport No/FIN	G6285055N
Date Of Birth	23/05/1989
Occupation	OUTDOOR
Date Of Driving Pass	20/12/2013
Driving Experience	4 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87149188
Fax Number	
Contact Number	OFFICE-87149188
Email Address	NOEMAIL

Address	7 GAMBAS CRESCENT #08-12
Postcode	757087
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH1982T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	YP5669H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	ZHAO XINGSHUANG
Approximate Age	
Injuries Sustain	CHEST & NECK
Injured person in which vehicle?	GBF7430R
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and;
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 **KANGJIE康洁**
KANGJIE TECHNOLOGY LIMITED LIABILITY PARTNERSHIP
Policyholder's Signature: T1011 05381
Date & Time: 12 Nov 2019 12:00 PM


Driver's Signature
(If driver is not the policyholder)
Date & Time


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attach

DECLARATION

We declare the foregoing particulars are true in every respect.

KANGJIE 康洁
 Policyholder's Signature: [Signature]
 Date & Time: 12/01/2018
 (if driver is not the policyholder)
 Date & Time: [Signature]

Reporting Centre Person's Signature: [Signature]
 Name: [Signature]
 NRIC/FIN No: [Signature]

Accident Sketch Plan

On 17.07.18 at about 16:20 hours at Woodlands Avenue 12 towards Gambas (After woodlands Avenue 5). While I was travelling on the right lane, traffic was slow moving.

Suddenly I heard a loud bang from behind and the impact forced my vehicle (A) to move forward, I tried to avoid hitting onto the vehicle (C) and immediately turned my steering to right, but unfortunately the great impact caused my vehicle (A) front left portion hit onto rear right portion of vehicle (C). When I alighted I realise it was vehicle (B) hit onto my rear portion causing damages on my vehicle (A) front left hand side and rear portion.

It was a chain collision of total 3 vehicles involved and I have one passenger inside my vehicle (A).

Vehicle (A): GBF7430R

Vehicle (B): GBH1982T

Vehicle (C): YP5669H



 **KANGJIE康洁**
KANGJIE TECHNOLOGY LIMITED LIABILITY PARTNERSHIP
Co. Reg. No: T10LL0938L
8B, 152 Woodlands Street 15 #06-775 Singapore 730152
Mobile: (0065) 9278 6118

 **KANGJIE康洁**
KANGJIE TECHNOLOGY LIMITED LIABILITY PARTNERSHIP
Co. Reg. No: T10LL0938L
8B, 152 Woodlands Street 15 #06-775 Singapore 730152
Mobile: (0065) 9278 6118

 **KANGJIE康洁**
KANGJIE TECHNOLOGY LIMITED LIABILITY PARTNERSHIP
Co. Reg. No: T10LL0938L
8B, 152 Woodlands Street 15 #06-775 Singapore 730152
Mobile: (0065) 9278 6118

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Limited Liability Partnership

Owner ID:

0938L

Vehicle Details

Vehicle No.:

GBF7430R

Vehicle to be Exported:

No

Intended De-registration Date:

17 Jul 2018

Vehicle Make:

NISSAN

Vehicle Model:

CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5

Primary Colour:

Silver

Manufacturing Year:

2016

Engine No.:

ZD30015078N

Chassis No.:

JN15C2F24Z0859241

Maximum Power Output:

-

Open Market Value:

\$24,942.00

Original Registration Date:

28 Feb 2017

First Registration Date:

28 Feb 2017

Transfer Count:

1

Actual ARF Paid:

\$1,248.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

27 Feb 2027

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

PQP Paid:

\$45,299.00

COE Rebate Amount:

\$39,016.00

Total Rebate Amount:

\$39,016.00

28/02/2017

\$ 36704.00

The information contained herein is correct as at 17 Jul 2018

OK



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

Find out more



nissan cabstar Price Range Depreciation Year Reg Vehicle Type

Advanced Search

Home » Used Cars » Direct Owners » Nissan Cabstar

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Car Leasing



Nissan Cabstar

Overview Financial Accessories Similar Research Photos Map

DIRECT OWNER

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$75,800	?
Depreciation	\$8,790 /yr. View models with similar depreciation	?
Reg Date	28-Feb-2017 (8yrs 7mths 9days COE left)	
Manufactured	2016	?
Mileage	-	
Transmission	Manual	
Engine Cap	2,953 cc	
Curb Weight	2,260 kg	?
Fuel type	Diesel	
Features	-	
Accessories	-	
Description	Powerful And Responsive Engine, Smooth Transmission Power In Gear Box. Mint Interior And Exterior Condition. Original Paintwork And Zero Accident. Full Aluminium Checkered Deck, Good Condition Cabin And Crane. All Hydraulic In Excellent Condition.	
COE	\$45,299	?
OMV	\$24,942	?
ARF	\$1,248	?
Dereg Value	\$39,044 as of today (change)	?
No. of Owners	2	?
Type of Veh	Truck	
Category	Direct Owner Sale	
Availability	Available	DIRECT OWNER

Add to Shortlist Add to Compare Add a Note

Posted on: 16-Jul-2018 | Last Updated on: 16-Jul-2018

Tags: Nissan Cabstar, 2017 Nissan Cabstar, Nissan, Cabstar, Used Nissan

Upfront Payment

» View Financial aid

Transfer Fee	\$25	?
Down Payment	\$7,580 (change)	Maximum 90% Loan ?
1st Instalment	\$1,005	?
Total Upfront Payment	\$8,610 (excluding insurance)	?

Estimates based on 90% loan at 3.4% interest rate. Check with seller for exact figure.



NO IMAGE AVAILABLE

100% FREE
PAPERWORK
SUPPORT FOR
BOTH BUYER
& SELLER

Price Analysis

Seller Information

Contact Person(s) Ryan

Enquiry Contact Seller

USEFUL FORMS

- » Indemnity form
- » Receipt
- » M01
- » Sales agreement
- » Hand-over form

Instructions on how to complete a seller to end-consumer deal

Regardless of buying or selling, we'll handle your paperwork, loans & insurance for FREE.



Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation



Solitaire Round Diamond 5.01ct. VVS1 - Color: F



Solitaire Princess Diamond 2.08ct. Internally Flawless - Color: F

JEWELLERY & WATCH PUBLIC AUCTION

SEIZED ASSETS - OVER 900 ITEMS

Saturday, 21st July
 Preview: 11am - Auction: 1pm - 5pm
 Mandarin Orchard Hotel
 333 Orchard Rd. Singapore

LAWSON'S
 Auctioneers
 Click For More INFORMATION



Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad
 Advertiser Login
 Ways of Selling

Cheapest In Market! High Spec With Autotailgate!



Cheapest In Market! Loan Up To 90% And Attractive Trade In, View To Believe!
 StarAd



AutoInn
 An Inspiration For Car Buyers

click here to view
 our **PRISTINE USED CARS**
 at **GREAT PRICES**

Browse by Category Save Search Print
 Sort by Date Posted 20 results/page

4 vehicles | Search cabstar | Advanced Search | Search | View All

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection	cabstar	Any	Any	2017	Any	Any	Any	Available
------------------	---------	-----	-----	------	-----	-----	-----	-----------



☐ Nissan Cabstar \$59,800 \$7,000 /yr 31-Jan-2017 2,953 cc - Truck Available

Fuel Type: Diesel

Only 1 Owner. Accident Free Unit! Original Condition With No Repair Needed. As Pretty As Brand New But Without The Long Wait To Be Running On The Road. Best Of All, Beautiful Double Digits Number, Ope...

Car (S) Pte Ltd

Posted: 14-Jul-2016 Tags: 2017 Nissan Cabstar, Nissan Cabstar, Nissan, Cabstar, Used Nissan



☐ Nissan Cabstar \$75,800 \$8,800 /yr 28-Feb-2017 2,953 cc - Truck Available

Fuel Type: Diesel

Powerful And Responsive Engine. Smooth Transmission Power In Gear Box, Mint Interior And Exterior Condition. Original Paintwork And Zero Accident. Full Aluminium Checkered Deck, Good Condition Cabin A...

Posted: 15-Jul-2016 Tags: 2017 Nissan Cabstar, Nissan Cabstar, Nissan, Cabstar, Used Nissan



☐ Nissan Cabstar \$73,200 \$7,860 /yr 10-Nov-2017 2,953 cc 10 km Truck Available

Fuel Type: Diesel

Double Transferred Brand New Unit, Immediately Stock. Comes With Tan Chong Warranty And Servicing. Reliable And Low Maintenance. Call Now Before It's Sold!

OK2 Pte Ltd

Posted: 04-Jun-2016 Tags: 2017 Nissan Cabstar, Nissan Cabstar, Nissan, Cabstar, Used Nissan



☐ Nissan Cabstar \$68,800 \$7,280 /yr 29-Dec-2017 2,953 cc - Truck Available

Fuel Type: Diesel

00% Loan Available! Competitive Interest Rate! Fast, Easy Approve And Hassle Free Loan Procedure. Immediate Insurance Quotation! Highest Trade In For Your Current Vehicle! Agent Warranty Unit. No Gimm...

Posted: 10-Jul-2016 Tags: 2017 Nissan Cabstar, Nissan Cabstar, Nissan, Cabstar, Used Nissan

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

[Home](#)
[New Cars](#)
[Used Cars](#)
[Sell My Car](#)
[Directory](#)
[Products](#)
[Insurance](#)
[Article](#)
[Forum](#)
[Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, no COE cars & GPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy/sell cabstar, cabstar Singapore, used cabstar Singapore, used cabstar, used vehicles Singapore or even buy/sell cabstar Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for Singapore jobs, real estate properties for sale, motor, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are followed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com



SHORTLISTED HISTORY

Compare

[About Us](#)
[Careers](#)
[Contact Us](#)
[Sitemap](#)
[Terms of Service](#)
[Privacy Policy](#)
[Personal Data Protection Statement](#)

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: visionautowork@gmail.com

DATE : 18.07.18

TO : CHINA MOTOR CLAIMS DEPTS

VEHICLE NO : GBF7430R

MODEL : NISSAN CABSTAR

DATE OF ACCIDENT : 17.07.18

TIME OF ACCIDENT : 16:20HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	FRONT BUMPER <i>del</i>	1	\$ 743.70	\$ 743.70	✓
2	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 772.60	\$ 772.60	+
3	HEAD LAMP LH <i>cracked</i>	1	\$ 496.40	\$ 496.40	✓
4	HEAD LAMP LOWER GARNISH LH <i>del</i>	1	\$ 112.10	\$ 112.10	✓
5	HEAD LAMP UPPER GARNISH LH <i>missing</i>	1	\$ 154.50	\$ 154.50	✓
6	SIDE MIRROR LH (ROUND) <i>cracked</i>	1	\$ 130.30	\$ 130.30	✓
7	SIDE MIRROR LH (RECTANGLE) <i>new</i>	1	\$ 290.80	\$ 290.80	+
8	SIDE MIRROR STAND LH <i>best</i>	1	\$ 593.40	\$ 593.40	✓
9	SIDE MIRROR STAND TOP COVER LH <i>missing</i>	1	\$ 21.80	\$ 21.80	✓
10	FRONT GRILLE <i>2 new</i>	1	\$ 397.20	\$ 397.20	+
11	FRONT GRILLE LOGO <i>1 new</i>	1	\$ 64.10	\$ 64.10	+
12	FRONT PANEL EMBLEM 'CABSTAR' <i>new</i>	1	\$ 72.40	\$ 72.40	+
13	FRONT CORNER PANEL LH <i>disturbed</i>	1	\$ 426.70	\$ 426.70	✓
14	FRONT WINDSCREEN GLASS <i>cracked</i>	1	\$ 1,147.40	\$ 1,147.40	✓
15	FRONT WINDSCREEN MOULDING (SET) <i>new</i>	1	\$ 369.50	\$ 369.50	✓
16	FRONT WIPER BLADE <i>new</i>	2	\$ 89.30	\$ 178.60	+
17	CABIN BACK GLASS RUBBER <i>new</i>	1	\$ 242.80	\$ 242.80	✓
18	CABIN BACK PANEL <i>repair</i>	1	\$ 1,283.40	\$ 1,283.40	+
19	CABIN BACK PILLAR <i>repair</i>	1	\$ 974.70	\$ 974.70	+
20	CABIN HINGE <i>new</i>	1	\$ 2,641.30	\$ 2,641.30	+
21	CABIN LOCK SYSTEM <i>new</i>	1	\$ 1,279.70	\$ 1,279.70	+
22	CABIN LOCK HOUSING LH <i>repair</i>	1	\$ 426.30	\$ 426.30	+
23	CABIN FLOOR CHASSIS MEMBER LH <i>repair</i>	1	\$ 1,055.10	\$ 1,055.10	+
24	AIR CON BLOWER MOTOR	1	\$ 1,987.60	\$ 1,987.60	?
25	AIR CON COOLING COIL C/W HEATER	1	\$ 2,476.30	\$ 2,476.30	?
26	FRONT STEP PANEL GARNISH LH <i>cracked</i>	1	\$ 217.60	\$ 217.60	✓

27	FRONT DOOR LH <i>Distorted</i>	1	\$ 1,679.40	\$ 1,679.40	✓
28	FRONT DOOR ARCED RUBBER LH ?	1	\$ 104.30	\$ 104.30	
29	FRONT DOOR FRAME WEATHER STRIP LH <i>ut</i>	1	\$ 167.80	\$ 167.80	-
30	FRONT DOOR OUTER HANDLE LH <i>Neu</i>	1	\$ 198.40	\$ 198.40	+
31	FRONT DOOR SIGNAL LAMP LH <i>Neu</i>	1	\$ 57.90	\$ 57.90	+
32	FRONT DOOR WIRE HARNESS LH <i>Neu</i>	1	\$ 1,542.50	\$ 1,542.50	+
33	FRONT DOOR OUTERSTRIP LH <i>ut</i>	1	\$ 117.40	\$ 117.40	-
34	FRONT DOOR HINGE LH <i>Best</i>	2	\$ 65.10	\$ 130.20	-
35	FRONT DOOR CHECKER LH <i>Best</i>	1	\$ 107.40	\$ 107.40	✓
36	FRONT DOOR GLASS INNER STRIP LH <i>2 Neu</i>	1	\$ 95.30	\$ 95.30	+
37	FRONT DOOR GLASS CHANNEL LH <i>↓ m</i>	1	\$ 86.10	\$ 86.10	+
38	FRONT DOOR GLASS CORNER GARNISH LH <i>ut</i>	1	\$ 109.20	\$ 109.20	-
39	FRONT DOOR POWER WINDOW MOTOR LH <i>Neu</i>	1	\$ 547.30	\$ 547.30	+
40	FRONT DOOR WEATHER STRIP LH <i>ut</i>	1	\$ 185.10	\$ 185.10	-
41	FRONT DOOR INNER LOCK LH <i>Revised</i>	1	\$ 386.50	\$ 386.50	-
42	FRONT DOOR LOCK CATCH LH <i>Neu</i>	1	\$ 25.10	\$ 25.10	+
43	FRONT DOOR INNER TRIM BOARD LH ?	1	\$ 874.40	\$ 874.40	
44	FRONT DOOR REGULATOR LH ?	1	\$ 257.90	\$ 257.90	
45	FRONT DOOR PILLAR (OUTER) LH <i>Distorted</i>	1	\$ 1,142.80	\$ 1,142.80	✓
46	FRONT DOOR PILLAR (FRONT INNER) LH <i>Revised</i>	1	\$ 1,239.60	\$ 1,239.60	+
47	FRONT WHEEL MUDGUARD LH <i>Neu</i>	1	\$ 768.40	\$ 768.40	+
48	FRONT WHEEL HOUSE PANEL LH <i>Neu</i>	1	\$ 854.30	\$ 854.30	+
49	DASHBOARD <i>Combined</i>	1	\$ 1,179.60	\$ 1,179.60	✓
50	DASHBOARD REINFORCEMENT <i>Neu</i>	1	\$ 984.50	\$ 984.50	+
51	DASH BOARD LOWER CENTER GARNISH ?	1	\$ 412.80	\$ 412.80	
52	GLOVE COMPARTMENT ?	1	\$ 521.60	\$ 521.60	
53	TAIL LAMP <i>Combined</i>	2	\$ 258.90	\$ 517.80	✓
54	TAIL LAMP SUPPORT BRACKET <i>Best</i>	1	\$ 104.30	\$ 104.30	✓
55	REAR NUMBER PLATE SUPPORT BRACKET <i>Best</i>	1	\$ 169.50	\$ 169.50	✓
56	SIDE GATE <i>Distorted</i>	2	\$ 2,136.80	\$ 4,273.60	✓
57	CARGO BED FRONT PANEL <i>Distorted</i>	1	\$ 1,694.30	\$ 1,694.30	✓
58	REAR END PANEL <i>Revised</i>	1	\$ 985.60	\$ 985.60	+

TOTAL PRICE \$ 40,077.20
 LESS 10% \$ 4,007.72
 SUB TOTAL PRICE \$ 36,069.48

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT ERP BRACKET <i>Neu</i>	1	\$ 40.00	\$ 40.00
2	HEAD LAMP LOWER GARNISH CLIP LH (SET) <i>Neu</i>	1	\$ 30.00	\$ 30.00
3	FRONT DOOR PILLAR SEALANT RH <i>Neu</i>	1	\$ 150.00	\$ 150.00
4	FRONT DOOR INNER TRIM BOARD CLIP LH (SET) <i>Neu</i>	1	\$ 50.00	\$ 50.00
5	FRONT DOOR LTA STICKER <i>Neu</i>	1	\$ 40.00	\$ 40.00
6	DASHBOARD CLIP (SET) <i>Neu</i>	1	\$ 150.00	\$ 150.00

7	REAR NUMBER PLATE <i>Best</i>	1	\$ 50.00	\$ 50.00	
8	CARGO BED LIFT PLATFORM <i>?</i>	1	\$ 12,000.00	\$ 12,000.00	
9	CARGO BED LIFTING ARM <i>?</i>	1	\$ 10,000.00	\$ 10,000.00	
10	CARGO BED LIFTING CYLINDER (SET) BIG <i>?</i>	1	\$ 6,000.00	\$ 6,000.00	
11	CARGO BED TILTING CYLINDER (SET) SMALL <i>?</i>	1	\$ 4,000.00	\$ 4,000.00	
12	CARGO BED LIFT SAFETY REINFORCEMENT <i>8?</i>	2	\$ 850.00	\$ 1,700.00	<i>?</i>
13	CARGO BED LIFT SAFETY REINFORCEMENT STICKER <i>nu</i>	2	\$ 120.00	\$ 240.00	<i>50.</i>
14	CARGO BED FLOOR BOARD COVER (ALUMINIUM) <i>Best</i>	1	\$ 3,800.00	\$ 3,800.00	<i>1200</i>
15	REAR SIDE GATE INNER BOARD COVER PROTECTION (ALUMINIUM) <i>nu</i>	2	\$ 600.00	\$ 1,200.00	<i>1000</i>
16	REAR STICKER '70KM/H' <i>nu</i>	1	\$ 30.00	\$ 30.00	<i>15</i>
17	REVERSE SENSOR (SET) <i>Revised</i>	1	\$ 220.00	\$ 220.00	<i>200</i>
18	REAR TOOLS BOX (SPECIAL TYPE) <i>Best</i>	1	\$ 3,800.00	\$ 3,800.00	<i>1000</i>

TOTAL \$ 43,500.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK	\$ 2,000.00	<i>1200</i>
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,600.00	<i>1000</i>
3	TO SPRAY TUFF COAT	\$ 250.00	<i>80</i>
4	WIRING, BULB CHECKING	\$ 350.00	<i>60</i>
5	CONDUCT WATER TER LEAKAGE TEST	\$ 150.00	<i>x</i>
6	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	<i>120</i>
7	TRANSFER FRONT DOOR MECHANISM LH	\$ 80.00	<i>40</i>
8	REMOVE AND REINSTALL WINDOW GLASS LH	\$ 60.00	<i>40</i>
9	REFOCUS HEADLAMP BEAM	\$ 60.00	<i>x</i>
10	VACCUM AND CLEAN FRONT WINDSCREEN GLASS	\$ 180.00	<i>120 x.</i>
11	REMOVE AND REINSTALL FRONT CABIN BACK GLASS	\$ 100.00	<i>60</i>
12	FRONT CHASSIS ALIGHMENT	\$ 250.00	<i>x.</i>
13	REMOVE AND REFIX AIRCON BLOWER AND REFILL AIRCON GAS	\$ 350.00	<i>250</i>
14	REMOVE AND REFIX DASHBOARD AND INTERNAL WIRING	\$ 650.00	<i>220</i>
15	REMOVE AND REFIX AUDIO SYSTEM	\$ 200.00	<i>x.</i>

16	REMOVE AND REFIX FRONT WINDSCREEN	\$ 120.00	✓
----	-----------------------------------	-----------	---

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 2,000.00	800.
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,800.00	1000.
3	REMOVE AND REFIX SIDE GATE (ALUMINIUM)	\$ 150.00	60.
4	REMOVE AND REFIX CARGO BED (ALUMINIUM)	\$ 1,200.00	120.
5	REMOVE AND REFIX REAR RAILLING	\$ 150.00	60.
6	ROMEVE & REINSTALL TRUCK LIFE GATE	\$ 1,600.00	200.
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x.

TOTAL \$ 13,730.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 79,569.48
 TOTAL LABOUR COST : \$ 13,730.00
 TOTAL REPAIR COST : \$ 93,299.48

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,


 SERVICE ADVISOR
 ABBY
 HP : 9856 4815

Adrian Ling.
 19/07/18.
 14 Days.

...CLAIM SUBFOLDER...(Pending for Survey Report)






































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Jul 2018		19 Jul 2018 10:22 Edit Adj Rpt	S\$24,063.99 Edit Estimates	S\$24,063.99 View Rpt		Pending for Survey Report Cancel Case















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	ID: -								
Main Claimant:	KANG JIE TECHNOLOGY LLP								
Vehicle Reg. No.:	GBF7430R	Date of Loss:	17/07/2018 00:00 - :59 [16 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D03540C02	Policy/Cover Note No.:	DMCVSN1806661800						
Vehicle Reg. No. (Insured):	GBH1982T	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Vision Autowork Pte Ltd (HQ) 8 KAKI BUKIT AVE 4,, #08-09 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 6341 6789								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Hwang Shiang Yi - 63896541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 30/07/2018]								
Adj Asg. Remarks:	NO EST, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

















Claim Documents

*GBF7430R (SNM18D03540C02)
[GBH1982T]

TP
KANG JIE TECHNOLOGY LLP
Jul 17 2018 12:00AM
[-]
Vision Autowork Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
2	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
3	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
4	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
5	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
6	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
7	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
8	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
9	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
10	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
11	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
12	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
13	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
14	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
15	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
16	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
17	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
18	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
19	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
20	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
21	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
22	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
23	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
24	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
25	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
26	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
27	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
28	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
29	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
30	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
31	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
32	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
33	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
34	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
35	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
36	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
37	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
39	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
40	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
41	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
42	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
43	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
44	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
45	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
46	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
47	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
48	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
49	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
50	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
51	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
52	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
53	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
54	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
55	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
56	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
57	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
58	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
59	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
60	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
61	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
62	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
63	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
64	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
65	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
66	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
67	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
68	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
69	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
70	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
71	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
72	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
73	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
74	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
75	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
76	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
77	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
78	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
79	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
80	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
81	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
82	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
83	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
84	23/07/18 14:54	General View	Load JPG	<input checked="" type="checkbox"/>
85	23/07/18 14:54	General View	Load JPG	<input checked="" type="checkbox"/>
86	23/07/18 14:54	General View	Load JPG	<input checked="" type="checkbox"/>
87	23/07/18 14:54	General View	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
89	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
90	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
91	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
92	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
93	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
94	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
95	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
96	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
97	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
98	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
99	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
100	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
101	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
102	23/07/18 14:54	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	19/07/18 10:21	PRS WITH TP GIA	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18013157/ATD3Q2

Date: 30/07/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN1806661800

Claimant Vehicle
No : GBF7430RInsured Vehicle
No : GBH1982T

Date of Loss: 17/07/2018

Nature of Claim: TP

Claim
No: SNM18D03540C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBF7430R

Make & Model: NISSAN CABSTAR, 3.0 (M)

Reg. Date: 28/02/2017 (Man. Year: 2016)

Colour: Silver

Engine Capacity: 2953 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: ZD30015078N

Chassis No: JN1SC2F24Z0859241

Odometer: 54948 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185 R15C

Rear Tyre Size: 155 R12C

Front Left Side: Wanli 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Wanli 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	79,569.48	18,633.99	60,935.49	76.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,730.00	5,430.00	8,300.00	60.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	93,299.48	24,063.99	69,235.49	74.21
+ GST 7.00/7.00% (S\$)	6,530.96	1,684.48	4,846.48	74.21
Nett Amount (S\$)	99,830.44	25,748.47	74,081.97	74.21

INSPECTION

Date of Assignment: 19/07/2018

Date Inspected: 19/07/2018 Inspected At:

Vision Autowork Pte Ltd (HQ)
8 KAKI BUKIT AVE 4, #08-09 PREMIER
@ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 14.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$39,671.51 NETT)

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 30 Jul 2018)	
Parts:	N/A	NISSAN CABSTAR 3.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF7430R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	743.70 FL	*743.70 FL
2	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	772.60 FL	*- FL
3	1		*HEAD LAMP LH	Cracked	496.40 FL	*496.40 FL
4	1		*HEAD LAMP LOWER GARNISH LH	Deformed	112.10 FL	*112.10 FL
5	1		*HEAD LAMP UPPER GARNISH LH	Missing	154.50 FL	*154.50 FL
6	1		*SIDE MIRROR LH (ROUND)	Cracked	130.30 FL	*130.30 FL
7	1		*SIDE MIRROR LH (RECTANGLE)	Not Necessary	290.80 FL	*- FL
8	1		*SIDE MIRROR STAND LH	Bent	593.40 FL	*593.40 FL
9	1		*SIDE MIRROR STAND TOP COVER LH	Missing	21.80 FL	*21.80 FL
10	1		*FRONT GRILLE	Not Necessary	397.20 FL	*- FL
11	1		*FRONT GRILLE LOGO	Not Necessary	64.10 FL	*- FL
12	1		*FRONT PANEL EMBLEM CABSTAR	Not Necessary	72.40 FL	*- FL
13	1		*FRONT CORNER PANEL LH	Distorted	426.70 FL	*426.70 FL
14	1		*FRONT WINDSCREEN GLASS	Cracked	1,147.40 FL	*1,147.40 FL
15	1		*SET FRONT WINDSCREEN MOULDING	Necessary	369.50 FL	*369.50 FL
16	2		*FRONT WIPER BLADE	Not Necessary	178.60 FL	*- FL
17	1		*CABIN BACK GLASS RUBBER	Necessary	242.80 FL	*242.80 FL
18	1		*CABIN BACK PANEL	Repair	1,283.40 FL	*- FL
19	1		*CABIN BACK PILLAR	Repair	974.70 FL	*- FL
20	1		*CABIN HINGE	Not Necessary	2,641.30 FL	*- FL
21	1		*CABIN LOCK SYSTEM	Not Necessary	1,279.70 FL	*- FL
22	1		*CABIN LOCK HOUSING LH	Repair	426.30 FL	*- FL
23	1		*CABIN FLOOR CHASSIS MEMBER LH	Repair	1,055.10 FL	*- FL
24	1		*AIR CON BLOWER MOTOR	*Check	1,987.60 FL	*- FL
25	1		*AIR CON COOLING COIL C/W HEATER	*Check	2,476.30 FL	*- FL
26	1		*FRONT STEP PANEL GARNISH LH	Cracked	217.60 FL	*217.60 FL
27	1		*FRONT DOOR LH	Distorted	1,679.40 FL	*1,679.40 FL
28	1		*FRONT DOOR ARCED RUBBER LH	*Check	104.30 FL	*- FL
29	1		*FRONT DOOR FRAME WEATHER STRIP LH	Cut	167.80 FL	*167.80 FL
30	1		*FRONT DOOR OUTER HANDLE LH	Not Necessary	198.40 FL	*- FL
31	1		*FRONT DOOR SIGNAL LAMP LH		57.90 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
32	1		*FRONT DOOR WIRE HARNESS LH	Not Necessary	1,542.50 FL	*- FL
33	1		*FRONT DOOR OUTERSTRIP LH	Cut	117.40 FL	*117.40 FL
34	2		*FRONT DOOR HINGE LH	Bent	130.20 FL	*130.20 FL
35	1		*FRONT DOOR CHECKER LH	Bent	107.40 FL	*107.40 FL
36	1		*FRONT DOOR GLASS INNER STRIP LH	Not Necessary	95.30 FL	*- FL
37	1		*FRONT DOOR GLASS CHANNEL LH	Not Necessary	86.10 FL	*- FL
38	1		*FRONT DOOR GLASS CORNER GARNISH LH	Cut	109.20 FL	*109.20 FL
39	1		*FRONT DOOR POWER WINDOW MOTOR LH	Not Necessary	547.30 FL	*- FL
40	1		*FRONT DOOR WEATHERSTRIP LH	Cut	185.10 FL	*185.10 FL
41	1		*FRONT DOOR INNER LOCK LH	Damaged	386.50 FL	*386.50 FL
42	1		*FRONT DOOR LOCK CATCH LH	Not Necessary	25.10 FL	*- FL
43	1		*FRONT DOOR INNER TRIM BOARD LH	*Check	874.40 FL	*- FL
44	1		*FRONT DOOR REGULATOR LH	*Check	257.90 FL	*- FL
45	1		*FRONT DOOR PILLAR (OUTER) LH	Distorted	1,142.80 FL	*1,142.80 FL
46	1		*FRONT DOOR PILLAR (FRONT INNER)LH	Repair	1,239.60 FL	*- FL
47	1		*FRONT WHEEL MUDGUARD LH	Not Necessary	768.40 FL	*- FL
48	1		*FRONT WHEEL HOUSE PANEL LH	Not Necessary	854.30 FL	*- FL
49	1		*DASHBOARD	Cracked	1,179.60 FL	*1,179.60 FL
50	1		*DASHBOARD REINFORCEMENT	Not Necessary	984.50 FL	*- FL
51	1		*DASH BOARD LOWER CENTER GARNISH	*Check	412.80 FL	*- FL
52	1		*GLOVE COMPARTMENT	*Check	521.60 FL	*- FL
53	2		*TAIL LAMP	Cracked	517.80 FL	*517.80 FL
54	1		*TAIL LAMP SUPPORT BRACKET	Bent	104.30 FL	*104.30 FL
55	1		*REAR NUMBER PLATE SUPPORT BRACKET	Bent	169.50 FL	*169.50 FL
56	2		*SIDE GATE	Dented	4,273.60 FL	*4,273.60 FL
57	1		*CARGO BED FRONT PANEL	Dented	1,694.30 FL	*1,694.30 FL
58	1		*REAR END PANEL	Repair	985.60 FL	*- FL
59	1		*FRONT ERP BRACKET	Necessary	40.00 FS	*20.00 FS
60	1		*SET HEAD LAMP LOWER GARNISH CLIP LH	Necessary	30.00 FS	*30.00 FS
61	1		*FRONT DOOR PILLAR SEALANT RH	Not Necessary	150.00 FS	*- FS
62	1		*SET FRONT DOOR INNER TRIM BOARD CLIP LH	Necessary	50.00 FS	*30.00 FS
63	1		*FRONT DOOR LTA STICKER	Necessary	40.00 FS	*30.00 FS
64	1		*SET DASHBOARD CLIP	Necessary	150.00 FS	*50.00 FS
65	1		*REAR NUMBER PLATE	Bent	50.00 FS	*50.00 FS
66	1		*CARGO BED LIFT PLATFORM	*Check	12,000.00 FS	*- FS
67	1		*CARGO BED LIFTING ARM	*Check	10,000.00 FS	*- FS
68	1		*SET CARGO BED LIFTING CYCLINDER BIG	*Check	6,000.00 FS	*- FS
69	1		*SET CARGO BED TILTING CYCLINDER SMALL	*Check	4,000.00 FS	*- FS
70	2		*CARGO BED LIFT SAFETY REINFORCEMENT	*Check	1,700.00 FS	*- FS
71	2		*CARGO BED LIFT SAFETY REINFORCEMENT STICKER	Necessary	240.00 FS	*50.00 FS
72	1		*CARGO BED FLOOR BOARD COVER (ALUMINIUM)	Bent	3,800.00 FS	*1,200.00 FS
73	2		*REAR SIDE GATE INNER BOARD COVER PROTECTION (ALUMINIUM)	Necessary	1,200.00 FS	*1,000.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
74	1		*REAR STICKER 70KM/H	Necessary	30.00 FS	*15.00 FS
75	1		*SET REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
76	1		*REAR TOOLS BOX (SPECIAL TYPE)	Bent	3,800.00 FS	*1,000.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	83,577.20	20,296.10
- List Item Discount on L Items 10.00/10.00% (\$\$)	4,007.72	1,662.11

Total Parts (\$\$)	79,569.48	18,633.99
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,WELD,CUT ,ADJUST ,KNOCK	New	2,000.00	1,200.00
2	TO PUTTY,SPRAY PAINT ,POLISH WAX	New	1,600.00	1,000.00
3	TO SPRAY TUFF COAT	New	250.00	80.00
4	WIRING ,BULB CHECKING	New	350.00	60.00
5	CONDUCT WATER TER LEAKAGE TEST	New	150.00	0.00
6	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	250.00	120.00
7	TRANSFER FRONT DOOR MECHANISM LH	New	80.00	40.00
8	REMOVE AND REINSTALL WINDOW GLASS LH	New	60.00	40.00
9	REFOCUS HEADLAMP BEAM	New	60.00	0.00
10	VACUUM AND CLEAN FRONT WINDSCREEN GLASS	New	180.00	0.00
11	REMOVE AND REINSTALL FRONT CABIN BACK GLASS	New	100.00	60.00
12	FRONT CHASSIS ALIGNMENT	New	250.00	0.00
13	REMOVE AND REFIX AIRCON BLOWER AND REFILL AIRCON GAS	New	350.00	250.00
14	REMOVE AND REFIX DASHBOARD AND INTERNAL WIRING	New	650.00	220.00
15	REMOVE AND REFIX AUDIO SYSTEM	New	200.00	0.00
16	REMOVE AND REFIX FRONT WINDSCREEN	New	120.00	120.00
17	TO PANEL BEAT ,WELD,CUT ,ADJUST ,KNOCK	New	2,000.00	800.00
18	TO PUTTY,SPRAY PAINT ,POLISH WAX	New	1,800.00	1,000.00
19	REMOVE AND REFIX SIDE GATE (ALUMINIUM)	New	150.00	60.00
20	REMOVE AND REFIX CARGO BED (ALUMINIUM)	New	1,200.00	120.00
21	REMOVE AND REFIX REAR RAILLING	New	150.00	60.00
22	REMOVE & REINSTALL TRUCK LIFE GATE	New	1,600.00	200.00
23	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			13,730.00	5,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >