



LIM YEW BOO SPRAY PAINT CO.

Blk 10, Sector C, #01-10, Sin Ming Ind. Est. Singapore 575645
 No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare, Singapore 575721
 Tel: 6453 4177 Fax: 6459 3724
 Email: limyewboo@singnet.com.sg
 Company Reg. No. : 200514/00L

MSIG INSURANCE (SINGAPORE) PTE LTD
 16 RAFFLES QUAY #24-01
 HONG LEONG BUILDING SINGAPORE 048581

Attention : Motor Claim Department
 Contact : 62209644 Fax No. : 62257402

Estimate : TP18/042

Date : 23/07/2018
 Vehicle Num. : SLN 9527Y
 Make/Model : MAZDA 6-2016
 Chassis/Eng# : JM6GL1071H0107340/PE20848533
 Accident Date : 17/07/2018
 Claim No. :
 Reference : LYB/SLN9527Y/MSIG/tp
 Policy No. :

Not Authorized
Resurvey B&C paint
8 1429-12

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS : FRONT GRILLE BASE		114.80
2.	2	FRONT GRILLE (BOTTOM)	137.70	275.40
3.	1	FRONT EMBLEM		122.70
4.	8	FRONT GRILLE SHORT CHROME	46.80	374.40
5.	2	FRONT GRILLE LONG CHROME	75.20	150.40
6.	1	FRONT NOSE PANEL		448.50

List Total S\$: 1,486.20
 10.00% Discount S\$: 148.62
20%
 1,337.58

1.	1	SPECIAL NETT ITEMS : FRONT NO PLATE (EMBOSS) + HOLDER		55.00
2.	2	FRONT SENSOR	283.00	566.00

Special Nett Total S\$: 621.00

LABOUR :
 TO CHECK & RECTIFY WIRING SYSTEM : 60.00
 LABOUR TO REPLACE THE SENSOR & CHECK SENSOR FUNCTIONS : 80.00
 TO RE-ALGN ON AFFECTED FRONT BUMPER, INNER PANEL, LABOUR TO REPLACE ABOVE RECOMMENDED PARTS : 250.00

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

All cheques should be crossed and made payable to Lim Yew Boo Spray Paint Co.

Customer

E. & O. E.